



13, 403 USF
15, 011 RSF

*THIS FLOOR IS CONFIGURED FOR A FULL FLOOR LBER
A RATED ACCESS CORRIDOR IS CURRENTLY ABSENT.
EXISTING INTERIOR PARTITIONS HAVE NOT BEEN SURVEYED.

NOT TO SCALE

