



VIA ELECTRONIC MAIL

June 14, 2022

**SUBJECT: Phase I Environmental Site Assessment
JCB 6855
6855 Jimmy Carter Boulevard
Norcross, Gwinnett County, Georgia 30071**

Point to Point Environmental (P2P) has completed the enclosed Phase I Environmental Site Assessment (ESA) for the above referenced site.

During the site reconnaissance performed on June 10, 2022, no Recognized Environmental Conditions (RECs) were identified onsite. A search of various local, state and federal databases revealed 37 mapped sites within the applicable radii of the subject property. None of these sites are considered to be an REC to the subject site. Since no RECs have been identified via either the site reconnaissance or government records, **P2P does not recommend any additional assessment for the subject property at this time.**

P2P appreciates the opportunity to provide you with our services. If you have any questions regarding the enclosed information, please do not hesitate to call us at (678) 656-4435.

Sincerely,

A handwritten signature in blue ink, appearing to read "Brian Mainor".

Brian Mainor, PMP
Project Manager

Enclosure

PHASE I ENVIRONMENTAL SITE ASSESSMENT

of

**JCB 6855
6855 Jimmy Carter Boulevard
Norcross, Gwinnett County, Georgia 30071**

PREPARED FOR:

**PREPARED BY:
Point to Point Environmental
1010 Pennsylvania Avenue
McDonough, GA 30253**

June 2022

TABLE OF CONTENTS

1) Summary	3
2) Introduction	3
a) Purpose.....	4
b) Limitations and Exceptions.....	4
c) Special Terms and Conditions	4
d) User Reliance.....	4
3) Site Description	5
a) Location and Legal Description	5
b) Site and Vicinity General Characteristics	5
c) Current Use of the Property.....	5
d) Description of Structures, Roads, Other Improvements on the Site	5
e) Current Uses of the Adjoining Properties	5
4) User Provided Information	6
a) Title Records.....	6
b) Environmental Liens or Activity and Use Limitations.....	6
c) Specialized Knowledge	6
d) Valuation Reduction for Environmental Issues.....	6
e) Owner, Property Manager, and Occupant Information.....	6
f) Reason for Performing Phase I.....	6
5) Records Review	6
a) Standard Environmental Record Sources.....	6
i) Mapped Sites	9
ii) Unmapped Sites	12
b) Additional Environmental Records Sources	12
c) Physical Setting Source(s).....	12
d) Historical Use Information on the Property.....	12
e) Historical Use Information on Adjoining Properties	13
f) Data Gaps	13
6) Site Reconnaissance.....	13
a) Methodology and Limiting Conditions.....	13
b) General Site Setting	14
7) Information from Interviews	15
8) Findings and Conclusions.....	16
9) References	17
10) Qualifications of Environmental Professionals.....	17
11) Environmental Professional Certification and Statement of Impartiality	17

TABLE OF APPENDICES

Appendix A	Figures
Appendix B	Database Report
Appendix C	Topographic Maps
Appendix D	Historical Aerial Report
Appendix E	Historical City Directory Report
Appendix F	Certificate of Liability Insurance

1) Summary

This report presents the results of the Phase I Environmental Site Assessment (ESA) conducted by Point to Point Environmental (P2P) on the subject property, hereinafter known as the site. The ESA includes information gathered from telephone and personal interviews, a physical reconnaissance of the site, a general reconnaissance of the site vicinity and surrounding properties, historical topographic maps, historical aerial photographs, environmental databases and public records. No soil and/or groundwater samples were collected as part of this assessment. **Based on the information reviewed, no evidence has been procured that indicates recognized environmental conditions (RECs) exist at the site.** As defined by the American Society for Testing and Materials (ASTM), an REC means “the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of future release to the environment.” A REC can additionally be categorized as historical (HREC) or controlled (CREC). ASTM defines a HREC as a past release of any hazardous substance or petroleum product that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority of meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls. ASTM defines a CREC as a recognized environmental condition resulting from a past release of hazardous substances or petroleum products that have been addressed to the satisfaction of the applicable regulatory authority. The hazardous substances or petroleum products that are allowed to remain in place are subject to the implementation of required controls.

During the site reconnaissance performed on June 10, 2022, no RECs were identified onsite. A search of various local, state and federal databases revealed 37 mapped sites within the applicable ASTM radii of the subject property. None of these sites are considered to be an REC to the subject site. Since no RECs have been identified via either the site reconnaissance or government records, **P2P does not recommend any additional assessment for the subject property at this time.**

2) Introduction

This assessment was conducted on behalf of _____ The subject site currently contains an office park and church which are bordered by an asphalt-paved parking lot and grassed and wooded areas that collectively comprises approximately 3.31 acres. This assessment was limited to the office park, church, asphalt-paved parking lot, and grassed and wooded areas.

a) **Purpose**

The purpose of this ESA is to identify, to the extent feasible, pursuant to the processes described herein, RECs in connection with the site. This is accomplished by having an environmental professional evaluate the applicable data for this and surrounding sites.

b) **Limitations and Exceptions**

In conducting this assessment, P2P relied on interviews with the property owner and other individuals knowledgeable about the site, an area reconnaissance, and public information best available at the time of the assessment. It is assumed that the information provided to P2P is true and accurate. No guarantee is expressed or implied that new or additional data would not change the professional opinion regarding the existence of, or potential for, RECs on this site. No environmental assessment can wholly eliminate uncertainty regarding the potential for RECs in connection with any site. P2P has performed appropriate inquiry for the ESA in substantial conformance with the Environmental Protection Agency Standards and Practices for All Appropriate Inquiries (40 CFR Part 312) and the scope and limitations of ASTM Standard Practice E1527-13.

c) **Special Terms and Conditions**

This ESA includes no sampling of any kind, including air, surface water, flora, fauna, soil, or drinking water. Any buried or dumped materials on site would not be discovered unless readily visible evidence of the burial or dumping was observed on the surface. The subject environmental assessment was performed in accordance with generally acceptable methods and practices of the profession. More in-depth assessment was beyond the scope of this project and would require a more focused Phase II ESA.

d) **User Reliance**

No other party is entitled to rely on this report for any purpose. P2P makes no representation or warranty concerning the accuracy or completeness of this report or any other representation or warranty, except as specifically agreed in the contract binding P2P and

3) Site Description

a) Location and Legal Description

The site is located at 6855 Jimmy Carter Boulevard in Norcross, Georgia, Gwinnett County. An aerial photograph showing property tax parcel boundaries of the site is shown on Figure 1 in Appendix A. The property is listed in the Gwinnett County tax records as parcel numbers 6275 201. The layout of the site is depicted on Figure 2.

b) Site and Vicinity General Characteristics

The site is located in a commercial-industrial-residential area of Gwinnett County and comprises 3.31 acres. The subject property can be accessed from the west via Jimmy Carter Boulevard. The subject site contains an office park and a church which are bordered by an asphalt-paved parking lot and grassed and wooded areas. Three structures are located onsite, including two office buildings and a church. Commercial properties surround the subject site on all sides. The Pet Suites Norcross Kennels and Captain D's Restaurant are located to the north of the subject site. The FedEx Ground – Norcross Package facility is located to the east of the subject site. The MJay's Specialty Baked Foods bakery and Mallen Industries, Inc. wholesale storage warehouse are located to the west of the subject site, across Jimmy Carter Boulevard. The Veridian Business Park is located to the south of the subject site. The site is connected to the Gwinnett County water and sewage systems. The property is generally flat and slopes towards the north.

c) Current Use of the Property

The site currently contains an office park and a church.

d) Description of Structures, Roads, Other Improvements on the Site

The subject property can be accessed from the west via Jimmy Carter Boulevard. The subject site contains an office park and a church which are bordered by an asphalt-paved parking lot and grassed and wooded areas. Three structures are located onsite, including two office buildings and a church.

e) Current Uses of the Adjoining Properties

Commercial properties surround the subject site on all sides. The Pet Suites Norcross Kennels and Captain D's Restaurant are located to the north of the subject site. The FedEx Ground – Norcross Package facility is located to the east of the subject site. The MJay's Specialty Baked Foods bakery and Mallen

Industries, Inc. wholesale storage warehouse are located to the west of the subject site, across Jimmy Carter Boulevard. The Veridian Business Park is located to the south of the subject site.

4) User Provided Information

a) Title Records

A Chain of Title detailing historical ownership was not specified within the scope of this assessment.

b) Environmental Liens or Activity and Use Limitations

An Environmental Lien and AUL Search was not specified within the scope of this assessment.

c) Specialized Knowledge

No specialized knowledge concerning the site was provided.

d) Valuation Reduction for Environmental Issues

No environmental conditions were observed or identified indicating that this property's value has been directly affected by any environmental issues.

e) Owner, Property Manager, and Occupant Information

Based on current Gwinnett County tax records, 6855 Jimmy Carter Boulevard, LLC owns the subject site.

f) Reason for Performing Phase I

This Phase I ESA was performed to meet the institution's requirements for risk management and liability limitations.

5) Records Review

a) Standard Environmental Record Sources

P2P contracted with Environmental Risk Information Service (ERIS) to conduct a review of state and federal public databases with regards to sites of environmental concern in the vicinity. The complete listing of databases, descriptions, and maps depicting results are included in the Database Report, which is provided in Appendix B.

<u>Database</u>	<u>Search Distance (miles)</u>
National Priority List (NPL).....	1.00
Proposed NPL.....	1.00
NPL Liens	TP
Delisted NPL	1.00
Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS).....	0.50
CERCLIS – Federal Facility	0.50
CERCLIS – No Further Remedial Action Planned	0.50
Corrective Action Report (CORRACTS).....	1.00
Resource Conservation and Recovery Act (RCRA) – Treatment, Storage, and Disposal (TSDF).....	0.50
RCRA Large Quantity Generators (LQG)	0.25
RCRA Small Quantity Generators (SQG)	0.25
RCRA Conditionally Exempt Small Quantity Generators (CESQG).....	0.25
U.S. Engineering Controls	0.50
U.S. Institutional Controls	0.50
Land Use Controls Information System (LUCIS).....	0.50
Emergency Response Notification System (ERNS).....	TP
State Hazardous Waste (SHWS).....	1.00
GA Non-Hazardous Sites Inventory (HSI).....	1.00
State Landfill (SWF/LF).....	0.50
Leaking Underground Storage Tank (LUST)	0.50
Indian LUST	0.50
Underground Storage Tank (UST)	0.25
Aboveground Storage Tank (AST)	0.25
Indian UST	0.25
FEMA UST.....	0.25
AUL.....	0.50
Institutional Controls	0.50
Voluntary Cleanup Program (VCP).....	0.50
Indian VCP	0.50
BROWNFIELDS.....	0.50
U.S. BROWNFIELDS	0.50
Debris Region 9	0.50
Open Dump Inventory (ODI)	0.50
SWRCY	0.50
Historic Landfills.....	0.50
Indian ODI	0.50

U.S. Clandestine Drug Labs (CDL).....	TP
Delisted SHWS.....	1.00
U.S. Historic CDL.....	TP
Liens 2	TP
Hazardous Materials Information Reporting System (HMIRS).....	TP
Georgia Spills (SPILLS)	TP
SPILLS 90	TP
Resource Conservation and Recovery Act (RCRA) – Non-Generator.....	0.25
Incident and Accident Data (DOT OPS).....	TP
Department of Defense (DOD)	1.00
Formerly Used Defense Sites (FUDS)	1.00
Superfund (CERCLIS) Consent Decrees CONSENT	1.00
Records of Decision (ROD)	1.00
Uranium Mill Tailings Sites (UMTRA)	0.50
US MINES	0.25
Toxic Chemical Release Inventory System (TRIS)	TP
Toxic Substances Control Act (TSCA)	TP
Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) / TSCA Tracking System (FTTS).....	TP
Historic FTTS.....	TP
Section 7 Tracking Systems (SSTS)	TP
Integrated Compliance Information System (ICIS)	TP
Polychlorinated Biphenyls (PCB) Activity Database System (PADS).....	TP
Materials Licensing Tracking System (MLTS)	TP
Radiation Information Database (RADINFO)	TP
Facility Index System / Facility Identification Initiative Program Summary Report (FINDS).....	TP
Resource Conservation and Recovery Act (RCRA) Administrative Action Tracking System (RAATS).....	TP
RMP	TP
NPDES Wastewater Permit List.....	TP
Drycleaners	0.25
Permitted Facility and Emissions Listing (AIRS)	TP
TIER 2.....	TP
Indian Reservations.....	1.00
State Coalition for Remediation (SCRD) of Drycleaners	0.50
US AIRS	TP
PRP	TP

Lead Smelters.....	TP
2020 COR ACTION	0.25
EPA Watchlist.....	TP
Coal Combustion Residues Surface Impoundments List (Coal Ash EPA).....	0.50
US Financial Assurance	TP
Steam-Electric Plan Operation Data (Coal Ash DOE)	TP
PCB Transformer	TP
Coal Ash Disposal Site Listing.....	0.50
Financial Assurance.....	TP

i) Mapped Sites

A total of 37 mapped sites were identified within the applicable radii from the subject site. However, due to the distance and elevation difference of these sites from the subject site, only sites within 615 feet of the subject site (eight sites) have been described within this report.

The Pet Suites – Norcross facility is listed as being located 88 feet north / northwest of the subject site. The facility was field verified to be located directly adjacent to the north and downgradient of the subject site. The Pet Suites – Norcross facility is listed on the FINDS / FRS database. The FINDS / FRS database reported stormwater discharge has historically been monitored at the facility address. No violations were reported. Since no violations were reported and due to the elevation difference from the subject site, the Pet Suites – Norcross facility is not considered to be an REC.

The Norcom, Inc. facility is listed as being located 245 feet west / southwest of the subject site. The facility is listed as being located 190 feet west and cross-gradient of the subject site, across Jimmy Carter Boulevard. The Norcom, Inc. facility is listed on the RCRA Non-Gen database. The RCRA Non-Gen database reported the facility was listed as being a non-generating handler of several solvents from May 1993 until at least January 1995. No violations were reported. Since no violations were reported and due to the distance and elevation difference from the subject site, the Norcom, Inc. facility is not considered to be an REC.

The RaceTrac #2329 facility is listed as being located 339 feet northwest of the subject site. The facility was field verified to be located 195 feet northwest and downgradient of the subject site. The RaceTrac #2329 facility is listed on the UST, SPILLS, and ALT Fuels databases. The UST database reported the facility is active with one 20,000-gallon gasoline UST, one compartmentalized 20,000-gallon gasoline / diesel UST, and one 15,000-gallon gasoline UST currently in-use. The Alt Fuels database

reported the facility contains ethanol-based fuels. The SPILLS database reported 100 gallons of sewage was released at the facility due to a damaged sewage line in June 2013; the issue was addressed by emergency response professionals and was resolved to the satisfaction of the regulatory authorities by July 2013. The database also reported a release of 25-30 gallons of gasoline fuel occurred at the facility due to an overflow from a gas pump in January 2015. The gasoline was contained, properly abated, and resolved to the satisfaction of the regulatory authorities by June 2015. No other violations were reported. Since no unresolved violations were reported and due to the distance and elevation difference from the subject site, the RaceTrac #2329 facility is not considered to be an REC.

The M D Hodges Enterprises, Inc. facility is listed as being located 439 feet south of the subject site. The facility was field verified to be located 458 feet southwest and cross-gradient of the subject site, across Jimmy Carter Boulevard. The M D Hodges Enterprises, Inc. facility is listed on the UST and LUST databases. The UST database reported one 3,000-gallon diesel UST and one 3,000-gallon gasoline UST have been removed from the facility. The LUST database reported the closure activities received a No Further Action Required (NFAR) status in January 2000 due to clean closure results. No violations were reported. Since no violations were reported and due to the distance and elevation difference from the subject site, the M D Hodges Enterprises, Inc. facility is not considered to be an REC.

The Coker Farm Remediation Site facility is listed as being located 593 feet southeast of the subject site. The facility was field verified to be located 154 feet southeast of the subject site. The Coker Farm Remediation Site facility is listed on the RCRA Non-Gen and SPILLS databases. The RCRA Non-Gen database reported the facility was listed as being a large quantity generator of Benzene from December 2004 until at least February 2006, and as a non-generating handler of Benzene in August 2007. The SPILLS database reported numerous drums were stored onsite in October 2004 which contained varnishes, PCBs, and resins and that some of the soil surrounding these drums had been impacted by these hazardous substances. Soil excavation and disposal activities were subsequently conducted by environmental professionals, and the issue was resolved to the satisfaction of as of June 2006. No other violations were reported. Since no violations were reported and due to the distance from the subject site, the Coker Farm Remediation Site facility is not considered to be an REC.

The BJ's Wholesale Club #161 and J C Penny Company Inc. facilities are listed as being located 601 feet west of the subject site. The facility was field verified to be located 585 feet northwest of the subject site. The BJ's

Wholesale Club #161 facility is listed on the RCRA Non-Gen, UST, LUST, SPILLS, and DTNK databases. The RCRA Non-Gen database reported the facility was listed as being a very small quantity generator of Benzene from September 2007 until at least July 2008, and as a non-generating handler of Benzene in February 2011. The DTNK database reported USTs have historically been utilized at the facility address. The UST database reported one 20,000-gallon gasoline UST and one compartmentalized 20,000-gallon gasoline UST have been removed from the subject site. The LUST database reported a confirmed release occurred at the facility in November 2013 which received a NFAR status in December 2013. The SPILLS database reported a spill of 15 to 50-gallons of gasoline occurred at the facility in November 2008 due to an overflow from a gas pump. While this release impacted stormwater features, no waterways were affected, and the release was properly contained and considered resolved to the satisfaction of the regulatory authorities in November 2008. No unresolved violations were reported. Since no unresolved violations have been reported and due to the distance and elevation difference from the subject site, the BJ's Wholesale Club #161 and J C Penny Company Inc. facilities are not considered to be an REC.

The FedEx Ground – Norcross Package facility is listed as being located 612 feet northeast of the subject site. The facility was field verified to be located directly adjacent to the northeast and downgradient of the subject site. The FedEx Ground – Norcross Package facility is listed on the UST, RCRA VSQG, TIER 2, SPILLS, and HMIRS databases. The UST database reported the facility is active with one 20,000-gallon diesel UST currently in-use. Additionally, the database denoted the means for expenses associated with remediation as being the responsibility of the owner / operator. The RCRA VSQG database reported the facility was listed as a very small quantity generator of arsenic, corrosive, ignitable, and reactive wastes in August 2018; no violations were reported. The Tier 2 database reported the facility actively monitors quantities of diesel fuels stored and utilized at the facility. The SPILLS database reported a release of 20 gallon of oil occurred at the facility on July 1, 2013 due to a blown truck engine which impacted a retention pond on the northeast portion of the facility. This release was abated by emergency response professionals and was considered resolved to the satisfaction of the regulatory authorities on July 4, 2013. The HMIRS database reported numerous minor hazardous material incidents over several years involving numerous solvents and chemical. Each of these incidents were properly contained, abated, and resolved to the satisfaction of the regulatory authorities. No unresolved violations were reported. Since no unresolved violations were reported and due to the elevation difference from the subject site, the FedEx Ground – Norcross Package facility is not considered to be an REC.

ii) Unmapped Sites

Unmapped sites are sites that appear on one or more searched databases, but which cannot be accurately located due to incomplete or missing address information. No unmapped sites were identified.

b) Additional Environmental Records Sources

No additional records were available or were provided.

c) Physical Setting Source(s)

The site is located within the Winder Slope District of the Southern Piedmont Section of the Piedmont Province. The gently rolling topography of the Winder Slope District slopes gradually from an elevation of 1,000 feet in the north to 700 feet at the southern edge. This district is dissected by the headwater tributaries of the major streams draining to the Atlantic Ocean. Numerous dome-shaped, granitic mountains are located in the interfluvies in the southern and western portions of this district. The stream valleys, which are fairly deep and narrow, lie 100-200 feet below the narrow, rounded stream divides. The western boundary follows the drainage divide that separates streams draining to the Atlantic Ocean from those draining to the Gulf of Mexico. The southern boundary approximates the 700-foot elevation where a break in regional slope occurs (Physiographic Map of Georgia, Clark and Zisa, 1976).

d) Historical Use Information on the Property

Current USGS topographic maps acquired from the USGS National Map and ERIIS were reviewed in order to attain additional knowledge pertaining to past site usage. Copies of the topographic maps are provided in Appendix C.

The USGS National Map and ERIIS topographic maps showed the site and adjacent properties to be developed similar to current conditions. Jimmy Carter Boulevard was depicted west of the subject site in all topographic maps.

Historical aerial photographs from 1938, 1940, 1952, 1960, 1968, 1972, 1982, 1993, 1999, 2005, 2006, 2007, 2009, 2010, 2013, 2015, 2017, and 2019 were reviewed in order to obtain additional historical information regarding the site. Copies of these photographs are provided in Appendix D.

The photographs from 1938 to 1972 depicted the subject site as being either agriculturally developed or undeveloped and grassed / wooded. The surrounding properties were depicted as being either agriculturally developed, undeveloped and grassed / wooded, or residentially developed. Peachtree Industrial

Boulevard was depicted as being under development to the north of the subject site in the photographs from 1968 and 1972.

The photographs from 1982 to 2015 depicted the subject site as being commercially developed similar to current conditions. The surrounding properties were depicted as being either commercially developed or undeveloped and grassed / wooded. The FedEx Ground – Norcross Package facility was first depicted to the northeast and downgradient of the subject site in 2013 and the RaceTrac #2329 facility was first depicted north and downgradient of the subject site in 2015.

The photographs from 2017 to 2019 depicted the subject site and surrounding properties to be developed similar to current conditions.

A search of City Directory listings of the current site address, 6855 Jimmy Carter Boulevard, indicated the site was first listed as an office park with numerous suites in 1982 until at least 2020, as it is today. The surrounding properties have historically been listed from 1982 to 2020 as having been utilized for commercial purposes similar to current conditions or for residential purposes. Neither the historical listings for the site or surrounding properties give any indication that their site operations might constitute an REC. A copy of the Historical Directory Report is provided in Appendix E.

e) Historical Use Information on Adjoining Properties

Historical topographic maps, aerial photographs, and city directory listings showed the site was agriculturally developed or undeveloped and grassed / wooded from 1938 until at least 1972. The surrounding properties were agriculturally developed, undeveloped and grassed / wooded, or residentially developed from 1938 until at least 1972.

f) Data Gaps

The data gaps exhibited by the lack of coverage from historical maps, directories, and photographs are not of major concern, since the site was undeveloped prior to its current usage as an office park and church. Therefore, P2P does not propose that these data gaps require sampling activities.

6) Site Reconnaissance

a) Methodology and Limiting Conditions

The site reconnaissance consisted of a site visit on June 10, 2022. This review was conducted to observe potential signs of environmental impairment

of the site. This ESA is limited only to those areas, which were reasonably accessible. Photographs obtained during the site reconnaissance are presented in Appendix A.

b) General Site Setting

The site is located in a commercial-industrial-residential area of Gwinnett County and comprises 3.31 acres. The subject property can be accessed from the west via Jimmy Carter Boulevard. The subject site contains an office park and a church which are bordered by an asphalt-paved parking lot and grassed and wooded areas. Three structures are located onsite, including two office buildings and a church. Commercial properties surround the subject site on all sides. The Pet Suites Norcross Kennels and Captain D's Restaurant are located to the north of the subject site. The FedEx Ground – Norcross Package facility is located to the east of the subject site. The MJay's Specialty Baked Foods bakery and Mallen Industries, Inc. wholesale storage warehouse are located to the west of the subject site, across Jimmy Carter Boulevard. The Veridian Business Park is located to the south of the subject site. The site is connected to the Gwinnett County water and sewage systems. The property is generally flat and slopes towards the north.

c) Exterior Observations

i) Hazardous Substances in Connection with Identified Uses

No hazardous substances were observed onsite.

ii) Hazardous Substance Containers and Unidentified Substance Containers

No hazardous substance containers or unidentified substance containers were observed onsite.

iii) Storage Tanks

No storage tanks were observed onsite.

iv) Indications of PCBs (including how contained and assessment of leakage or potential for leakage)

No indications of PCBs or PCBs-containing structures were observed at the site. Manufacture of transformers containing PCBs ceased in the late 1970s. Commercial sites constructed since that period no longer utilize transformers containing PCBs. One pad-mounted transformer was observed on the east side of the subject site. No leaks, stains, spills, or

other environmental issues were observed to be associated with this transformer. No pole-mounted transformers were observed onsite.

v) Indications of Solid Waste Disposal

Solid wastes produced at the site are collected in several dumpsters located on the east side of the subject site. Additionally, some general trash and debris were located adjacent to these dumpsters. Advanced Disposal disposes of this waste. No leaks, stains, spills, or other environmental issues were observed adjacent to these dumpsters.

d) Interior Observations

The subject site contains three buildings, including two office buildings and a church building. Each of these buildings were locked during the site reconnaissance and were unable to be inspected internally in order to verify that no RECs were located within the respective buildings.

The office buildings are wood-framed buildings with brick siding and membrane roofing. The buildings are slab-on-grade foundation. The visible interior of the buildings contains drywall interior walling, carpeted and tile flooring, and acoustical false-tile ceilings. A floor drain was observed within an accessible bathroom area of this buildings. General office supplies are furniture were observed within the visible portions of the buildings. No leaks, stains, spills, or other environmental issues were observed throughout the buildings. Furthermore, no obvious evidence of asbestos containing materials or lead-based paints was observed to be associated with the buildings during the P2P site reconnaissance.

The church building is a wood-framed building with brick siding and membrane roofing. The building is slab-on-grade foundation. None of the interior of the church was visible during the site reconnaissance. However, no leaks, stains, spills, or other environmental issues were observed to be associated with the exterior of the building. Furthermore, no obvious evidence of asbestos containing materials or lead-based paints was observed to be associated with the exterior of the building during the P2P site reconnaissance.

7) Information from Interviews

Firefighter Christopher Chapman was interviewed by telephone on June 14, 2022. Mr. Chapman has been with the Gwinnett County Fire Department for over three years. Mr. Chapman stated that public water and sewage is available along Jimmy Carter Boulevard. Mr. Chapman is unaware of any environmental issues associated with the subject site.

8) Findings and Conclusions

The site is located in a commercial-industrial-residential area of Gwinnett County and comprises 3.31 acres. The subject property can be accessed from the west via Jimmy Carter Boulevard. The subject site contains an office park and a church which are bordered by an asphalt-paved parking lot and grassed and wooded areas. Three structures are located onsite, including two office buildings and a church. Commercial properties surround the subject site on all sides. The Pet Suites Norcross Kennels and Captain D's Restaurant are located to the north of the subject site. The FedEx Ground – Norcross Package facility is located to the east of the subject site. The MJay's Specialty Baked Foods bakery and Mallen Industries, Inc. wholesale storage warehouse are located to the west of the subject site, across Jimmy Carter Boulevard. The Veridian Business Park is located to the south of the subject site. The site is connected to the Gwinnett County water and sewage systems. The property is generally flat and slopes towards the north.

During the site reconnaissance performed on June 10, 2022, no RECs were identified onsite. A search of various local, state and federal databases revealed 37 mapped sites within the applicable ASTM radii of the subject property. None of these sites are considered to be an REC to the subject site. Since no RECs have been identified via either the site reconnaissance or government records, **P2P does not recommend any additional assessment for the subject property at this time.**

9) References

"Hydrogeologic Evaluation for Underground Injection Control in Northern Georgia", 1984, Georgia Geological Survey, Hydrologic Atlas 12.

Database Report dated May 18, 2022.

Historical Aerial Report dated May 18, 2022.

Historical City Directory Report dated May 23, 2022.

Physical Setting Report dated May 17, 2022.

10) Qualifications of Environmental Professionals

See Attached Profile

11) Environmental Professional Certification and Statement of Impartiality

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in section 312.10 of 40 CFR 312, and I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject site. I have developed and performed the all-appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312 and the scope and limitations of ASTM Standard Practice E1527-13.

Neither Mark Faas, nor any staff member assigned to this investigation has any interest or contemplated interest, financial or otherwise, in the subject or surrounding properties, or in any entity which owns, leases, or occupies the subject or surrounding properties or which may be responsible for environmental issues identified during the course of this investigation, and has no personal bias with respect to the parties involved. This is certified as true and correct to the best of our knowledge. The above information and attachments are subject to penalty for false statements under 18 U.S.C. Section 1001.

Signed,



Brian Mainor, PMP
Project Manager



Mark Faas
Chief Executive Officer

Profiles

BRIAN MAINOR

Project Manager

Credentials

Kennesaw State University, Project Management Certification, 2019
Georgia College & State University, B.S. Environmental Science, 2015
OSHA 40-Hour Hazardous Waste Worker's Certification
Project Management Professional Certification

Experience Summary

Mr. Mainor has six years of experience in environmental assessment and corrective action activities. Currently, as a Project Manager for Point to Point Environmental, Mr. Mainor is responsible for field activities such as Phase I & II environmental site assessments, underground storage tank closures, and site assessments including soil sampling, monitoring well installation, groundwater sampling, potentiometric surface monitoring, and operations and maintenance of remediation system equipment. Mr. Mainor has conducted field water resource surveys, environmental database searches, and both topographic and land surveys. Mr. Mainor is also responsible for the preparation of Phase I & II reports, Corrective Action Plan –Parts A and B reports, UST closure reports, monitoring reports, site investigation plans, and Discharge Monitoring Reports in accordance with National Pollutant Discharge Elimination System requirements.

During Mr. Mainor's tenure at Lockerly Arboretum, he performed ecological, hydraulic and topographical field research such as groundwater and surface water sampling, soil sampling, physiochemical analysis, piezometer installation, slug tests, and conductivity tests. Mr. Mainor utilized GIS software to produce ecological inventories, trail maps and water resource map data for use of both Lockerly Arboretum and Baldwin County. Mr. Mainor was also responsible for geospatial analysis of ecological data provided by Lockerly Arboretum and preparation of site maps for associated properties.

Employment History

July 2015 – Present	Point to Point Environmental Project Manager
Sept. 2013 – May 2015	Lockerly Arboretum Environmental Educator

MARK D. FAAS
Chief Executive Officer

Credentials

University of Georgia, B.S. Environmental Health, 1999
Managing Environmental Compliance – Georgia Tech Research Institute
Petroleum Vapor Intrusion: Fundamentals of Screening, Investigation, and Management - ITRC
Natural Attenuation for Remediation of Contaminated Sites
OSHA 40-Hour Hazardous Waste Worker's Certification
Georgia Class A and Class B Certified UST Operator

Experience Summary

Mr. Faas has 21 years' experience in environmental consulting. Mr. Faas is proficient in conducting environmental assessment, monitoring and remediation of contaminated air, groundwater, surface water, soil, and soil gasses and vapor. Mr. Faas also has extensive experience in completing subsurface investigations, environmental site assessments, managing environmental compliance and emergency response, and in resolving regulatory compliance issues.

Mr. Faas has completed environmental corrective action activities for approximately 20 public and privately owned landfills and over 500 hazardous waste and petroleum sites across the southeast spanning a variety of physiographic regions. Environmental activities completed for these projects have included the assessment and remediation of air, soil, groundwater, surface water, and soil vapors and gases. In addition to being directly responsible for the assessment and monitoring of these impacted sites, Mr. Faas has also completed subsurface investigations and remediation alternatives evaluation, selection and design incorporated into Assessment of Corrective Measures reports, Compliance Status Reports and Corrective Action Plans. Mr. Faas has designed, installed, operated and monitored over 100 remedial solutions for contaminated sites which include both in-situ and ex-situ remediation alternatives.

Currently, as Chief Executive Officer for Point to Point Environmental, Mr. Faas is responsible for managing, technical review and oversight for field investigations and report production for all environmental and geotechnical projects including Environmental Site Assessments, Corrective Action Plans, UST closure and assessment activities, subsurface investigations, indoor air quality assessments, and site monitoring and remediation. Mr. Faas is also directly responsible for all environmental remediation pilot testing, evaluation, design, installation and oversight of operations, maintenance and monitoring.

During Mr. Faas' tenure as the Senior Project Manager for Georgia Oilmen's Services, Mr. Faas was responsible for providing oversight for all environmental assessment and remediation projects including field investigations and report production. Mr. Faas' responsibilities included coordination among staff, clients, regulators, contractors, real estate agents, property developers, engineers, lenders and lawyers on projects that required environmental investigation and remediation. As an emergency responder, Mr. Faas, acted as a site safety supervisor, performed site remedial operations, and coordinated regulatory compliance.


During Mr. Faas' tenure with Moreland Altobelli Associates, Inc., he performed environmental monitoring of contaminated groundwater, surface water, and soil. Mr. Faas was responsible for all groundwater, surface water, leachate, and methane gas sampling at hazardous waste sites, RCRA, underground storage tank and landfill management projects. This included conducting regular sampling events, monitoring well installation, development, maintenance, and repair, and completion of all associated documentation and reports required for clients and Environmental Protection Division compliance. Mr. Faas was also responsible for hydrogeologic evaluations, pump tests, slug tests, contour mapping, geotechnical investigations, sampling of public and private water supplies, constructed wetland and stormwater management projects, calibration and installation of automated sampling equipment, and supervision of erosion control evaluation.

Employment History

January 2019	Point to Point Environmental Chief Executive Officer
August 2014 – December 2018	Point to Point Environmental Director of Environmental and Geotechnical Services
2002 – August 2014	Georgia Oilmen's Services, Inc. Senior Project Manager / Environmental Specialist
2000 – 2002	Moreland Altobelli Associates, Inc. Environmental Geologist

Appendix A


Figures



NOT TO SCALE		Project: JCB 6855 6855 Jimmy Carter Blvd Norcross, GA 30071; Gwinnett County	Title: Site Vicinity and Property Tax Parcel Boundaries		Figure 1
Drawn By: BDM	Date: 6/13/22			Point to Point Environmental	
Client:					



NOT TO SCALE		Project: JCB 6855 6855 Jimmy Carter Blvd Norcross, GA 30071; Gwinnett County	Title: Site Plan		Figure 2
Drawn By: BDM	Date: 6/13/22			Point to Point Environmental	
Client:					



Exterior of office buildings on subject site, interior of maintenance room, interior of representative bathroom

Date: 6/13/2022

Compiled by: BDM

Client:

Project:

JCB 6855

6855 Jimmy Carter Boulevard
Norcross, GA 30071, Gwinnett Co.

Title: Site Photograph

Point to Point Environmental



**Figure
3a**



Exterior of onsite church and associated office spaces, breezeway, dumpster, and pad-mounted transformer

Date: 6/13/2022

Compiled by: BDM

Client:

Project:

JCB 6855

6855 Jimmy Carter Boulevard

Norcross, GA 30071, Gwinnett Co.

Title: Site Photograph

Point to Point Environmental



Figure

3b

Appendix B

Database Report



DATABASE REPORT

Project Property:	<i>JCB 6855 6855 Jimmy Carter Blvd Norcross GA 30071</i>
Project No:	<i>E220085</i>
Report Type:	<i>Database Report</i>
Order No:	<i>22051600831</i>
Requested by:	<i>Point to Point Environmental</i>
Date Completed:	<i>May 18, 2022</i>

Table of Contents

Table of Contents.....	2
Executive Summary.....	3
Executive Summary: Report Summary.....	4
Executive Summary: Site Report Summary - Project Property.....	8
Executive Summary: Site Report Summary - Surrounding Properties.....	9
Executive Summary: Summary by Data Source.....	16
Map.....	26
Aerial.....	29
Topographic Map.....	30
Detail Report.....	31
Unplottable Summary.....	489
Unplottable Report.....	490
Appendix: Database Descriptions.....	491
Definitions.....	502

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property: JCB 6855
6855 Jimmy Carter Blvd Norcross GA 30071

Project No: E220085

Coordinates:

Latitude: 33.9416822
Longitude: -84.2370447
UTM Northing: 3,759,129.30
UTM Easting: 755,364.72
UTM Zone: UTM Zone 16S

Elevation: 1,012 FT

Order Information:

Order No: 22051600831
Date Requested: May 16, 2022
Requested by: Point to Point Environmental
Report Type: Database Report

Historicals/Products:

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
<u>Standard Environmental Records</u>								
Federal								
DOE FUSRAP	Y	1	0	0	0	0	0	0
NPL	Y	1	0	0	0	0	0	0
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	0	0	0	-	0
ODI	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	0	0	-	0
CERCLIS	Y	0.5	0	0	1	0	-	1
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	1	0	-	1
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	0	0	0
RCRA TSD	Y	0.5	0	0	0	0	-	0
RCRA LQG	Y	0.25	0	0	1	-	-	1
RCRA SQG	Y	0.25	0	0	0	-	-	0
RCRA VSQG	Y	0.25	0	1	1	-	-	2
RCRA NON GEN	Y	0.25	0	4	7	-	-	11
RCRA CONTROLS	Y	0.5	0	0	0	0	-	0
FED ENG	Y	0.5	0	0	0	0	-	0
FED INST	Y	0.5	0	0	0	0	-	0
LUCIS	Y	0.5	0	0	0	0	-	0
NPL IC	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	-	-	-	-	0
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
FRP	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	0	0	-	-	0
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	0	-	-	0
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	0	0	0	0	0

State

SHWS	Y	1	0	0	1	0	1	2
DELISTED SHWS	Y	1	0	0	1	0	1	2
REMOVED HSI	Y	1	0	0	0	0	0	0
NON HSI	Y	1	0	0	0	1	7	8
HSRA NOTIF	Y	1	0	0	5	2	11	18
SWF/LF	Y	0.5	0	0	0	1	-	1
LANDFILLS	Y	0.5	0	0	0	2	-	2
LUST	Y	0.5	0	3	2	1	-	6
DELISTED LST	Y	0.5	0	0	0	0	-	0
UST	Y	0.25	0	5	2	-	-	7
DTNK	Y	0.25	0	1	0	-	-	1
INST	Y	0.5	0	0	0	0	-	0
AUL	Y	0.5	0	0	0	0	-	0
VCP	Y	0.5	0	0	0	0	-	0
BROWNFIELDS	Y	0.5	0	0	0	0	-	0

Tribal

INDIAN LUST	Y	0.5	0	0	0	0	-	0
INDIAN UST	Y	0.25	0	0	0	-	-	0
DELISTED ILST	Y	0.5	0	0	0	0	-	0
DELISTED IUST	Y	0.25	0	0	0	-	-	0

County

No County standard environmental record sources available for this State.

Additional Environmental Records

Federal

FINDS/FRS	Y	PO	0	1	-	-	-	1
TRIS	Y	PO	0	-	-	-	-	0
PFAS TRI	Y	0.5	0	0	0	0	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
PFAS NPL	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0
PFAS SSEHRI	Y	0.5	0	0	0	0	-	0
ERNS PFAS	Y	0.5	0	0	0	0	-	0
HMIRS	Y	0.125	0	12	-	-	-	12
NCDL	Y	0.125	0	0	-	-	-	0
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	0	-	-	-	-	0
FED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	0	0	0	0	0
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0
MLTS	Y	PO	0	-	-	-	-	0
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	0	0	0
URANIUM	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	1	0	-	-	1
CONSENT DECREES	Y	0.25	0	0	0	-	-	0
SSTS	Y	0.25	0	0	0	-	-	0
PCB	Y	0.5	0	0	0	0	-	0

State

SPILLS	Y	0.125	0	6	-	-	-	6
DRYCLEANERS	Y	0.25	0	0	1	-	-	1
DELISTED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
TIER 2	Y	0.125	0	1	-	-	-	1

Tribal

No Tribal additional environmental record sources available for this State.

<i>Database</i>	<i>Searched</i>	<i>Search</i>	<i>Project</i>	<i>Within</i>	<i>0.125mi</i>	<i>0.25mi to</i>	<i>0.50mi to</i>	<i>Total</i>
<i>County</i>		<i>Radius</i>	<i>Property</i>	<i>0.12mi</i>	<i>to 0.25mi</i>	<i>0.50mi</i>	<i>1.00mi</i>	
	<i>No County additional environmental record sources available for this State.</i>							

<i>Total:</i>	<i>0</i>	<i>35</i>	<i>23</i>	<i>7</i>	<i>20</i>	<i>85</i>

** PO – Property Only*

** 'Property and adjoining properties' database search radii are set at 0.25 miles.*

Executive Summary: Site Report Summary - Project Property

<i>Map Key</i>	<i>DB</i>	<i>Company/Site Name</i>	<i>Address</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev Diff (ft)</i>	<i>Page Number</i>

No records found in the selected databases for the project property.

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	FINDS/FRS	PET SUITES - NORCROSS	33.942278, -84.237556 UNKNOWN GA 00000 <i>Registry ID:</i> 110070007145	NNW	0.02 / 87.97	4	31
2	RCRA NON GEN	NORCOM INC	6866 JIMMY CARTER BLVD NORCROSS GA 30071 <i>EPA Handler ID:</i> GAD981218464	WSW	0.05 / 245.07	-11	31
3	SPILLS		6875 Jimmy Carter Blvd Norcross GA <i>Complaint ID Source Facility ID Dt Complaint CI:</i> 71449 07/04/2013 00:00:00	NW	0.06 / 339.18	-8	33
3	UST	RaceTrac #2329 - Jimmy Carter	6875 JIMMY CARTER BLVD NORCROSS GA <i>Facility ID:</i> 10002289 <i>Tank Status Legacy Tank No:</i> Currently in Use 1, Currently in Use 2A, Currently in Use 2B, Currently in Use 3	NW	0.06 / 339.18	-8	34
3	SPILLS		6875 Jimmy Cater Blvd. Norcross GA <i>Complaint ID Source Facility ID Dt Complaint CI:</i> 75630 06/30/2015 00:00:00	NW	0.06 / 339.18	-8	36
3	ALT FUELS	RaceTrac #2329	6875 Jimmy Carter Blvd Norcross GA 30071 <i>ID:</i> 70620	NW	0.06 / 339.18	-8	37
4	UST	M D HODGES ENTERPRISES INC	6796 JIMMY CARTER BLVD NORCROSS GA <i>Facility ID:</i> 9067228 <i>Tank Status Legacy Tank No:</i> Removed from Ground 1, Removed from Ground 2	S	0.08 / 438.70	-5	37
4	LUST	M D HODGES ENTERPRISES INC	6796 JIMMY CARTER BLVD NORCROSS GA 30071 <i>Facility ID Cleanup Status No Further Action Date:</i> 9067228 NFA - Clean Closure 1/25/2000	S	0.08 / 438.70	-5	38
5	RCRA NON GEN	COKER FARM REMEDIATION SITE	6271 ATLANTIC BLVD NORCROSS GA 30071 <i>EPA Handler ID:</i> GAR000039487	SE	0.11 / 593.47	-11	38
5	SPILLS		6271 ATLANTIC BLVD NORCROSS GA <i>Complaint ID Source Facility ID Dt Complaint CI:</i> 29190 06/29/2006 00:00:00	SE	0.11 / 593.47	-11	41
6	RCRA NON GEN	BJ'S WHOLESALE CLUB # 0161	6344 CASH COURT NORCROSS GA 30071 <i>EPA Handler ID:</i> GAR000050856	W	0.11 / 601.34	-16	43
6	LUST	BJS CLUB #161	6344 CASH CT NORCROSS GA 30071 <i>Facility ID Cleanup Status No Further Action Date:</i> 10000729 NFA - No Further Action 12/3/2013	W	0.11 / 601.34	-16	45

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
6	UST	BJS CLUB #161	6344 CASH CT NORCROSS GA	W	0.11 / 601.34	-16	45
			Facility ID: 10000729 Tank Status / Legacy Tank No: Removed from Ground I 1, Removed from Ground I 2A, Removed from Ground I 2B				
6	SPILLS		6344 CASH COURT NORCROSS GA	W	0.11 / 601.34	-16	46
			Complaint ID / Source Facility ID / Dt Complaint CI: 54775 #10000729 02/23/2014 00:00:00				
6	SPILLS		6344 CASH COURT NORCROSS GA	W	0.11 / 601.34	-16	47
			Complaint ID / Source Facility ID / Dt Complaint CI: 54766 #10000729 02/23/2014 00:00:00				
6	DTNK	J C PENNEY CO INC	6344 CASH CT NORCROSS GA	W	0.11 / 601.34	-16	48
7	HMIRS		6265 Atlanta Blvd Norcross GA	NE	0.12 / 612.03	1	48
7	HMIRS		6265 Atlanti Blvd Norcross GA	NE	0.12 / 612.03	1	50
7	UST	FEDEX GROUND- NORCROSS	6265 ATLANTIC BLVD NORCROSS GA	NE	0.12 / 612.03	1	52
			Facility ID: 10002182 Tank Status / Legacy Tank No: Currently in Use I 1				
7	HMIRS		6265 Atlantic Blvd ATLANTA GA	NE	0.12 / 612.03	1	52
7	HMIRS		6265 Atlantic Blvd Norcross GA	NE	0.12 / 612.03	1	54
7	HMIRS		6265 Atlanti Blvd NORCROSS GA	NE	0.12 / 612.03	1	224
7	TIER 2	FedEx Ground Package System, Inc.	6265 Atlantic Blvd. Norcross GA 30071	NE	0.12 / 612.03	1	226
			Facility ID: 6795388				
7	RCRA VSQG	FEDEX GROUND	6265 ATLANTIC BLVD NORCROSS GA 30071	NE	0.12 / 612.03	1	229
			EPA Handler ID: GAR000084616				
7	HMIRS		6265 Atlantic Blvd Norcross GA	NE	0.12 / 612.03	1	230

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
7	HMIRS		6265 Atlantic Blvd Norcross GA	NE	0.12 / 612.03	1	430
7	HMIRS		6265 Atlantic Blvd ATLANTA GA	NE	0.12 / 612.03	1	431
7	HMIRS		6265 Atlanta Blvd Norcross GA	NE	0.12 / 612.03	1	433
7	HMIRS		6265 Atlantic Blvd NORCROSS GA	NE	0.12 / 612.03	1	435
8	SPILLS		6265 Atlantic Ave. Norcross GA	ESE	0.12 / 614.85	-15	436
Complaint ID Source Facility ID Dt Complaint CI: 71472 07/04/2013 00:00:00							
9	HMIRS		6562 Atlantic Blvd NORCROSS GA	SSE	0.12 / 627.82	-6	437
9	HMIRS		6562 Atlantic Blvd NORCROSS GA	SSE	0.12 / 627.82	-6	439
10	RCRA NON GEN	M D HODGES ENTERPRISES INC	3033 ADRIATIC COURT NORCROSS GA 30071	WSW	0.12 / 645.39	-12	441
EPA Handler ID: GAR000009902							
10	UST	M D HODGES ENTERPRISES INC	3033 ADRIATIC COURT EAST POINT GA	WSW	0.12 / 645.39	-12	442
Facility ID: 9067298 Tank Status Legacy Tank No: Removed from Ground 1							
10	LUST	M D HODGES ENTERPRISES INC	3033 ADRIATIC COURT EAST POINT GA 30311	WSW	0.12 / 645.39	-12	442
Facility ID Cleanup Status No Further Action Date: 9067298 NFA - Clean Closure 7/17/1998							
11	DELISTED SHWS	Panolam Industries	6300 Atlantic Boulevard Norcross GA 30071-	SE	0.14 / 758.04	-11	442
HSI ID: 10532							
11	HSRA NOTIF	PANOLAM INDUSTRIES FACILITY - PARCEL 5	6300 ATLANTIC BOULEVARD NORCROSS GA 30071-	SE	0.14 / 758.04	-11	443
Notif ID: 4115							
11	HSRA NOTIF	PANOLAM INDUSTRIES, INC.	6300 ATLANTIC BLVD NORCROSS GA	SE	0.14 / 758.04	-11	443
Notif ID: 3004							

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
11	HSRA NOTIF	PANOLAM INDUSTRIES, INC.	6300 ATLANTIC BLVD., NW NORCROSS GA 30071- <i>Notif ID: 6507</i>	SE	0.14 / 758.04	-11	443
11	SHWS	Panolam Industries	6300 Atlantic Boulevard Norcross GA 30071- <i>HSI ID: 10532</i>	SE	0.14 / 758.04	-11	444
12	RCRA NON GEN	CREATIVE SYSTEMS GROUP INC	3015 ADRIATIC CT NORCROSS GA 30071 <i>EPA Handler ID: GAD981217177</i>	SW	0.16 / 839.20	-10	445
13	RCRA NON GEN	LUCENT TECHNOLOGIES INC	3017 ADRIATIC CT NORCROSS GA 30071 <i>EPA Handler ID: GAD984311258</i>	SW	0.16 / 841.07	-10	447
14	RCRA NON GEN	NORDSON CORP	6755 JIMMY CARTER BLVD NORCROSS GA 30071 <i>EPA Handler ID: GAD981219736</i>	SSE	0.16 / 847.53	-6	448
15	RCRA LQG	THE HANSON GROUP LLC	3044 ADRIATIC CT PEACHTREE CORNERS GA 30071 <i>EPA Handler ID: GAR000091785</i>	SW	0.16 / 848.95	-11	450
16	RCRA NON GEN	ARCHITECTURAL SIENINE INC	3040 ADRIATIC COURT NORCROSS GA 30071 <i>EPA Handler ID: GAR000007526</i>	SW	0.17 / 893.72	-8	452
17	CERCLIS	WYANDOTTE PAINT PRODUCTS CO	6369 OLD PEACHTREE RD NORCROSS GA 30071 <i>Site EPA ID: GAD003480183</i>	NNW	0.23 / 1,204.74	-24	454
17	CERCLIS NFRAP	WYANDOTTE PAINT PRODUCTS CO	6369 OLD PEACHTREE RD NORCROSS GA 30071 <i>Site EPA ID: GAD003480183</i>	NNW	0.23 / 1,204.74	-24	455
17	RCRA VSQG	FERRO CORPORATION - NORCROSS SITE	6369 PEACHTREE ST NORCROSS GA 30071 <i>EPA Handler ID: GAD003480183</i>	NNW	0.23 / 1,204.74	-24	457
18	RCRA NON GEN	BRANDONS PRINTING	6725 JIMMY CARTER BLVD NORCROSS GA 30071 <i>EPA Handler ID: GA0000187815</i>	SSE	0.23 / 1,208.09	-3	471
19	UST	PIB CIRCLE-K	6385 Peachtree Industrial Blvd Peachtree Corners GA <i>Facility ID: 10002810</i> <i>Tank Status / Legacy Tank No: Currently in Use I 1B, Currently in Use I 2A, Currently in Use I 1A, Currently in Use I 2B</i>	NW	0.24 / 1,262.07	-9	472
20	RCRA NON GEN	COURTESY CLEANERS	6405-C PEACHTREE IND. BLVD NORCROSS GA 30092 <i>EPA Handler ID: GAD984289215</i>	WNW	0.24 / 1,275.39	-4	474

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
20	RCRA NON GEN	CSF DEVELOPMENT CORP	6405 PEACHTREE IND BLVD STE B NORCROSS GA 30092 EPA Handler ID: GAR000008870	WNW	0.24 / 1,275.39	-4	475
20	UST	PLATINUM REAL ESTATE PARTNERS LLC	6405 PEACHTREE IND BLVD NORCROSS GA Facility ID: 670143 Tank Status / Legacy Tank No: Currently in Use I 1, Currently in Use I 2, Currently in Use I 3, Currently in Use I 5, Currently in Use I 4	WNW	0.24 / 1,275.39	-4	477
20	LUST	PLATINUM REAL ESTATE PARTNERS LLC	6405 PEACHTREE IND BLVD NORCROSS GA 30092 Facility ID / Cleanup Status / No Further Action Date: 670143 NFA - No Further Action I 5/22/1997	WNW	0.24 / 1,275.39	-4	479
20	DRYCLEANERS	European Cleaners	6405 Peachtree Industrial Boulevard Norcross GA 30092	WNW	0.24 / 1,275.39	-4	479
20	HSRA NOTIF	PLATINUM REAL ESTATE PARTNERS LLC (formerly Conv Square)	6405 PEACHTREE INDUSTRIAL BLVD NORCROSS GA 30092- Notif ID: 6523	WNW	0.24 / 1,275.39	-4	479
20	HSRA NOTIF	CONVENIENCE SQUARE-6405 PCHTREE IND BLVD	6405 PEACHTREE INDUSTRIAL BOULEVARD NORCROSS GA Notif ID: 2666	WNW	0.24 / 1,275.39	-4	479
20	LUST	PLATINUM REAL ESTATE PARTNERS LLC	6405 PEACHTREE IND BLVD NORCROSS GA 30092 Facility ID / Cleanup Status / No Further Action Date: 670143 In Remediation I	WNW	0.24 / 1,275.39	-4	480
21	LUST	MAYER ELECTRIC SUPPLY	6460 PEACHTREE IND BLVD NORCROSS GA 30071 Facility ID / Cleanup Status / No Further Action Date: 9067098 NFA - Clean Closure I 10/27/2010	W	0.34 / 1,811.55	-42	480
22	NON HSI	Overlook Bay Apartments	6520 Hillandale Dr. Norcross GA 30092	WNW	0.40 / 2,136.90	-55	480
22	HSRA NOTIF	OVERLOOK BAY APARTMENTS	6520 HILLDALE DRIVE NORCROSS GA Notif ID: 2427	WNW	0.40 / 2,136.90	-55	480
22	HSRA NOTIF	THE FIELDS AT PEACHTREE CORNERS APARTMENTS	6520 HILLANDALE DRIVE NORCROSS GA 30092- Notif ID: 6646	WNW	0.40 / 2,136.90	-55	481
23	LANDFILLS	WMI BJ landfill PH3&4	JONES MILL RD DORAVILLE GA DR0110 No ID: 259	SSW	0.42 / 2,232.53	-12	481

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
<u>24</u>	LANDFILLS	WMI BJ Landfill Expansion	JONES MILL RD DORAVILLE GA DR0110 No ID: 258	SSW	0.43 / 2,246.64	-11	<u>481</u>
<u>25</u>	SWF/LF	WASTE ELIMINATOR INC.	3025 Jones Mill Rd Norcross GA 30071 Permit No: 067-041P(MRF)	WSW	0.44 / 2,300.28	28	<u>482</u>
<u>26</u>	DELISTED SHWS	Southern Pipe Coating Operation (Former)	6420 Corley Road Norcross GA 30071- HSI ID: 10757	SSE	0.58 / 3,087.68	39	<u>482</u>
<u>26</u>	HSRA NOTIF	SOUTHERN PIPE COATING OPERATION (FORMER)	6420 CORLEY ROAD NORCROSS GA Notif ID: 3804	SSE	0.58 / 3,087.68	39	<u>483</u>
<u>26</u>	SHWS	Southern Pipe Coating Operation (Former)	6420 Corley Road Norcross GA 30071- HSI ID: 10757	SSE	0.58 / 3,087.68	39	<u>483</u>
<u>27</u>	HSRA NOTIF	MR. CLEAN (FORMER)	3375 HOLCOMB BRIDGE ROAD NORCROSS GA 30092- Notif ID: 6385	NNW	0.65 / 3,418.74	-61	<u>484</u>
<u>28</u>	NON HSI	Harris Beauty Supply Co.	6341 or 6041 Peachtree Industrial Blvd. Norcross GA 30092	NE	0.66 / 3,497.75	-12	<u>484</u>
<u>29</u>	HSRA NOTIF	BAY COLONY BUSINESS CENTER	6621 BAY CIRCLE NORCROSS GA Notif ID: 2749	WSW	0.68 / 3,587.35	12	<u>485</u>
<u>30</u>	NON HSI	Market Place Shopping Ctr.	6135 Peachtree Pkwy. Norcross GA 30092	N	0.69 / 3,661.03	-82	<u>485</u>
<u>30</u>	HSRA NOTIF	MARKET PLACE SHOPPING CENTER	6135 PEACHTREE PARKWAY NORCROSS GA Notif ID: 2954	N	0.69 / 3,661.03	-82	<u>485</u>
<u>31</u>	NON HSI	Elegant Cleaners	3380 Holcomb Bridge Road Norcross GA 30092	NNW	0.70 / 3,682.44	-47	<u>485</u>
<u>31</u>	HSRA NOTIF	ELEGANT CLEANERS	3380 HOLCOMB BRIDGE ROAD NORCROSS GA 30092- Notif ID: 4737	NNW	0.70 / 3,682.44	-47	<u>485</u>
<u>32</u>	NON HSI	Post Corners Apartments	3341 Peachtree Corners Circle, NW Norcross GA 30092	WNW	0.77 / 4,063.41	-29	<u>486</u>

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
32	HSRA NOTIF	POST CORNERS APARTMENTS	3341 PEACHTREE CORNER CIRCLE NW NORCROSS GA <i>Notif ID: 4047</i>	WNW	0.77 / 4,063.41	-29	486
33	NON HSI	AKZO Coatings, Inc.	6369 Old Peachtree Rd. Norcross GA 30071	SSE	0.79 / 4,161.27	56	486
33	HSRA NOTIF	WYANDOFFE PAINT PRODUCTS	6369 OLD PEACHTREE RD NORCROSS GA 30071- <i>Notif ID: 5388</i>	SSE	0.79 / 4,161.27	56	486
33	HSRA NOTIF	AKZO COATINGS, INC.	6369 OLD PEACHTREE RD. NORCROSS GA <i>Notif ID: 2576</i>	SSE	0.79 / 4,161.27	56	487
34	NON HSI	Properties of Stephen E. Champ	6354 Buford Highway Norcross GA 30093	SSE	0.87 / 4,599.91	69	487
35	HSRA NOTIF	STEPHEN E. CHAMP PROPERTY	6354 BUFORD HIGHWAY GA <i>Notif ID: 4274</i>	SSE	0.88 / 4,624.93	68	487
36	HSRA NOTIF	PEACHTREE INDUSTRIAL MERCURY SPILL	6767 PEACHTREE INDUSTRIAL BOULEVARD NORCROSS GA <i>Notif ID: 3160</i>	WSW	0.88 / 4,627.49	-24	487
37	NON HSI	Tennant Company (Former)	5805 Peachtree Corners East Norcross GA 30092	NE	0.98 / 5,156.73	13	488
37	HSRA NOTIF	TENNANT COMPANY PROPERTY (FORMER)	5805 PEACHTREE CORNERS EAST NORCROSS GA 30092- <i>Notif ID: 4319</i>	NE	0.98 / 5,156.73	13	488

Executive Summary: Summary by Data Source

Standard

Federal

CERCLIS - Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS

A search of the CERCLIS database, dated Oct 25, 2013 has found that there are 1 CERCLIS site(s) within approximately 0.50 miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
WYANDOTTE PAINT PRODUCTS CO	6369 OLD PEACHTREE RD NORCROSS GA 30071	NNW	0.23 / 1,204.74	17

Site EPA ID: GAD003480183

CERCLIS NFRAP - CERCLIS - No Further Remedial Action Planned

A search of the CERCLIS NFRAP database, dated Oct 25, 2013 has found that there are 1 CERCLIS NFRAP site(s) within approximately 0.50 miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
WYANDOTTE PAINT PRODUCTS CO	6369 OLD PEACHTREE RD NORCROSS GA 30071	NNW	0.23 / 1,204.74	17

Site EPA ID: GAD003480183

RCRA LQG - RCRA Generator List

A search of the RCRA LQG database, dated Apr 11, 2022 has found that there are 1 RCRA LQG site(s) within approximately 0.25 miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
THE HANSON GROUP LLC	3044 ADRIATIC CT PEACHTREE CORNERS GA 30071	SW	0.16 / 848.95	15

EPA Handler ID: GAR000091785

RCRA VSQG - RCRA Very Small Quantity Generators List

A search of the RCRA VSQG database, dated Apr 11, 2022 has found that there are 2 RCRA VSQG site(s) within approximately 0.25 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
FEDEX GROUND	6265 ATLANTIC BLVD NORCROSS GA 30071	NE	0.12 / 612.03	7

EPA Handler ID: GAR000084616

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
FERRO CORPORATION - NORCROSS SITE	6369 PEACHTREE ST NORCROSS GA 30071	NNW	0.23 / 1,204.74	17

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>

EPA Handler ID: GAD003480183

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Apr 11, 2022 has found that there are 11 RCRA NON GEN site(s) within approximately 0.25 miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>

NORCOM INC	6866 JIMMY CARTER BLVD NORCROSS GA 30071	WSW	0.05 / 245.07	<u>2</u>

EPA Handler ID: GAD981218464

COKER FARM REMEDIATION SITE	6271 ATLANTIC BLVD NORCROSS GA 30071	SE	0.11 / 593.47	<u>5</u>

EPA Handler ID: GAR000039487

BJ'S WHOLESALE CLUB # 0161	6344 CASH COURT NORCROSS GA 30071	W	0.11 / 601.34	<u>6</u>

EPA Handler ID: GAR000050856

M D HODGES ENTERPRISES INC	3033 ADRIATIC COURT NORCROSS GA 30071	WSW	0.12 / 645.39	<u>10</u>

EPA Handler ID: GAR000009902

CREATIVE SYSTEMS GROUP INC	3015 ADRIATIC CT NORCROSS GA 30071	SW	0.16 / 839.20	<u>12</u>

EPA Handler ID: GAD981217177

LUCENT TECHNOLOGIES INC	3017 ADRIATIC CT NORCROSS GA 30071	SW	0.16 / 841.07	<u>13</u>

EPA Handler ID: GAD984311258

NORDSON CORP	6755 JIMMY CARTER BLVD NORCROSS GA 30071	SSE	0.16 / 847.53	<u>14</u>

EPA Handler ID: GAD981219736

ARCHITECTURAL SIENINE INC	3040 ADRIATIC COURT NORCROSS GA 30071	SW	0.17 / 893.72	<u>16</u>

EPA Handler ID: GAR000007526

BRANDONS PRINTING	6725 JIMMY CARTER BLVD NORCROSS GA 30071	SSE	0.23 / 1,208.09	<u>18</u>

EPA Handler ID: GA0000187815

COURTESY CLEANERS	6405-C PEACHTREE IND. BLVD NORCROSS GA 30092	WNW	0.24 / 1,275.39	<u>20</u>

EPA Handler ID: GAD984289215

CSF DEVELOPMENT CORP	6405 PEACHTREE IND BLVD STE B NORCROSS GA 30092	WNW	0.24 / 1,275.39	<u>20</u>

EPA Handler ID: GAR000008870

State

SHWS - Hazardous Site Inventory

A search of the SHWS database, dated Jul 1, 2021 has found that there are 2 SHWS site(s) within approximately 1.00 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
Southern Pipe Coating Operation (Former)	6420 Corley Road Norcross GA 30071-	SSE	0.58 / 3,087.68	<u>26</u>
<i>HSI ID: 10757</i>				

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
Panoram Industries	6300 Atlantic Boulevard Norcross GA 30071-	SE	0.14 / 758.04	<u>11</u>
<i>HSI ID: 10532</i>				

DELISTED SHWS - Delisted Hazardous Site Inventory Listing

A search of the DELISTED SHWS database, dated Jul 1, 2021 has found that there are 2 DELISTED SHWS site(s) within approximately 1.00 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
Southern Pipe Coating Operation (Former)	6420 Corley Road Norcross GA 30071-	SSE	0.58 / 3,087.68	<u>26</u>
<i>HSI ID: 10757</i>				

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
Panoram Industries	6300 Atlantic Boulevard Norcross GA 30071-	SE	0.14 / 758.04	<u>11</u>
<i>HSI ID: 10532</i>				

NON HSI - Hazard Evaluation Score (Non-Hazardous Site Inventory)

A search of the NON HSI database, dated Jul 31, 2014 has found that there are 8 NON HSI site(s) within approximately 1.00 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
AKZO Coatings, Inc.	6369 Old Peachtree Rd. Norcross GA 30071	SSE	0.79 / 4,161.27	<u>33</u>
Properties of Stephen E. Champ	6354 Buford Highway Norcross GA 30093	SSE	0.87 / 4,599.91	<u>34</u>
Tennant Company (Former)	5805 Peachtree Corners East Norcross GA 30092	NE	0.98 / 5,156.73	<u>37</u>

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
Overlook Bay Apartments	6520 Hillandale Dr. Norcross GA 30092	WNW	0.40 / 2,136.90	<u>22</u>
Harris Beauty Supply Co.	6341 or 6041 Peachtree Industrial Blvd. Norcross GA 30092	NE	0.66 / 3,497.75	<u>28</u>
Market Place Shopping Ctr.	6135 Peachtree Pkwy. Norcross GA 30092	N	0.69 / 3,661.03	<u>30</u>
Elegant Cleaners	3380 Holcomb Bridge Road Norcross GA 30092	NNW	0.70 / 3,682.44	<u>31</u>
Post Corners Apartments	3341 Peachtree Corners Circle, NW Norcross GA 30092	WNW	0.77 / 4,063.41	<u>32</u>

HSRA NOTIF - Hazardous Site Response Notifications

A search of the HSRA NOTIF database, dated Apr 4, 2022 has found that there are 18 HSRA NOTIF site(s) within approximately 1.00 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
SOUTHERN PIPE COATING OPERATION (FORMER)	6420 CORLEY ROAD NORCROSS GA <i>Notif ID: 3804</i>	SSE	0.58 / 3,087.68	<u>26</u>
BAY COLONY BUSINESS CENTER	6621 BAY CIRCLE NORCROSS GA <i>Notif ID: 2749</i>	WSW	0.68 / 3,587.35	<u>29</u>
WYANDOFFE PAINT PRODUCTS	6369 OLD PEACHTREE RD NORCROSS GA 30071- <i>Notif ID: 5388</i>	SSE	0.79 / 4,161.27	<u>33</u>
AKZO COATINGS, INC.	6369 OLD PEACHTREE RD. NORCROSS GA <i>Notif ID: 2576</i>	SSE	0.79 / 4,161.27	<u>33</u>
STEPHEN E. CHAMP PROPERTY	6354 BUFORD HIGHWAY GA <i>Notif ID: 4274</i>	SSE	0.88 / 4,624.93	<u>35</u>
TENNANT COMPANY PROPERTY (FORMER)	5805 PEACHTREE CORNERS EAST NORCROSS GA 30092- <i>Notif ID: 4319</i>	NE	0.98 / 5,156.73	<u>37</u>

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
PANOLAM INDUSTRIES FACILITY - PARCEL 5	6300 ATLANTIC BOULEVARD NORCROSS GA 30071- <i>Notif ID: 4115</i>	SE	0.14 / 758.04	<u>11</u>
PANOLAM INDUSTRIES, INC.	6300 ATLANTIC BLVD NORCROSS GA <i>Notif ID: 3004</i>	SE	0.14 / 758.04	<u>11</u>
PANOLAM INDUSTRIES, INC.	6300 ATLANTIC BLVD., NW NORCROSS GA 30071- <i>Notif ID: 6507</i>	SE	0.14 / 758.04	<u>11</u>
PLATINUM REAL ESTATE PARTNERS LLC (formerly Conv Square)	6405 PEACHTREE INDUSTRIAL BLVD NORCROSS GA 30092- <i>Notif ID: 6523</i>	WNW	0.24 / 1,275.39	<u>20</u>
CONVENIENCE SQUARE-6405 PCHTREE IND BLVD	6405 PEACHTREE INDUSTRIAL BOULEVARD NORCROSS GA <i>Notif ID: 2666</i>	WNW	0.24 / 1,275.39	<u>20</u>
OVERLOOK BAY APARTMENTS	6520 HILLDALE DRIVE NORCROSS GA <i>Notif ID: 2427</i>	WNW	0.40 / 2,136.90	<u>22</u>
THE FIELDS AT PEACHTREE CORNERS APARTMENTS	6520 HILLDALE DRIVE NORCROSS GA 30092- <i>Notif ID: 6646</i>	WNW	0.40 / 2,136.90	<u>22</u>
MR. CLEAN (FORMER)	3375 HOLCOMB BRIDGE ROAD NORCROSS GA 30092- <i>Notif ID: 6385</i>	NNW	0.65 / 3,418.74	<u>27</u>
MARKET PLACE SHOPPING CENTER	6135 PEACHTREE PARKWAY NORCROSS GA <i>Notif ID: 2954</i>	N	0.69 / 3,661.03	<u>30</u>
ELEGANT CLEANERS	3380 HOLCOMB BRIDGE ROAD NORCROSS GA 30092- <i>Notif ID: 4737</i>	NNW	0.70 / 3,682.44	<u>31</u>
POST CORNERS APARTMENTS	3341 PEACHTREE CORNER CIRCLE NW NORCROSS GA <i>Notif ID: 4047</i>	WNW	0.77 / 4,063.41	<u>32</u>
PEACHTREE INDUSTRIAL MERCURY SPILL	6767 PEACHTREE INDUSTRIAL BOULEVARD NORCROSS GA <i>Notif ID: 3160</i>	WSW	0.88 / 4,627.49	<u>36</u>

SWF/LF - Solid Waste Disposal Facilities

A search of the SWF/LF database, dated Jul 17, 2020 has found that there are 1 SWF/LF site(s) within approximately 0.50 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
WASTE ELIMINATOR INC.	3025 Jones Mill Rd Norcross GA 30071	WSW	0.44 / 2,300.28	25
<i>Permit No: 067-041P(MRF)</i>				

LANDFILLS - Historic and Current Landfills through 1999

A search of the LANDFILLS database, dated Dec 31, 1999 has found that there are 2 LANDFILLS site(s) within approximately 0.50 miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
WMI BJ landfill PH3&4	JONES MILL RD DORAVILLE GA	SSW	0.42 / 2,232.53	23
<i>DR0110 No ID: 259</i>				
WMI BJ Landfill Expansion	JONES MILL RD DORAVILLE GA	SSW	0.43 / 2,246.64	24
<i>DR0110 No ID: 258</i>				

LUST - Leaking Underground Storage Tanks

A search of the LUST database, dated Jan 6, 2022 has found that there are 6 LUST site(s) within approximately 0.50 miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
M D HODGES ENTERPRISES INC	6796 JIMMY CARTER BLVD NORCROSS GA 30071	S	0.08 / 438.70	4
<i>Facility ID Cleanup Status No Further Action Date: 9067228 NFA - Clean Closure 1/25/2000</i>				
BJS CLUB #161	6344 CASH CT NORCROSS GA 30071	W	0.11 / 601.34	6
<i>Facility ID Cleanup Status No Further Action Date: 10000729 NFA - No Further Action 12/3/2013</i>				
M D HODGES ENTERPRISES INC	3033 ADRIATIC COURT EAST POINT GA 30311	WSW	0.12 / 645.39	10
<i>Facility ID Cleanup Status No Further Action Date: 9067298 NFA - Clean Closure 7/17/1998</i>				
PLATINUM REAL ESTATE PARTNERS LLC	6405 PEACHTREE IND BLVD NORCROSS GA 30092	WNW	0.24 / 1,275.39	20
<i>Facility ID Cleanup Status No Further Action Date: 670143 In Remediation </i>				
PLATINUM REAL ESTATE PARTNERS LLC	6405 PEACHTREE IND BLVD NORCROSS GA 30092	WNW	0.24 / 1,275.39	20
<i>Facility ID Cleanup Status No Further Action Date: 670143 NFA - No Further Action 5/22/1997</i>				
MAYER ELECTRIC SUPPLY	6460 PEACHTREE IND BLVD NORCROSS GA 30071	W	0.34 / 1,811.55	21
<i>Facility ID Cleanup Status No Further Action Date: 9067098 NFA - Clean Closure 10/27/2010</i>				

UST - Underground Storage Tanks

A search of the UST database, dated Jan 6, 2022 has found that there are 7 UST site(s) within approximately 0.25 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
FEDEX GROUND-NORCROSS	6265 ATLANTIC BLVD NORCROSS GA	NE	0.12 / 612.03	7
Facility ID: 10002182 Tank Status Legacy Tank No: Currently in Use 1				
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
RaceTrac #2329 - Jimmy Carter	6875 JIMMY CARTER BLVD NORCROSS GA	NW	0.06 / 339.18	3
Facility ID: 10002289 Tank Status Legacy Tank No: Currently in Use 1, Currently in Use 2A, Currently in Use 2B, Currently in Use 3				
M D HODGES ENTERPRISES INC	6796 JIMMY CARTER BLVD NORCROSS GA	S	0.08 / 438.70	4
Facility ID: 9067228 Tank Status Legacy Tank No: Removed from Ground 1, Removed from Ground 2				
BJS CLUB #161	6344 CASH CT NORCROSS GA	W	0.11 / 601.34	6
Facility ID: 10000729 Tank Status Legacy Tank No: Removed from Ground 1, Removed from Ground 2A, Removed from Ground 2B				
M D HODGES ENTERPRISES INC	3033 ADRIATIC COURT EAST POINT GA	WSW	0.12 / 645.39	10
Facility ID: 9067298 Tank Status Legacy Tank No: Removed from Ground 1				
PIB CIRCLE-K	6385 Peachtree Industrial Blvd Peachtree Corners GA	NW	0.24 / 1,262.07	19
Facility ID: 10002810 Tank Status Legacy Tank No: Currently in Use 1B, Currently in Use 2A, Currently in Use 1A, Currently in Use 2B				
PLATINUM REAL ESTATE PARTNERS LLC	6405 PEACHTREE IND BLVD NORCROSS GA	WNW	0.24 / 1,275.39	20
Facility ID: 670143 Tank Status Legacy Tank No: Currently in Use 1, Currently in Use 2, Currently in Use 3, Currently in Use 5, Currently in Use 4				

DTNK - Delisted Storage Tanks

A search of the DTNK database, dated Jan 6, 2022 has found that there are 1 DTNK site(s) within approximately 0.25 miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
J C PENNEY CO INC	6344 CASH CT NORCROSS GA	W	0.11 / 601.34	6

Non Standard

Federal

FINDS/FRS - Facility Registry Service/Facility Index

A search of the FINDS/FRS database, dated Nov 2, 2020 has found that there are 1 FINDS/FRS site(s) within approximately 0.02 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
PET SUITES - NORCROSS	33.942278, -84.237556 UNKNOWN GA 00000	NNW	0.02 / 87.97	<u>1</u>

Registry ID: 110070007145

HMIRS - Hazardous Materials Information Reporting System

A search of the HMIRS database, dated Sep 1, 2020 has found that there are 12 HMIRS site(s) within approximately 0.12 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
	6265 Atlanta Blvd Norcross GA	NE	0.12 / 612.03	<u>7</u>
	6265 Atlantic Blvd ATLANTA GA	NE	0.12 / 612.03	<u>7</u>
	6265 Atlantc Blvd Norcross GA	NE	0.12 / 612.03	<u>7</u>
	6265 Atlanta Blvd Norcross GA	NE	0.12 / 612.03	<u>7</u>
	6265 Atlantc Blvd Norcross GA	NE	0.12 / 612.03	<u>7</u>
	6265 Atlantic Blvd ATLANTA GA	NE	0.12 / 612.03	<u>7</u>
	6265 Atlantic Blvd Norcross GA	NE	0.12 / 612.03	<u>7</u>
	6265 Atlanttic Blvd NORCROSS GA	NE	0.12 / 612.03	<u>7</u>
	6265 Atlanttic Blvd NORCROSS GA	NE	0.12 / 612.03	<u>7</u>
	6265 Atlantic Blvd Norcross GA	NE	0.12 / 612.03	<u>7</u>

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>

6562 Atlantic Blvd NORCROSS GA	SSE	0.12 / 627.82	<u>9</u>

6562 Atlantic Blvd NORCROSS GA	SSE	0.12 / 627.82	<u>9</u>

ALT FUELS - Alternative Fueling Stations

A search of the ALT FUELS database, dated Mar 7, 2022 has found that there are 1 ALT FUELS site(s) within approximately 0.25 miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>

RaceTrac #2329	6875 Jimmy Carter Blvd Norcross GA 30071	NW	0.06 / 339.18	<u>3</u>

ID: 70620

State

SPILLS - Oil or Hazardous Material Spills or Releases

A search of the SPILLS database, dated Mar 28, 2022 has found that there are 6 SPILLS site(s) within approximately 0.12 miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>

6875 Jimmy Cater Blvd. Norcross GA	NW	0.06 / 339.18	<u>3</u>

Complaint ID | Source Facility ID | Dt Complaint CI: 75630 | | 06/30/2015 00:00:00

6875 Jimmy Carter Blvd Norcross GA	NW	0.06 / 339.18	<u>3</u>

Complaint ID | Source Facility ID | Dt Complaint CI: 71449 | | 07/04/2013 00:00:00

6271 ATLANTIC BLVD NORCROSS GA	SE	0.11 / 593.47	<u>5</u>

Complaint ID | Source Facility ID | Dt Complaint CI: 29190 | | 06/29/2006 00:00:00

6344 CASH COURT NORCROSS GA	W	0.11 / 601.34	<u>6</u>

Complaint ID | Source Facility ID | Dt Complaint CI: 54775 | #10000729 | 02/23/2014 00:00:00

6344 CASH COURT NORCROSS GA	W	0.11 / 601.34	<u>6</u>

Complaint ID | Source Facility ID | Dt Complaint CI: 54766 | #10000729 | 02/23/2014 00:00:00

6265 Atlantic Ave. Norcross GA	ESE	0.12 / 614.85	<u>8</u>

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>

Complaint ID | Source Facility ID | Dt Complaint CI: 71472 | | 07/04/2013 00:00:00

DRYCLEANERS - Dry Cleaning Facilities

A search of the DRYCLEANERS database, dated Dec 6, 2021 has found that there are 1 DRYCLEANERS site(s) within approximately 0.25 miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>

European Cleaners	6405 Peachtree Industrial Boulevard Norcross GA 30092	WNW	0.24 / 1,275.39	20


TIER 2 - Tier 2 Report

A search of the TIER 2 database, dated Mar 21, 2022 has found that there are 1 TIER 2 site(s) within approximately 0.12 miles of the project property.


<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>

FedEx Ground Package System, Inc.	6265 Atlantic Blvd. Norcross GA 30071	NE	0.12 / 612.03	7

Facility ID: 6795388




 Project Property	 Buffer Outline	 Freeways; Highways	 State	 FWS Special Designation Areas
▲ Eris Sites with Higher Elevation	▲ Eris Sites with Same Elevation	▲ Eris Sites with Lower Elevation	○ Eris Sites with Unknown Elevation	 National Wetland
 Eris Areas with Higher Elevation	 Eris Areas with Same Elevation	 Eris Areas with Lower Elevation	 Eris Areas with Unknown Elevation	 Indian Reserve Land
				 Plume
				 100 Year Flood Zone
				 500 Year Flood Zone
		 Traffic Circle; Ramp	 Country	
		 Major & Minor Arterial	 National Wetland	
		 Traffic Circle; Ramp	 Indian Reserve Land	
		 Local Road	 Plume	
		 Rail	 100 Year Flood Zone	
			 500 Year Flood Zone	




Map: 0.5 Mile Radius

Order Number: 22051600831

Address: 6855 Jimmy Carter Blvd, Norcross, GA





Map: 0.25 Mile Radius

Order Number: 22051600831

Address: 6855 Jimmy Carter Blvd, Norcross, GA



Project Property Buffer Outline

- ▲ Eris Sites with Higher Elevation
- ▲ Eris Sites with Same Elevation
- ▼ Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Eris Areas with Higher Elevation
- Eris Areas with Same Elevation
- Eris Areas with Lower Elevation
- Eris Areas with Unknown Elevation

- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail

- State
- Country

FWS Special Designation Areas

- National Wetland
- Indian Reserve Land
- Plume
- 100 Year Flood Zone
- 500 Year Flood Zone

84°14'30"W

84°14'W

33°57'N

33°57'N

33°56'30"N

33°56'30"N

33°56'N

33°56'N

0.1 0.05 0 0.1 Miles

1:10000

Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community

Aerial Year: 2020


Order Number: 22051600831

Address: 6855 Jimmy Carter Blvd, Norcross, GA



Source: ESRI World Imagery

© ERIS Information Inc.



Topographic Map Year: 2017

Address: 6855 Jimmy Carter Blvd, GA

Quadrangle(s): Chamblee, GA; Norcross, GA

Source: USGS Topographic Map

Order Number: 22051600831



© ERIS Information Inc.

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 1	NNW	0.02 / 87.97	1,016.49 / 4	PET SUITES - NORCROSS 33.942278, -84.237556 UNKNOWN GA 00000	FINDS/FRS
Registry ID:		110070007145				
FIPS Code:						
HUC Code:		03130001				
Site Type Name:		STATIONARY				
Location Description:						
Supplemental Location:						
Create Date:		13-FEB-17				
Update Date:						
Interest Types:		ICIS-NPDES NON-MAJOR, STORM WATER CONSTRUCTION				
SIC Codes:						
SIC Code Descriptions:						
NAICS Codes:						
NAICS Code Descriptions:						
Conveyor:		ICIS				
Federal Facility Code:						
Federal Agency Name:						
Tribal Land Code:						
Tribal Land Name:						
Congressional Dist No:		07				
Census Block Code:		131350503061001				
EPA Region Code:		04				
County Name:						
US/Mexico Border Ind:						
Latitude:		33.942278				
Longitude:		-84.237556				
Reference Point:		ACRES POINTS NOT REPRESENTED BY 101-107				
Coord Collection Method:						
Accuracy Value:						
Datum:		NAD83				
Source:						
Facility Detail Rprt URL:		https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070007145				
Program Acronyms:						
NPDES:GAR150830						

2	1 of 1	WSW	0.05 / 245.07	1,001.39 / -11	NORCOM INC 6866 JIMMY CARTER BLVD NORCROSS GA 30071	RCRA NON GEN
EPA Handler ID:		GAD981218464				
Gen Status Universe:		No Report				
Contact Name:		RONALD DELOZIER				
Contact Address:		P O BOX 80766 , , ATLANTA , GA, 30366 , US				
Contact Phone No and Ext:		404-447-5525				
Contact Email:						
Contact Country:		US				
County Name:		GWINNETT				
EPA Region:		04				
Land Type:						
Receive Date:		19950123				
Location Latitude:						
Location Longitude:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>Violation/Evaluation Summary</u>						
Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Apr, 2022.					
<u>Evaluation Details</u>						
Evaluation Start Date:	19930507					
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE					
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:	State					
<u>Handler Summary</u>						
Importer Activity:	No					
Mixed Waste Generator:	No					
Transporter Activity:	No					
Transfer Facility:	No					
Onsite Burner Exemption:	No					
Furnace Exemption:	No					
Underground Injection Activity:	No					
Commercial TSD:	No					
Used Oil Transporter:	No					
Used Oil Transfer Facility:	No					
Used Oil Processor:	No					
Used Oil Refiner:	No					
Used Oil Burner:	No					
Used Oil Market Burner:	No					
Used Oil Spec Marketer:	No					
<u>Hazardous Waste Handler Details</u>						
Sequence No:	1					
Receive Date:	19930507					
Handler Name:	NORCOM INC					
Source Type:	Implementer					
Federal Waste Generator Code:	N					
Generator Code Description:	Not a Generator, Verified					
<u>Hazardous Waste Handler Details</u>						
Sequence No:	1					
Receive Date:	19950123					
Handler Name:	NORCOM INC					
Source Type:	Notification					
Federal Waste Generator Code:	N					
Generator Code Description:	Not a Generator, Verified					
<u>Waste Code Details</u>						
Hazardous Waste Code:	P010					
Waste Code Description:	ARSENIC ACID H3ASO4					
Hazardous Waste Code:	U151					
Waste Code Description:	MERCURY					
Hazardous Waste Code:	U204					
Waste Code Description:	SELENIUM ACID (OR) SELENIUM DIOXIDE					
Hazardous Waste Code:	P104					
Waste Code Description:	SILVER CYANIDE (OR) SILVER CYANIDE AG(CN)					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazardous Waste Code:		P013				
Waste Code Description:		BARIUM CYANIDE				
Hazardous Waste Code:		U032				
Waste Code Description:		CALCIUM CHROMATE (OR) CHROMIC ACID H2CRO4, CALCIUM SALT				
Hazardous Waste Code:		U144				
Waste Code Description:		ACETIC ACID, LEAD(2+) SALT (OR) LEAD ACETATE				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:	Current Owner				Street No:	
Type:	Private				Street 1:	OWNERSTREET
Name:	KAUFFMANN NORMAN J				Street 2:	
Date Became Current:					City:	OWNERCITY
Date Ended Current:					State:	WY
Phone:	404-555-1212				Country:	
Source Type:	Notification				Zip Code:	99999
Owner/Operator Ind:	Current Operator				Street No:	
Type:	Private				Street 1:	OPERSTREET
Name:	OPERNAME				Street 2:	
Date Became Current:					City:	OPERCITY
Date Ended Current:					State:	WY
Phone:	404-555-1212				Country:	
Source Type:	Implementer				Zip Code:	99999
<u>Historical Handler Details</u>						
Receive Dt:	19930507					
Generator Code Description:	Not a Generator, Verified					
Handler Name:	NORCOM INC					
3	1 of 4	NW	0.06 / 339.18	1,004.32 / -8	6875 Jimmy Carter Blvd Norcross GA	SPILLS
Complaint ID:	71449				Concern1 Code:	SS1
Source Facility ID:					Primary Concern:	Sewage spill
Pers Recd ID:					Concern1 Rules:	
Associate ID:					Concern1 OCGA:	
Login ID:					Concern2 Code:	
Entry Person ID:					Secondary Concern:	
Status:	Closed				Concern2 Rules:	
Active?:					Concern2 OCGA:	
Dt Complaint Cl:	07/04/2013 00:00:00				Source Facility Name:	Racetrack Gas Station
Date Received:	06/27/2013 11:12:53				Source City:	Norcross
Caller Represents:	GW & Environmental Svcs				Source County:	
Owner Assign Date:	06/27/2013 00:00:00				Source State:	Georgia
Owner Accept Date:	06/27/2013 00:00:00				Source Postal Code:	
Investigation Date:					Source Email:	
FUI Need:					Source Street2:	
Resolved?:					Src Primary Phone:	
Refer 2:					Src Prim Ph Type:	
Ten Day Follow Up?:					Source Sec Phone:	
Caller Name:	Jarrett Baggett				Src Sec Ph Type:	
Caller Middle Name:					Src Other Phone:	
Caller City:	Atlanta				Src Other Ph Type:	
Caller County:					Src Contact Name:	Lisa Ciotoli
Caller State:	Georgia				Branch Code:	PCB-ERT
Caller Postal Code:	30328				Current Office:	Emergency Response Team
Caller Phone:					Branch Active?:	Yes
Call Primary Phone:					Prog Branch Code:	
Prim Phone Type:					Program Branch:	
Secondary Phone:					Prog Branch Active:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Sec Phone Type:				Comp County ID:		
Caller Email:				Complaint County:		
Caller Street:				Gwinnett		
6655 Peachtree Dunwoody Road				Current Owner:		
Caller Street2:				Network, Emergency Response		
Caller Other Phone:				Approved Date:		
Call Other Ph Type:				Date Entered:		
Program Code:				06/27/2013 11:19:02		
Program:				Entered by:		
Source Street:				Reid, Wallace		
6875 Jimmy Carter Blvd				Received by:		
Complaint Directions:				Reid, Wallace		
Review Comments:				Review by:		
Complaint Location:				Campbell, Jerry		
Complaint Nature:						
6875 Jimmy Carter Blvd						

Report of 100 gallons of raw sewage spilled from a damage sewage line. No waterways/storm drains affected. Groundwater & Environmental Services responsible for the cleanup.

Briefed Jacki Scarbary @11:25 via telephone

Spills Details

Event ID:		Investigator:	T Jackson
Entry by ID:		Entry Date:	06/27/2013 00:00:00
Investigator ID:		Follow Up Needed?:	
Event Code:		Active?:	
Event:		Code Desc:	Initial Investigation
Event Date: 06/26/2013 00:00:00		Entered by:	Jackson, Ted
Comments:			

WSPB BDO T Jackson provided J Baggett of Groundwater & Environmental Services an ERT Release & Remediation Report for completion.

Event ID:		Investigator:		Jscarbary	
Entry by ID:		Entry Date:		06/27/2013 00:00:00	
Investigator ID:		Follow Up Needed?:			
Event Code:		Active?:			
Event:		Code Desc:		Initial Investigation	
Event Date:		06/27/2013 00:00:00	Entered by:		Scarbary, Jacki
Comments:					

1125 hrs: Received page from GEMA - called to confirm receipt.

1135 hrs: Left message for Ted Jackson, WSPB BDO, and provided details of spill. Transferred for investigation.

<u>3</u>	2 of 4	NW	0.06 / 339.18	1,004.32 / -8	RaceTrac #2329 - Jimmy Carter 6875 JIMMY CARTER BLVD NORCROSS GA	UST

Facility ID:		10002289
County:		Gwinnett
State:		
Note:		Documents related to facilities in Georgia can be searched on the Georgia EPD Online System (GEOS) for Permitting, Compliance and Facility Information: https://geos.epd.georgia.gov/GA/GEOS/Public/Client/GA_GEOS/Public/Pages/PublicApplicationList.aspx

Underground Storage Tank Data

Tank Status:		Currently in Use
Legacy Tank No:		1
Tank Constr Descr:		Composite Double Walled
Content Descr:		Gas (Historical Use)
Pipe Descr:		Double-Walled Fiberglass
Pipe Type:		Pressurized
Tank Capacity:		20000
Tank Overfill Date:		12/6/2013
Tank Overfill Exempt:		FALSE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tank Spill Exempt:		FALSE				
Tank Spill Instl Dt:		12/6/2013				
Tank Overfill Type:		Overfill Alarm				
Tank Install Date:		12/6/2013				
Tank Status:		Currently in Use				
Legacy Tank No:		2A				
Tank Constr Descr:		Composite Double Walled				
Content Descr:		E-85				
Pipe Descr:		Double-Walled Fiberglass				
Pipe Type:		Pressurized				
Tank Capacity:		10000				
Tank Overfill Date:		12/6/2013				
Tank Overfill Exempt:		FALSE				
Tank Spill Exempt:		FALSE				
Tank Spill Instl Dt:		12/6/2013				
Tank Overfill Type:		Overfill Alarm				
Tank Install Date:		12/6/2013				
Tank Status:		Currently in Use				
Legacy Tank No:		2B				
Tank Constr Descr:		Composite Double Walled				
Content Descr:		Diesel				
Pipe Descr:		Double-Walled Fiberglass				
Pipe Type:		Pressurized				
Tank Capacity:		10000				
Tank Overfill Date:		12/6/2013				
Tank Overfill Exempt:		FALSE				
Tank Spill Exempt:		FALSE				
Tank Spill Instl Dt:		12/6/2013				
Tank Overfill Type:		Overfill Alarm				
Tank Install Date:		12/6/2013				
Tank Status:		Currently in Use				
Legacy Tank No:		3				
Tank Constr Descr:		Composite Double Walled				
Content Descr:		Gas (Historical Use)				
Pipe Descr:		Double-Walled Fiberglass				
Pipe Type:		Pressurized				
Tank Capacity:		15000				
Tank Overfill Date:		12/6/2013				
Tank Overfill Exempt:		FALSE				
Tank Spill Exempt:		FALSE				
Tank Spill Instl Dt:		12/6/2013				
Tank Overfill Type:		Overfill Alarm				
Tank Install Date:		12/6/2013				

Facility Owner (Revised Jul 2021)

Lemir ID:	162863	State:	GA
County:	Gwinnett	Zip Code:	30339
Facility Status:	Active	Responsiblity:	RO
Location Status:	Active	Start Date:	4/24/2019 7:56:10 PM
First Name:	Jordan	End Date:	
Last Name:	Woodfin	Area Code:	770
Mailing City:	Atlanta	Phone:	4317600
Mailing Address:	200 Galleria Parkway SE, Suite 900		
Location Name:	RT 2329 JIMMY CARTER; ASID: 3947		
Email:	jwoodfin@racetrac.com		
Company Name:	RaceTrac Petroleum Inc		

Lemir ID:	162863	State:	GA
County:	Gwinnett	Zip Code:	30339
Facility Status:	Active	Responsiblity:	RO
Location Status:	Active	Start Date:	
First Name:	Lisa	End Date:	
Last Name:	Ciotoli	Area Code:	770
Mailing City:	Atlanta	Phone:	4317600

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Mailing Address:		200 Galleria Pkwy SE				
Location Name:		RT 2329 JIMMY CARTER; ASID: 3947				
Email:		gepd_correspondence@racetrac.com				
Company Name:		RaceTrac Petroleum, Inc.				

<u>3</u>	3 of 4	NW	0.06 / 339.18	1,004.32 / -8	6875 Jimmy Cater Blvd. Norcross GA	SPILLS
Complaint ID:		75630	Concern1 Code: GFS			
Source Facility ID:			Primary Concern: Gasoline fuel spill			
Pers Recd ID:			Concern1 Rules:			
Associate ID:			Concern1 OCGA:			
Login ID:			Concern2 Code:			
Entry Person ID:			Secondary Concern:			
Status:		Closed	Concern2 Rules:			
Active?:			Concern2 OCGA:			
Dt Complaint Cl:		06/30/2015 00:00:00	Source Facility Name: Race Trac			
Date Received:		01/06/2015 13:43:31	Source City:			
Caller Represents:		Race Trac	Source County:			
Owner Assign Date:		01/06/2015 00:00:00	Source State: Georgia			
Owner Accept Date:		01/06/2015 00:00:00	Source Postal Code:			
Investigation Date:			Source Email:			
FUI Need:			Source Street2:			
Resolved?:			Src Primary Phone:			
Refer 2:			Src Prim Ph Type:			
Ten Day Follow Up?:			Source Sec Phone:			
Caller Name:		Joy McLaughlin	Src Sec Ph Type:			
Caller Middle Name:			Src Other Phone:			
Caller City:			Src Other Ph Type:			
Caller County:			Src Contact Name: Joy McLaughlin			
Caller State:		Georgia	Branch Code: PCB-ERT			
Caller Postal Code:			Current Office: Emergency Response Team			
Caller Phone:			Branch Active?: Yes			
Call Primary Phone:			Prog Branch Code:			
Prim Phone Type:			Program Branch:			
Secondary Phone:			Prog Branch Active:			
Sec Phone Type:			Comp County ID:			
Caller Email:			Complaint County: Gwinnett			
Caller Street:			Current Owner: White, Stephen			
Caller Street2:			Approved Date:			
Caller Other Phone:			Date Entered: 01/06/2015 13:48:32			
Call Other Ph Type:			Entered by: Dalton, Ijanna			
Program Code:			Received by: Dalton, Ijanna			
Program:			Review by: Campbell, Jerry			
Source Street:						
Complaint Directions:						
Review Comments:						
Complaint Location:		6875 Jimmy Cater Blvd.				
Complaint Nature:						

Caller reporting a spill of gasoline in the amount of 25 to 30 gallons. The spill was caused by an overflow at a gas pump. No water ways affected. The spill has been cleaned up by the fire department.

Spills Details

Event ID:		Investigator:	Stephen White
Entry by ID:		Entry Date:	01/06/2015 00:00:00
Investigator ID:		Follow Up Needed?:	
Event Code:		Active?:	
Event:		Code Desc:	Initial Investigation
Event Date:		Entered by:	White, Stephen
Comments:			

@1400 spoke with Ms. Ciotoli and confirmed 30 gallons of diesel fuel was released due to an overflow from a gas dispenser. The spill was contained on site, and no drainage systems are believed to be impacted. Gwinnett Fire contained fuel, and Racetrac has called SWS to complete the cleanup and

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
inspect the stormdrains. I will await a final report from Ms. Ciotoli.						
Event ID: Entry by ID: Investigator ID: Event Code: Event: Event Date: Comments:			Investigator: Entry Date: Follow Up Needed?: Active?: Code Desc: Entered by:			
06/18/2015 00:00:00			whites 06/18/2015 00:00:00 Follow-Up Investigation White, Stephen			
Jan. 26 followed up with Ms. Ciotoli. She stated that once report is prepared that she would forward it to me.						
Event ID: Entry by ID: Investigator ID: Event Code: Event: Event Date: Comments:			Investigator: Entry Date: Follow Up Needed?: Active?: Code Desc: Entered by:			
06/19/2015 00:00:00			whites 06/19/2015 00:00:00 Follow-Up Investigation White, Stephen			
Received final report from Racetrac detailing cleanup performed by SWS Environmental. SWS used boom and pad, and flushed the storm drain to remove contaminated water. Report detailed waste was taken to EWS Alabama Inc. Manifest #'s 011956010. No further EPD ERT action required at this time. Recommend closure of this report.						
<u>3</u>	4 of 4	NW	0.06 / 339.18	1,004.32 / -8	RaceTrac #2329 6875 Jimmy Carter Blvd Norcross GA 30071	ALT FUELS
Fuel Type Code: Station Phone: Expected Date: BD Blends: NG Fill Type Code: NG PSI: Federal Agency ID: Open Date: NG Vehicle Class: LPG Primary: E85 Blender Pump: NG Fill Type Desc: Hydrogen is Retail: Federal Agency: Facility Type: Dt Last Confirmed: Restricted Access: Fed Agency Name: Hydrogen Status Link: Status: Owner Type Desc: E85 Blender Pump Desc: NG Vehicle Class Desc: Geocode Status Desc: LPG Primary Desc: E85 Other Ethanol Blends: EV Pricing: EV Pricing French: EV on Site Renewable Source: Intersection Directions:			ID: Updated at: CNG Dispenser No: CNG Site Renew Src: CNG Tot Compr Cap: CNG Storage Cap: CNG Fill Type Code: CNG PSI: CNG Vehicle Class: LNG Site Renew Src: LNG Vehicle Class: LPG Nozzle Types: Hydrogen Pressures: Hydrogen Standards: Latitude: Longitude:			
E85: E85 Ethanol 770-248-0083 2015-10-15 false CONVENIENCE_STORE 2021-08-04 Open: The station is open. Privately owned The station does not have a blender pump. Premise (building name, property name, shopping center, etc.) level accuracy.			70620 2022-02-10 19:42:29 UTC 33.942355 -84.237605			
<u>4</u>	1 of 2	S	0.08 / 438.70	1,007.75 / -5	M D HODGES ENTERPRISES INC 6796 JIMMY CARTER BLVD NORCROSS GA	UST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
County:		Gwinnett				
State:						
Note:		Documents related to facilities in Georgia can be searched on the Georgia EPD Online System (GEOS) for Permitting, Compliance and Facility Information: https://geos.epd.georgia.gov/GA/GEOS/Public/Client/GA_GEOS/Public/Pages/PublicApplicationList.aspx				
<u>Underground Storage Tank Data</u>						
Tank Status:		Removed from Ground				
Legacy Tank No:		1				
Tank Constr Descr:		Marked Unknown				
Content Descr:		Diesel				
Pipe Descr:		Unknown				
Pipe Type:						
Tank Capacity:		3000				
Tank Overfill Date:						
Tank Overfill Exempt:						
Tank Spill Exempt:						
Tank Spill Instl Dt:						
Tank Overfill Type:						
Tank Install Date:		3/7/1996				
Tank Status:		Removed from Ground				
Legacy Tank No:		2				
Tank Constr Descr:		Marked Unknown				
Content Descr:		Gas (Historical Use)				
Pipe Descr:		Unknown				
Pipe Type:						
Tank Capacity:		3000				
Tank Overfill Date:						
Tank Overfill Exempt:						
Tank Spill Exempt:						
Tank Spill Instl Dt:						
Tank Overfill Type:						
Tank Install Date:		3/7/1996				
<u>4</u>	2 of 2	S	0.08 / 438.70	1,007.75 / -5	M D HODGES ENTERPRISES INC 6796 JIMMY CARTER BLVD NORCROSS GA 30071	LUST
Facility ID:		9067228				
County:		Gwinnett				
Cleanup Status:		NFA - Clean Closure				
Confirm Release Date:						
No Further Action Date:		1/25/2000				
Project Manager:		William Logan				
Site Code Description:		Owner/Operator funded site				
Project Name:		UST - CLOSURE - M D HODGES ENTERPRISES INC				
<u>5</u>	1 of 2	SE	0.11 / 593.47	1,001.10 / -11	COKER FARM REMEDIATION SITE 6271 ATLANTIC BLVD NORCROSS GA 30071	RCRA NON GEN
EPA Handler ID:		GAR000039487				
Gen Status Universe:		No Report				
Contact Name:		EDWARD JAMISON				
Contact Address:		US				
Contact Phone No and Ext:		518-385-7979				
Contact Email:		EDWARD.JAMISON@GE.COM				
Contact Country:		US				
County Name:		GWINNETT				
EPA Region:		04				
Land Type:		Private				
Receive Date:		20070829				
Location Latitude:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Location Longitude:						
<u>Violation/Evaluation Summary</u>						
Note:		NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).				
<u>Handler Summary</u>						
Importer Activity:		No				
Mixed Waste Generator:		No				
Transporter Activity:		No				
Transfer Facility:		No				
Onsite Burner Exemption:		No				
Furnace Exemption:		No				
Underground Injection Activity:		No				
Commercial TSD:		No				
Used Oil Transporter:		No				
Used Oil Transfer Facility:		No				
Used Oil Processor:		No				
Used Oil Refiner:		No				
Used Oil Burner:		No				
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		1				
Receive Date:		20041201				
Handler Name:		COKER FARM REMEDIATION SITE				
Source Type:		Notification				
Federal Waste Generator Code:		1				
Generator Code Description:		Large Quantity Generator				
<u>Waste Code Details</u>						
Hazardous Waste Code:		D008				
Waste Code Description:		LEAD				
Hazardous Waste Code:		D001				
Waste Code Description:		IGNITABLE WASTE				
Hazardous Waste Code:		D018				
Waste Code Description:		BENZENE				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		1				
Receive Date:		20060223				
Handler Name:		COKER FARM REMEDIATION SITE				
Source Type:		Annual/Biennial Report				
Federal Waste Generator Code:		1				
Generator Code Description:		Large Quantity Generator				
<u>Waste Code Details</u>						
Hazardous Waste Code:		D008				
Waste Code Description:		LEAD				
Hazardous Waste Code:		D001				
Waste Code Description:		IGNITABLE WASTE				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazardous Waste Code:		D018				
Waste Code Description:		BENZENE				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		2				
Receive Date:		20070829				
Handler Name:		COKER FARM REMEDIATION SITE				
Source Type:		Notification				
Federal Waste Generator Code:		N				
Generator Code Description:		Not a Generator, Verified				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:		Current Owner			Street No:	
Type:		Private			Street 1:	6271 ATLANTIC BLVD
Name:		JENNY COKER			Street 2:	
Date Became Current:		19490101			City:	NORCROSS
Date Ended Current:					State:	GA
Phone:					Country:	US
Source Type:		Notification			Zip Code:	30071
Owner/Operator Ind:		Current Operator			Street No:	
Type:		Private			Street 1:	
Name:		GE ENERGY			Street 2:	
Date Became Current:		20041010			City:	
Date Ended Current:					State:	
Phone:					Country:	US
Source Type:		Notification			Zip Code:	
Owner/Operator Ind:		Current Operator			Street No:	
Type:		Private			Street 1:	
Name:		GE ENERGY			Street 2:	
Date Became Current:		20041206			City:	
Date Ended Current:					State:	
Phone:					Country:	US
Source Type:		Annual/Biennial Report			Zip Code:	
Owner/Operator Ind:		Current Owner			Street No:	
Type:		Private			Street 1:	6271 ATLANTIC BLVD
Name:		JENNY COKER			Street 2:	
Date Became Current:		19490101			City:	NORCROSS
Date Ended Current:					State:	GA
Phone:					Country:	US
Source Type:		Annual/Biennial Report			Zip Code:	30071
Owner/Operator Ind:		Current Owner			Street No:	6271
Type:		Private			Street 1:	ATLANTIC BLVD
Name:		JENNY COKER			Street 2:	
Date Became Current:		19490101			City:	NORCROSS
Date Ended Current:					State:	GA
Phone:					Country:	US
Source Type:		Notification			Zip Code:	30071
Owner/Operator Ind:		Current Operator			Street No:	
Type:		Private			Street 1:	
Name:		GE ENERGY			Street 2:	
Date Became Current:		20041206			City:	
Date Ended Current:					State:	
Phone:					Country:	US
Source Type:		Notification			Zip Code:	
<u>Historical Handler Details</u>						
Receive Dt:		20060223				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Generator Code Description:		Large Quantity Generator				
Handler Name:		COKER FARM REMEDIATION SITE				
Receive Dt:		20041201				
Generator Code Description:		Large Quantity Generator				
Handler Name:		COKER FARM REMEDIATION SITE				

5	2 of 2	SE	0.11 / 593.47	1,001.10 / -11	6271 ATLANTIC BLVD NORCROSS GA	SPILLS
Complaint ID:		29190	Concern1 Code:		HWM	
Source Facility ID:			Primary Concern:		Hazardous Waste Management	
Pers Recd ID:			Concern1 Rules:		391-3-11	
Associate ID:			Concern1 OCGA:		12-8-60	
Login ID:			Concern2 Code:			
Entry Person ID:			Secondary Concern:			
Status:		Closed	Concern2 Rules:			
Active?:			Concern2 OCGA:			
Dt Complaint Cl:		06/29/2006 00:00:00	Source Facility Name:		VIRGINIA COKER	
Date Received:		10/04/2004 14:20:00	Source City:		NORCROSS	
Caller Represents:		GE	Source County:			
Owner Assign Date:		10/04/2004 00:00:00	Source State:		Georgia	
Owner Accept Date:		10/04/2004 00:00:00	Source Postal Code:			
Investigation Date:			Source Email:			
FUI Need:			Source Street2:			
Resolved?:			Src Primary Phone:			
Refer 2:			Src Prim Ph Type:			
Ten Day Follow Up?:			Source Sec Phone:			
Caller Name:		DAVID BOSS /SERV CTR MGR	Src Sec Ph Type:			
Caller Middle Name:			Src Other Phone:			
Caller City:		NORCROSS	Src Other Ph Type:			
Caller County:			Src Contact Name:			
Caller State:		Georgia	Branch Code:		PCB-ERT	
Caller Postal Code:			Current Office:		Emergency Response Team	
Caller Phone:			Branch Active?:		Yes	
Call Primary Phone:			Prog Branch Code:			
Prim Phone Type:			Program Branch:			
Secondary Phone:			Prog Branch Active:			
Sec Phone Type:			Comp County ID:			
Caller Email:			Complaint County:		Gwinnett	
Caller Street:			Current Owner:		Langley, Bert	
Caller Street2:			Approved Date:			
Caller Other Phone:			Date Entered:		10/04/2004 21:55:00	
Call Other Ph Type:			Entered by:		Smiley, Mary	
Program Code:			Received by:		Smiley, Mary	
Program:			Review by:		Langley, Bert	
Source Street:		6271 ATLANTIC BLVD				
Complaint Directions:						
Review Comments:						
Complaint Location:		6271 ATLANTIC BLVD				
Complaint Nature:						

ERT 100404-05

A FORMER DECEASED GE EMPLOYEE REMOVED 110CT 55 GAL SIZE DRUMS FROM GE PROPERTY APPROX THIRTY YEARS AGO. SOME DRUMS CONTAIN OIL WITH PCB, LIQUID AND SOLID VANISHES AND RESINS. THERE IS A SMALL AMOUNT OF COPPER AND INSULATION MATERIAL ON THE GROUND. THERE IS ALSO A 2 GAL PUDDLE OF RESINS. MOST OF THE DRUMS ARE RUSTY AND EMPTY, BUT SOME STILL HAVE CHEMICALS IN THEM.

THE FORMER EMPLOYEE RETIRED IN 1984-5. HIS WIFE IS NOW TRYING TO SELL THE PROPERTY.

GE LABELS ARE ON THE DRUMS AND GE WILL BE RESPONSIBLE FOR REMOVAL OF THE DRUMS. GE HAS ALREADY CONTACTED URS (NO TELEPHONE OR ADDRESS WAS AVAILABLE AT THE TIME I SPOKE TO MR BOSS) TO ACCESS THE DRUMS. APPARENTLY, THE FORMER EMPLOYEE WANTED TO USE THE DRUMS AS TRASH CONTAINERS AND RECYCLE THE METALS.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Spills Details						
Event ID:				Investigator:	bert langley	
Entry by ID:				Entry Date:	10/05/2004 00:00:00	
Investigator ID:				Follow Up Needed?:		
Event Code:				Active?:		
Event:				Code Desc:	Initial Investigation	
Event Date:	10/04/2004 00:00:00			Entered by:	Langley, Bert	
Comments:	Spoke With Patricia Barmeyer (Attorney) And Jane Gardner (Ge Corporate Attorney). They Are On Way To Meeting With Hazardous Waste To Determine If This Project Is Best Handled By Ert Or Hazardous Waste. Ge Prefers It To Be Handled As An Ert Action. Ge Plans To Have Drums Removed Asap And To Begin Characterizing The Site To Determine If There Is Any Contamination.					
Event ID:				Investigator:	bert langley	
Entry by ID:				Entry Date:	10/06/2004 00:00:00	
Investigator ID:				Follow Up Needed?:		
Event Code:				Active?:		
Event:				Code Desc:	Follow-Up Investigation	
Event Date:	10/06/2004 00:00:00			Entered by:	Langley, Bert	
Comments:	Spoke With Ed Jamison(518-xxx-xxxx) Who Will Be The Technical Contact For This Project. Ge Has Hired A Consultant And Will Indertake A Site Survey Today. Results Of The Survey Will Be Used To De4velop A Work Plan For Site Characterization And Remediation. Plan Is To Remove Drums Asap And To Then Verify No Contamination Remains.					
Event ID:				Investigator:	bert langley	
Entry by ID:				Entry Date:	10/14/2004 00:00:00	
Investigator ID:				Follow Up Needed?:		
Event Code:				Active?:		
Event:				Code Desc:	Follow-Up Investigation	
Event Date:	10/11/2004 00:00:00			Entered by:	Langley, Bert	
Comments:	Received Voice Mail Message From Ed Jamison. Site Visit Has Been Conducted. Most Of The Drums Were Actually Used To Contain Copper For Recycling And Will Not Likely Be A Problem. Some Drums Did Contain Liquid And These Were Sampled. Once Sample Results Are Available Plans To Remove The Drums Will Continue . Spoke With Mr. Jamison On 10/18. Sample Results Indicate Some Levels Of Pcb'S (Up To 40,000 Ppm) In Actual Waste Products. Also Some Possible Benzene And Ignitables. Plan On Contracting To Remove All Drums And Visible Spilled Materials. After Drums Have Been Removed And Properly Disposed Will Conduct Sampling To Determine Any Residual Contamination.					
Event ID:				Investigator:	bert langley	
Entry by ID:				Entry Date:	11/16/2004 00:00:00	
Investigator ID:				Follow Up Needed?:		
Event Code:				Active?:		
Event:				Code Desc:	Follow-Up Investigation	
Event Date:	11/16/2004 00:00:00			Entered by:	Langley, Bert	
Comments:	Received Call From Ed Jamison. All Drums Have Been Placed In Roll-Off Awaiting Disposal. Six Areas Of Obviously Cntaminated Soil Have Been Excavated. Confirmation Sampling Will Be Done Later This Week.					
Event ID:				Investigator:	bert langley	
Entry by ID:				Entry Date:	02/09/2005 00:00:00	
Investigator ID:				Follow Up Needed?:		
Event Code:				Active?:		
Event:				Code Desc:	Follow-Up Investigation Report	
Event Date:	02/08/2005 00:00:00			Entered by:	Langley, Bert	
Comments:	Call From Ed Jamison. Ge Has Delineated The Extent Of Contamination. It Is Greater Than Originally Suspected. Total Area Is 500-600 Feet Long, With A Maximum Widthe Of Nearly 200 Feet. Contamination Extends To A Depth Of 7-8'. Intentions Are Still To Excavate And Backfill, But Extent Of The Area Will Require More Planning And Preparation Than Originally Thought.					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	1 of 6	W	0.11 / 601.34	996.34 / -16	BJ'S WHOLESALE CLUB # 0161 6344 CASH COURT NORCROSS GA 30071	RCRA NON GEN

EPA Handler ID: GAR000050856
Gen Status Universe: No Report
Contact Name: BILL PETERS
Contact Address: 25 , RESEARCH DR , , WEST BOROUGH , MA, 01581 , US
Contact Phone No and Ext: 774-512-5535 8842
Contact Email:
Contact Country: US
County Name: GWINNETT
EPA Region: 04
Land Type: Private
Receive Date: 20110201
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20110201
Handler Name: BJ'S WHOLESALE CLUB # 0161
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20070917
Handler Name: BJ'S WHOLESALE CLUB # 0161
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazardous Waste Code:		D002				
Waste Code Description:		CORROSIVE WASTE				
Hazardous Waste Code:		D018				
Waste Code Description:		BENZENE				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		2				
Receive Date:		20080702				
Handler Name:		BJ'S WHOLESALE CLUB # 0161				
Source Type:		Notification				
Federal Waste Generator Code:		3				
Generator Code Description:		Very Small Quantity Generator				
<u>Waste Code Details</u>						
Hazardous Waste Code:		D001				
Waste Code Description:		IGNITABLE WASTE				
Hazardous Waste Code:		D002				
Waste Code Description:		CORROSIVE WASTE				
Hazardous Waste Code:		D018				
Waste Code Description:		BENZENE				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:		Current Operator			Street No:	
Type:		Private			Street 1:	
Name:		OPERATOR			Street 2:	
Date Became Current:					City:	
Date Ended Current:					State:	
Phone:					Country:	US
Source Type:		Notification			Zip Code:	
Owner/Operator Ind:		Previous Operator			Street No:	
Type:		Private			Street 1:	ONE MERCER RD
Name:		BJ'S WHOLESALE CLUB			Street 2:	
Date Became Current:		20040905			City:	NATICK
Date Ended Current:		20110129			State:	ME
Phone:					Country:	US
Source Type:		Notification			Zip Code:	01760
Owner/Operator Ind:		Current Operator			Street No:	
Type:		Private			Street 1:	ONE MERCER RD
Name:		BJ'S WHOLESALE CLUB			Street 2:	
Date Became Current:		20040905			City:	NATICK
Date Ended Current:					State:	ME
Phone:					Country:	US
Source Type:		Notification			Zip Code:	01760
Owner/Operator Ind:		Current Owner			Street No:	
Type:		Private			Street 1:	
Name:		OWNER			Street 2:	
Date Became Current:					City:	
Date Ended Current:					State:	
Phone:					Country:	US
Source Type:		Notification			Zip Code:	
Owner/Operator Ind:		Previous Owner			Street No:	
Type:		Private			Street 1:	ONE MERCER RD
Name:		BJ'S WHOLESALE CLUB			Street 2:	
Date Became Current:		20040905			City:	NATICK

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Date Ended Current:	20110129			State:	ME	
Phone:				Country:	US	
Source Type:	Notification			Zip Code:	01760	
Owner/Operator Ind:	Current Owner			Street No:		
Type:	Private			Street 1:	ONE MERCER RD	
Name:	BJ'S WHOLESALE CLUB			Street 2:		
Date Became Current:	20040905			City:	NATICK	
Date Ended Current:				State:	ME	
Phone:				Country:	US	
Source Type:	Notification			Zip Code:	01760	

Historical Handler Details

Receive Dt: 20080702
Generator Code Description: Very Small Quantity Generator
Handler Name: BJ'S WHOLESALE CLUB # 0161

Receive Dt: 20070917
Generator Code Description: Very Small Quantity Generator
Handler Name: BJ'S WHOLESALE CLUB # 0161

<u>6</u>	2 of 6	W	0.11 / 601.34	996.34 / -16	BJS CLUB #161 6344 CASH CT NORCROSS GA 30071	LUST
Facility ID:	10000729					
County:	Gwinnett					
Cleanup Status:	NFA - No Further Action					
Confirm Release Date:	11/25/2013					
No Further Action Date:	12/3/2013					
Project Manager:	Ron Wallace					
Site Code Description:	Owner/Operator funded site					
Project Name:	UST - 1 - BJS CLUB #161					

<u>6</u>	3 of 6	W	0.11 / 601.34	996.34 / -16	BJS CLUB #161 6344 CASH CT NORCROSS GA	UST
Facility ID:	10000729					
County:	Gwinnett					
State:						
Note:	Documents related to facilities in Georgia can be searched on the Georgia EPD Online System (GEOS) for Permitting, Compliance and Facility Information: https://geos.epd.georgia.gov/GA/GEOS/Public/Client/GA_GEOS/Public/Pages/PublicApplicationList.aspx					

Underground Storage Tank Data

Tank Status: Removed from Ground
Legacy Tank No: 1
Tank Constr Descr: Fiberglass Double Walled
Content Descr: Gas (Historical Use)
Pipe Descr: Double-Walled Flex
Pipe Type: Pressurized
Tank Capacity: 20000
Tank Overfill Date: 8/9/2004
Tank Overfill Exempt: FALSE
Tank Spill Exempt: FALSE
Tank Spill Instl Dt: 8/9/2004
Tank Overfill Type:
Tank Install Date: 7/13/2004

Tank Status: Removed from Ground
Legacy Tank No: 2A

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tank Constr Descr: Fiberglass Double Walled Content Descr: Gas (Historical Use) Pipe Descr: Double-Walled Flex Pipe Type: Tank Capacity: 12000 Tank Overfill Date: 8/9/2004 Tank Overfill Exempt: FALSE Tank Spill Exempt: FALSE Tank Spill Instl Dt: 8/9/2004 Tank Overfill Type: Overfill Alarm Tank Install Date: 7/13/2004 Tank Status: Removed from Ground Legacy Tank No: 2B Tank Constr Descr: Fiberglass Double Walled Content Descr: Gas (Historical Use) Pipe Descr: Double-Walled Flex Pipe Type: Tank Capacity: 8000 Tank Overfill Date: 8/9/2004 Tank Overfill Exempt: FALSE Tank Spill Exempt: FALSE Tank Spill Instl Dt: 8/9/2004 Tank Overfill Type: Overfill Alarm Tank Install Date: 7/13/2004						
<u>6</u>	4 of 6	W	0.11 / 601.34	996.34 / -16	6344 CASH COURT NORCROSS GA	SPILLS
Complaint ID: 54775 Source Facility ID: #10000729 Pers Recd ID: Associate ID: Login ID: Entry Person ID: Status: Closed Active?: Dt Complaint Cl: 02/23/2014 00:00:00 Date Received: 11/10/2008 15:24:00 Caller Represents: B.J. WHOLESALE Owner Assign Date: 11/10/2008 00:00:00 Owner Accept Date: 11/10/2008 00:00:00 Investigation Date: FUI Need: Resolved?: Refer 2: Ten Day Follow Up?: Caller Name: JORGE GOMEZ Caller Middle Name: Caller City: CARLSBAD Caller County: Caller State: California Caller Postal Code: 92008 Caller Phone: Call Primary Phone: Prim Phone Type: Secondary Phone: Sec Phone Type: Caller Email: Caller Street: 1905 ASTON AVE Caller Street2: Caller Other Phone: Call Other Ph Type: Program Code: Program: Source Street: UNKNOWN Complaint Directions:						
Concern1 Code: GFS Primary Concern: Gasoline fuel spill Concern1 Rules: Concern1 OCGA: Concern2 Code: Secondary Concern: Concern2 Rules: Concern2 OCGA: Source Facility Name: PETROLEUM TRANSPORT Source City: Source County: Source State: Georgia Source Postal Code: Source Email: Source Street2: Src Primary Phone: Src Prim Ph Type: Source Sec Phone: Src Sec Ph Type: Src Other Phone: Src Other Ph Type: Src Contact Name: SCOTT JOHNSON Branch Code: PCB-ERT Current Office: Emergency Response Team Branch Active?: Yes Prog Branch Code: Program Branch: Prog Branch Active: Comp County ID: Complaint County: Gwinnett Current Owner: Network, Emergency Response Approved Date: Date Entered: 11/10/2008 15:24:00 Entered by: Reid, Wallace Received by: Reid, Wallace Review by: Campbell, Jerry						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Review Comments:

Complaint Location: 6344 CASH COURT

Complaint Nature:

APPROXIMATELY 50 GALLONS OF GASOLINE FUEL SPILLED FROM A GAS PUMP OVERFLOW. PETROLEUM TRANSPORT AND FIRST ENVIRONMENTAL RESPONSIBLE FOR CLEAN-UP. STORM DRAINS AFFECTED.

PAGED: KEN PERRY @15:35, ID#6248

BRIEFED: KEN PERRY @15:50

Spills Details

Event ID:		Investigator:	Ken Perry
Entry by ID:		Entry Date:	02/23/2014 00:00:00
Investigator ID:		Follow Up Needed?:	
Event Code:		Active?:	
Event:		Code Desc:	Initial Investigation
Event Date:	11/10/2008 00:00:00	Entered by:	Perry, Kenneth
Comments:			

Rec'd two notifications of same UST overfill during fuel delivery. First report by Gwinnett FD (CTS #54766) and second report by BJ Wholesale. Both incident reports were handled and considered closed by Ken Perry, ERT. Subsequently, both incident reports were reassigned for proper closure. Refer to this CTS report #54775 for details.

Surface release of gasoline due to UST overfill. Therefore, no subsurface media affected. Estimated quantity of 15 to 20 gal (reported by Gwinnett FD) up to ~50 gal (reported by BJ's) was released. The jobber, Petroleum Transport, secured a cleanup contractor, First Environmental, who responded and handled cleanup activities. Although storm drains were affected onsite, there was no indication of release affecting Waters of the State. Due to minimal release quantity and response by FD and cleanup contractor, release was considered contained. No waterway impact reported. No further cleanup action recommended.

6	5 of 6	W	0.11 / 601.34	996.34 / -16	6344 CASH COURT NORCROSS GA	SPILLS
Complaint ID:	54766	Concern1 Code:	GFS			
Source Facility ID:	#10000729	Primary Concern:	Gasoline fuel spill			
Pers Recd ID:		Concern1 Rules:				
Associate ID:		Concern1 OCGA:				
Login ID:		Concern2 Code:				
Entry Person ID:		Secondary Concern:				
Status:	Closed	Concern2 Rules:				
Active?:		Concern2 OCGA:				
Dt Complaint Cl:	02/23/2014 00:00:00	Source Facility Name:	PETROLUEM TRANSPORT			
Date Received:	11/10/2008 13:45:00	Source City:	Norcross			
Caller Represents:	GWINNETT CO FIRE	Source County:				
Owner Assign Date:	11/10/2008 00:00:00	Source State:	Georgia			
Owner Accept Date:	11/10/2008 00:00:00	Source Postal Code:	30071			
Investigation Date:		Source Email:				
FUI Need:		Source Street2:				
Resolved?:		Src Primary Phone:				
Refer 2:		Src Prim Ph Type:				
Ten Day Follow Up?:		Source Sec Phone:				
Caller Name:	CHIP BROOKS	Src Sec Ph Type:				
Caller Middle Name:		Src Other Phone:				
Caller City:		Src Other Ph Type:				
Caller County:		Src Contact Name:	SCOTT JOHNSON			
Caller State:	Georgia	Branch Code:	PCB-ERT			
Caller Postal Code:		Current Office:	Emergency Response Team			
Caller Phone:		Branch Active?:	Yes			
Call Primary Phone:		Prog Branch Code:				
Prim Phone Type:		Program Branch:				
Secondary Phone:		Prog Branch Active:				
Sec Phone Type:		Comp County ID:				
Caller Email:		Complaint County:	Gwinnett			
Caller Street:		Current Owner:	Network, Emergency Response			
Caller Street2:		Approved Date:				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Caller Other Phone: Call Other Ph Type: Program Code: Program: Source Street: 6344 Cash Ct Complaint Directions: Review Comments: Complaint Location: 6344 CASH COURT Complaint Nature:				Date Entered: 11/10/2008 13:45:00 Entered by: Jholt, Received by: Jholt, Review by: Campbell, Jerry		

REPORT OF A SPILL OF 15 TO 20 GALLONS OF GASOLINE INTO A STORM DRAIN

FIRST ENVIRONMENTAL IS CONDUCTING THE CLEAN UP.

PAGED KEN PERRY ID#6242

Spills Details

Event ID:		Investigator:	ken perry
Entry by ID:		Entry Date:	02/23/2014 00:00:00
Investigator ID:		Follow Up Needed?:	
Event Code:		Active?:	
Event:		Code Desc:	Initial Investigation
Event Date:	11/10/2008 00:00:00	Entered by:	Perry, Kenneth
Comments:			

Rec'd two notifications of same UST overfill during fuel delivery. First report by Gwinnett FD and second report by BJ Wholesale. Both incident reports were handled and considered closed by Ken Perry, ERT. Subsequently, both incident reports were reassigned for proper closure. See subsequent CTS report #54775 for details.

6	6 of 6	W	0.11 / 601.34	996.34 / -16	J C PENNEY CO INC 6344 CASH CT NORCROSS GA	DTNK

Delisted Storage Tanks

Facility ID:	9067139	GIS Date:	
Facility Status:		Horiz Collect Mthd:	
Facility Type:		Horiz Mthd Acc Unt:	
County:	WINNETT	Financ Resp Mechan:	
Address Verified:		Latitude:	
Georgia District:		Longitude:	
Prog Int Type Desc:	UST	Original Source:	UST
Prog Inte Start Dt:	7/24/1989	Record Date:	27-JUL-2015
Prog Intere End Dt:			
Location Descr:			
PI Comment:	{PREV.LOC}-> J C PENNEY CO INC		

7	1 of 13	NE	0.12 / 612.03	1,013.74 / 1	6265 Atlanta Blvd Norcross GA	HMIRS

Incident County: GWINNETT

HMIR Historical Reports

Report No:	X-2013090143	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	08/15/2013	Report Submit Src:	XML
Time of Incident:	1635	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazardous Class:		FLAMMABLE - COMBUSTIBLE LIQUID		Mode Transport:		Highway
Commodity Short Nm:		GASOLINE INCLUDES GASOLI		Transport Phase:		UNLOADING
Commodity Long Nm:		GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL WITH NOT MORE THAN 10% ALCOHOL		Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:		No
ID No:		UN1203		Mat Ship Approv No:		
Haz Waste Ind:		No		Undecl Hazmat Ship?:		No
Haz Waste EPA No:				Packaging Type:		Non-Bulk
HMIS Tox Inhalation?:		No		Packing Group:		II
TIH Hazard Zone:				Carrier Reporter:		FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:		0.25		CR Street Name:		1000 FED EX DR
Unit of Measure:		Liquid - Gallon		CR City:		CORAOPOLIS
What Failed:		109		CR State:		PA
What Failed Desc:		Closure (e.g. Cap Top or Plug)		CR Postal Code:		15108-9373
How Failed Code:		308		CR Non US State:		
How Failed Desc:		Leaked		CR Fed DOT ID:		265752
Failure Cause Code:		526		CR Hazmat Reg ID:		051910551007S
Failure Cause Desc:		Loose Closure Component or Device		CR Country:		US
Ident. Markings:		4G/Y31.6/S/10USA/+AA3579		Shipper Name:		MOTIVA ENTERPRISES LLC
Cont1 Pkging Type:				Shipper Street Name:		4201 WINTERS CHAPEL RD
Cont1 Const Mat:				Shipper City:		ATLANTA
Cont1 Head Type:				Shipper State:		GA
Cont1 Pkg Capacity:				Shipper Postal:		30360-3150
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:		US
C1 Pkg Amt UOM:				Shipper Waybill:		427541762800215
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:		DORAVILLE
Cont1 Pkg Mnfctr:				Origin State:		GEORGIA
Cont1 Pkg Mnfc Dt:				Origin Postal:		30360
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:		US
C1 Test Const Mat:				Destination City:		ABAC
C1 Pkg Dsign Pres.:				Destination State:		GEORGIA
C1 Dsign Press UOM:				Destination Postal:		31794
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:		US
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:		No		Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:		0
RAM Pkg Cert.:		FALSE		Haz NonHosp Old:		0
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		0
RAM Nuclide S:				Total Hazmat Injuries:		0
RAM Transport Index:				Evacuation Indicator:		No
RAM UOM:				Public Evacuated:		0
RAM Activity Rpted:				Employees Evac:		0
RAM UOM Rpted:				Total Evacuated:		0
RAM Activity:				Total Evacuation Hrs:		0
RAM Activity UOM:				Major Artery Closed:		No
RAM Mat Safety:				Mjr Artery Hrs Closed:		0
Spillage Result:		Yes		Material Involved:		No
Fire Result:		No		Estimated Speed:		0
Explosion Result:		No		Weather Conditions:		
Water Sewer Result:		No		Vehicle Overturn:		No
Gas Dispersion:		No		Vehicle Left Roadway:		No
Environment Damage:		No		Passenger Aircraft:		No
No Release Result:		No		Cargo Baggage:		
Fire EMS Report:		No		Ship Non Transport:		No
Fire EMS EMS Report:				Ship Air First Flight:		No
Police Report:		No		Ship Air Subflight:		No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Police Report No: In House Cleanup: Yes Other Cleanup: No Damage > 500: No Material Loss: 0 Carrier Damage: 0 Property Damage: 0 Response Cost: 0 Remediation Cost: 0 Damage Old Form: 0 Total Damages Amt: 0 Hazmat Fatality: No Haz Fatal Employees: 0 Haz Fatal Respndrs: 0 Haz Fatal Gen Public: 0 Tot Hazmat Fatalities: 0 Non Hazmat Fatality: No Non Hazmat FataIs: 0 Hazmat Injury: No Haz Hospital Empl: 0 Haz Hospital Resp: 0 Haz Hosp Gen Public: 0 Haz Hosp Old Form: 0 Total Haz Hosp Inj: 0 Haz Non Hosp Empl: 0 Haz Non Hosp Resp: 0 Description of Events: Ship Init Transport: No Ship Phase Transfer: No Contact Name: GEORGE FETSKO Contact Title: SAFETY PROCESS SPECIALIST I - HAZMAT Contact Business: Fedex Ground Package System Inc. Contact Street: 1000 Fedex Drive Contact City: Moon Township Contact State: PA Contact Postal: 15108 Contact Non US St: Contact Country: US Inc. Report Prepared: Carrier HMIS Serious Incidnt: No HMIS Serious Fatality: No HMIS Serious Injury: No HMIS Flight Plan: No HMIS Serious Evacs: No HMIS Major Artery: No HMIS Bulk Release: No HMIS Marine Pollutnt: No HMIS Radioactive: No HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt HMIS Container Code: 4G HMIS Container Desc: Fiberboard box HMIS Bulk Incident: No Undeclared Shipment: No The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.						
Recommend Actions Taken:						

7	2 of 13	NE	0.12 / 612.03	1,013.74 / 1	6265 Atlantic Blvd Norcross GA	HMIRS
Incident County:		GWINNETT				

HMIR Historical Reports

Report No:	X-2012120289	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	11/28/2012	Report Submit Src:	XML
Time of Incident:	2130	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	METHANOL	Transport Phase:	LOADING
Commodity Long Nm:	METHANOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1230	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	2.6418	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	303	CR Non US State:	
How Failed Desc:	Burst or Ruptured	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:	4G/Y16/S/11USA/HEDWIN	Shipper Name:	FISHER SCIENTIFIC COMPANY LLC
Cont1 Pkging Type:		Shipper Street Name:	2775 HORIZON RIDGE CT
Cont1 Const Mat:		Shipper City:	SUWANEE
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:		Shipper Postal:	30024-3592
C1 Capacity UOM:		Shipper Non US St:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	39064579110081
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	SUWANEE
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:					Origin Postal:	30024
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	ORLANDO
C1 Pkg Dsign Pres.:					Destination State:	FLORIDA
C1 Dsign Press UOM:					Destination Postal:	32806
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
ID No:	UN1170				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	BROADWAY WAREHOUSES OF ILLINOIS INC
Cont1 Pkging Type:	Box				Shipper Street Name:	7750 INDUSTRIAL DR
Cont1 Const Mat:	Fiberboard				Shipper City:	FOREST PARK
Cont1 Head Type:					Shipper State:	IL
Cont1 Pkg Capacity:					Shipper Postal:	60130-2520
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	99351624870
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	FOREST PARK
Cont1 Pkg Mnfctr:					Origin State:	ILLINOIS
Cont1 Pkg Mnfct Dt:					Origin Postal:	60130
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30305
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

7	5 of 13	NE	0.12 / 612.03	1,013.74 / 1	6265 Atlantic Blvd Norcross GA	HMIRS

Incident County: GWINNETT

HMIR Historical Reports

Report No:	X-2012120361	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	12/04/2012	Report Submit Src:	XML
Time of Incident:	2130	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS N.O.S.	Transport Phase:	UNLOADING
Commodity Long Nm:	FLAMMABLE LIQUIDS N.O.S.	Incident Occrrnce:	
Trade Name:	Acetone	Mat Ship Approval?:	No
ID No:	UN1993	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.007812	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	GEORGIA GRAPHICS INC
Cont1 Pkging Type:	Box	Shipper Street Name:	7055 AMWILER INDSTR L E
Cont1 Const Mat:	Fiberboard	Shipper City:	ATLANTA
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:		Shipper Postal:	30360-2833
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	30738232457873
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	DORAVILLE
Cont1 Pkg Mnfctr:		Origin State:	GEORGIA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Mnfct Dt:					Origin Postal:	30360
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	DALTON
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30720
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>HMIR Historical Reports</u>						
Report No:	X-2012100097				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	09/12/2012				Report Submit Src:	XML
Time of Incident:	2200				Inc Multiple Rows:	No
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	NITRIC ACID OTHER THAN R				Transport Phase:	UNLOADING
Commodity Long Nm:	NITRIC ACID OTHER THAN RED FUMING WITH AT LEAST 65 PERCENT BUT NOT MORE THAN 70 PERCENT NITRIC ACID				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN2031				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.264180				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	303				CR Non US State:	
How Failed Desc:	Burst or Ruptured				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:					Shipper Name:	FEDEX GROUND PACKAGE SYSTEM INC.
Cont1 Pkging Type:	Box				Shipper Street Name:	2410 UNITED DR
Cont1 Const Mat:	Fiberboard				Shipper City:	GREENVILLE
Cont1 Head Type:					Shipper State:	NC
Cont1 Pkg Capacity:					Shipper Postal:	27834-6539
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	889027825009116
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	GREENVILLE
Cont1 Pkg Mnfctr:					Origin State:	NORTH CAROLINA
Cont1 Pkg Mnfct Dt:					Origin Postal:	27834
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	SUWANEE
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30024
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:	No			Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	Moon Township	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:	0			HMIS Container Code:	BOX FBR	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box or carton	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014100247	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	09/17/2014	Report Submit Src:	XML
Time of Incident:	1800	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	METHANOL	Transport Phase:	LOADING
Commodity Long Nm:	METHANOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1230	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1.056720	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108-9373
How Failed Code:	305	CR Non US State:	
How Failed Desc:	Crushed	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:	4G/X10.9/S/13/USA/M4109	Shipper Name:	SIGMA-ALDRICH CORPORATION
Cont1 Pkging Type:		Shipper Street Name:	6000 N TEUTONIA AVE
Cont1 Const Mat:		Shipper City:	MILWAUKEE
Cont1 Head Type:		Shipper State:	WI

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Capacity:					Shipper Postal:	53209-3645
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	36553834415601
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	MILWAUKEE
Cont1 Pkg Mnfctr:					Origin State:	WISCONSIN
Cont1 Pkg Mnfc Dt:					Origin Postal:	53209
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:		The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2012100413				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	10/02/2012				Report Submit Src:	XML
Time of Incident:	0900				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	ETHANOL OR ETHYL ALCOHOL				Transport Phase:	UNLOADING
Commodity Long Nm:	ETHANOL OR ETHYL ALCOHOL OR ETHANOL SOLUTIONS OR ETHYL ALCOHOL SOLUTIONS				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1170				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.007812				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:	4G/Y25/S/12USA/M5586				Shipper Name:	MERCEDES MEDICAL LLC
Cont1 Pkging Type:					Shipper Street Name:	7590 COMMERCE CT
Cont1 Const Mat:					Shipper City:	SARASOTA
Cont1 Head Type:					Shipper State:	FL
Cont1 Pkg Capacity:					Shipper Postal:	34243-3217
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	33796370256076
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	SARASOTA
Cont1 Pkg Mnfctr:					Origin State:	FLORIDA
Cont1 Pkg Mnfcct Dt:					Origin Postal:	34243
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	CHAMBLEE
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30341
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:					The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.	

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2018030168	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	02/17/2018	Report Submit Src:	XML
Time of Incident:	0700	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI	Transport Phase:	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1824	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.25	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
How Failed Desc:	Leaked				CR Fed DOT ID: 265752	
Failure Cause Code:	526				CR Hazmat Reg ID: 051910551007S	
Failure Cause Desc:	Loose Closure Component or Device				CR Country: US	
Ident. Markings:	4G/Y24.7/S/17/USA/M4172				Shipper Name: ECOLAB INC.	
Cont1 Pkging Type:	Box				Shipper Street Name: 90 PIEDMONT INDUSTRIAL DR	
Cont1 Const Mat:	Fiberboard				Shipper City: WINSTON SALEM	
Cont1 Head Type:					Shipper State: NC	
Cont1 Pkg Capacity:	0				Shipper Postal: 27107-6876	
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country: US	
C1 Pkg Amt UOM:					Shipper Waybill: 757771683187746	
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City: WINSTON SALEM	
Cont1 Pkg Mnfctr:					Origin State: NORTH CAROLINA	
Cont1 Pkg Mnfc Dt:					Origin Postal: 27107	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country: US	
C1 Test Const Mat:	Fiberboard				Destination City: ATLANTA	
C1 Pkg Dsign Pres.:					Destination State: GEORGIA	
C1 Dsign Press UOM:					Destination Postal: 30329	
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country: US	
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public: 0	
RAM Pkg Cert.:	FALSE				Haz NonHosp Old: 0	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj: 0	
RAM Nuclide S:					Total Hazmat Injuries: 0	
RAM Transport Index:					Evacuation Indicator: No	
RAM UOM:					Public Evacuated: 0	
RAM Activity Rpted:					Employees Evac: 0	
RAM UOM Rpted:					Total Evacuated: 0	
RAM Activity:	0				Total Evacuation Hrs: 0	
RAM Activity UOM:					Major Artery Closed: No	
RAM Mat Safety:					Mjr Artery Hrs Closed: 0	
Spillage Result:	Yes				Material Involved: No	
Fire Result:	No				Estimated Speed: 0	
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn: No	
Gas Dispersion:	No				Vehicle Left Roadway: No	
Environment Damage:	No				Passenger Aircraft: No	
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport: No	
Fire EMS EMS Report:					Ship Air First Flight: No	
Police Report:	No				Ship Air Subflight: No	
Police Report No:					Ship Init Transport: No	
In House Cleanup:	Yes				Ship Phase Transfer: No	
Other Cleanup:	No				Contact Name: GEORGE FETSKO	
Damage > 500:	No				Contact Title: HAZMAT - SAFETY ADVISOR	
Material Loss:	0				Contact Business: Fedex Ground Package System Inc.	
Carrier Damage:	0				Contact Street: 1000 Fedex Drive	
Property Damage:	0				Contact City: CORAOPOLIS	
Response Cost:	0				Contact State: PA	
Remediation Cost:	0				Contact Postal: 15108	
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country: US	
Hazmat Fatality:	No				Inc. Report Prepared: Carrier	
Haz Fatal Employees:	0				HMIS Serious Incidnt: No	
Haz Fatal Respndrs:	0				HMIS Serious Fatality: No	
Haz Fatal Gen Public:	0				HMIS Serious Injury: No	
Tot Hazmat Fatalities:	0				HMIS Flight Plan: No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: WET BOX WAS FOUND ON THE DOCK. AS I LOOKED INSIDE THE BOX THERE WAS 4 1GAL JUGS OF MACHINE WAREWASHING DETERGENT BUT 3 OF THEM HAD LOOSE CAPS New Comments:					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014010030	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	12/05/2013	Report Submit Src:	XML
Time of Incident:	1659	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC	Transport Phase:	LOADING
Commodity Long Nm:	CORROSIVE LIQUID BASIC INORGANIC N. O.S.	Incident Occrrnce:	
Trade Name:	Sodium Hydroxide Al	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.1250	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	NALCO COMPANY LLC
Cont1 Pkging Type:	Jerrican	Shipper Street Name:	7701 HIGHWAY 90A
Cont1 Const Mat:	Plastic	Shipper City:	SUGAR LAND
Cont1 Head Type:		Shipper State:	TX
Cont1 Pkg Capacity:	0	Shipper Postal:	77478-2121
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	532835499631
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	SUGAR LAND
Cont1 Pkg Mnfctr:		Origin State:	TEXAS
Cont1 Pkg Mnfc Dt:		Origin Postal:	77478
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Plastic	Destination City:	ATLANTA
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30324
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvc Pres.:		Cont2 Pkg Capacity:	
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	
C1 Device Type:		Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:		Cont2 Pkg No:	
C1 Device Model:		Cont2 Pkg No Failed:	
NRC No:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	CONT PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic container no capacity or description given
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014020279	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	02/04/2014	Report Submit Src:	XML
Time of Incident:	1700	Inc Multiple Rows:	No
Haz Class Code:	5.1	Inc Non US State:	
Hazardous Class:	OXIDIZER	Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	Transport Phase:	LOADING
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES STABILIZED WITH ACIDS WATER AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	Incident Occrrnce:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Trade Name:	stabilized			Mat Ship Approval?:	No	
ID No:	UN3149			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:	0.1250			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	104			CR State:	PA	
What Failed Desc:	Body			CR Postal Code:	15108-9373	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	REPROCESSING PRODUCTS CORPORATION	
Cont1 Pkging Type:	Box			Shipper Street Name:	3984 QUEBEC AVE N	
Cont1 Const Mat:	Fiberboard			Shipper City:	MINNEAPOLIS	
Cont1 Head Type:				Shipper State:	MN	
Cont1 Pkg Capacity:				Shipper Postal:	55427-1244	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	915475935242949	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	CRYSTAL	
Cont1 Pkg Mnfctr:				Origin State:	MINNESOTA	
Cont1 Pkg Mnfcct Dt:				Origin Postal:	55427	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	SANDY SPRINGS	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30350	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2017080188			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	07/12/2017			Report Submit Src:	XML	
Time of Incident:	0556			Inc Multiple Rows:	No	
Haz Class Code:	8			Inc Non US State:		
Hazardous Class:	CORROSIVE MATERIAL			Mode Transport:	Highway	
Commodity Short Nm:	CORROSIVE LIQUID ACIDIC			Transport Phase:	LOADING	
Commodity Long Nm:	CORROSIVE LIQUID ACIDIC INORGANIC N. O.S.			Incident Occrrnce:		
Trade Name:	(PHOSPHORIC ACID HY			Mat Ship Approval?:	No	
ID No:	UN3264			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:	1			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g. Cap Top or Plug)			CR Postal Code:	15108-9373	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	ZEP INC	
Cont1 Pkging Type:	Box			Shipper Street Name:	71 BUSINESS PARK DR	
Cont1 Const Mat:	Fiberboard			Shipper City:	CARTERSVILLE	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:				Shipper Postal:	30121	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	496166002012970	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	CARTERSVILLE	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfct Dt:				Origin Postal:	30121	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	TUCKER	
C1 Pkg Dsgn Pres.:				Destination State:	GEORGIA	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Dsign Press UOM:				Destination Postal:	30084	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?: No				Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.: FALSE				Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result: Yes				Material Involved:	No	
Fire Result: No				Estimated Speed:	0	
Explosion Result: No				Weather Conditions:		
Water Sewer Result: No				Vehicle Overturn:	No	
Gas Dispersion: No				Vehicle Left Roadway:	No	
Environment Damage: No				Passenger Aircraft:	No	
No Release Result: No				Cargo Baggage:		
Fire EMS Report: No				Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report: No				Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup: Yes				Ship Phase Transfer:	No	
Other Cleanup: No				Contact Name:	GEORGE FETSKO	
Damage > 500: No				Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss: 0				Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage: 0				Contact Street:	1000 Fedex Drive	
Property Damage: 0				Contact City:	CORAOPOLIS	
Response Cost: 0				Contact State:	PA	
Remediation Cost: 0				Contact Postal:	15108	
Damage Old Form: 0				Contact Non US St:		
Total Damages Amt: 0				Contact Country:	US	
Hazmat Fatality: No				Inc. Report Prepared:	Carrier	
Haz Fatal Employees: 0				HMIS Serious Incidnt:	No	
Haz Fatal Respndrs: 0				HMIS Serious Fatality:	No	
Haz Fatal Gen Public: 0				HMIS Serious Injury:	No	
Tot Hazmat Fatalities: 0				HMIS Flight Plan:	No	
Non Hazmat Fatality: No				HMIS Serious Evacs:	No	
Non Hazmat Fatals: 0				HMIS Major Artery:	No	
Hazmat Injury: No				HMIS Bulk Release:	No	
Haz Hospital Empl: 0				HMIS Marine Pollutnt:	No	
Haz Hospital Resp: 0				HMIS Radioactive:	No	
Haz Hosp Gen Public: 0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form: 0				HMIS Container Code:	BOX FBR	
Total Haz Hosp Inj: 0				HMIS Container Desc:	Fiberboard box or carton	
Haz Non Hosp Empl: 0				HMIS Bulk Incident:	No	
Haz Non Hosp Resp: 0				Undeclared Shipment:	No	
Description of Events:		The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.				

Recommend Actions Taken:

HMIR Historical Reports

Report No: X-2017090379

Fed DOT Agency Nm:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	08/23/2017			Report Submit Src:	XML	
Time of Incident:	0405			Inc Multiple Rows:	No	
Haz Class Code:	5.2			Inc Non US State:		
Hazardous Class:	ORGANIC PEROXIDE			Mode Transport:	Highway	
Commodity Short Nm:	ORGANIC PEROXIDE TYPE F			Transport Phase:	LOADING	
Commodity Long Nm:	ORGANIC PEROXIDE TYPE F LIQUID			Incident Occrrnce:		
Trade Name:	peracetic acid			Mat Ship Approval?:	No	
ID No:	UN3109			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:	0.1250			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	104			CR State:	PA	
What Failed Desc:	Body			CR Postal Code:	15108-9373	
How Failed Code:	309			CR Non US State:		
How Failed Desc:	Punctured			CR Fed DOT ID:	265752	
Failure Cause Code:	516			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g. nails)			CR Country:	US	
Ident. Markings:				Shipper Name:	ZEP INC	
Cont1 Pkging Type:	Jerrican			Shipper Street Name:	71 BUSINESS PARK CT	
Cont1 Const Mat:	Plastic			Shipper City:	CARTERSVILLE	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:	0			Shipper Postal:	30121	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	486166002143162	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	CARTERSVILLE	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfc Dt:				Origin Postal:	30121	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Plastic			Destination City:	TUCKER	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30084	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggaqe:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	PAIL PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic pail open head capacity 10 gallons or less
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2018070572	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	06/25/2018	Report Submit Src:	XML
Time of Incident:	2203	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	ETHYL ALCOHOL	Transport Phase:	UNLOADING
Commodity Long Nm:	ETHYL ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1170	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	DECON LABORATORIES INC.
Cont1 Pkging Type:	Jerrican	Shipper Street Name:	460 GLENNIE CIR
Cont1 Const Mat:	Plastic	Shipper City:	KING OF PRUSSIA
Cont1 Head Type:		Shipper State:	PA
Cont1 Pkg Capacity:		Shipper Postal:	19406-2682
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	695774781486004510
Cont1 Pkg No:		Ship Hazmat Reg ID:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg NO Failed:				Origin City:	KING OF PRUSSIA	
Cont1 Pkg Mnfctr:				Origin State:	PENNSYLVANIA	
Cont1 Pkg Mnfc Dt:				Origin Postal:	19406	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:		Plastic		Destination City:	ATLANTA	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30322	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:		No		Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:		FALSE		Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:		Yes		Material Involved:	No	
Fire Result:		No		Estimated Speed:	0	
Explosion Result:		No		Weather Conditions:		
Water Sewer Result:		No		Vehicle Overturn:	No	
Gas Dispersion:		No		Vehicle Left Roadway:	No	
Environment Damage:		No		Passenger Aircraft:	No	
No Release Result:		No		Cargo Baggage:		
Fire EMS Report:		No		Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:		No		Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:		Yes		Ship Phase Transfer:	No	
Other Cleanup:		No		Contact Name:	GEORGE FETSKO	
Damage > 500:		No		Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:		0		Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:		0		Contact Street:	1000 Fedex Drive	
Property Damage:		0		Contact City:	CORAOPOLIS	
Response Cost:		0		Contact State:	PA	
Remediation Cost:		0		Contact Postal:	15108	
Damage Old Form:		0		Contact Non US St:		
Total Damages Amt:		0		Contact Country:	US	
Hazmat Fatality:		No		Inc. Report Prepared:	Carrier	
Haz Fatal Employees:		0		HMIS Serious Incidnt:	No	
Haz Fatal Respntrs:		0		HMIS Serious Fatality:	No	
Haz Fatal Gen Public:		0		HMIS Serious Injury:	No	
Tot Hazmat Fatalities:		0		HMIS Flight Plan:	No	
Non Hazmat Fatality:		No		HMIS Serious Evacs:	No	
Non Hazmat Fatals:		0		HMIS Major Artery:	No	
Hazmat Injury:		No		HMIS Bulk Release:	No	
Haz Hospital Empl:		0		HMIS Marine Pollutnt:	No	
Haz Hospital Resp:		0		HMIS Radioactive:	No	
Haz Hosp Gen Public:		0		HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:		0		HMIS Container Code:	CONT	
Total Haz Hosp Inj:		0		HMIS Container Desc:	Container no description given (do not use if at all possible)	
Haz Non Hosp Empl:		0		HMIS Bulk Incident:	No	
Haz Non Hosp Resp:		0		Undeclared Shipment:	No	
Description of Events:		Original comments: BOX WAS FOUND ON DOCK WET. AS I LOOKED INSIDE THERE WERE 4 1 GAL				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
BOTTLES OF ETHANOL 2 HAD LOOSE CAPS THE OTHER 2 WAS OK New Comments:						
Recommend Actions Taken:						
<u>HMIR Historical Reports</u>						
Report No:	X-2014020310				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	02/06/2014				Report Submit Src:	XML
Time of Incident:	1630				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	ACETONITRILE				Transport Phase:	LOADING
Commodity Long Nm:	ACETONITRILE				Incident Occrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1648				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1.056720				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	304				CR Non US State:	
How Failed Desc:	Cracked				CR Fed DOT ID:	265752
Failure Cause Code:	502				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Broken Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	SIGMA-ALDRICH CORPORATION
Cont1 Pkging Type:	Box				Shipper Street Name:	6000 N TEUTONIA AVE
Cont1 Const Mat:	Fiberboard				Shipper City:	MILWAUKEE
Cont1 Head Type:					Shipper State:	WI
Cont1 Pkg Capacity:	0				Shipper Postal:	53209-3645
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	36553829915987
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	BROWN DEER
Cont1 Pkg Mnfctr:					Origin State:	WISCONSIN
Cont1 Pkg Mnfct Dt:					Origin Postal:	53209
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:	No			Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat FataIs:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:	0			HMIS Container Code:	BOX FBR	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box or carton	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2016090646	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	08/25/2016	Report Submit Src:	XML
Time of Incident:	2338	Inc Multiple Rows:	Yes
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC	Transport Phase:	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUID BASIC INORGANIC N. O.S.	Incident Occrrnce:	
Trade Name:	(contains Potassium	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.50	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:	4G/Yy21.1/S/16 Usa/+BZ0775	Shipper Name:	DIVERSITECH CORPORATION
Cont1 Pkging Type:		Shipper Street Name:	2175 E PARK DR NE
Cont1 Const Mat:		Shipper City:	CONYERS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30013-5773
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	701396650994
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	CONYERS
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:					Origin Postal:	30013
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	BERKELEY LAKE
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30096
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2016040256				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	03/11/2016				Report Submit Src:	XML
Time of Incident:	1016				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	ADHESIVES CONTAINING A				Transport Phase:	IN TRANSIT
Commodity Long Nm:	ADHESIVES CONTAINING A FLAMMABLE LIQUID				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1133				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.007812				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:	4G/Y12.5/S/14				Shipper Name:	DECK RITE LLC
Cont1 Pkging Type:					Shipper Street Name:	3912 E PROGRESS ST
Cont1 Const Mat:					Shipper City:	NORTH LITTLE ROCK
Cont1 Head Type:					Shipper State:	AR
Cont1 Pkg Capacity:					Shipper Postal:	72114-5239
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	60750426625
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	NORTH LITTLE ROCK
Cont1 Pkg Mnfctr:					Origin State:	ARKANSAS
Cont1 Pkg Mnfc Dt:					Origin Postal:	72114
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	DORAVILLE
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30360
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:					The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.	

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2015060331	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	06/02/2015	Report Submit Src:	XML
Time of Incident:	2305	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS CORRO	Transport Phase:	IN TRANSIT
Commodity Long Nm:	FLAMMABLE LIQUIDS CORROSIVE N.O.S.	Incident Occrrnce:	
Trade Name:	TRIMETHYLBENZENE AM	Mat Ship Approval?:	No
ID No:	UN2924	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	3.25	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	AXALTA COATING SYSTEMS LLC	
Cont1 Pkging Type:	Box			Shipper Street Name:	7961 WINCHESTER RD	
Cont1 Const Mat:	Fiberboard			Shipper City:	FRONT ROYAL	
Cont1 Head Type:				Shipper State:	VA	
Cont1 Pkg Capacity:				Shipper Postal:	22630-6901	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	27875525191	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	FRONT ROYAL	
Cont1 Pkg Mnfctr:				Origin State:	VIRGINIA	
Cont1 Pkg Mnfc Dt:				Origin Postal:	22630	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	CUMMING	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30040	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:	Can	
C1 Head Thick UOM:				Cont2 Const Mat:	Metal (any type)	
C1 Pkg Srvs Pres.:				Cont2 Pkg Capacity:		
C1 Srvs Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:	0			HMIS Container Code:	BOX FBR	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box or carton	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2013100391	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	09/30/2013	Report Submit Src:	XML
Time of Incident:	1633	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	PETROLEUM DISTILLATES N	Transport Phase:	LOADING
Commodity Long Nm:	PETROLEUM DISTILLATES N.O.S. OR PETROLEUM PRODUCTS N.O.S.	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1268	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	4	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108-9373
How Failed Code:	304	CR Non US State:	
How Failed Desc:	Cracked	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:		Shipper Name:	VOLVO PENTA OF THE AMERICAS LLC
Cont1 Pkging Type:	Drum	Shipper Street Name:	3020 EVERGREEN DR
Cont1 Const Mat:	Plastic	Shipper City:	DULUTH
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30096-5830
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	342519570209063
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	BERKELEY LAKE
Cont1 Pkg Mnfctr:		Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:		Origin Postal:	30096
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Plastic	Destination City:	BEND
C1 Pkg Dsign Pres.:		Destination State:	OREGON
C1 Dsign Press UOM:		Destination Postal:	97702
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvs Pres.:		Cont2 Pkg Capacity:	
C1 Srvs Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	
C1 Device Type:		Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:		Cont2 Pkg No:	
C1 Device Model:		Cont2 Pkg No Failed:	
NRC No:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2012110225				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	10/19/2012				Report Submit Src:	XML
Time of Incident:	1430				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS N.O.S.				Transport Phase:	UNLOADING
Commodity Long Nm:	FLAMMABLE LIQUIDS N.O.S.				Incident Occrrnce:	
Trade Name:	XYLENE ETHYLBENZENE				Mat Ship Approval?:	No
ID No:	UN1993				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
TIH Hazard Zone:			Carrier Reporter:			FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.066045			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g. Cap Top or Plug)			CR Postal Code:	15108-9373	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	NCH CORPORATION	
Cont1 Pkging Type:	Box			Shipper Street Name:	1300 E NORTHGATE	
Cont1 Const Mat:	Fiberboard			Shipper City:	IRVING	
Cont1 Head Type:				Shipper State:	TX	
Cont1 Pkg Capacity:				Shipper Postal:	75062	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	76974570463783	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	IRVING	
Cont1 Pkg Mnfctr:				Origin State:	TEXAS	
Cont1 Pkg Mnfct Dt:				Origin Postal:	75062	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	CUMMING	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30041	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:			Haz NonHosp Public:			0
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		0
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		0
RAM Nuclide S:				Total Hazmat Injuries:		0
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	Moon Township	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2018090052	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	08/13/2018	Report Submit Src:	XML
Time of Incident:	2017	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	COMPOUNDS CLEANING LIQU	Transport Phase:	UNLOADING
Commodity Long Nm:	COMPOUNDS CLEANING LIQUID	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	NA1993	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	140	CR State:	PA
What Failed Desc:	Outer Frame	CR Postal Code:	15108-9373
How Failed Code:	309	CR Non US State:	
How Failed Desc:	Punctured	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:	4G/Y30/S/17 USA/+CM0042	Shipper Name:	FEDEX GROUND
Cont1 Pkging Type:	Box	Shipper Street Name:	6265 ATLANTIC BLVD
Cont1 Const Mat:	Fiberboard	Shipper City:	NORCROSS
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:		Shipper Postal:	30071-1308
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	307382889090122517253
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	NORCROSS
Cont1 Pkg Mnfctr:		Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:		Origin Postal:	30071
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Fiberboard	Destination City:	ATLANTA
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30360
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvc Pres.:		Cont2 Pkg Capacity:	
C1 Srvc Press UOM:		Cont2 Capacity UOM:	

Order No: 22051600831

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatafs:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2017120286			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	11/21/2017			Report Submit Src:	XML	
Time of Incident:	0745			Inc Multiple Rows:	No	
Haz Class Code:	8			Inc Non US State:		
Hazardous Class:	CORROSIVE MATERIAL			Mode Transport:	Highway	
Commodity Short Nm:	CORROSIVE LIQUID ACIDIC			Transport Phase:	LOADING	
Commodity Long Nm:	CORROSIVE LIQUID ACIDIC INORGANIC N. O.S.			Incident Occrrnce:		
Trade Name:	Phosphoric Acid Hyd			Mat Ship Approval?:	No	
ID No:	UN3264			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:	0.25			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g. Cap Top or Plug)			CR Postal Code:	15108-9373	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	ZEP NASS GDC	
Cont1 Pkging Type:	Box			Shipper Street Name:	71 BUSINESS PARK DR	
Cont1 Const Mat:	Fiberboard			Shipper City:	CARTERSVILLE	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:				Shipper Postal:	30121	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	486166002436745	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	CARTERSVILLE	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfct Dt:				Origin Postal:	30121	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30324
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report No:	X-2012090263				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	08/28/2012				Report Submit Src:	XML
Time of Incident:	2330				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL				Transport Phase:	UNLOADING
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1219				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.264180				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	305				CR Non US State:	
How Failed Desc:	Crushed				CR Fed DOT ID:	265752
Failure Cause Code:	515				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Human Error				CR Country:	US
Ident. Markings:	4G/Y11.5/S/11				Shipper Name:	XZILON INC
Cont1 Pkging Type:					Shipper Street Name:	3384 WEST OSBORN ROAD
Cont1 Const Mat:					Shipper City:	PHOENIX
Cont1 Head Type:					Shipper State:	AZ
Cont1 Pkg Capacity:					Shipper Postal:	85017
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	709667230302850
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	PHOENIX
Cont1 Pkg Mnfctr:					Origin State:	ARIZONA
Cont1 Pkg Mnfct Dt:					Origin Postal:	85017
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	LOGANVILLE
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30052
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2017110064	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	10/06/2017	Report Submit Src:	XML
Time of Incident:	0018	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	HYPOCHLORITE SOLUTIONS	Transport Phase:	LOADING
Commodity Long Nm:	HYPOCHLORITE SOLUTIONS	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1791	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.264180	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	ECOLAB INC.
Cont1 Pkging Type:	Jerrican	Shipper Street Name:	125 SOUTHSIDE CT STE 100
Cont1 Const Mat:	Plastic	Shipper City:	MCDONOUGH
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30253-7448
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	916079072035144
Cont1 Pkg No:		Ship Hazmat Reg ID:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg NO Failed:			Origin City:		MCDONOUGH	
Cont1 Pkg Mnfctr:			Origin State:		GEORGIA	
Cont1 Pkg Mnfc Dt:			Origin Postal:		30253	
Cont1 Pkg Serial NO:			Origin Non US St:			
C1 Pkg Last Test Dt:			Origin Country:		US	
C1 Test Const Mat:		Plastic	Destination City:		ORMOND BEACH	
C1 Pkg Dsign Pres.:			Destination State:		FLORIDA	
C1 Dsign Press UOM:			Destination Postal:		32174	
C1 Pkg Shell Thick:			Destination Non US:			
C1 Shell Thick UOM:			Destination Country:		US	
C1 Head Thickness:			Cont2 Package Type:			
C1 Head Thick UOM:			Cont2 Const Mat:			
C1 Pkg Srvc Pres.:			Cont2 Pkg Capacity:			
C1 Srvc Press UOM:			Cont2 Capacity UOM:			
C1 Valve/Device Fail?:		No	Cont2 Pkg Amount:			
C1 Device Type:			Cont2 Pkg Amt UOM:			
C1 Device Mnfctr:			Cont2 Pkg No:			
C1 Device Model:			Cont2 Pkg No Failed:			
NRC No:						
RAM Pkg Category:			Haz NonHosp Public:		0	
RAM Pkg Cert.:		FALSE	Haz NonHosp Old:		0	
RAM Pkg Cert. NBR:			Tot Haz Non Hosp Inj:		0	
RAM Nuclide S:			Total Hazmat Injuries:		0	
RAM Transport Index:			Evacuation Indicator:		No	
RAM UOM:			Public Evacuated:		0	
RAM Activity Rpted:			Employees Evac:		0	
RAM UOM Rpted:			Total Evacuated:		0	
RAM Activity:		0	Total Evacuation Hrs:		0	
RAM Activity UOM:			Major Artery Closed:		No	
RAM Mat Safety:			Mjr Artery Hrs Closed:		0	
Spillage Result:		Yes	Material Involved:		No	
Fire Result:		No	Estimated Speed:		0	
Explosion Result:		No	Weather Conditions:			
Water Sewer Result:		No	Vehicle Overturn:		No	
Gas Dispersion:		No	Vehicle Left Roadway:		No	
Environment Damage:		No	Passenger Aircraft:		No	
No Release Result:		No	Cargo Baggage:			
Fire EMS Report:		No	Ship Non Transport:		No	
Fire EMS EMS Report:			Ship Air First Flight:		No	
Police Report:		No	Ship Air Subflight:		No	
Police Report No:			Ship Init Transport:		No	
In House Cleanup:		Yes	Ship Phase Transfer:		No	
Other Cleanup:		No	Contact Name:		GEORGE FETSKO	
Damage > 500:		No	Contact Title:		HAZMAT - SAFETY ADVISOR	
Material Loss:		0	Contact Business:		Fedex Ground Package System Inc.	
Carrier Damage:		0	Contact Street:		1000 Fedex Drive	
Property Damage:		0	Contact City:		CORAOPOLIS	
Response Cost:		0	Contact State:		PA	
Remediation Cost:		0	Contact Postal:		15108	
Damage Old Form:		0	Contact Non US St:			
Total Damages Amt:		0	Contact Country:		US	
Hazmat Fatality:		No	Inc. Report Prepared:		Carrier	
Haz Fatal Employees:		0	HMIS Serious Incidnt:		No	
Haz Fatal Respntrs:		0	HMIS Serious Fatality:		No	
Haz Fatal Gen Public:		0	HMIS Serious Injury:		No	
Tot Hazmat Fatalities:		0	HMIS Flight Plan:		No	
Non Hazmat Fatality:		No	HMIS Serious Evacs:		No	
Non Hazmat Fatals:		0	HMIS Major Artery:		No	
Hazmat Injury:		No	HMIS Bulk Release:		No	
Haz Hospital Empl:		0	HMIS Marine Pollutnt:		No	
Haz Hospital Resp:		0	HMIS Radioactive:		No	
Haz Hosp Gen Public:		0	HMIS Gen Pkg Type:		OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:		0	HMIS Container Code:		PAIL PLS	
Total Haz Hosp Inj:		0	HMIS Container Desc:		Plastic pail open head capacity 10 gallons or less	
Haz Non Hosp Empl:		0	HMIS Bulk Incident:		No	
Haz Non Hosp Resp:		0	Undeclared Shipment:		No	
Description of Events:			The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.						
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2013110321				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	11/01/2013				Report Submit Src:	XML
Time of Incident:	1635				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	ETHANOL SOLUTIONS				Transport Phase:	LOADING
Commodity Long Nm:	ETHANOL SOLUTIONS				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1170				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	309				CR Non US State:	
How Failed Desc:	Punctured				CR Fed DOT ID:	265752
Failure Cause Code:	522				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Inadequate Procedures				CR Country:	US
Ident. Markings:					Shipper Name:	UNIVAR USA INC.
Cont1 Pkging Type:	Drum				Shipper Street Name:	1 ALCHEMY PL
Cont1 Const Mat:	Aluminum				Shipper City:	DORAVILLE
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30360-2719
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	23940115003552
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	ATLANTA
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:					Origin Postal:	30360
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Aluminum				Destination City:	SPRING HILL
C1 Pkg Dsign Pres.:					Destination State:	TENNESSEE
C1 Dsign Press UOM:					Destination Postal:	37174
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM MTL
Total Haz Hosp Inj:	0				HMIS Container Desc:	Metal drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2016090646	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	08/25/2016	Report Submit Src:	XML
Time of Incident:	2338	Inc Multiple Rows:	Yes
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC	Transport Phase:	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUID BASIC INORGANIC N. O.S.	Incident Occrrnce:	
Trade Name:	Contains potassium a	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1.50	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	312	CR Non US State:	
How Failed Desc:	Torn Off or Damaged	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	DIVERSITECH CORPORATION
Cont1 Pkging Type:	Box	Shipper Street Name:	2175 E PARK DR NE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Const Mat:	Fiberboard				Shipper City:	CONYERS
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30013-5773
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	2506707701396650983
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	CONYERS
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:					Origin Postal:	30013
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	DULUTH
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30096
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2018090371				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	08/27/2018				Report Submit Src:	XML
Time of Incident:	2000				Inc Multiple Rows:	No
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	FORMIC ACID WITH MORE TH				Transport Phase:	UNLOADING
Commodity Long Nm:	FORMIC ACID WITH MORE THAN 85% ACID BY MASS				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1779				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.0625				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:	4G/X9/S/18/USA/M4109				Shipper Name:	SIGMA-ALDRICH CORPORATION
Cont1 Pkging Type:	Box				Shipper Street Name:	6000 N TEUTONIA AVE
Cont1 Const Mat:	Fiberboard				Shipper City:	MILWAUKEE
Cont1 Head Type:					Shipper State:	WI
Cont1 Pkg Capacity:					Shipper Postal:	53209-3645
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	365538036553874598869
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	MILWAUKEE
Cont1 Pkg Mnfctr:					Origin State:	WISCONSIN
Cont1 Pkg MnfcDt:					Origin Postal:	53209
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	TUCKER
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30084
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:				Original comments: PACKAGE WAS FOUND WET ON DOCK. AS I LOOKED INSIDE THERE WAS A BOTTLE OF FORMIC ACID WITH A LOOSE CAP New Comments:		

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2015090016	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	08/29/2014	Report Submit Src:	XML
Time of Incident:	1100	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC	Transport Phase:	IN TRANSIT
Commodity Long Nm:	CORROSIVE LIQUID BASIC INORGANIC N. O.S.	Incident Occrrnce:	
Trade Name:	(Contains potassuim	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	5	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108-9373

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	517				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Improper Preparation for Transportation				CR Country:	US
Ident. Markings:	4G/Y21.1/S/15 USA/+BZ0775				Shipper Name:	DIVERSITECH CORPORATION
Cont1 Pkging Type:					Shipper Street Name:	2175 E PARK DR NE
Cont1 Const Mat:					Shipper City:	CONYERS
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30013-5773
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	645431699508
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	CONYERS
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:					Origin Postal:	30013
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srv Pres.:					Cont2 Pkg Capacity:	
C1 Srv Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2018050753	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	04/29/2018	Report Submit Src:	XML
Time of Incident:	2300	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI	Transport Phase:	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1824	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.0625	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:	NO MARKINGS GIVEN	Shipper Name:	CEVA LOGISTICS
Cont1 Pkging Type:	Jerrican	Shipper Street Name:	125 SOUTHSIDE CT
Cont1 Const Mat:	Plastic	Shipper City:	MCDONOUGH
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:		Shipper Postal:	30253-7448
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	916079074527821
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	MCDONOUGH
Cont1 Pkg Mnfctr:		Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:		Origin Postal:	30253
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Plastic	Destination City:	ATLANTA
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30329
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvc Pres.:		Cont2 Pkg Capacity:	
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	
C1 Device Type:		Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:		Cont2 Pkg No:	
C1 Device Model:		Cont2 Pkg No Failed:	
NRC No:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	NO MARKI
Total Haz Hosp Inj:	0				HMIS Container Desc:	
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:		Original comments: Bucket of pail was found wet on dock. as I examined the pail I notice liquid leaking from cap New Comments:				
Recommend Actions Taken:						
<u>HMIR Historical Reports</u>						
Report No:	X-2014080098				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	07/10/2014				Report Submit Src:	XML
Time of Incident:	1655				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS N.O.S.				Transport Phase:	LOADING
Commodity Long Nm:	FLAMMABLE LIQUIDS N.O.S.				Incident Occrrnce:	
Trade Name:	Alcohol Solution				Mat Ship Approval?:	No
ID No:	UN1993				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Qty Released:	0.1250				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	N/A
Cont1 Pkging Type:	Box				Shipper Street Name:	ILLEGIBLE
Cont1 Const Mat:	Fiberboard				Shipper City:	NORCROSS
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30071
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	111111111111113
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	NORCROSS
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:					Origin Postal:	30071
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	NORCROSS
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30071
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2016060877				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	05/31/2016				Report Submit Src:	XML
Time of Incident:	2345				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	ETHYL ALCOHOL				Transport Phase:	LOADING
Commodity Long Nm:	ETHYL ALCOHOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1170				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.15				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	517				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Improper Preparation for Transportation				CR Country:	US
Ident. Markings:					Shipper Name:	VWR INTERNATIONAL LLC
Cont1 Pkging Type:	Box				Shipper Street Name:	1050 SATELLITE BLVD NW
Cont1 Const Mat:	Fiberboard				Shipper City:	SUWANEE
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30024-2883
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	408394874704729
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	SUWANEE
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnftc Dt:					Origin Postal:	30024
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	BLOOMINGDALE
C1 Pkg Dsign Pres.:					Destination State:	TENNESSEE
C1 Dsign Press UOM:					Destination Postal:	37660
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public: 0		
RAM Pkg Cert.: FALSE				Haz NonHosp Old: 0		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj: 0		
RAM Nuclide S:				Total Hazmat Injuries: 0		
RAM Transport Index:				Evacuation Indicator: No		
RAM UOM:				Public Evacuated: 0		
RAM Activity Rpted:				Employees Evac: 0		
RAM UOM Rpted:				Total Evacuated: 0		
RAM Activity:				Total Evacuation Hrs: 0		
RAM Activity UOM:				Major Artery Closed: No		
RAM Mat Safety:				Mjr Artery Hrs Closed: 0		
Spillage Result: Yes				Material Involved: No		
Fire Result: No				Estimated Speed: 0		
Explosion Result: No				Weather Conditions:		
Water Sewer Result: No				Vehicle Overturn: No		
Gas Dispersion: No				Vehicle Left Roadway: No		
Environment Damage: No				Passenger Aircraft: No		
No Release Result: No				Cargo Baggage:		
Fire EMS Report: No				Ship Non Transport: No		
Fire EMS EMS Report:				Ship Air First Flight: No		
Police Report: No				Ship Air Subflight: No		
Police Report No:				Ship Init Transport: No		
In House Cleanup: Yes				Ship Phase Transfer: No		
Other Cleanup: No				Contact Name: GEORGE FETSKO		
Damage > 500: No				Contact Title: HAZMAT - SAFETY ADVISOR		
Material Loss: 0				Contact Business: Fedex Ground Package System Inc.		
Carrier Damage: 0				Contact Street: 1000 Fedex Drive		
Property Damage: 0				Contact City: CORAOPOLIS		
Response Cost: 0				Contact State: PA		
Remediation Cost: 0				Contact Postal: 15108		
Damage Old Form: 0				Contact Non US St:		
Total Damages Amt: 0				Contact Country: US		
Hazmat Fatality: No				Inc. Report Prepared: Carrier		
Haz Fatal Employees: 0				HMIS Serious Incidnt: No		
Haz Fatal Respndrs: 0				HMIS Serious Fatality: No		
Haz Fatal Gen Public: 0				HMIS Serious Injury: No		
Tot Hazmat Fatalities: 0				HMIS Flight Plan: No		
Non Hazmat Fatality: No				HMIS Serious Evacs: No		
Non Hazmat Fatais: 0				HMIS Major Artery: No		
Hazmat Injury: No				HMIS Bulk Release: No		
Haz Hospital Empl: 0				HMIS Marine Pollutnt: No		
Haz Hospital Resp: 0				HMIS Radioactive: No		
Haz Hosp Gen Public: 0				HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt		
Haz Hosp Old Form: 0				HMIS Container Code: BOX FBR		
Total Haz Hosp Inj: 0				HMIS Container Desc: Fiberboard box or carton		
Haz Non Hosp Empl: 0				HMIS Bulk Incident: No		
Haz Non Hosp Resp: 0				Undeclared Shipment: No		
Description of Events:		The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:		X-2018060119			Fed DOT Agency Nm:	
Report Type:		A hazardous material incident			Fed DOT Report No:	
Date of Incident:		05/09/2018			Report Submit Src: XML	
Time of Incident:		1500			Inc Multiple Rows: No	
Haz Class Code:		3			Inc Non US State:	
Hazardous Class:		FLAMMABLE - COMBUSTIBLE LIQUID			Mode Transport: Highway	
Commodity Short Nm:		ETHANOL SOLUTIONS			Transport Phase: UNLOADING	
Commodity Long Nm:		ETHANOL SOLUTIONS			Incident Occrrnce:	
Trade Name:					Mat Ship Approval?: No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
ID No:	UN1170				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.1875				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:	4G/Y20.0/S/18 USA/+AA8398				Shipper Name:	SLMP LLC
Cont1 Pkgng Type:	Box				Shipper Street Name:	2090 COMMERCE DR
Cont1 Const Mat:	Fiberboard				Shipper City:	MCKINNEY
Cont1 Head Type:					Shipper State:	TX
Cont1 Pkg Capacity:					Shipper Postal:	75069-8203
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	1009093100909319999144
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	MCKINNEY
Cont1 Pkg Mnfctr:					Origin State:	TEXAS
Cont1 Pkg Mnfct Dt:					Origin Postal:	75069
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30309
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: BOX WAS FOUND ON DOCK WET. AS I LOOKED INSIDE THERE WERE 4 1GAL BOTTLES OF 100% REAGENT ALCOHOL BUT 1 BOTTLE HAD A LOOSE CAP. New Comments:					
Recommend Actions Taken:						

HMIR Historical Reports

Report No:	X-2014110237	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	10/20/2014	Report Submit Src:	XML
Time of Incident:	1835	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	METHANOL	Transport Phase:	UNLOADING
Commodity Long Nm:	METHANOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1230	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	3.70	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	135	CR State:	PA
What Failed Desc:	Loading or Unloading Lines	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	CARDINAL HEALTH INC.
Cont1 Pkgng Type:	Box	Shipper Street Name:	7611 BRANDON WOODS BLVD
Cont1 Const Mat:	Fiberboard	Shipper City:	BALTIMORE
Cont1 Head Type:		Shipper State:	MD
Cont1 Pkg Capacity:	0	Shipper Postal:	21226-1740
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	173967192014633
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	BALTIMORE
Cont1 Pkg Mnfctr:		Origin State:	MARYLAND
Cont1 Pkg Mnfc Dt:		Origin Postal:	21226
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Fiberboard	Destination City:	ATLANTA
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30322
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	Bottle

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Head Thick UOM: C1 Pkg Srvc Pres.: C1 Srvc Press UOM: C1 Valve/Device Fail?: No C1 Device Type: C1 Device Mnfctr: C1 Device Model: NRC No:				Cont2 Const Mat: Cont2 Pkg Capacity: Cont2 Capacity UOM: Cont2 Pkg Amount: Cont2 Pkg Amt UOM: Cont2 Pkg No: Cont2 Pkg No Failed:		Plastic
RAM Pkg Category: RAM Pkg Cert.: FALSE RAM Pkg Cert. NBR: RAM Nuclide S: RAM Transport Index: RAM UOM: RAM Activity Rpted: RAM UOM Rpted: RAM Activity: 0 RAM Activity UOM: RAM Mat Safety: Spillage Result: Yes Fire Result: No Explosion Result: No Water Sewer Result: No Gas Dispersion: No Environment Damage: No No Release Result: No Fire EMS Report: No Fire EMS EMS Report: Police Report: No Police Report No: In House Cleanup: Yes Other Cleanup: No Damage > 500: No Material Loss: 0 Carrier Damage: 0 Property Damage: 0 Response Cost: 0 Remediation Cost: 0 Damage Old Form: 0 Total Damages Amt: 0 Hazmat Fatality: No Haz Fatal Employees: 0 Haz Fatal Respndrs: 0 Haz Fatal Gen Public: 0 Tot Hazmat Fatalities: 0 Non Hazmat Fatality: No Non Hazmat FataIs: 0 Hazmat Injury: No Haz Hospital Empl: 0 Haz Hospital Resp: 0 Haz Hosp Gen Public: 0 Haz Hosp Old Form: 0 Total Haz Hosp Inj: 0 Haz Non Hosp Empl: 0 Haz Non Hosp Resp: 0				Haz NonHosp Public: 0 Haz NonHosp Old: 0 Tot Haz Non Hosp Inj: 0 Total Hazmat Injuries: 0 Evacuation Indicator: No Public Evacuated: 0 Employees Evac: 0 Total Evacuated: 0 Total Evacuation Hrs: 0 Major Artery Closed: No Mjr Artery Hrs Closed: 0 Material Involved: No Estimated Speed: 0 Weather Conditions: Vehicle Overturn: No Vehicle Left Roadway: No Passenger Aircraft: No Cargo Baggage: Ship Non Transport: No Ship Air First Flight: No Ship Air Subflight: No Ship Init Transport: No Ship Phase Transfer: No Contact Name: GEORGE FETSKO Contact Title: HAZMAT - SAFETY ADVISOR Contact Business: Fedex Ground Package System Inc. Contact Street: 1000 Fedex Drive Contact City: CORAOPOLIS Contact State: PA Contact Postal: 15108 Contact Non US St: Contact Country: US Inc. Report Prepared: Carrier HMIS Serious Incidnt: No HMIS Serious Fatality: No HMIS Serious Injury: No HMIS Flight Plan: No HMIS Serious Evacs: No HMIS Major Artery: No HMIS Bulk Release: No HMIS Marine Pollutnt: No HMIS Radioactive: No HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt HMIS Container Code: BOX FBR HMIS Container Desc: Fiberboard box or carton HMIS Bulk Incident: No Undeclared Shipment: No		
Description of Events:				The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.		
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:		X-2017120093		Fed DOT Agency Nm:		
Report Type:		A hazardous material incident		Fed DOT Report No:		
Date of Incident:		11/08/2017		Report Submit Src:		XML
Time of Incident:		0925		Inc Multiple Rows:		No
Haz Class Code:		5.1		Inc Non US State:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazardous Class:		OXIDIZER			Mode Transport:	Highway
Commodity Short Nm:		HYDROGEN PEROXIDE AND PE			Transport Phase:	LOADING
Commodity Long Nm:		HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES STABILIZED WITH ACIDS WATER AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID			Incident Occrnce:	
Trade Name:		stabilized			Mat Ship Approval?:	No
ID No:		UN3149			Mat Ship Approv No:	
Haz Waste Ind:		No			Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.026418				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	MEDIVATORS INC.
Cont1 Pkging Type:	Box				Shipper Street Name:	14605 28TH AVE N
Cont1 Const Mat:	Fiberboard				Shipper City:	MINNEAPOLIS
Cont1 Head Type:					Shipper State:	MN
Cont1 Pkg Capacity:					Shipper Postal:	55447-4822
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	91101235447379
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	MINNEAPOLIS
Cont1 Pkg Mnfctr:					Origin State:	MINNESOTA
Cont1 Pkg Mnfc Dt:					Origin Postal:	55447
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	TUCKER
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30084
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire EMS EMS Report:						
Police Report:	No				Ship Air First Flight:	No
Police Report No:					Ship Air Subflight:	No
In House Cleanup:	Yes				Ship Init Transport:	No
Other Cleanup:	No				Ship Phase Transfer:	No
Damage > 500:	No				Contact Name:	GEORGE FETSKO
Material Loss:	0				Contact Title:	HAZMAT - SAFETY ADVISOR
Carrier Damage:	0				Contact Business:	Fedex Ground Package System Inc.
Property Damage:	0				Contact Street:	1000 Fedex Drive
Response Cost:	0				Contact City:	CORAOPOLIS
Remediation Cost:	0				Contact State:	PA
Damage Old Form:	0				Contact Postal:	15108
Total Damages Amt:	0				Contact Non US St:	
Hazmat Fatality:	No				Contact Country:	US
Haz Fatal Employees:	0				Inc. Report Prepared:	Carrier
Haz Fatal Respndrs:	0				HMIS Serious Incidnt:	No
Haz Fatal Gen Public:	0				HMIS Serious Fatality:	No
Tot Hazmat Fatalities:	0				HMIS Serious Injury:	No
Non Hazmat Fatality:	No				HMIS Flight Plan:	No
Non Hazmat Fatafs:	0				HMIS Serious Evacs:	No
Hazmat Injury:	No				HMIS Major Artery:	No
Haz Hospital Empl:	0				HMIS Bulk Release:	No
Haz Hospital Resp:	0				HMIS Marine Pollutnt:	No
Haz Hosp Gen Public:	0				HMIS Radioactive:	No
Haz Hosp Old Form:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Total Haz Hosp Inj:	0				HMIS Container Code:	BOX FBR
Haz Non Hosp Empl:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Resp:	0				HMIS Bulk Incident:	No
Description of Events:					Undeclared Shipment:	No

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2017080451	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	07/20/2017	Report Submit Src:	XML
Time of Incident:	1000	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	ETHYL ALCOHOL SOLUTIONS	Transport Phase:	UNLOADING
Commodity Long Nm:	ETHYL ALCOHOL SOLUTIONS	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1170	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	3.75	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	ALEX C. FERGUSON LLC
Cont1 Pkging Type:	Box	Shipper Street Name:	5121 COFFEY AVE STE D
Cont1 Const Mat:	Fiberboard	Shipper City:	CHAMBERSBURG
Cont1 Head Type:		Shipper State:	PA
Cont1 Pkg Capacity:		Shipper Postal:	17201-4127
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	1078449664565473472
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	CHAMBERSBURG
Cont1 Pkg Mnfctr:		Origin State:	PENNSYLVANIA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Mnfct Dt:					Origin Postal:	17201
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	NORCROSS
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30093
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						
The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.						
Recommend Actions Taken:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>HMIR Historical Reports</u>						
Report No:	X-2014090144				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	08/14/2014				Report Submit Src:	XML
Time of Incident:	1645				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	METHANOL				Transport Phase:	LOADING
Commodity Long Nm:	METHANOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1230				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	4.226880				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	304				CR Non US State:	
How Failed Desc:	Cracked				CR Fed DOT ID:	265752
Failure Cause Code:	502				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Broken Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	SIGMA-ALDRICH CORPORATION
Cont1 Pkging Type:	Box				Shipper Street Name:	6000 N TEUTONIA AVE
Cont1 Const Mat:	Fiberboard				Shipper City:	MILWAUKEE
Cont1 Head Type:					Shipper State:	WI
Cont1 Pkg Capacity:					Shipper Postal:	53209-3645
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	36553833760191
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	BROWN DEER
Cont1 Pkg Mnfctr:					Origin State:	WISCONSIN
Cont1 Pkg Mnfct Dt:					Origin Postal:	53209
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	SANDY SPRINGS
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30342
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
<u>HMIR Historical Reports</u>						
Report No:	X-2016090346				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	08/22/2016				Report Submit Src:	XML
Time of Incident:	2024				Inc Multiple Rows:	No
Haz Class Code:	5.1				Inc Non US State:	
Hazardous Class:	OXIDIZER				Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE				Transport Phase:	UNLOADING
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES STABILIZED WITH ACIDS WATER AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID				Incident Occrrnce:	
Trade Name:	stabilized				Mat Ship Approval?:	No
ID No:	UN3149				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.007812				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:					Shipper Name:	MEDIVATORS INC.
Cont1 Pkging Type:	Box				Shipper Street Name:	14605 28TH AVE N

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Const Mat:	Fiberboard			Shipper City:	MINNEAPOLIS	
Cont1 Head Type:				Shipper State:	MN	
Cont1 Pkg Capacity:	0			Shipper Postal:	55447-4822	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	91101235082389	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	MINNEAPOLIS	
Cont1 Pkg Mnfctr:				Origin State:	MINNESOTA	
Cont1 Pkg Mnfc Dt:				Origin Postal:	55447	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	ATLANTA	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30322	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2018020267				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	01/24/2018				Report Submit Src:	XML
Time of Incident:	0800				Inc Multiple Rows:	Yes
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI				Transport Phase:	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.1250				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:	4G/Y24.7/S/17/USA/M4172				Shipper Name:	ECOLAB INC.
Cont1 Pkging Type:					Shipper Street Name:	90 PIEDMONT INDUSTRIAL DR
Cont1 Const Mat:					Shipper City:	WINSTON SALEM
Cont1 Head Type:					Shipper State:	NC
Cont1 Pkg Capacity:					Shipper Postal:	27107-6876
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	7577716757771683146897
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	WINSTON SALEM
Cont1 Pkg Mnfctr:					Origin State:	NORTH CAROLINA
Cont1 Pkg Mnfc Dt:					Origin Postal:	27107
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:					Original comments: PACKAGE WAS FOUND ON DOCK WET. SO I LOOK INSIDE THE BOX. APO N OPENING THE BOX THERE WAS 4 1GAL JUGS OF MACHINE WAREWASHI NG DETERGENT IN THE BOX BUT 2 OFTHE 1GAL JUGS HAD LOOSE CAP S New Comments:	

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2012110049	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	10/04/2012	Report Submit Src:	XML
Time of Incident:	0730	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	ETHYL ALCOHOL	Transport Phase:	LOADING
Commodity Long Nm:	ETHYL ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1170	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108-9373
How Failed Code:	305	CR Non US State:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
How Failed Desc:	Crushed				CR Fed DOT ID: 265752	
Failure Cause Code:	515				CR Hazmat Reg ID: 051910551007S	
Failure Cause Desc:	Human Error				CR Country: US	
Ident. Markings:					Shipper Name: DECON LABORATORIES INC.	
Cont1 Pkging Type:	Jerrican				Shipper Street Name: 460 GLENNIE CIR	
Cont1 Const Mat:	Plastic				Shipper City: KING OF PRUSSIA	
Cont1 Head Type:					Shipper State: PA	
Cont1 Pkg Capacity:	0				Shipper Postal: 19406-2682	
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country: US	
C1 Pkg Amt UOM:					Shipper Waybill: 69577466150172	
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City: KING OF PRUSSIA	
Cont1 Pkg Mnfctr:					Origin State: PENNSYLVANIA	
Cont1 Pkg Mnfc Dt:					Origin Postal: 19406	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country: US	
C1 Test Const Mat:	Plastic				Destination City: ATLANTA	
C1 Pkg Dsign Pres.:					Destination State: GEORGIA	
C1 Dsign Press UOM:					Destination Postal: 30322	
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country: US	
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public: 0	
RAM Pkg Cert.:	FALSE				Haz NonHosp Old: 0	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj: 0	
RAM Nuclide S:					Total Hazmat Injuries: 0	
RAM Transport Index:					Evacuation Indicator: No	
RAM UOM:					Public Evacuated: 0	
RAM Activity Rpted:					Employees Evac: 0	
RAM UOM Rpted:					Total Evacuated: 0	
RAM Activity:	0				Total Evacuation Hrs: 0	
RAM Activity UOM:					Major Artery Closed: No	
RAM Mat Safety:					Mjr Artery Hrs Closed: 0	
Spillage Result:	Yes				Material Involved: No	
Fire Result:	No				Estimated Speed: 0	
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn: No	
Gas Dispersion:	No				Vehicle Left Roadway: No	
Environment Damage:	No				Passenger Aircraft: No	
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport: No	
Fire EMS EMS Report:					Ship Air First Flight: No	
Police Report:	No				Ship Air Subflight: No	
Police Report No:					Ship Init Transport: No	
In House Cleanup:	Yes				Ship Phase Transfer: No	
Other Cleanup:	No				Contact Name: GEORGE FETSKO	
Damage > 500:	No				Contact Title: SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0				Contact Business: Fedex Ground Package System Inc.	
Carrier Damage:	0				Contact Street: 1000 Fedex Drive	
Property Damage:	0				Contact City: Moon Township	
Response Cost:	0				Contact State: PA	
Remediation Cost:	0				Contact Postal: 15108	
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country: US	
Hazmat Fatality:	No				Inc. Report Prepared: Carrier	
Haz Fatal Employees:	0				HMIS Serious Incidnt: No	
Haz Fatal Respndrs:	0				HMIS Serious Fatality: No	
Haz Fatal Gen Public:	0				HMIS Serious Injury: No	
Tot Hazmat Fatalities:	0				HMIS Flight Plan: No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	CONT PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic container no capacity or description given
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2013050158	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	04/10/2013	Report Submit Src:	XML
Time of Incident:	1630	Inc Multiple Rows:	No
Haz Class Code:	5.1	Inc Non US State:	
Hazardous Class:	OXIDIZER	Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	Transport Phase:	LOADING
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES STABILIZED WITH ACIDS WATER AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN3149	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.50	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:	4G/Y26.3/S/13USA/+AA4759	Shipper Name:	MAR COR PURIFICATION INC.
Cont1 Pkging Type:		Shipper Street Name:	14550 28TH AVE N
Cont1 Const Mat:		Shipper City:	MINNEAPOLIS
Cont1 Head Type:		Shipper State:	MN
Cont1 Pkg Capacity:		Shipper Postal:	55447-4817
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	753963334393666
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	MINNEAPOLIS
Cont1 Pkg Mnfctr:		Origin State:	MINNESOTA
Cont1 Pkg Mnfct Dt:		Origin Postal:	55447
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:		Destination City:	ROSWELL
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30076
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvc Pres.:		Cont2 Pkg Capacity:	
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public: 0		
RAM Pkg Cert.: FALSE				Haz NonHosp Old: 0		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj: 0		
RAM Nuclide S:				Total Hazmat Injuries: 0		
RAM Transport Index:				Evacuation Indicator: No		
RAM UOM:				Public Evacuated: 0		
RAM Activity Rpted:				Employees Evac: 0		
RAM UOM Rpted:				Total Evacuated: 0		
RAM Activity:				Total Evacuation Hrs: 0		
RAM Activity UOM:				Major Artery Closed: No		
RAM Mat Safety:				Mjr Artery Hrs Closed: 0		
Spillage Result: Yes				Material Involved: No		
Fire Result: No				Estimated Speed: 0		
Explosion Result: No				Weather Conditions:		
Water Sewer Result: No				Vehicle Overturn: No		
Gas Dispersion: No				Vehicle Left Roadway: No		
Environment Damage: No				Passenger Aircraft: No		
No Release Result: No				Cargo Baggage:		
Fire EMS Report: No				Ship Non Transport: No		
Fire EMS EMS Report:				Ship Air First Flight: No		
Police Report: No				Ship Air Subflight: No		
Police Report No:				Ship Init Transport: No		
In House Cleanup: Yes				Ship Phase Transfer: No		
Other Cleanup: No				Contact Name: GEORGE FETSKO		
Damage > 500: No				Contact Title: SAFETY PROCESS SPECIALIST I - HAZMAT		
Material Loss: 0				Contact Business: Fedex Ground Package System Inc.		
Carrier Damage: 0				Contact Street: 1000 Fedex Drive		
Property Damage: 0				Contact City: Moon Township		
Response Cost: 0				Contact State: PA		
Remediation Cost: 0				Contact Postal: 15108		
Damage Old Form: 0				Contact Non US St:		
Total Damages Amt: 0				Contact Country: US		
Hazmat Fatality: No				Inc. Report Prepared: Carrier		
Haz Fatal Employees: 0				HMIS Serious Incidnt: No		
Haz Fatal Respndrs: 0				HMIS Serious Fatality: No		
Haz Fatal Gen Public: 0				HMIS Serious Injury: No		
Tot Hazmat Fatalities: 0				HMIS Flight Plan: No		
Non Hazmat Fatality: No				HMIS Serious Evacs: No		
Non Hazmat FataIs: 0				HMIS Major Artery: No		
Hazmat Injury: No				HMIS Bulk Release: No		
Haz Hospital Empl: 0				HMIS Marine Pollutnt: No		
Haz Hospital Resp: 0				HMIS Radioactive: No		
Haz Hosp Gen Public: 0				HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt		
Haz Hosp Old Form: 0				HMIS Container Code: 4G		
Total Haz Hosp Inj: 0				HMIS Container Desc: Fiberboard box		
Haz Non Hosp Empl: 0				HMIS Bulk Incident: No		
Haz Non Hosp Resp: 0				Undeclared Shipment: No		
Description of Events:				The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.		
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:		X-2014020161		Fed DOT Agency Nm:		
Report Type:		A hazardous material incident		Fed DOT Report No:		
Date of Incident:		01/24/2014		Report Submit Src: XML		
Time of Incident:		1625		Inc Multiple Rows: No		
Haz Class Code:		3		Inc Non US State:		
Hazardous Class:		FLAMMABLE - COMBUSTIBLE LIQUID		Mode Transport: Highway		
Commodity Short Nm:		COMPOUNDS CLEANING LIQU		Transport Phase: LOADING		
Commodity Long Nm:		COMPOUNDS CLEANING LIQUID		Incident Occrrnce:		
Trade Name:		acetone		Mat Ship Approval?: No		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
ID No:	NA1993				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.1250				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	309				CR Non US State:	
How Failed Desc:	Punctured				CR Fed DOT ID:	265752
Failure Cause Code:	516				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g. nails)				CR Country:	US
Ident. Markings:					Shipper Name:	GEORGIA GRAPHICS INC
Cont1 Pkging Type:	Drum				Shipper Street Name:	7055 AMWILER INDSTR L E
Cont1 Const Mat:	Aluminum				Shipper City:	ATLANTA
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30360-2833
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	30738232506229
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	DORAVILLE
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfctr Dt:					Origin Postal:	30360
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Aluminum				Destination City:	CONYERS
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30013
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM MTL
Total Haz Hosp Inj:	0				HMIS Container Desc:	Metal drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2018010282	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	12/29/2017	Report Submit Src:	XML
Time of Incident:	1934	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS N.O.S.	Transport Phase:	LOADING
Commodity Long Nm:	FLAMMABLE LIQUIDS N.O.S.	Incident Occrrnce:	
Trade Name:	(Methyl Alcohol Nitr	Mat Ship Approval?:	No
ID No:	UN1993	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.0625	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	110	CR State:	PA
What Failed Desc:	Cover	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:	4G/Y24/S/17 USA/+CO1300	Shipper Name:	SIG MANUFACTURING CO. INC.
Cont1 Pkging Type:		Shipper Street Name:	401 S FRONT ST 7
Cont1 Const Mat:		Shipper City:	MONTEZUMA
Cont1 Head Type:		Shipper State:	IA
Cont1 Pkg Capacity:		Shipper Postal:	50171-7702
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	525081725018479076
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	MONTEZUMA
Cont1 Pkg Mnfctr:		Origin State:	IOWA
Cont1 Pkg Mnfct Dt:		Origin Postal:	50171
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:		Destination City:	SNELLVILLE
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30078
C1 Pkg Shell Thick:		Destination Non US:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Shell Thick UOM: C1 Head Thickness: C1 Head Thick UOM: C1 Pkg Srvc Pres.: C1 Srvc Press UOM: C1 Valve/Device Fail?: No C1 Device Type: C1 Device Mnfctr: C1 Device Model: NRC No:				Destination Country: US Cont2 Package Type: Cont2 Const Mat: Cont2 Pkg Capacity: Cont2 Capacity UOM: Cont2 Pkg Amount: Cont2 Pkg Amt UOM: Cont2 Pkg No: Cont2 Pkg No Failed:		
RAM Pkg Category: RAM Pkg Cert.: FALSE RAM Pkg Cert. NBR: RAM Nuclide S: RAM Transport Index: RAM UOM: RAM Activity Rpted: RAM UOM Rpted: RAM Activity: RAM Activity UOM: RAM Mat Safety: Spillage Result: Yes Fire Result: No Explosion Result: No Water Sewer Result: No Gas Dispersion: No Environment Damage: No No Release Result: No Fire EMS Report: No Fire EMS EMS Report: Police Report: No Police Report No: In House Cleanup: Yes Other Cleanup: No Damage > 500: No Material Loss: 0 Carrier Damage: 0 Property Damage: 0 Response Cost: 0 Remediation Cost: 0 Damage Old Form: 0 Total Damages Amt: 0 Hazmat Fatality: No Haz Fatal Employees: 0 Haz Fatal Respndrs: 0 Haz Fatal Gen Public: 0 Tot Hazmat Fatalities: 0 Non Hazmat Fatality: No Non Hazmat Fatafs: 0 Hazmat Injury: No Haz Hospital Empl: 0 Haz Hospital Resp: 0 Haz Hosp Gen Public: 0 Haz Hosp Old Form: 0 Total Haz Hosp Inj: 0 Haz Non Hosp Empl: 0 Haz Non Hosp Resp: 0				Haz NonHosp Public: 0 Haz NonHosp Old: 0 Tot Haz Non Hosp Inj: 0 Total Hazmat Injuries: 0 Evacuation Indicator: No Public Evacuated: 0 Employees Evac: 0 Total Evacuated: 0 Total Evacuation Hrs: 0 Major Artery Closed: No Mjr Artery Hrs Closed: 0 Material Involved: No Estimated Speed: 0 Weather Conditions: Vehicle Overturn: No Vehicle Left Roadway: No Passenger Aircraft: No Cargo Baggage: Ship Non Transport: No Ship Air First Flight: No Ship Air Subflight: No Ship Init Transport: No Ship Phase Transfer: No Contact Name: GEORGE FETSKO Contact Title: HAZMAT - SAFETY ADVISOR Contact Business: Fedex Ground Package System Inc. Contact Street: 1000 Fedex Drive Contact City: CORAOPOLIS Contact State: PA Contact Postal: 15108 Contact Non US St: Contact Country: US Inc. Report Prepared: Carrier HMIS Serious Incidnt: No HMIS Serious Fatality: No HMIS Serious Injury: No HMIS Flight Plan: No HMIS Serious Evacs: No HMIS Major Artery: No HMIS Bulk Release: No HMIS Marine Pollutnt: No HMIS Radioactive: No HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt HMIS Container Code: 4G HMIS Container Desc: Fiberboard box HMIS Bulk Incident: No Undeclared Shipment: No		
Description of Events:				The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.		
Recommend Actions Taken:						
HMIR Historical Reports						
Report No: X-2013100392 Report Type: A hazardous material incident Date of Incident: 09/30/2013				Fed DOT Agency Nm: Fed DOT Report No: Report Submit Src: XML		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Time of Incident:	1646			Inc Multiple Rows:	No	
Haz Class Code:	3			Inc Non US State:		
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID			Mode Transport:	Highway	
Commodity Short Nm:	PETROLEUM DISTILLATES N			Transport Phase:	LOADING	
Commodity Long Nm:	PETROLEUM DISTILLATES N.O.S. OR PETROLEUM PRODUCTS N.O.S.			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1268			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:	0.25			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g. Cap Top or Plug)			CR Postal Code:	15108-9373	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	N/A	
Cont1 Pkgng Type:	Box			Shipper Street Name:	ILLEGIBLE	
Cont1 Const Mat:	Fiberboard			Shipper City:	NORCROSS	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:				Shipper Postal:	30071	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	111111111111111	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	NORCROSS	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfc Dt:				Origin Postal:	30071	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	NORCROSS	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30071	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2018050789				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	05/02/2018				Report Submit Src:	XML
Time of Incident:	2301				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	GASOLINE INCLUDES GASOLI				Transport Phase:	UNLOADING
Commodity Long Nm:	GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL WITH NOT MORE THAN 10% ALCOHOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1203				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.0625				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:	4G/Y28/S/15USA/+BR9196				Shipper Name:	INDIVIDUAL NOT A COMPANY
Cont1 Pkging Type:	Box				Shipper Street Name:	4127 WINTERS CHAPEL RD
Cont1 Const Mat:	Fiberboard				Shipper City:	ATLANTA
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30360
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	4275417734283189062
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	ATLANTA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfct Dt:				Origin Postal:	30360	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	TIFTON	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	31794	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:			Original comments: WHEN I GOT THE PACKAGE THE BOX WAS WET. SO I OPENED THE PACK AGE AND SO THAT TWO CONTAINERS OF GASOLINE WAS LEAKING. New Comments:			
Recommend Actions Taken:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>HMIR Historical Reports</u>						
Report No:	X-2012100028				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	09/06/2012				Report Submit Src:	XML
Time of Incident:	2100				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	PENTANES				Transport Phase:	UNLOADING
Commodity Long Nm:	PENTANES				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1265				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.264180				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	304				CR Non US State:	
How Failed Desc:	Cracked				CR Fed DOT ID:	265752
Failure Cause Code:	502				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Broken Component or Device				CR Country:	US
Ident. Markings:	4G/X10.9/S/12/USA/M4109				Shipper Name:	SIGMA-ALDRICH CORPORATION
Cont1 Pkging Type:					Shipper Street Name:	6000 N TEUTONIA AVE
Cont1 Const Mat:					Shipper City:	MILWAUKEE
Cont1 Head Type:					Shipper State:	WI
Cont1 Pkg Capacity:					Shipper Postal:	53209-3645
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	36553821007246
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	BROWN DEER
Cont1 Pkg Mnfctr:					Origin State:	WISCONSIN
Cont1 Pkg Mnfct Dt:					Origin Postal:	53209
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
<u>HMIR Historical Reports</u>						
Report No:	X-2012100414			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	10/02/2012			Report Submit Src:	XML	
Time of Incident:	0600			Inc Multiple Rows:	No	
Haz Class Code:	8			Inc Non US State:		
Hazardous Class:	CORROSIVE MATERIAL			Mode Transport:	Highway	
Commodity Short Nm:	CORROSIVE LIQUID ACIDIC			Transport Phase:	UNLOADING	
Commodity Long Nm:	CORROSIVE LIQUID ACIDIC ORGANIC N.O. S.			Incident Occrrnce:		
Trade Name:	Isothiazolinone Micr			Mat Ship Approval?:	No	
ID No:	UN3265			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:	0.25			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	104			CR State:	PA	
What Failed Desc:	Body			CR Postal Code:	15108-9373	
How Failed Code:	309			CR Non US State:		
How Failed Desc:	Punctured			CR Fed DOT ID:	265752	
Failure Cause Code:	511			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Dropped			CR Country:	US	
Ident. Markings:				Shipper Name:	NALCO COMPANY LLC	
Cont1 Pkging Type:	Drum			Shipper Street Name:	125 NALCO WAY	
Cont1 Const Mat:	Plastic			Shipper City:	ELLWOOD CITY	
Cont1 Head Type:				Shipper State:	PA	
Cont1 Pkg Capacity:	0			Shipper Postal:	16117-4129	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	44537038098609
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	ELLPORT
Cont1 Pkg Mnfctr:					Origin State:	PENNSYLVANIA
Cont1 Pkg Mnfcct Dt:					Origin Postal:	16117
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30309
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic drum

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2013040185				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	03/22/2013				Report Submit Src:	XML
Time of Incident:	1730				Inc Multiple Rows:	No
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC				Transport Phase:	LOADING
Commodity Long Nm:	CORROSIVE LIQUID BASIC INORGANIC N. O.S.				Incident Occrrnce:	
Trade Name:	contains Phosphates				Mat Ship Approval?:	No
ID No:	UN3266				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	2				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	A.B.C. COMPOUNDING COMPANY INC.
Cont1 Pkging Type:	Box				Shipper Street Name:	2600 DOGWOOD DR SE
Cont1 Const Mat:	Fiberboard				Shipper City:	CONYERS
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30013-1503
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	31858262231010
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	LAKE CITY
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:					Origin Postal:	30260
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	SUWANEE
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30024
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:					The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.	

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014050177	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	04/15/2014	Report Submit Src:	XML
Time of Incident:	1623	Inc Multiple Rows:	No
Haz Class Code:	5.2	Inc Non US State:	
Hazardous Class:	ORGANIC PEROXIDE	Mode Transport:	Highway
Commodity Short Nm:	ORGANIC PEROXIDE TYPE F	Transport Phase:	UNLOADING
Commodity Long Nm:	ORGANIC PEROXIDE TYPE F LIQUID	Incident Occrrnce:	
Trade Name:	(Persisept)	Mat Ship Approval?:	No
ID No:	UN3109	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.0125	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Failure Cause Desc:		Loose Closure Component or Device		CR Country:	US	
Ident. Markings:		4G/Y5.7/S/14/USA/+BR9244		Shipper Name:	TRIPLE S/OHL	
Cont1 Pkging Type:				Shipper Street Name:	900 KRINER ROAD	
Cont1 Const Mat:				Shipper City:	CHAMBERSBURG	
Cont1 Head Type:				Shipper State:	PA	
Cont1 Pkg Capacity:				Shipper Postal:	17202	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	530702383345	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	CHAMBERSBURG	
Cont1 Pkg Mnfctr:				Origin State:	PENNSYLVANIA	
Cont1 Pkg Mnfc Dt:				Origin Postal:	17202	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:				Destination City:	ROSWELL	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30076	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatafs:	0			HMIS Major Artery:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2014110030				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	10/01/2014				Report Submit Src:	XML
Time of Incident:	1730				Inc Multiple Rows:	No
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	POTASSIUM HYDROXIDE SOL				Transport Phase:	LOADING
Commodity Long Nm:	POTASSIUM HYDROXIDE SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1814				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	5.000927				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	309				CR Non US State:	
How Failed Desc:	Punctured				CR Fed DOT ID:	265752
Failure Cause Code:	516				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g. nails)				CR Country:	US
Ident. Markings:					Shipper Name:	STERIS CORPORATION
Cont1 Pkging Type:	Drum				Shipper Street Name:	8525 PAGE AVE
Cont1 Const Mat:	Plastic				Shipper City:	SAINT LOUIS
Cont1 Head Type:					Shipper State:	MO
Cont1 Pkg Capacity:	0				Shipper Postal:	63114-6014
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	63106975098390
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	BRECKENRIDGE HILLS
Cont1 Pkg Mnfctr:					Origin State:	MISSOURI
Cont1 Pkg MnfcDt:					Origin Postal:	63114
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2018040290	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	03/21/2018	Report Submit Src:	XML
Time of Incident:	2200	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC	Transport Phase:	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUID BASIC INORGANIC N. O.S.	Incident Occrrnce:	
Trade Name:	CONTAINS SODIUM MET	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Qty Released:	0.0625				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	A.B.C. COMPOUNDING COMPANY INC.
Cont1 Pkging Type:	Drum				Shipper Street Name:	2600 DOGWOOD DR SE
Cont1 Const Mat:	Metal other than steel or aluminum				Shipper City:	CONYERS
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30013-1503
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	318582412826165842
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	CONYERS
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:					Origin Postal:	30013
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Metal other than steel or aluminum				Destination City:	SUWANEE
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30024
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	CONT
Total Haz Hosp Inj:	0				HMIS Container Desc:	Container no description given (do not use if at all possible)
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: ONE BOTTLE HAD A LOOSE CAP New Comments:					
Recommend Actions Taken:						

HMIR Historical Reports

Report No:	X-2018080306	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	07/05/2018	Report Submit Src:	XML
Time of Incident:	2200	Inc Multiple Rows:	No
Haz Class Code:	5.1	Inc Non US State:	
Hazardous Class:	OXIDIZER	Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	Transport Phase:	UNLOADING
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES STABILIZED WITH ACIDS WATER AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN3149	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.1250	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:	4G/Y14.8/S/18 USA/+AA5566	Shipper Name:	MEDIVATORS INC.
Cont1 Pkging Type:	Box	Shipper Street Name:	14605 28TH AVE N
Cont1 Const Mat:	Fiberboard	Shipper City:	MINNEAPOLIS
Cont1 Head Type:		Shipper State:	MN
Cont1 Pkg Capacity:		Shipper Postal:	55447-4822
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	911012437364387935
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	MINNEAPOLIS
Cont1 Pkg Mnfctr:		Origin State:	MINNESOTA
Cont1 Pkg Mnfc Dt:		Origin Postal:	55447
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Fiberboard	Destination City:	TUCKER
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30084
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						
						Original comments: Box was found on dock wet. As I looked inside there was 2 inner packages both boxes had 2 bottles of Rapiocide PA inside of it. 1 box had no damage the 2nd box had 2 damage bottles with loose caps New Comments:
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2017120081				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	11/07/2017				Report Submit Src:	XML
Time of Incident:	2330				Inc Multiple Rows:	No
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Commodity Short Nm:	BATTERY FLUID ACID				Transport Phase:	UNLOADING
Commodity Long Nm:	BATTERY FLUID ACID				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN2796				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.25				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	CAROLINA HANDLING LLC
Cont1 Pkgng Type:	Jerrican				Shipper Street Name:	1955 MONTREAL RD
Cont1 Const Mat:	Plastic				Shipper City:	TUCKER
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30084-5218
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	148805889030131148738
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	TUCKER
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:					Origin Postal:	30084
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	DINSMORE
C1 Pkg Dsign Pres.:					Destination State:	FLORIDA
C1 Dsign Press UOM:					Destination Postal:	32219
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srv Pres.:					Cont2 Pkg Capacity:	
C1 Srv Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	PAIL PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic pail open head capacity 10 gallons or less
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2016110579				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	10/26/2016				Report Submit Src:	XML
Time of Incident:	2042				Inc Multiple Rows:	No
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID ACIDIC				Transport Phase:	IN TRANSIT
Commodity Long Nm:	CORROSIVE LIQUID ACIDIC INORGANIC N. O.S.				Incident Occrrnce:	
Trade Name:	(Phosporic & Hydroch				Mat Ship Approval?:	No
ID No:	UN3264				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.007812				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	SWISHER HYGIENE
Cont1 Pkging Type:	Box				Shipper Street Name:	516 MONCEAUX RD
Cont1 Const Mat:	Fiberboard				Shipper City:	LAWRENCEVILLE
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30046
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	73610265470058758
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	LAWRENCEVILLE
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:					Origin Postal:	30046
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Test Const Mat:	Fiberboard				Destination City:	LAWRENCEVILLE
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30046
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report No:	X-2015030283				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	02/26/2015				Report Submit Src:	XML
Time of Incident:	1000				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	COMPOUNDS CLEANING LIQU				Transport Phase:	UNLOADING
Commodity Long Nm:	COMPOUNDS CLEANING LIQUID				Incident Occrrnce:	
Trade Name:	ACETONEHEPTANE				Mat Ship Approval?:	No
ID No:	NA1993				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.50				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	GEORGIA GRAPHICS INC
Cont1 Pkging Type:	Box				Shipper Street Name:	7055 AMWILER INDSTRL E
Cont1 Const Mat:	Fiberboard				Shipper City:	ATLANTA
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30360-2833
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	30738232550734
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	DORAVILLE
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:					Origin Postal:	30360
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	DECATUR
C1 Pkg Dsign Pres.:					Destination State:	ALABAMA
C1 Dsign Press UOM:					Destination Postal:	35601
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014090142	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	08/08/2014	Report Submit Src:	XML
Time of Incident:	1700	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE SOLID BASIC	Transport Phase:	LOADING
Commodity Long Nm:	CORROSIVE SOLID BASIC INORGANIC N.O. S.	Incident Occrrnce:	
Trade Name:	sodium hydroxide	Mat Ship Approval?:	No
ID No:	UN3262	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	14	CR Street Name:	1000 FED EX DR
Unit of Measure:	Solid - Pound	CR City:	CORAOPOLIS
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108-9373
How Failed Code:	309	CR Non US State:	
How Failed Desc:	Punctured	CR Fed DOT ID:	265752
Failure Cause Code:	516	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g. nails)	CR Country:	US
Ident. Markings:		Shipper Name:	CEVA LOGISTICS
Cont1 Pkging Type:	Box	Shipper Street Name:	125 SOUTHSIDE CT
Cont1 Const Mat:	Fiberboard	Shipper City:	MCDONOUGH
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:		Shipper Postal:	30253-7448
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Amt UOM:					Shipper Waybill:	916079075091895
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	MCDONOUGH
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:					Origin Postal:	30253
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	LAWRENCEVILLE
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30044
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Description of Events:		The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2018070591			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	06/26/2018			Report Submit Src:	XML	
Time of Incident:	2100			Inc Multiple Rows:	No	
Haz Class Code:	3			Inc Non US State:		
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID			Mode Transport:	Highway	
Commodity Short Nm:	METHANOL			Transport Phase:	UNLOADING	
Commodity Long Nm:	METHANOL			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1230			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:	0.1250			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g. Cap Top or Plug)			CR Postal Code:	15108-9373	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:	4G/Y6.4/S/17 USA/aa4303			Shipper Name:	FISHER SCIENTIFIC COMPANY L.L.C.	
Cont1 Pkgng Type:				Shipper Street Name:	3970 JOHNS CREEK CT # 500	
Cont1 Const Mat:				Shipper City:	SUWANEE	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:				Shipper Postal:	30024-1297	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	39064596123020390645736071	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	SUWANEE	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfct Dt:				Origin Postal:	30024	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:				Destination City:	JACKSON	
C1 Pkg Dsign Pres.:				Destination State:	MISSISSIPPI	
C1 Dsign Press UOM:				Destination Postal:	39216	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: BOX WAS FOUND ON FLOOR WET. AS I LOOKED INSIDE THERE WAS 1 B OTTLE METHANOL WITH A LOOSE CAP New Comments:					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2013010242	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	01/02/2013	Report Submit Src:	XML
Time of Incident:	1630	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	ALCOHOLS N.O.S.	Transport Phase:	LOADING
Commodity Long Nm:	ALCOHOLS N.O.S.	Incident Occrrnce:	
Trade Name:	Ethanol/Methanol	Mat Ship Approval?:	No
ID No:	UN1987	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.264180	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108-9373
How Failed Code:	305	CR Non US State:	
How Failed Desc:	Crushed	CR Fed DOT ID:	265752
Failure Cause Code:	515	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Human Error	CR Country:	US
Ident. Markings:		Shipper Name:	LEICA BIOSYSTEMS RICHMOND INC.
Cont1 Pkging Type:	Box	Shipper Street Name:	5205 RTE 12
Cont1 Const Mat:	Fiberboard	Shipper City:	RICHMOND

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Head Type:					Shipper State:	IL
Cont1 Pkg Capacity:	0				Shipper Postal:	60071
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	60226515879166
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	RICHMOND
Cont1 Pkg Mnfctr:					Origin State:	ILLINOIS
Cont1 Pkg Mnfc Dt:					Origin Postal:	60071
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ALPHARETTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30005
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2017120249				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	11/15/2017				Report Submit Src:	XML
Time of Incident:	0830				Inc Multiple Rows:	No
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI				Transport Phase:	IN TRANSIT
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.20				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	ECOLAB INC.
Cont1 Pkging Type:	Box				Shipper Street Name:	90 PIEDMONT INDUSTRIAL DR
Cont1 Const Mat:	Fiberboard				Shipper City:	WINSTON SALEM
Cont1 Head Type:					Shipper State:	NC
Cont1 Pkg Capacity:					Shipper Postal:	27107-6876
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	7577716757771683020470
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	WINSTON SALEM
Cont1 Pkg Mnfctr:					Origin State:	NORTH CAROLINA
Cont1 Pkg Mnfct Dt:					Origin Postal:	27107
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:				Material Involved:	No	
Fire Result:				Estimated Speed:	0	
Explosion Result:				Weather Conditions:		
Water Sewer Result:				Vehicle Overturn:	No	
Gas Dispersion:				Vehicle Left Roadway:	No	
Environment Damage:				Passenger Aircraft:	No	
No Release Result:				Cargo Baggage:		
Fire EMS Report:				Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:				Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:				Ship Phase Transfer:	No	
Other Cleanup:				Contact Name:	GEORGE FETSKO	
Damage > 500:				Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:				Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:				Contact Street:	1000 Fedex Drive	
Property Damage:				Contact City:	CORAOPOLIS	
Response Cost:				Contact State:	PA	
Remediation Cost:				Contact Postal:	15108	
Damage Old Form:				Contact Non US St:		
Total Damages Amt:				Contact Country:	US	
Hazmat Fatality:				Inc. Report Prepared:	Carrier	
Haz Fatal Employees:				HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:				HMIS Serious Fatality:	No	
Haz Fatal Gen Public:				HMIS Serious Injury:	No	
Tot Hazmat Fatalities:				HMIS Flight Plan:	No	
Non Hazmat Fatality:				HMIS Serious Evacs:	No	
Non Hazmat Fatals:				HMIS Major Artery:	No	
Hazmat Injury:				HMIS Bulk Release:	No	
Haz Hospital Empl:				HMIS Marine Pollutnt:	No	
Haz Hospital Resp:				HMIS Radioactive:	No	
Haz Hosp Gen Public:				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:				HMIS Container Code:	BOX FBR	
Total Haz Hosp Inj:				HMIS Container Desc:	Fiberboard box or carton	
Haz Non Hosp Empl:				HMIS Bulk Incident:	No	
Haz Non Hosp Resp:				Undeclared Shipment:	No	
Description of Events:				The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.		
Recommend Actions Taken:						
<u>HMIR Historical Reports</u>						
Report No:	X-2014100088			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	09/08/2014			Report Submit Src:	XML	
Time of Incident:	2200			Inc Multiple Rows:	No	
Haz Class Code:	3			Inc Non US State:		
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID			Mode Transport:	Highway	
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL			Transport Phase:	IN TRANSIT	
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1219			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:	1			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	104			CR State:	PA	
What Failed Desc:	Body			CR Postal Code:	15108-9373	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:	4G/Y5.2/S/16/USA/+ AI4406			Shipper Name:	MCKESSON HBOC COMPANY	
Cont1 Pkging Type:				Shipper Street Name:	2975 Evergreen Boulevard	
Cont1 Const Mat:				Shipper City:	BERKELEY	
Cont1 Head Type:				Shipper State:	MO	
Cont1 Pkg Capacity:				Shipper Postal:	63134	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	30816977808942	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	BERKELEY LAKE	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfc Dt:				Origin Postal:	30096	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:				Destination City:	MILWAUKEE	
C1 Pkg Dsign Pres.:				Destination State:	WISCONSIN	
C1 Dsign Press UOM:				Destination Postal:	53205	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respntrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non Hazmat Fatal:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2018020267				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	01/24/2018				Report Submit Src:	XML
Time of Incident:	0800				Inc Multiple Rows:	Yes
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI				Transport Phase:	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.1250				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:	4G/Y24.7/S/17/USA/M4172				Shipper Name:	ECOLAB INC.
Cont1 Pkging Type:					Shipper Street Name:	90 PIEDMONT INDUSTRIAL DR
Cont1 Const Mat:					Shipper City:	WINSTON SALEM
Cont1 Head Type:					Shipper State:	NC
Cont1 Pkg Capacity:					Shipper Postal:	27107-6876
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	7577716757771683146880
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	WINSTON SALEM
Cont1 Pkg Mnfctr:					Origin State:	NORTH CAROLINA
Cont1 Pkg Mnfct Dt:					Origin Postal:	27107
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: PACKAGE WAS FOUND ON DOCK WET. SO I LOOK INSIDE THE BOX. APO N OPENING THE BOX THERE WAS 4 1GAL JUGS OF MACHINE WAREWASHI NG DETERGENT IN THE BOX BUT 2 OFTHE 1GAL JUGS HAD LOOSE CAP S New Comments:					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2017090510	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	08/21/2017	Report Submit Src:	XML
Time of Incident:	1018	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI	Transport Phase:	IN TRANSIT
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1824	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	5	CR Street Name:	1000 FED EX DR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g. Cap Top or Plug)			CR Postal Code:	15108-9373	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	ECOLAB INC.	
Cont1 Pkging Type:	Drum			Shipper Street Name:	125 SOUTHSIDE CT STE 100	
Cont1 Const Mat:	Plastic			Shipper City:	MCDONOUGH	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:	0			Shipper Postal:	30253-7448	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	916079073204099	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	MCDONOUGH	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfc Dt:				Origin Postal:	30253	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Plastic			Destination City:	ATLANTA	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30319	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014060047	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	05/06/2014	Report Submit Src:	XML
Time of Incident:	1705	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	ACETONITRILE	Transport Phase:	LOADING
Commodity Long Nm:	ACETONITRILE	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1648	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.264180	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	128	CR State:	PA
What Failed Desc:	Inner Packaging	CR Postal Code:	15108-9373
How Failed Code:	304	CR Non US State:	
How Failed Desc:	Cracked	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:		Shipper Name:	ALDRICH CHEMICAL CO. LLC
Cont1 Pkging Type:	Box	Shipper Street Name:	6000 N TEUTONIA AVE
Cont1 Const Mat:	Fiberboard	Shipper City:	MILWAUKEE
Cont1 Head Type:		Shipper State:	WI
Cont1 Pkg Capacity:	0	Shipper Postal:	53209-3645
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	36553831709185
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	BROWN DEER
Cont1 Pkg Mnfctr:		Origin State:	WISCONSIN
Cont1 Pkg Mnfc Dt:		Origin Postal:	53209
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Fiberboard	Destination City:	CHAMBLEE
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30341
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	Bottle
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvc Pres.:		Cont2 Pkg Capacity:	
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	
C1 Device Type:		Cont2 Pkg Amt UOM:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Device Mnfctr: C1 Device Model: NRC No:				Cont2 Pkg No: Cont2 Pkg No Failed:		
RAM Pkg Category:				Haz NonHosp Public: 0		
RAM Pkg Cert.: FALSE				Haz NonHosp Old: 0		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj: 0		
RAM Nuclide S:				Total Hazmat Injuries: 0		
RAM Transport Index:				Evacuation Indicator: No		
RAM UOM:				Public Evacuated: 0		
RAM Activity Rpted:				Employees Evac: 0		
RAM UOM Rpted:				Total Evacuated: 0		
RAM Activity: 0				Total Evacuation Hrs: 0		
RAM Activity UOM:				Major Artery Closed: No		
RAM Mat Safety:				Mjr Artery Hrs Closed: 0		
Spillage Result: Yes				Material Involved: No		
Fire Result: No				Estimated Speed: 0		
Explosion Result: No				Weather Conditions:		
Water Sewer Result: No				Vehicle Overturn: No		
Gas Dispersion: No				Vehicle Left Roadway: No		
Environment Damage: No				Passenger Aircraft: No		
No Release Result: No				Cargo Baggage:		
Fire EMS Report: No				Ship Non Transport: No		
Fire EMS EMS Report:				Ship Air First Flight: No		
Police Report: No				Ship Air Subflight: No		
Police Report No:				Ship Init Transport: No		
In House Cleanup: Yes				Ship Phase Transfer: No		
Other Cleanup: No				Contact Name: GEORGE FETSKO		
Damage > 500: No				Contact Title: HAZMAT - SAFETY ADVISOR		
Material Loss: 0				Contact Business: Fedex Ground Package System Inc.		
Carrier Damage: 0				Contact Street: 1000 Fedex Drive		
Property Damage: 0				Contact City: CORAOPOLIS		
Response Cost: 0				Contact State: PA		
Remediation Cost: 0				Contact Postal: 15108		
Damage Old Form: 0				Contact Non US St:		
Total Damages Amt: 0				Contact Country: US		
Hazmat Fatality: No				Inc. Report Prepared: Carrier		
Haz Fatal Employees: 0				HMIS Serious Incidnt: No		
Haz Fatal Respndrs: 0				HMIS Serious Fatality: No		
Haz Fatal Gen Public: 0				HMIS Serious Injury: No		
Tot Hazmat Fatalities: 0				HMIS Flight Plan: No		
Non Hazmat Fatality: No				HMIS Serious Evacs: No		
Non Hazmat Fatals: 0				HMIS Major Artery: No		
Hazmat Injury: No				HMIS Bulk Release: No		
Haz Hospital Empl: 0				HMIS Marine Pollutnt: No		
Haz Hospital Resp: 0				HMIS Radioactive: No		
Haz Hosp Gen Public: 0				HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt		
Haz Hosp Old Form: 0				HMIS Container Code: BOX FBR		
Total Haz Hosp Inj: 0				HMIS Container Desc: Fiberboard box or carton		
Haz Non Hosp Empl: 0				HMIS Bulk Incident: No		
Haz Non Hosp Resp: 0				Undeclared Shipment: No		
Description of Events:				The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.		
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:		X-2013060051		Fed DOT Agency Nm:		
Report Type:		A hazardous material incident		Fed DOT Report No:		
Date of Incident:		05/08/2013		Report Submit Src:		XML
Time of Incident:		1705		Inc Multiple Rows:		No
Haz Class Code:		3		Inc Non US State:		
Hazardous Class:		FLAMMABLE - COMBUSTIBLE LIQUID		Mode Transport:		Highway
Commodity Short Nm:		ETHYL ALCOHOL		Transport Phase:		LOADING
Commodity Long Nm:		ETHYL ALCOHOL		Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:		No
ID No:		UN1170		Mat Ship Approv No:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Waste Ind:	No				Undecl Hazmat Ship?: No	
Haz Waste EPA No:					Packaging Type: Non-Bulk	
HMIS Tox Inhalation?:	No				Packing Group: II	
TIH Hazard Zone:					Carrier Reporter: FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:	1				CR Street Name: 1000 FED EX DR	
Unit of Measure:	Liquid - Gallon				CR City: CORAOPOLIS	
What Failed:	109				CR State: PA	
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code: 15108-9373	
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID: 265752	
Failure Cause Code:	526				CR Hazmat Reg ID: 051910551007S	
Failure Cause Desc:	Loose Closure Component or Device				CR Country: US	
Ident. Markings:	4G/Y28/S/13USA/M4899				Shipper Name: DECON LABORATORIES INC.	
Cont1 Pkgg Type:					Shipper Street Name: 460 GLENNIE CIR	
Cont1 Const Mat:					Shipper City: KING OF PRUSSIA	
Cont1 Head Type:					Shipper State: PA	
Cont1 Pkg Capacity:					Shipper Postal: 19406-2682	
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country: US	
C1 Pkg Amt UOM:					Shipper Waybill: 69577450056015	
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City: KING OF PRUSSIA	
Cont1 Pkg Mnfctr:					Origin State: PENNSYLVANIA	
Cont1 Pkg Mnfct Dt:					Origin Postal: 19406	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country: US	
C1 Test Const Mat:					Destination City: ATLANTA	
C1 Pkg Dsign Pres.:					Destination State: GEORGIA	
C1 Dsign Press UOM:					Destination Postal: 30329	
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country: US	
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name: GEORGE FETSKO	
Damage > 500:	No				Contact Title: SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0				Contact Business: Fedex Ground Package System Inc.	
Carrier Damage:	0				Contact Street: 1000 Fedex Drive	
Property Damage:	0				Contact City: Moon Township	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2017090186	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	08/16/2017	Report Submit Src:	XML
Time of Incident:	1500	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	GASOLINE INCLUDES GASOLI	Transport Phase:	UNLOADING
Commodity Long Nm:	GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL WITH NOT MORE THAN 10% ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1203	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.264180	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	MOTIVA ENTERPRISES LLC
Cont1 Pkging Type:	Box	Shipper Street Name:	4201 WINTERS CHAPEL RD
Cont1 Const Mat:	Fiberboard	Shipper City:	ATLANTA
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30360-3150
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	4275417998030122906948
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	DORAVILLE
Cont1 Pkg Mnfctr:		Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:		Origin Postal:	30360
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Fiberboard	Destination City:	TIFTON
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	31794
C1 Pkg Shell Thick:		Destination Non US:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Shell Thick UOM: C1 Head Thickness: C1 Head Thick UOM: C1 Pkg Srvc Pres.: C1 Srvc Press UOM: C1 Valve/Device Fail?: No C1 Device Type: C1 Device Mnfctr: C1 Device Model: NRC No:				Destination Country: US Cont2 Package Type: Can Cont2 Const Mat: Metal (any type) Cont2 Pkg Capacity: Cont2 Capacity UOM: Cont2 Pkg Amount: Cont2 Pkg Amt UOM: Cont2 Pkg No: Cont2 Pkg No Failed:		
RAM Pkg Category: RAM Pkg Cert.: FALSE RAM Pkg Cert. NBR: RAM Nuclide S: RAM Transport Index: RAM UOM: RAM Activity Rpted: RAM UOM Rpted: RAM Activity: 0 RAM Activity UOM: RAM Mat Safety: Spillage Result: Yes Fire Result: No Explosion Result: No Water Sewer Result: No Gas Dispersion: No Environment Damage: No No Release Result: No Fire EMS Report: No Fire EMS EMS Report: Police Report: No Police Report No: In House Cleanup: Yes Other Cleanup: No Damage > 500: No Material Loss: 0 Carrier Damage: 0 Property Damage: 0 Response Cost: 0 Remediation Cost: 0 Damage Old Form: 0 Total Damages Amt: 0 Hazmat Fatality: No Haz Fatal Employees: 0 Haz Fatal Respndrs: 0 Haz Fatal Gen Public: 0 Tot Hazmat Fatalities: 0 Non Hazmat Fatality: No Non Hazmat Fatafs: 0 Hazmat Injury: No Haz Hospital Empl: 0 Haz Hospital Resp: 0 Haz Hosp Gen Public: 0 Haz Hosp Old Form: 0 Total Haz Hosp Inj: 0 Haz Non Hosp Empl: 0 Haz Non Hosp Resp: 0 Description of Events:				Haz NonHosp Public: 0 Haz NonHosp Old: 0 Tot Haz Non Hosp Inj: 0 Total Hazmat Injuries: 0 Evacuation Indicator: No Public Evacuated: 0 Employees Evac: 0 Total Evacuated: 0 Total Evacuation Hrs: 0 Major Artery Closed: No Mjr Artery Hrs Closed: 0 Material Involved: No Estimated Speed: 0 Weather Conditions: Vehicle Overturn: No Vehicle Left Roadway: No Passenger Aircraft: No Cargo Baggage: Ship Non Transport: No Ship Air First Flight: No Ship Air Subflight: No Ship Init Transport: No Ship Phase Transfer: No Contact Name: GEORGE FETSKO Contact Title: HAZMAT - SAFETY ADVISOR Contact Business: Fedex Ground Package System Inc. Contact Street: 1000 Fedex Drive Contact City: CORAOPOLIS Contact State: PA Contact Postal: 15108 Contact Non US St: Contact Country: US Inc. Report Prepared: Carrier HMIS Serious Incidnt: No HMIS Serious Fatality: No HMIS Serious Injury: No HMIS Flight Plan: No HMIS Serious Evacs: No HMIS Major Artery: No HMIS Bulk Release: No HMIS Marine Pollutnt: No HMIS Radioactive: No HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt HMIS Container Code: BOX FBR HMIS Container Desc: Fiberboard box or carton HMIS Bulk Incident: No Undeclared Shipment: No		
Recommend Actions Taken:				The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.		
HMIR Historical Reports						
Report No: X-2017100409 Report Type: A hazardous material incident Date of Incident: 09/28/2017				Fed DOT Agency Nm: Fed DOT Report No: Report Submit Src: XML		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Time of Incident:	1503				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL				Transport Phase:	IN TRANSIT
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1219				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.039062				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	309				CR Non US State:	
How Failed Desc:	Punctured				CR Fed DOT ID:	265752
Failure Cause Code:	516				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g. nails)				CR Country:	US
Ident. Markings:	4g/y24/s/17				Shipper Name:	LEHMAN INC
Cont1 Pkgng Type:					Shipper Street Name:	1585 GREENLEAF AVE
Cont1 Const Mat:					Shipper City:	ELK GROVE VILLAGE
Cont1 Head Type:					Shipper State:	IL
Cont1 Pkg Capacity:					Shipper Postal:	60007-5524
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	277958664566639300
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	ELK GROVE VILLAGE
Cont1 Pkg Mnfctr:					Origin State:	ILLINOIS
Cont1 Pkg Mnfc Dt:					Origin Postal:	60007
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	NORCROSS
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30071
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014060105	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	05/12/2014	Report Submit Src:	XML
Time of Incident:	1650	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT L	Transport Phase:	LOADING
Commodity Long Nm:	PAINT INCLUDING PAINT LACQUER ENAMEL STAIN SHELLAC SOLUTIONS VARNISH POLISH LIQUID FILLER AND LIQUID LACQUER BASE	Incident Occrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1263	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.1250	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	528	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Missing Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	W.W. GRAINGER INC.
Cont1 Pkgng Type:	Box	Shipper Street Name:	101 SOUTHCHASE BLVD
Cont1 Const Mat:	Fiberboard	Shipper City:	FOUNTAIN INN
Cont1 Head Type:		Shipper State:	SC
Cont1 Pkg Capacity:	0	Shipper Postal:	29644-9037
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	132603475544352
Cont1 Pkg No:		Ship Hazmat Reg ID:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg NO Failed:					Origin City:	FOUNTAIN INN
Cont1 Pkg Mnfctr:					Origin State:	SOUTH CAROLINA
Cont1 Pkg Mnfc Dt:					Origin Postal:	29644
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:		Fiberboard			Destination City:	DUNWOODY
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30346
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:		No			Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:		FALSE			Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:		0			Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:		Yes			Material Involved:	No
Fire Result:		No			Estimated Speed:	0
Explosion Result:		No			Weather Conditions:	
Water Sewer Result:		No			Vehicle Overturn:	No
Gas Dispersion:		No			Vehicle Left Roadway:	No
Environment Damage:		No			Passenger Aircraft:	No
No Release Result:		No			Cargo Baggage:	
Fire EMS Report:		No			Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:		No			Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:		Yes			Ship Phase Transfer:	No
Other Cleanup:		No			Contact Name:	GEORGE FETSKO
Damage > 500:		No			Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:		0			Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:		0			Contact Street:	1000 Fedex Drive
Property Damage:		0			Contact City:	CORAOPOLIS
Response Cost:		0			Contact State:	PA
Remediation Cost:		0			Contact Postal:	15108
Damage Old Form:		0			Contact Non US St:	
Total Damages Amt:		0			Contact Country:	US
Hazmat Fatality:		No			Inc. Report Prepared:	Carrier
Haz Fatal Employees:		0			HMIS Serious Incidnt:	No
Haz Fatal Respntrs:		0			HMIS Serious Fatality:	No
Haz Fatal Gen Public:		0			HMIS Serious Injury:	No
Tot Hazmat Fatalities:		0			HMIS Flight Plan:	No
Non Hazmat Fatality:		No			HMIS Serious Evacs:	No
Non Hazmat Fatals:		0			HMIS Major Artery:	No
Hazmat Injury:		No			HMIS Bulk Release:	No
Haz Hospital Empl:		0			HMIS Marine Pollutnt:	No
Haz Hospital Resp:		0			HMIS Radioactive:	No
Haz Hosp Gen Public:		0			HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:		0			HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:		0			HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:		0			HMIS Bulk Incident:	No
Haz Non Hosp Resp:		0			Undeclared Shipment:	No
Description of Events:		The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.						
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2016080616			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	07/29/2016			Report Submit Src:	XML	
Time of Incident:	1432			Inc Multiple Rows:	No	
Haz Class Code:	5.1			Inc Non US State:		
Hazardous Class:	OXIDIZER			Mode Transport:	Highway	
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE			Transport Phase:	IN TRANSIT	
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES STABILIZED WITH ACIDS WATER AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID			Incident Occrrnce:		
Trade Name:	stabilized			Mat Ship Approval?:	No	
ID No:	UN3149			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:	0.0625			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g. Cap Top or Plug)			CR Postal Code:	15108-9373	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	MEDIVATORS INC.	
Cont1 Pkging Type:	Box			Shipper Street Name:	14605 28TH AVE N	
Cont1 Const Mat:	Fiberboard			Shipper City:	MINNEAPOLIS	
Cont1 Head Type:				Shipper State:	MN	
Cont1 Pkg Capacity:	0			Shipper Postal:	55447-4822	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	91101235088374	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	MINNEAPOLIS	
Cont1 Pkg Mnfctr:				Origin State:	MINNESOTA	
Cont1 Pkg Mnfct Dt:				Origin Postal:	55447	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	ATLANTA	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30322	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014100096	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	09/09/2014	Report Submit Src:	XML
Time of Incident:	1700	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	NITRIC ACID OTHER THAN R	Transport Phase:	IN TRANSIT
Commodity Long Nm:	NITRIC ACID OTHER THAN RED FUMING WITH AT LEAST 65 PERCENT BUT NOT MORE THAN 70 PERCENT NITRIC ACID	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN2031	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.1250	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108-9373
How Failed Code:	304	CR Non US State:	
How Failed Desc:	Cracked	CR Fed DOT ID:	265752

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Failure Cause Code:	502				CR Hazmat Reg ID: 051910551007S	
Failure Cause Desc:	Broken Component or Device				CR Country: US	
Ident. Markings:					Shipper Name: DUDA ENERGY LLC	
Cont1 Pkging Type:	Box				Shipper Street Name: 1112 BROOKS ST SE	
Cont1 Const Mat:	Fiberboard				Shipper City: DECATUR	
Cont1 Head Type:					Shipper State: AL	
Cont1 Pkg Capacity:					Shipper Postal: 35601-6599	
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country: US	
C1 Pkg Amt UOM:					Shipper Waybill: 78009656188	
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City: DECATUR	
Cont1 Pkg Mnfctr:					Origin State: ALABAMA	
Cont1 Pkg Mnfc Dt:					Origin Postal: 35601	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country: US	
C1 Test Const Mat:	Fiberboard				Destination City: LAWRENCEVILLE	
C1 Pkg Dsign Pres.:					Destination State: GEORGIA	
C1 Dsign Press UOM:					Destination Postal: 30043	
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country: US	
C1 Head Thickness:					Cont2 Package Type: Bottle	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public: 0	
RAM Pkg Cert.:	FALSE				Haz NonHosp Old: 0	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj: 0	
RAM Nuclide S:					Total Hazmat Injuries: 0	
RAM Transport Index:					Evacuation Indicator: No	
RAM UOM:					Public Evacuated: 0	
RAM Activity Rpted:					Employees Evac: 0	
RAM UOM Rpted:					Total Evacuated: 0	
RAM Activity:					Total Evacuation Hrs: 0	
RAM Activity UOM:					Major Artery Closed: No	
RAM Mat Safety:					Mjr Artery Hrs Closed: 0	
Spillage Result:	Yes				Material Involved: No	
Fire Result:	No				Estimated Speed: 0	
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn: No	
Gas Dispersion:	No				Vehicle Left Roadway: No	
Environment Damage:	No				Passenger Aircraft: No	
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport: No	
Fire EMS EMS Report:					Ship Air First Flight: No	
Police Report:	No				Ship Air Subflight: No	
Police Report No:					Ship Init Transport: No	
In House Cleanup:	Yes				Ship Phase Transfer: No	
Other Cleanup:	No				Contact Name: GEORGE FETSKO	
Damage > 500:	No				Contact Title: HAZMAT - SAFETY ADVISOR	
Material Loss:	0				Contact Business: Fedex Ground Package System Inc.	
Carrier Damage:	0				Contact Street: 1000 Fedex Drive	
Property Damage:	0				Contact City: CORAOPOLIS	
Response Cost:	0				Contact State: PA	
Remediation Cost:	0				Contact Postal: 15108	
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country: US	
Hazmat Fatality:	No				Inc. Report Prepared: Carrier	
Haz Fatal Employees:	0				HMIS Serious Incidnt: No	
Haz Fatal Respntrs:	0				HMIS Serious Fatality: No	
Haz Fatal Gen Public:	0				HMIS Serious Injury: No	
Tot Hazmat Fatalities:	0				HMIS Flight Plan: No	
Non Hazmat Fatality:	No				HMIS Serious Evacs: No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non Hazmat Fatal:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2016060832				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	05/31/2016				Report Submit Src:	XML
Time of Incident:	0018				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	PETROLEUM DISTILLATES N				Transport Phase:	UNLOADING
Commodity Long Nm:	PETROLEUM DISTILLATES N.O.S. OR PETROLEUM PRODUCTS N.O.S.				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1268				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.007812				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	TEST EQUIPMENT DISTRIBUTORS LLC
Cont1 Pkging Type:	Box				Shipper Street Name:	1959 PARKER CT STE D
Cont1 Const Mat:	Fiberboard				Shipper City:	STONE MOUNTAIN
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30087-3449
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	2367824684910
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	STONE MOUNTAIN
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:					Origin Postal:	30087
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	PALMETTO
C1 Pkg Dsign Pres.:					Destination State:	FLORIDA
C1 Dsign Press UOM:					Destination Postal:	34221
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:					The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.	

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014060207	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	05/16/2014	Report Submit Src:	XML
Time of Incident:	2351	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	ETHANOL SOLUTIONS	Transport Phase:	LOADING
Commodity Long Nm:	ETHANOL SOLUTIONS	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1170	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Qty Released:	1				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	SLMP LLC
Cont1 Pkging Type:	Box				Shipper Street Name:	2090 COMMERCE DR
Cont1 Const Mat:	Fiberboard				Shipper City:	MCKINNEY
Cont1 Head Type:					Shipper State:	TX
Cont1 Pkg Capacity:					Shipper Postal:	75069-8203
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	100909316527548
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	MC KINNEY
Cont1 Pkg Mnfctr:					Origin State:	TEXAS
Cont1 Pkg Mnfct Dt:					Origin Postal:	75071
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	DECATUR
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30030
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2017110270	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	10/17/2017	Report Submit Src:	XML
Time of Incident:	0107	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI	Transport Phase:	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1824	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.003904	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:	4g/y24..7/s/17/usa/m4172	Shipper Name:	ECOLAB INC.
Cont1 Pkging Type:		Shipper Street Name:	90 PIEDMONT INDUSTRIAL DR
Cont1 Const Mat:		Shipper City:	WINSTON SALEM
Cont1 Head Type:		Shipper State:	NC
Cont1 Pkg Capacity:		Shipper Postal:	27107-6876
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	757771682960821
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	WINSTON SALEM
Cont1 Pkg Mnfctr:		Origin State:	NORTH CAROLINA
Cont1 Pkg Mnfct Dt:		Origin Postal:	27107
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:		Destination City:	ATLANTA
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30329
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvc Pres.:		Cont2 Pkg Capacity:	
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public: 0		
RAM Pkg Cert.: FALSE				Haz NonHosp Old: 0		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj: 0		
RAM Nuclide S:				Total Hazmat Injuries: 0		
RAM Transport Index:				Evacuation Indicator: No		
RAM UOM:				Public Evacuated: 0		
RAM Activity Rpted:				Employees Evac: 0		
RAM UOM Rpted:				Total Evacuated: 0		
RAM Activity:				Total Evacuation Hrs: 0		
RAM Activity UOM:				Major Artery Closed: No		
RAM Mat Safety:				Mjr Artery Hrs Closed: 0		
Spillage Result: Yes				Material Involved: No		
Fire Result: No				Estimated Speed: 0		
Explosion Result: No				Weather Conditions:		
Water Sewer Result: No				Vehicle Overturn: No		
Gas Dispersion: No				Vehicle Left Roadway: No		
Environment Damage: No				Passenger Aircraft: No		
No Release Result: No				Cargo Baggage:		
Fire EMS Report: No				Ship Non Transport: No		
Fire EMS EMS Report:				Ship Air First Flight: No		
Police Report: No				Ship Air Subflight: No		
Police Report No:				Ship Init Transport: No		
In House Cleanup: Yes				Ship Phase Transfer: No		
Other Cleanup: No				Contact Name: GEORGE FETSKO		
Damage > 500: No				Contact Title: HAZMAT - SAFETY ADVISOR		
Material Loss: 0				Contact Business: Fedex Ground Package System Inc.		
Carrier Damage: 0				Contact Street: 1000 Fedex Drive		
Property Damage: 0				Contact City: CORAOPOLIS		
Response Cost: 0				Contact State: PA		
Remediation Cost: 0				Contact Postal: 15108		
Damage Old Form: 0				Contact Non US St:		
Total Damages Amt: 0				Contact Country: US		
Hazmat Fatality: No				Inc. Report Prepared: Carrier		
Haz Fatal Employees: 0				HMIS Serious Incidnt: No		
Haz Fatal Respndrs: 0				HMIS Serious Fatality: No		
Haz Fatal Gen Public: 0				HMIS Serious Injury: No		
Tot Hazmat Fatalities: 0				HMIS Flight Plan: No		
Non Hazmat Fatality: No				HMIS Serious Evacs: No		
Non Hazmat FataIs: 0				HMIS Major Artery: No		
Hazmat Injury: No				HMIS Bulk Release: No		
Haz Hospital Empl: 0				HMIS Marine Pollutnt: No		
Haz Hospital Resp: 0				HMIS Radioactive: No		
Haz Hosp Gen Public: 0				HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt		
Haz Hosp Old Form: 0				HMIS Container Code: 4G		
Total Haz Hosp Inj: 0				HMIS Container Desc: Fiberboard box		
Haz Non Hosp Empl: 0				HMIS Bulk Incident: No		
Haz Non Hosp Resp: 0				Undeclared Shipment: No		
Description of Events:				The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.		
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:		X-2018050790		Fed DOT Agency Nm:		
Report Type:		A hazardous material incident		Fed DOT Report No:		
Date of Incident:		05/02/2018		Report Submit Src:		XML
Time of Incident:		2302		Inc Multiple Rows:		No
Haz Class Code:		3		Inc Non US State:		
Hazardous Class:		FLAMMABLE - COMBUSTIBLE LIQUID		Mode Transport:		Highway
Commodity Short Nm:		DIESEL FUEL		Transport Phase:		UNLOADING
Commodity Long Nm:		DIESEL FUEL		Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:		No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
ID No:	UN1202				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.0625				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:	4G/Y28/S/15USA/+BR9196				Shipper Name:	INDIVIDUALNOT A COMPANY
Cont1 Pkging Type:	Box				Shipper Street Name:	4172 WINTERS CHAPEL RD
Cont1 Const Mat:	Fiberboard				Shipper City:	POMPANO BEACH
Cont1 Head Type:					Shipper State:	FL
Cont1 Pkg Capacity:					Shipper Postal:	33069-4108
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	4275417734283189073
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	POMPANO BEACH
Cont1 Pkg Mnfctr:					Origin State:	FLORIDA
Cont1 Pkg Mnfct Dt:					Origin Postal:	33069
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	TIFTON
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	31794
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: WHEN I GOT THE PACKAGE IT WAS WET. SO WHEN I OPENED IT TWO O F THE CONTAINERS WERE WET. New Comments:					
Recommend Actions Taken:						

HMIR Historical Reports

Report No:	X-2016030412	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	02/23/2016	Report Submit Src:	XML
Time of Incident:	1046	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	METHANOL	Transport Phase:	IN TRANSIT
Commodity Long Nm:	METHANOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1230	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.007812	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	VWR INTERNATIONAL LLC
Cont1 Pkgng Type:	Box	Shipper Street Name:	1050 SATELLITE BLVD NW
Cont1 Const Mat:	Fiberboard	Shipper City:	SUWANEE
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:		Shipper Postal:	30024-2883
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	408394874378036
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	SUWANEE
Cont1 Pkg Mnfctr:		Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:		Origin Postal:	30024
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Fiberboard	Destination City:	HIALEAH
C1 Pkg Dsign Pres.:		Destination State:	FLORIDA
C1 Dsign Press UOM:		Destination Postal:	33014
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	Bottle

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Head Thick UOM: C1 Pkg Srvc Pres.: C1 Srvc Press UOM: C1 Valve/Device Fail?: No C1 Device Type: C1 Device Mnfctr: C1 Device Model: NRC No:				Cont2 Const Mat: Cont2 Pkg Capacity: Cont2 Capacity UOM: Cont2 Pkg Amount: Cont2 Pkg Amt UOM: Cont2 Pkg No: Cont2 Pkg No Failed:		Plastic
RAM Pkg Category: RAM Pkg Cert.: FALSE RAM Pkg Cert. NBR: RAM Nuclide S: RAM Transport Index: RAM UOM: RAM Activity Rpted: RAM UOM Rpted: RAM Activity: RAM Activity UOM: RAM Mat Safety: Spillage Result: Yes Fire Result: No Explosion Result: No Water Sewer Result: No Gas Dispersion: No Environment Damage: No No Release Result: No Fire EMS Report: No Fire EMS EMS Report: Police Report: No Police Report No: In House Cleanup: Yes Other Cleanup: No Damage > 500: No Material Loss: 0 Carrier Damage: 0 Property Damage: 0 Response Cost: 0 Remediation Cost: 0 Damage Old Form: 0 Total Damages Amt: 0 Hazmat Fatality: No Haz Fatal Employees: 0 Haz Fatal Respndrs: 0 Haz Fatal Gen Public: 0 Tot Hazmat Fatalities: 0 Non Hazmat Fatality: No Non Hazmat FataIs: 0 Hazmat Injury: No Haz Hospital Empl: 0 Haz Hospital Resp: 0 Haz Hosp Gen Public: 0 Haz Hosp Old Form: 0 Total Haz Hosp Inj: 0 Haz Non Hosp Empl: 0 Haz Non Hosp Resp: 0 Description of Events:				Haz NonHosp Public: 0 Haz NonHosp Old: 0 Tot Haz Non Hosp Inj: 0 Total Hazmat Injuries: 0 Evacuation Indicator: No Public Evacuated: 0 Employees Evac: 0 Total Evacuated: 0 Total Evacuation Hrs: 0 Major Artery Closed: No Mjr Artery Hrs Closed: 0 Material Involved: No Estimated Speed: 0 Weather Conditions: Vehicle Overturn: No Vehicle Left Roadway: No Passenger Aircraft: No Cargo Baggage: Ship Non Transport: No Ship Air First Flight: No Ship Air Subflight: No Ship Init Transport: No Ship Phase Transfer: No Contact Name: GEORGE FETSKO Contact Title: HAZMAT - SAFETY ADVISOR Contact Business: Fedex Ground Package System Inc. Contact Street: 1000 Fedex Drive Contact City: CORAOPOLIS Contact State: PA Contact Postal: 15108 Contact Non US St: Contact Country: US Inc. Report Prepared: Carrier HMIS Serious Incidnt: No HMIS Serious Fatality: No HMIS Serious Injury: No HMIS Flight Plan: No HMIS Serious Evacs: No HMIS Major Artery: No HMIS Bulk Release: No HMIS Marine Pollutnt: No HMIS Radioactive: No HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt HMIS Container Code: BOX FBR HMIS Container Desc: Fiberboard box or carton HMIS Bulk Incident: No Undeclared Shipment: No		
Recommend Actions Taken:						
HMIR Historical Reports						
Report No: X-2013040173 Report Type: A hazardous material incident Date of Incident: 03/21/2013 Time of Incident: 1645 Haz Class Code: 5.1				Fed DOT Agency Nm: Fed DOT Report No: Report Submit Src: XML Inc Multiple Rows: No Inc Non US State:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazardous Class:		OXIDIZER			Mode Transport:	Highway
Commodity Short Nm:		HYDROGEN PEROXIDE AND PE			Transport Phase:	LOADING
Commodity Long Nm:		HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES STABILIZED WITH ACIDS WATER AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID			Incident Occrnce:	
Trade Name:		stabilized			Mat Ship Approval?:	No
ID No:		UN3149			Mat Ship Approv No:	
Haz Waste Ind:		No			Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.026418				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	MAR COR PURIFICATION INC.
Cont1 Pkgng Type:	Box				Shipper Street Name:	14550 28TH AVE N
Cont1 Const Mat:	Fiberboard				Shipper City:	MINNEAPOLIS
Cont1 Head Type:					Shipper State:	MN
Cont1 Pkg Capacity:					Shipper Postal:	55447-4817
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	753963334386910
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	MINNEAPOLIS
Cont1 Pkg Mnfctr:					Origin State:	MINNESOTA
Cont1 Pkg Mnfc Dt:					Origin Postal:	55447
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30309
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2014090158				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	08/15/2014				Report Submit Src:	XML
Time of Incident:	1746				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	ACETONE				Transport Phase:	LOADING
Commodity Long Nm:	ACETONE				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1090				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.25				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	N/A
Cont1 Pkging Type:	Box				Shipper Street Name:	ILLEGIBLE
Cont1 Const Mat:	Fiberboard				Shipper City:	NORCROSS
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30071
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	111111111111111
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	NORCROSS
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Mnfct Dt:					Origin Postal:	30071
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	NORCROSS
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30071
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
HMIR Historical Reports						
Report No:	X-2017120296				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	11/24/2017				Report Submit Src:	XML
Time of Incident:	1930				Inc Multiple Rows:	No
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC				Transport Phase:	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUID BASIC INORGANIC N. O.S.				Incident Occrrnce:	
Trade Name:	potassium hydroxide				Mat Ship Approval?:	No
ID No:	UN3266				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	Yes
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1.75				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	DIVERSITECH CORPORATION
Cont1 Pkging Type:	Box				Shipper Street Name:	6650 SUGARLOAF PKWY # 100
Cont1 Const Mat:	Fiberboard				Shipper City:	DULUTH
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30097-4365
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	889030132853297
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	DULUTH
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:					Origin Postal:	30097
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	DULUTH
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30097
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	Yes
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2018120223				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	11/07/2018				Report Submit Src:	XML
Time of Incident:	1900				Inc Multiple Rows:	No
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI				Transport Phase:	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.0625				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	CEVA LOGISTICS
Cont1 Pkging Type:	Drum				Shipper Street Name:	125 SOUTHSIDE CT
Cont1 Const Mat:	Plastic				Shipper City:	MCDONOUGH
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30253-7448

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country: US		
C1 Pkg Amt UOM:				Shipper Waybill: 916079075465184		
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City: MCDONOUGH		
Cont1 Pkg Mnfctr:				Origin State: GEORGIA		
Cont1 Pkg Mnfct Dt:				Origin Postal: 30253		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country: US		
C1 Test Const Mat: Plastic				Destination City: ATLANTA		
C1 Pkg Dsign Pres.:				Destination State: GEORGIA		
C1 Dsign Press UOM:				Destination Postal: 30340		
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country: US		
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?: No				Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public: 0		
RAM Pkg Cert.: FALSE				Haz NonHosp Old: 0		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj: 0		
RAM Nuclide S:				Total Hazmat Injuries: 0		
RAM Transport Index:				Evacuation Indicator: No		
RAM UOM:				Public Evacuated: 0		
RAM Activity Rpted:				Employees Evac: 0		
RAM UOM Rpted:				Total Evacuated: 0		
RAM Activity:				Total Evacuation Hrs: 0		
RAM Activity UOM:				Major Artery Closed: No		
RAM Mat Safety:				Mjr Artery Hrs Closed: 0		
Spillage Result: Yes				Material Involved: No		
Fire Result: No				Estimated Speed: 0		
Explosion Result: No				Weather Conditions:		
Water Sewer Result: No				Vehicle Overturn: No		
Gas Dispersion: No				Vehicle Left Roadway: No		
Environment Damage: No				Passenger Aircraft: No		
No Release Result: No				Cargo Baggage:		
Fire EMS Report: No				Ship Non Transport: No		
Fire EMS EMS Report:				Ship Air First Flight: No		
Police Report: No				Ship Air Subflight: No		
Police Report No:				Ship Init Transport: No		
In House Cleanup: Yes				Ship Phase Transfer: No		
Other Cleanup: No				Contact Name: GEORGE FETSKO		
Damage > 500: No				Contact Title: HAZMAT - SAFETY ADVISOR		
Material Loss: 0				Contact Business: Fedex Ground Package System Inc.		
Carrier Damage: 0				Contact Street: 1000 Fedex Drive		
Property Damage: 0				Contact City: CORAOPOLIS		
Response Cost: 0				Contact State: PA		
Remediation Cost: 0				Contact Postal: 15108		
Damage Old Form: 0				Contact Non US St:		
Total Damages Amt: 0				Contact Country: US		
Hazmat Fatality: No				Inc. Report Prepared: Carrier		
Haz Fatal Employees: 0				HMIS Serious Incidnt: No		
Haz Fatal Respndrs: 0				HMIS Serious Fatality: No		
Haz Fatal Gen Public: 0				HMIS Serious Injury: No		
Tot Hazmat Fatalities: 0				HMIS Flight Plan: No		
Non Hazmat Fatality: No				HMIS Serious Evacs: No		
Non Hazmat Fatals: 0				HMIS Major Artery: No		
Hazmat Injury: No				HMIS Bulk Release: No		
Haz Hospital Empl: 0				HMIS Marine Pollutnt: No		
Haz Hospital Resp: 0				HMIS Radioactive: No		
Haz Hosp Gen Public: 0				HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt		
Haz Hosp Old Form: 0				HMIS Container Code: CONT		
Total Haz Hosp Inj: 0				HMIS Container Desc: Container no description given (do not use if at		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Non Hosp Empl: 0 Haz Non Hosp Resp: 0 Description of Events: Original comments: PACKAGE FOUND WITH LOOSE CAP AND LEAKING New Comments: Recommend Actions Taken:						all possible) No No
HMIR Historical Reports						
Report No: X-2015020161 Report Type: A hazardous material incident Date of Incident: 01/22/2015 Time of Incident: 1040 Haz Class Code: 3 Hazardous Class: FLAMMABLE - COMBUSTIBLE LIQUID Commodity Short Nm: FLAMMABLE LIQUIDS N.O.S. Commodity Long Nm: FLAMMABLE LIQUIDS N.O.S. Trade Name: ACETONEHEPTANE ID No: UN1993 Haz Waste Ind: No Haz Waste EPA No: HMIS Tox Inhalation?: No TIH Hazard Zone: Qty Released: 0.528360 Unit of Measure: Liquid - Gallon What Failed: 104 What Failed Desc: Body How Failed Code: 309 How Failed Desc: Punctured Failure Cause Code: 515 Failure Cause Desc: Human Error Ident. Markings: Cont1 Pkging Type: Drum Cont1 Const Mat: Aluminum Cont1 Head Type: Cont1 Pkg Capacity: 0 C1 Capacity UOM: Cont1 Pkg Amt: 0 C1 Pkg Amt UOM: Cont1 Pkg No: C1 Pkg NO Failed: Cont1 Pkg Mnfctr: Cont1 Pkg Mnfct Dt: Cont1 Pkg Serial NO: C1 Pkg Last Test Dt: C1 Test Const Mat: Aluminum C1 Pkg Dsign Pres.: C1 Dsign Press UOM: C1 Pkg Shell Thick: C1 Shell Thick UOM: C1 Head Thickness: C1 Head Thick UOM: C1 Pkg Srvc Pres.: C1 Srvc Press UOM: C1 Valve/Device Fail?: No C1 Device Type: C1 Device Mnfctr: C1 Device Model: NRC No:						HMIS Bulk Incident: No Undeclared Shipment: No Fed DOT Agency Nm: Fed DOT Report No: Report Submit Src: XML Inc Multiple Rows: No Inc Non US State: Mode Transport: Highway Transport Phase: LOADING Incident Occrrnce: Mat Ship Approval?: No Mat Ship Approv No: Undecl Hazmat Ship?: No Packaging Type: Non-Bulk Packing Group: II Carrier Reporter: FEDEX GROUND PACKAGE SYSTEM INC. CR Street Name: 1000 FED EX DR CR City: CORAOPOLIS CR State: PA CR Postal Code: 15108-9373 CR Non US State: CR Fed DOT ID: 265752 CR Hazmat Reg ID: 051910551007S CR Country: US Shipper Name: GEORGIA GRAPHICS INC Shipper Street Name: 7055 AMWILER INDSTR L E Shipper City: ATLANTA Shipper State: GA Shipper Postal: 30360-2833 Shipper Non US St: Shipper Country: US Shipper Waybill: 30738232546607 Ship Hazmat Reg ID: Origin City: DORAVILLE Origin State: GEORGIA Origin Postal: 30360 Origin Non US St: Origin Country: US Destination City: ORLANDO Destination State: FLORIDA Destination Postal: 32805 Destination Non US: Destination Country: US Cont2 Package Type: Cont2 Const Mat: Cont2 Pkg Capacity: Cont2 Capacity UOM: Cont2 Pkg Amount: Cont2 Pkg Amt UOM: Cont2 Pkg No: Cont2 Pkg No Failed:
RAM Pkg Category: RAM Pkg Cert.: FALSE RAM Pkg Cert. NBR: RAM Nuclide S: RAM Transport Index: RAM UOM: RAM Activity Rpted: RAM UOM Rpted: RAM Activity: 0						Haz NonHosp Public: 0 Haz NonHosp Old: 0 Tot Haz Non Hosp Inj: 0 Total Hazmat Injuries: 0 Evacuation Indicator: No Public Evacuated: 0 Employees Evac: 0 Total Evacuated: 0 Total Evacuation Hrs: 0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Activity UOM:			Major Artery Closed:			No
RAM Mat Safety:			Mjr Artery Hrs Closed:			0
Spillage Result:	Yes		Material Involved:			No
Fire Result:	No		Estimated Speed:			0
Explosion Result:	No		Weather Conditions:			
Water Sewer Result:	No		Vehicle Overturn:			No
Gas Dispersion:	No		Vehicle Left Roadway:			No
Environment Damage:	No		Passenger Aircraft:			No
No Release Result:	No		Cargo Baggage:			
Fire EMS Report:	No		Ship Non Transport:			No
Fire EMS EMS Report:			Ship Air First Flight:			No
Police Report:	No		Ship Air Subflight:			No
Police Report No:			Ship Init Transport:			No
In House Cleanup:	Yes		Ship Phase Transfer:			No
Other Cleanup:	No		Contact Name:			GEORGE FETSKO
Damage > 500:	No		Contact Title:			HAZMAT - SAFETY ADVISOR
Material Loss:	0		Contact Business:			Fedex Ground Package System Inc.
Carrier Damage:	0		Contact Street:			1000 Fedex Drive
Property Damage:	0		Contact City:			CORAOPOLIS
Response Cost:	0		Contact State:			PA
Remediation Cost:	0		Contact Postal:			15108
Damage Old Form:	0		Contact Non US St:			
Total Damages Amt:	0		Contact Country:			US
Hazmat Fatality:	No		Inc. Report Prepared:			Carrier
Haz Fatal Employees:	0		HMIS Serious Incidnt:			No
Haz Fatal Respntrs:	0		HMIS Serious Fatality:			No
Haz Fatal Gen Public:	0		HMIS Serious Injury:			No
Tot Hazmat Fatalities:	0		HMIS Flight Plan:			No
Non Hazmat Fatality:	No		HMIS Serious Evacs:			No
Non Hazmat Fatals:	0		HMIS Major Artery:			No
Hazmat Injury:	No		HMIS Bulk Release:			No
Haz Hospital Empl:	0		HMIS Marine Pollutnt:			No
Haz Hospital Resp:	0		HMIS Radioactive:			No
Haz Hosp Gen Public:	0		HMIS Gen Pkg Type:			OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0		HMIS Container Code:			DRUM MTL
Total Haz Hosp Inj:	0		HMIS Container Desc:			Metal drum
Haz Non Hosp Empl:	0		HMIS Bulk Incident:			No
Haz Non Hosp Resp:	0		Undeclared Shipment:			No
Description of Events:			The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.			

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2013060096	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	05/10/2013	Report Submit Src:	XML
Time of Incident:	2130	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	GASOLINE INCLUDES GASOLI	Transport Phase:	UNLOADING
Commodity Long Nm:	GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL WITH NOT MORE THAN 10% ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1203	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.25	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Failure Cause Desc:		Loose Closure Component or Device		CR Country:	US	
Ident. Markings:		4G/Y31.6/S/10USA/+AA3579		Shipper Name:	MOTIVA ENTERPRISES LLC	
Cont1 Pkging Type:				Shipper Street Name:	4201 WINTERS CHAPEL RD	
Cont1 Const Mat:				Shipper City:	ATLANTA	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:				Shipper Postal:	30360-3150	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	427541762800178	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	DORAVILLE	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfct Dt:				Origin Postal:	30360	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:				Destination City:	ABAC	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	31794	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	Moon Township	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatafs:	0			HMIS Major Arterv:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazmat Injury: No Haz Hospital Empl: 0 Haz Hospital Resp: 0 Haz Hosp Gen Public: 0 Haz Hosp Old Form: 0 Total Haz Hosp Inj: 0 Haz Non Hosp Empl: 0 Haz Non Hosp Resp: 0 Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper. Recommend Actions Taken: HMIR Historical Reports Report No: X-2017100130 Report Type: A hazardous material incident Date of Incident: 09/13/2017 Time of Incident: 1044 Haz Class Code: 8 Hazardous Class: CORROSIVE MATERIAL Commodity Short Nm: DISINFECTANTS LIQUID C Commodity Long Nm: DISINFECTANTS LIQUID CORROSIVE N.O. Trade Name: (quatamary ammonium ID No: UN1903 Haz Waste Ind: No Haz Waste EPA No: HMIS Tox Inhalation?: No TIH Hazard Zone: Qty Released: 0.528360 Unit of Measure: Liquid - Gallon What Failed: 109 What Failed Desc: Closure (e.g. Cap Top or Plug) How Failed Code: 308 How Failed Desc: Leaked Failure Cause Code: 526 Failure Cause Desc: Loose Closure Component or Device Ident. Markings: 4G/y23.9/s/17/usa/+BR10195 Cont1 Pkging Type: Cont1 Const Mat: Cont1 Head Type: Cont1 Pkg Capacity: C1 Capacity UOM: Cont1 Pkg Amt: C1 Pkg Amt UOM: Cont1 Pkg No: C1 Pkg NO Failed: Cont1 Pkg Mnfctr: Cont1 Pkg Mnfc Dt: Cont1 Pkg Serial NO: C1 Pkg Last Test Dt: C1 Test Const Mat: C1 Pkg Dsign Pres.: C1 Dsign Press UOM: C1 Pkg Shell Thick: C1 Shell Thick UOM: C1 Head Thickness: C1 Head Thick UOM: C1 Pkg Srvc Pres.: C1 Srvc Press UOM: C1 Valve/Device Fail?: No C1 Device Type: C1 Device Mnfctr: C1 Device Model: NRC No: Fed DOT Agency Nm: Fed DOT Report No: Report Submit Src: XML Inc Multiple Rows: No Inc Non US State: Mode Transport: Highway Transport Phase: LOADING Incident Occrrnce: Mat Ship Approval?: No Mat Ship Approv No: Undecl Hazmat Ship?: No Packaging Type: Non-Bulk Packing Group: II Carrier Reporter: FEDEX GROUND PACKAGE SYSTEM INC. CR Street Name: 1000 FED EX DR CR City: CORAOPOLIS CR State: PA CR Postal Code: 15108-9373 CR Non US State: CR Fed DOT ID: 265752 CR Hazmat Reg ID: 051910551007S CR Country: US Shipper Name: NXKEM USA LLC Shipper Street Name: 7855 N FAULKNER RD Shipper City: MILWAUKEE Shipper State: WI Shipper Postal: 53224 Shipper Non US St: Shipper Country: US Shipper Waybill: 172416830172118 Ship Hazmat Reg ID: Origin City: MILWAUKEE Origin State: WISCONSIN Origin Postal: 53224 Origin Non US St: Origin Country: US Destination City: NORCROSS Destination State: GEORGIA Destination Postal: 30071 Destination Non US: Destination Country: US Cont2 Package Type: Cont2 Const Mat: Cont2 Pkg Capacity: Cont2 Capacity UOM: Cont2 Pkg Amount: Cont2 Pkg Amt UOM: Cont2 Pkg No: Cont2 Pkg No Failed: RAM Pkg Category: Haz NonHosp Public: 0						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2012120262	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	11/26/2012	Report Submit Src:	XML
Time of Incident:	1632	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL	Transport Phase:	UNLOADING
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1219	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.039062	CR Street Name:	1000 FED EX DR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	139			CR State:	PA	
What Failed Desc:	O-Ring or Seals			CR Postal Code:	15108-9373	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	511			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Dropped			CR Country:	US	
Ident. Markings:				Shipper Name:	MCGOWAN ENTERPRISES INC.	
Cont1 Pkging Type:	Box			Shipper Street Name:	12225 WORLD TRADE DR D	
Cont1 Const Mat:	Fiberboard			Shipper City:	SAN DIEGO	
Cont1 Head Type:				Shipper State:	CA	
Cont1 Pkg Capacity:				Shipper Postal:	92128-3719	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	62974362592636	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	SAN DIEGO	
Cont1 Pkg Mnfctr:				Origin State:	CALIFORNIA	
Cont1 Pkg Mnfc Dt:				Origin Postal:	92128	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	BERKELEY LAKE	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30096	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvs Pres.:				Cont2 Pkg Capacity:		
C1 Srvs Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	Moon Township	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2016090684	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	08/29/2016	Report Submit Src:	XML
Time of Incident:	2338	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC	Transport Phase:	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUID BASIC INORGANIC N. O.S.	Incident Occrrnce:	
Trade Name:	(sodium hydroxide)	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	ZEP MFG SALES 310
Cont1 Pkging Type:	Box	Shipper Street Name:	71 BUSINESS PARK CT NW
Cont1 Const Mat:	Fiberboard	Shipper City:	CARTERSVILLE
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:		Shipper Postal:	30121-1200
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	222733011470325
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	ATLANTA
Cont1 Pkg Mnfctr:		Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:		Origin Postal:	30336
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Fiberboard	Destination City:	NORCROSS
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30071
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	Bottle
C1 Head Thick UOM:		Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:		Cont2 Pkg Capacity:	
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public: 0		
RAM Pkg Cert.: FALSE				Haz NonHosp Old: 0		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj: 0		
RAM Nuclide S:				Total Hazmat Injuries: 0		
RAM Transport Index:				Evacuation Indicator: No		
RAM UOM:				Public Evacuated: 0		
RAM Activity Rpted:				Employees Evac: 0		
RAM UOM Rpted:				Total Evacuated: 0		
RAM Activity:				Total Evacuation Hrs: 0		
RAM Activity UOM:				Major Artery Closed: No		
RAM Mat Safety:				Mjr Artery Hrs Closed: 0		
Spillage Result: Yes				Material Involved: No		
Fire Result: No				Estimated Speed: 0		
Explosion Result: No				Weather Conditions:		
Water Sewer Result: No				Vehicle Overturn: No		
Gas Dispersion: No				Vehicle Left Roadway: No		
Environment Damage: No				Passenger Aircraft: No		
No Release Result: No				Cargo Baggage:		
Fire EMS Report: No				Ship Non Transport: No		
Fire EMS EMS Report:				Ship Air First Flight: No		
Police Report: No				Ship Air Subflight: No		
Police Report No:				Ship Init Transport: No		
In House Cleanup: Yes				Ship Phase Transfer: No		
Other Cleanup: No				Contact Name: GEORGE FETSKO		
Damage > 500: No				Contact Title: HAZMAT - SAFETY ADVISOR		
Material Loss: 0				Contact Business: Fedex Ground Package System Inc.		
Carrier Damage: 0				Contact Street: 1000 Fedex Drive		
Property Damage: 0				Contact City: CORAOPOLIS		
Response Cost: 0				Contact State: PA		
Remediation Cost: 0				Contact Postal: 15108		
Damage Old Form: 0				Contact Non US St:		
Total Damages Amt: 0				Contact Country: US		
Hazmat Fatality: No				Inc. Report Prepared: Carrier		
Haz Fatal Employees: 0				HMIS Serious Incidnt: No		
Haz Fatal Respndrs: 0				HMIS Serious Fatality: No		
Haz Fatal Gen Public: 0				HMIS Serious Injury: No		
Tot Hazmat Fatalities: 0				HMIS Flight Plan: No		
Non Hazmat Fatality: No				HMIS Serious Evacs: No		
Non Hazmat FataIs: 0				HMIS Major Artery: No		
Hazmat Injury: No				HMIS Bulk Release: No		
Haz Hospital Empl: 0				HMIS Marine Pollutnt: No		
Haz Hospital Resp: 0				HMIS Radioactive: No		
Haz Hosp Gen Public: 0				HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt		
Haz Hosp Old Form: 0				HMIS Container Code: BOX FBR		
Total Haz Hosp Inj: 0				HMIS Container Desc: Fiberboard box or carton		
Haz Non Hosp Empl: 0				HMIS Bulk Incident: No		
Haz Non Hosp Resp: 0				Undeclared Shipment: No		
Description of Events:		The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:		X-2017120235		Fed DOT Agency Nm:		
Report Type:		A hazardous material incident		Fed DOT Report No:		
Date of Incident:		11/16/2017		Report Submit Src: XML		
Time of Incident:		0001		Inc Multiple Rows: No		
Haz Class Code:		8		Inc Non US State:		
Hazardous Class:		CORROSIVE MATERIAL		Mode Transport: Highway		
Commodity Short Nm:		POTASSIUM HYDROXIDE SOL		Transport Phase: LOADING		
Commodity Long Nm:		POTASSIUM HYDROXIDE SOLUTION		Incident Occrrnce:		
Trade Name:				Mat Ship Approval?: No		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
ID No:	UN1814				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.10				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	309				CR Non US State:	
How Failed Desc:	Punctured				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:					Shipper Name:	VWR INTERNATIONAL LLC
Cont1 Pkging Type:	Jerrican				Shipper Street Name:	1050 SATELLITE BLVD NW
Cont1 Const Mat:	Plastic				Shipper City:	SUWANEE
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30024-2883
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	4083948739681535394
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	SUWANEE
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:					Origin Postal:	30024
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	CLEARWATER
C1 Pkg Dsign Pres.:					Destination State:	FLORIDA
C1 Dsign Press UOM:					Destination Postal:	33762
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fataals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	PAIL PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic pail open head capacity 10 gallons or less
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2018050216	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	04/16/2018	Report Submit Src:	XML
Time of Incident:	1730	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC	Transport Phase:	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUID BASIC INORGANIC N. O.S.	Incident Occrrnce:	
Trade Name:	(Contains potassuim	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.1250	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:	4G/Y19.4/S/18USA/+BZ1194	Shipper Name:	DIVERSITECH CORPORATION
Cont1 Pkging Type:	Box	Shipper Street Name:	2175 E PARK DR NE
Cont1 Const Mat:	Fiberboard	Shipper City:	CONYERS
Cont1 Head Type:	Removable	Shipper State:	GA
Cont1 Pkg Capacity:		Shipper Postal:	30013-5773
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	2506707434102111520
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	CONYERS
Cont1 Pkg Mnfctr:		Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:		Origin Postal:	30013
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Fiberboard	Destination City:	ATLANTA
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30329

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:		Original comments: BOX WAS FOUND ON DOCK WET. AS I LOOKED INSIDE THERE WERE 4 1GAL BOTTLE OF TRIPLE D UNIVERSAL CLEANER BUT 2 BOTTLES HAD LOOSE CAPS New Comments:				
Recommend Actions Taken:						

HMIR Historical Reports

Report No:	X-2013120187	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	11/15/2013	Report Submit Src:	XML

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Time of Incident:	1648				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	GASOLINE INCLUDES GASOLI				Transport Phase:	UNLOADING
Commodity Long Nm:	GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL WITH NOT MORE THAN 10% ALCOHOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1203				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.25				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	MOTIVA ENTERPRISES LLC
Cont1 Pkging Type:	Box				Shipper Street Name:	4201 WINTERS CHAPEL RD
Cont1 Const Mat:	Fiberboard				Shipper City:	ATLANTA
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30360-3150
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	427541762800284
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	DORAVILLE
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfcct Dt:					Origin Postal:	30360
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ABAC
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	31794
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire EMS EMS Report:						
Police Report:	No				Ship Air First Flight:	No
Police Report No:					Ship Air Subflight:	No
In House Cleanup:	Yes				Ship Init Transport:	No
Other Cleanup:	No				Ship Phase Transfer:	No
Damage > 500:	No				Contact Name:	GEORGE FETSKO
Material Loss:	0				Contact Title:	HAZMAT - SAFETY ADVISOR
Carrier Damage:	0				Contact Business:	Fedex Ground Package System Inc.
Property Damage:	0				Contact Street:	1000 Fedex Drive
Response Cost:	0				Contact City:	CORAOPOLIS
Remediation Cost:	0				Contact State:	PA
Damage Old Form:	0				Contact Postal:	15108
Total Damages Amt:	0				Contact Non US St:	
Hazmat Fatality:	No				Contact Country:	US
Haz Fatal Employees:	0				Inc. Report Prepared:	Carrier
Haz Fatal Respndrs:	0				HMIS Serious Incidnt:	No
Haz Fatal Gen Public:	0				HMIS Serious Fatality:	No
Tot Hazmat Fatalities:	0				HMIS Serious Injury:	No
Non Hazmat Fatality:	No				HMIS Flight Plan:	No
Non Hazmat Fatafs:	0				HMIS Serious Evacs:	No
Hazmat Injury:	No				HMIS Major Artery:	No
Haz Hospital Empl:	0				HMIS Bulk Release:	No
Haz Hospital Resp:	0				HMIS Marine Pollutnt:	No
Haz Hosp Gen Public:	0				HMIS Radioactive:	No
Haz Hosp Old Form:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Total Haz Hosp Inj:	0				HMIS Container Code:	BOX FBR
Haz Non Hosp Empl:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Resp:	0				HMIS Bulk Incident:	No
Description of Events:					Undeclared Shipment:	No

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014050261	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	04/21/2014	Report Submit Src:	XML
Time of Incident:	1816	Inc Multiple Rows:	No
Haz Class Code:	5.1	Inc Non US State:	
Hazardous Class:	OXIDIZER	Mode Transport:	Highway
Commodity Short Nm:	TRICHLOROISOCYANURIC ACI	Transport Phase:	LOADING
Commodity Long Nm:	TRICHLOROISOCYANURIC ACID DRY	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN2468	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	CR Street Name:	1000 FED EX DR
Unit of Measure:	Solid - Pound	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	BIOLAB CONYERS GA
Cont1 Pkging Type:	Box	Shipper Street Name:	1350 LESTER RD NW
Cont1 Const Mat:	Fiberboard	Shipper City:	CONYERS
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30012-3906
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	423630401673489
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	CONYERS
Cont1 Pkg Mnfctr:		Origin State:	GEORGIA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Mnfct Dt: Cont1 Pkg Serial NO: C1 Pkg Last Test Dt: C1 Test Const Mat: Fiberboard C1 Pkg Dsign Pres.: C1 Dsign Press UOM: C1 Pkg Shell Thick: C1 Shell Thick UOM: C1 Head Thickness: C1 Head Thick UOM: C1 Pkg Srvc Pres.: C1 Srvc Press UOM: C1 Valve/Device Fail?: No C1 Device Type: C1 Device Mnfctr: C1 Device Model: NRC No:					Origin Postal: 30012 Origin Non US St: Origin Country: US Destination City: SUWANEE Destination State: GEORGIA Destination Postal: 30024 Destination Non US: Destination Country: US Cont2 Package Type: Can Cont2 Const Mat: Plastic Cont2 Pkg Capacity: Cont2 Capacity UOM: Cont2 Pkg Amount: Cont2 Pkg Amt UOM: Cont2 Pkg No: Cont2 Pkg No Failed:	
RAM Pkg Category: RAM Pkg Cert.: FALSE RAM Pkg Cert. NBR: RAM Nuclide S: RAM Transport Index: RAM UOM: RAM Activity Rpted: RAM UOM Rpted: RAM Activity: 0 RAM Activity UOM: RAM Mat Safety: Spillage Result: Yes Fire Result: No Explosion Result: No Water Sewer Result: No Gas Dispersion: No Environment Damage: No No Release Result: No Fire EMS Report: No Fire EMS EMS Report: Police Report: No Police Report No: In House Cleanup: Yes Other Cleanup: No Damage > 500: No Material Loss: 0 Carrier Damage: 0 Property Damage: 0 Response Cost: 0 Remediation Cost: 0 Damage Old Form: 0 Total Damages Amt: 0 Hazmat Fatality: No Haz Fatal Employees: 0 Haz Fatal Respntrs: 0 Haz Fatal Gen Public: 0 Tot Hazmat Fatalities: 0 Non Hazmat Fatality: No Non Hazmat Fatals: 0 Hazmat Injury: No Haz Hospital Empl: 0 Haz Hospital Resp: 0 Haz Hosp Gen Public: 0 Haz Hosp Old Form: 0 Total Haz Hosp Inj: 0 Haz Non Hosp Empl: 0 Haz Non Hosp Resp: 0 Description of Events:					Haz NonHosp Public: 0 Haz NonHosp Old: 0 Tot Haz Non Hosp Inj: 0 Total Hazmat Injuries: 0 Evacuation Indicator: No Public Evacuated: 0 Employees Evac: 0 Total Evacuated: 0 Total Evacuation Hrs: 0 Major Artery Closed: No Mjr Artery Hrs Closed: 0 Material Involved: No Estimated Speed: 0 Weather Conditions: Vehicle Overturn: No Vehicle Left Roadway: No Passenger Aircraft: No Cargo Baggage: Ship Non Transport: No Ship Air First Flight: No Ship Air Subflight: No Ship Init Transport: No Ship Phase Transfer: No Contact Name: GEORGE FETSKO Contact Title: HAZMAT - SAFETY ADVISOR Contact Business: Fedex Ground Package System Inc. Contact Street: 1000 Fedex Drive Contact City: CORAOPOLIS Contact State: PA Contact Postal: 15108 Contact Non US St: Contact Country: US Inc. Report Prepared: Carrier HMIS Serious Incidnt: No HMIS Serious Fatality: No HMIS Serious Injury: No HMIS Flight Plan: No HMIS Serious Evacs: No HMIS Major Artery: No HMIS Bulk Release: No HMIS Marine Pollutnt: No HMIS Radioactive: No HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt HMIS Container Code: BOX FBR HMIS Container Desc: Fiberboard box or carton HMIS Bulk Incident: No Undeclared Shipment: No	
Recommend Actions Taken:						
The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>HMIR Historical Reports</u>						
Report No:	X-2017110063				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	10/06/2017				Report Submit Src:	XML
Time of Incident:	0012				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	METHANOL				Transport Phase:	LOADING
Commodity Long Nm:	METHANOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1230				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.001308				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:	4g/y25/s/16/usa/m5586				Shipper Name:	MCKESSON MEDICAL-SURGICAL TOP HOLDINGS INC.
Cont1 Pkging Type:					Shipper Street Name:	1005 SATELLITE BLVD NW # 100
Cont1 Const Mat:					Shipper City:	SUWANEE
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30024-2882
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	1146899664833599331
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	SUWANEE
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:					Origin Postal:	30024
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	CLARKSVILLE
C1 Pkg Dsign Pres.:					Destination State:	TENNESSEE
C1 Dsign Press UOM:					Destination Postal:	37040
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2017090210				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	08/16/2017				Report Submit Src:	XML
Time of Incident:	0647				Inc Multiple Rows:	No
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI				Transport Phase:	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.264180				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:					Shipper Name:	ECOLAB INC.
Cont1 Pkging Type:	Box				Shipper Street Name:	90 PIEDMONT INDUSTRIAL DR
Cont1 Const Mat:	Fiberboard				Shipper City:	WINSTON SALEM
Cont1 Head Type:					Shipper State:	NC
Cont1 Pkg Capacity:					Shipper Postal:	27107-6876

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	75777167577716828313
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	WINSTON SALEM
Cont1 Pkg Mnfctr:					Origin State:	NORTH CAROLINA
Cont1 Pkg Mnfct Dt:					Origin Postal:	27107
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	DULUTH
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30096
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:		The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2017090211				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	08/17/2017				Report Submit Src:	XML
Time of Incident:	1203				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	ETHANOL SOLUTIONS				Transport Phase:	UNLOADING
Commodity Long Nm:	ETHANOL SOLUTIONS				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1170				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.264180				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:					Shipper Name:	DECON LABORATORIES INC.
Cont1 Pkging Type:	Jerrican				Shipper Street Name:	460 GLENNIE CIR
Cont1 Const Mat:	Plastic				Shipper City:	KING OF PRUSSIA
Cont1 Head Type:					Shipper State:	PA
Cont1 Pkg Capacity:	0				Shipper Postal:	19406-2682
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	695774779988220985
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	KING OF PRUSSIA
Cont1 Pkg Mnfctr:					Origin State:	PENNSYLVANIA
Cont1 Pkg Mnfcct Dt:					Origin Postal:	19406
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	PAIL PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic pail open head capacity 10 gallons or less
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2016120062	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	11/02/2016	Report Submit Src:	XML
Time of Incident:	2155	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	GASOLINE INCLUDES GASOLI	Transport Phase:	LOADING
Commodity Long Nm:	GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL WITH NOT MORE THAN 10% ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1203	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.007812	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:	4g/y28/s/15 usa/+BR9196			Shipper Name:	MOTIVA ENTERPRISES LLC	
Cont1 Pkging Type:				Shipper Street Name:	4201 WINTERS CHAPEL RD	
Cont1 Const Mat:				Shipper City:	ATLANTA	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:				Shipper Postal:	30360-3150	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	4275417665207850618	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	DORAVILLE	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfc Dt:				Origin Postal:	30360	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:				Destination City:	TIFTON	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	31794	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2013050256				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	04/16/2013				Report Submit Src:	XML
Time of Incident:	1700				Inc Multiple Rows:	No
Haz Class Code:	5.1				Inc Non US State:	
Hazardous Class:	OXIDIZER				Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE				Transport Phase:	LOADING
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES STABILIZED WITH ACIDS WATER AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN3149				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.039062				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:	4G/Y6.1/S/13USA/AA4750				Shipper Name:	STERIS CORPORATION
Cont1 Pkging Type:					Shipper Street Name:	8525 PAGE AVE
Cont1 Const Mat:					Shipper City:	SAINT LOUIS
Cont1 Head Type:					Shipper State:	MO
Cont1 Pkg Capacity:					Shipper Postal:	63114-6014
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	63106970969350
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	BRECKENRIDGE HILLS
Cont1 Pkg Mnfctr:					Origin State:	MISSOURI
Cont1 Pkg Mnfc Dt:					Origin Postal:	63114
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Device Mnfctr:			Cont2 Pkg No:			
C1 Device Model:			Cont2 Pkg No Failed:			
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	Moon Township	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respntrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2015090258	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	08/20/2015	Report Submit Src:	XML
Time of Incident:	1000	Inc Multiple Rows:	No
Haz Class Code:	5.1	Inc Non US State:	
Hazardous Class:	OXIDIZER	Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AQUEO	Transport Phase:	IN TRANSIT
Commodity Long Nm:	HYDROGEN PEROXIDE AQUEOUS SOLUTIONS WITH NOT LESS THAN 20 PERCENT BUT NOT MORE THAN 40	Incident Occrrnce:	

DB

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2012100044	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	09/06/2012	Report Submit Src:	XML
Time of Incident:	2130	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	HYDROCHLORIC ACID SOLUT	Transport Phase:	UNLOADING
Commodity Long Nm:	HYDROCHLORIC ACID SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1789	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.528360	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	305	CR Non US State:	
How Failed Desc:	Crushed	CR Fed DOT ID:	265752
Failure Cause Code:	534	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Too Much Weight on Package	CR Country:	US
Ident. Markings:	4G/Y32/S/12	Shipper Name:	VWR INTERNATIONAL LLC
Cont1 Pkging Type:		Shipper Street Name:	1050 SATELLITE BLVD NW
Cont1 Const Mat:		Shipper City:	SUWANEE
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:		Shipper Postal:	30024-2883
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	408394871018027
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	SUWANEE
Cont1 Pkg Mnfctr:		Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:		Origin Postal:	30024
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:		Destination City:	COLUMBUS
C1 Pkg Dsgn Pres.:		Destination State:	MISSISSIPPI

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Dsign Press UOM:				Destination Postal:		39701
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:		US
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?: No				Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:		0
RAM Pkg Cert.: FALSE				Haz NonHosp Old:		0
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		0
RAM Nuclide S:				Total Hazmat Injuries:		0
RAM Transport Index:				Evacuation Indicator:		No
RAM UOM:				Public Evacuated:		0
RAM Activity Rpted:				Employees Evac:		0
RAM UOM Rpted:				Total Evacuated:		0
RAM Activity:				Total Evacuation Hrs:		0
RAM Activity UOM:				Major Artery Closed:		No
RAM Mat Safety:				Mjr Artery Hrs Closed:		0
Spillage Result: Yes				Material Involved:		No
Fire Result: No				Estimated Speed:		0
Explosion Result: No				Weather Conditions:		
Water Sewer Result: No				Vehicle Overturn:		No
Gas Dispersion: No				Vehicle Left Roadway:		No
Environment Damage: No				Passenger Aircraft:		No
No Release Result: No				Cargo Baggage:		
Fire EMS Report: No				Ship Non Transport:		No
Fire EMS EMS Report:				Ship Air First Flight:		No
Police Report: No				Ship Air Subflight:		No
Police Report No:				Ship Init Transport:		No
In House Cleanup: Yes				Ship Phase Transfer:		No
Other Cleanup: No				Contact Name:		GEORGE FETSKO
Damage > 500: No				Contact Title:		SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss: 0				Contact Business:		Fedex Ground Package System Inc.
Carrier Damage: 0				Contact Street:		1000 Fedex Drive
Property Damage: 0				Contact City:		Moon Township
Response Cost: 0				Contact State:		PA
Remediation Cost: 0				Contact Postal:		15108
Damage Old Form: 0				Contact Non US St:		
Total Damages Amt: 0				Contact Country:		US
Hazmat Fatality: No				Inc. Report Prepared:		Carrier
Haz Fatal Employees: 0				HMIS Serious Incidnt:		No
Haz Fatal Respndrs: 0				HMIS Serious Fatality:		No
Haz Fatal Gen Public: 0				HMIS Serious Injury:		No
Tot Hazmat Fatalities: 0				HMIS Flight Plan:		No
Non Hazmat Fatality: No				HMIS Serious Evacs:		No
Non Hazmat Fatals: 0				HMIS Major Artery:		No
Hazmat Injury: No				HMIS Bulk Release:		No
Haz Hospital Empl: 0				HMIS Marine Pollutnt:		No
Haz Hospital Resp: 0				HMIS Radioactive:		No
Haz Hosp Gen Public: 0				HMIS Gen Pkg Type:		OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form: 0				HMIS Container Code:		4G
Total Haz Hosp Inj: 0				HMIS Container Desc:		Fiberboard box
Haz Non Hosp Empl: 0				HMIS Bulk Incident:		No
Haz Non Hosp Resp: 0				Undeclared Shipment:		No
Description of Events:		The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.				

Recommend Actions Taken:

HMIR Historical Reports

Report No: X-2018050771

Fed DOT Agency Nm:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	05/01/2018			Report Submit Src:	XML	
Time of Incident:	2300			Inc Multiple Rows:	No	
Haz Class Code:	3			Inc Non US State:		
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID			Mode Transport:	Highway	
Commodity Short Nm:	PRINTING INK FLAMMABLE			Transport Phase:	UNLOADING	
Commodity Long Nm:	PRINTING INK FLAMMABLE OR PRINTING INK RELATED MATERIAL (INCLUDING PRINTING INK THINNING OR REDUCING COMPOUND) FLAMMABLE			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1210			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:	0.0625			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g. Cap Top or Plug)			CR Postal Code:	15108-9373	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:	NO MARKINGS GIVEN			Shipper Name:	GEORGIA GRAPHICS INC	
Cont1 Pkging Type:	Jerrican			Shipper Street Name:	7055 AMWILER INDSTR L E	
Cont1 Const Mat:	Aluminum			Shipper City:	ATLANTA	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:				Shipper Postal:	30360-2833	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	30738232666947	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	ATLANTA	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfc Dt:				Origin Postal:	30360	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Aluminum			Destination City:	SANFORD	
C1 Pkg Dsign Pres.:				Destination State:	FLORIDA	
C1 Dsign Press UOM:				Destination Postal:	32771	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	NO MARKI
Total Haz Hosp Inj:	0				HMIS Container Desc:	
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: BOX WAS FOUND WET ON DOCK. AS I LOOKED INSIDE THERE WAS 2 1G AL CANS OF METERING ROLLER CLEANER WITH LOOSE CAPS New Comments:					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2015040260	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	03/19/2015	Report Submit Src:	XML
Time of Incident:	2345	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	ETHANOL OR ETHYL ALCOHOL	Transport Phase:	IN TRANSIT
Commodity Long Nm:	ETHANOL OR ETHYL ALCOHOL OR ETHANOL SOLUTIONS OR ETHYL ALCOHOL SOLUTIONS	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1170	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108-9373
How Failed Code:	309	CR Non US State:	
How Failed Desc:	Punctured	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:		Shipper Name:	RICHARD-ALLAN SCIENTIFIC COMPANY
Cont1 Pkging Type:	Box	Shipper Street Name:	4481 CAMPUS DR
Cont1 Const Mat:	Fiberboard	Shipper City:	KALAMAZOO
Cont1 Head Type:		Shipper State:	MI
Cont1 Pkg Capacity:		Shipper Postal:	49008-2590
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Amt UOM:					Shipper Waybill:	49002119935067
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	KALAMAZOO
Cont1 Pkg Mnfctr:					Origin State:	MICHIGAN
Cont1 Pkg Mnfct Dt:					Origin Postal:	49008
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Description of Events:		The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2017110330			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	10/19/2017			Report Submit Src:	XML	
Time of Incident:	1810			Inc Multiple Rows:	No	
Haz Class Code:	8			Inc Non US State:		
Hazardous Class:	CORROSIVE MATERIAL			Mode Transport:	Highway	
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI			Transport Phase:	UNLOADING	
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1824			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:	1			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g. Cap Top or Plug)			CR Postal Code:	15108-9373	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	ECOLAB INC.	
Cont1 Pkging Type:	Drum			Shipper Street Name:	125 SOUTHSIDE CT STE 100	
Cont1 Const Mat:	Plastic			Shipper City:	MCDONOUGH	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:	0			Shipper Postal:	30253-7448	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	889030128842663	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	MCDONOUGH	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfct Dt:				Origin Postal:	30253	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Plastic			Destination City:	MCDONOUGH	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30253	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014060045	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	05/06/2014	Report Submit Src:	XML
Time of Incident:	1638	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	PETROLEUM PRODUCTS N.O.	Transport Phase:	LOADING
Commodity Long Nm:	PETROLEUM PRODUCTS N.O.S.	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1268	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.25	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	311	CR Non US State:	
How Failed Desc:	Structural	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	N/A
Cont1 Pkgng Type:	Box	Shipper Street Name:	ILLEGIBLE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Const Mat:	Fiberboard				Shipper City:	NORCROSS
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30071
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	111111111111111
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	NORCROSS
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:					Origin Postal:	30071
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	NORCROSS
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30071
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2017110329				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	10/19/2017				Report Submit Src:	XML
Time of Incident:	0411				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	ETHANOL OR ETHYL ALCOHOL				Transport Phase:	LOADING
Commodity Long Nm:	ETHANOL OR ETHYL ALCOHOL OR ETHANOL SOLUTIONS OR ETHYL ALCOHOL SOLUTIONS				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1170				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.039062				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	305				CR Non US State:	
How Failed Desc:	Crushed				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:	4G/X1.5/S/11/USA/AA0747				Shipper Name:	KMX CHEMICAL CORP.
Cont1 Pkging Type:					Shipper Street Name:	30474 ENERGY DR
Cont1 Const Mat:					Shipper City:	NEW CHURCH
Cont1 Head Type:					Shipper State:	VA
Cont1 Pkg Capacity:					Shipper Postal:	23415
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	244767760003918
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	NEW CHURCH
Cont1 Pkg Mnfctr:					Origin State:	VIRGINIA
Cont1 Pkg Mnfc Dt:					Origin Postal:	23415
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	CUMMING
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30040
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:		The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.				

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2017120331	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	11/24/2017	Report Submit Src:	XML
Time of Incident:	1700	Inc Multiple Rows:	No
Haz Class Code:	5.1	Inc Non US State:	
Hazardous Class:	OXIDIZER	Mode Transport:	Highway
Commodity Short Nm:	CALCIUM HYPOCHLORITE HY	Transport Phase:	UNLOADING
Commodity Long Nm:	CALCIUM HYPOCHLORITE HYDRATED OR CALCIUM HYPOCHLORITE HYDRATED MIXTURES WITH NOT LESS THAN 5.5 PERCENT BUT NOT MORE THAN 16 PERCENT WATER	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN2880	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	Yes
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
TIH Hazard Zone:			Carrier Reporter:			FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	15			CR Street Name:	1000 FED EX DR	
Unit of Measure:	Solid - Pound			CR City:	CORAOPOLIS	
What Failed:	104			CR State:	PA	
What Failed Desc:	Body			CR Postal Code:	15108-9373	
How Failed Code:	303			CR Non US State:		
How Failed Desc:	Burst or Ruptured			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure Component or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	ECOLAB INC.	
Cont1 Pkging Type:	Drum			Shipper Street Name:	125 SOUTHSIDE CT STE 100	
Cont1 Const Mat:	Metal other than steel or aluminum			Shipper City:	MCDONOUGH	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:	0			Shipper Postal:	30253-7448	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	889030132953331	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	MCDONOUGH	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfct Dt:				Origin Postal:	30253	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Metal other than steel or aluminum			Destination City:	ORMOND BEACH	
C1 Pkg Dsign Pres.:				Destination State:	FLORIDA	
C1 Dsign Press UOM:				Destination Postal:	32174	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM MTL
Total Haz Hosp Inj:	0				HMIS Container Desc:	Metal drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	Yes
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2013030227	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	02/25/2013	Report Submit Src:	XML
Time of Incident:	1654	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC	Transport Phase:	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUID BASIC INORGANIC N. O.S.	Incident Occrrnce:	
Trade Name:	contains Phosphates	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	2	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108-9373
How Failed Code:	305	CR Non US State:	
How Failed Desc:	Crushed	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:		Shipper Name:	A.B.C. COMPOUNDING COMPANY INC.
Cont1 Pkging Type:	Box	Shipper Street Name:	2600 DOGWOOD DR SE
Cont1 Const Mat:	Fiberboard	Shipper City:	CONYERS
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30013-1503
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	31858262223176
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	LAKE CITY
Cont1 Pkg Mnfctr:		Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:		Origin Postal:	30260
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Fiberboard	Destination City:	SUWANEE
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30024
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	Bottle
C1 Head Thick UOM:		Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:		Cont2 Pkg Capacity:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:		
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:		
RAM Transport Index:				Evacuation Indicator:		
RAM UOM:				Public Evacuated:		
RAM Activity Rpted:				Employees Evac:		
RAM UOM Rpted:				Total Evacuated:		
RAM Activity:	0			Total Evacuation Hrs:		
RAM Activity UOM:				Major Artery Closed:		
RAM Mat Safety:				Mjr Artery Hrs Closed:		
Spillage Result:	Yes			Material Involved:		
Fire Result:	No			Estimated Speed:		
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:		
Gas Dispersion:	No			Vehicle Left Roadway:		
Environment Damage:	No			Passenger Aircraft:		
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:		
Fire EMS EMS Report:				Ship Air First Flight:		
Police Report:	No			Ship Air Subflight:		
Police Report No:				Ship Init Transport:		
In House Cleanup:	Yes			Ship Phase Transfer:		
Other Cleanup:	No			Contact Name:		
Damage > 500:	No			Contact Title:		
Material Loss:	0			Contact Business:		
Carrier Damage:	0			Contact Street:		
Property Damage:	0			Contact City:		
Response Cost:	0			Contact State:		
Remediation Cost:	0			Contact Postal:		
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:		
Hazmat Fatality:	No			Inc. Report Prepared:		
Haz Fatal Employees:	0			HMIS Serious Incidnt:		
Haz Fatal Respndrs:	0			HMIS Serious Fatality:		
Haz Fatal Gen Public:	0			HMIS Serious Injury:		
Tot Hazmat Fatalities:	0			HMIS Flight Plan:		
Non Hazmat Fatality:	No			HMIS Serious Evacs:		
Non Hazmat Fatals:	0			HMIS Major Artery:		
Hazmat Injury:	No			HMIS Bulk Release:		
Haz Hospital Empl:	0			HMIS Marine Pollutnt:		
Haz Hospital Resp:	0			HMIS Radioactive:		
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:		
Haz Hosp Old Form:	0			HMIS Container Code:		
Total Haz Hosp Inj:	0			HMIS Container Desc:		
Haz Non Hosp Empl:	0			HMIS Bulk Incident:		
Haz Non Hosp Resp:	0			Undeclared Shipment:		
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2018040299			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	03/22/2018			Report Submit Src:		
Time of Incident:	1400			Inc Multiple Rows:		
Haz Class Code:	8			Inc Non US State:		
Hazardous Class:	CORROSIVE MATERIAL			Mode Transport:		
Commodity Short Nm:	CORROSIVE LIQUID BASIC			Transport Phase:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Commodity Long Nm:		CORROSIVE LIQUID BASIC INORGANIC N.		Incident Occrrnce:		
Trade Name:		O.S.		Mat Ship Approval?:	No	
ID No:		sodium hydroxide		Mat Ship Approv No:		
Haz Waste Ind:		UN3266		Undecl Hazmat Ship?:	No	
Haz Waste EPA No:		No		Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:		No		Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.	
Qty Released:		0.1875		CR Street Name:	1000 FED EX DR	
Unit of Measure:		Liquid - Gallon		CR City:	CORAOPOLIS	
What Failed:		109		CR State:	PA	
What Failed Desc:		Closure (e.g. Cap Top or Plug)		CR Postal Code:	15108-9373	
How Failed Code:		308		CR Non US State:		
How Failed Desc:		Leaked		CR Fed DOT ID:	265752	
Failure Cause Code:		526		CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:		Loose Closure Component or Device		CR Country:	US	
Ident. Markings:				Shipper Name:	A.B.C. COMPOUNDING COMPANY INC.	
Cont1 Pkging Type:		Jerrican		Shipper Street Name:	2600 DOGWOOD DR SE	
Cont1 Const Mat:		Steel		Shipper City:	CONYERS	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:		1		Shipper Postal:	30013-1503	
C1 Capacity UOM:		LGA		Shipper Non US St:		
Cont1 Pkg Amt:		1		Shipper Country:	US	
C1 Pkg Amt UOM:		LGA		Shipper Waybill:	318582412826165864	
Cont1 Pkg No:		4		Ship Hazmat Reg ID:		
C1 Pkg NO Failed:		4		Origin City:	CONYERS	
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfct Dt:				Origin Postal:	30013	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:		Steel		Destination City:	SUWANEE	
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30024	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:	Can	
C1 Head Thick UOM:				Cont2 Const Mat:	Metal (any type)	
C1 Pkg Srvs Pres.:				Cont2 Pkg Capacity:		
C1 Srvs Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:		No		Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:		FALSE		Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:		Yes		Material Involved:	No	
Fire Result:		No		Estimated Speed:	0	
Explosion Result:		No		Weather Conditions:		
Water Sewer Result:		No		Vehicle Overturn:	No	
Gas Dispersion:		No		Vehicle Left Roadway:	No	
Environment Damage:		No		Passenger Aircraft:	No	
No Release Result:		No		Cargo Baggage:		
Fire EMS Report:		No		Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:		No		Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:		Yes		Ship Phase Transfer:	No	
Other Cleanup:		No		Contact Name:	GEORGE FETSKO	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	CONT
Total Haz Hosp Inj:	0				HMIS Container Desc:	Container no description given (do not use if at all possible)
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: BOX WAS FOUND ON DOCK WET. AS I LOOKED INSIDE THE BOX THERE WERE 4 1GAL JUGS OF BRANSON GP FORMULATED CLEANING CONCENTRATE. ALL 4 JUGS HAD LOOSE CAPS. New Comments:					
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2017120248				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	11/15/2017				Report Submit Src:	XML
Time of Incident:	0830				Inc Multiple Rows:	No
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI				Transport Phase:	IN TRANSIT
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.10				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	ECOLAB INC.
Cont1 Pkging Type:	Box				Shipper Street Name:	90 PIEDMONT INDUSTRIAL DR
Cont1 Const Mat:	Fiberboard				Shipper City:	WINSTON SALEM
Cont1 Head Type:					Shipper State:	NC
Cont1 Pkg Capacity:					Shipper Postal:	27107-6876
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	7577716757771683020456
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	WINSTON SALEM
Cont1 Pkg Mnfctr:					Origin State:	NORTH CAROLINA
Cont1 Pkg Mnft Dt:					Origin Postal:	27107
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Dsign Pres.:				Destination State:		GEORGIA
C1 Dsign Press UOM:				Destination Postal:		30329
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:		US
C1 Head Thickness:				Cont2 Package Type:		Bottle
C1 Head Thick UOM:				Cont2 Const Mat:		Plastic
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?: No				Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:		0
RAM Pkg Cert.:				Haz NonHosp Old:		0
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		0
RAM Nuclide S:				Total Hazmat Injuries:		0
RAM Transport Index:				Evacuation Indicator:		No
RAM UOM:				Public Evacuated:		0
RAM Activity Rpted:				Employees Evac:		0
RAM UOM Rpted:				Total Evacuated:		0
RAM Activity:				Total Evacuation Hrs:		0
RAM Activity UOM:				Major Artery Closed:		No
RAM Mat Safety:				Mjr Artery Hrs Closed:		0
Spillage Result:				Material Involved:		No
Fire Result:				Estimated Speed:		0
Explosion Result:				Weather Conditions:		
Water Sewer Result:				Vehicle Overturn:		No
Gas Dispersion:				Vehicle Left Roadway:		No
Environment Damage:				Passenger Aircraft:		No
No Release Result:				Cargo Baggage:		
Fire EMS Report:				Ship Non Transport:		No
Fire EMS EMS Report:				Ship Air First Flight:		No
Police Report:				Ship Air Subflight:		No
Police Report No:				Ship Init Transport:		No
In House Cleanup:				Ship Phase Transfer:		No
Other Cleanup:				Contact Name:		GEORGE FETSKO
Damage > 500:				Contact Title:		HAZMAT - SAFETY ADVISOR
Material Loss:				Contact Business:		Fedex Ground Package System Inc.
Carrier Damage:				Contact Street:		1000 Fedex Drive
Property Damage:				Contact City:		CORAOPOLIS
Response Cost:				Contact State:		PA
Remediation Cost:				Contact Postal:		15108
Damage Old Form:				Contact Non US St:		
Total Damages Amt:				Contact Country:		US
Hazmat Fatality:				Inc. Report Prepared:		Carrier
Haz Fatal Employees:				HMIS Serious Incidnt:		No
Haz Fatal Respndrs:				HMIS Serious Fatality:		No
Haz Fatal Gen Public:				HMIS Serious Injury:		No
Tot Hazmat Fatalities:				HMIS Flight Plan:		No
Non Hazmat Fatality:				HMIS Serious Evacs:		No
Non Hazmat Fatals:				HMIS Major Artery:		No
Hazmat Injury:				HMIS Bulk Release:		No
Haz Hospital Empl:				HMIS Marine Pollutnt:		No
Haz Hospital Resp:				HMIS Radioactive:		No
Haz Hosp Gen Public:				HMIS Gen Pkg Type:		OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:				HMIS Container Code:		BOX FBR
Total Haz Hosp Inj:				HMIS Container Desc:		Fiberboard box or carton
Haz Non Hosp Empl:				HMIS Bulk Incident:		No
Haz Non Hosp Resp:				Undeclared Shipment:		No
Description of Events:				The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.		

Recommend Actions Taken:

HMIR Historical Reports

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report No:	X-2012100064				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	09/07/2012				Report Submit Src:	XML
Time of Incident:	2247				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	HEXANES				Transport Phase:	LOADING
Commodity Long Nm:	HEXANES				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1208				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.528360				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108-9373
How Failed Code:	303				CR Non US State:	
How Failed Desc:	Burst or Ruptured				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:	4G/Y28.1/S/12				Shipper Name:	FISHER SCIENTIFIC COMPANY LLC
Cont1 Pkging Type:					Shipper Street Name:	2775 HORIZON RIDGE CT
Cont1 Const Mat:					Shipper City:	SUWANEE
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30024-3592
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	39064577779242
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	SUWANEE
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:					Origin Postal:	30024
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	GULFPORT
C1 Pkg Dsign Pres.:					Destination State:	MISSISSIPPI
C1 Dsign Press UOM:					Destination Postal:	39501
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2018040130	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	03/12/2018	Report Submit Src:	XML
Time of Incident:	2345	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL	Transport Phase:	UNLOADING
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1219	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.1250	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:	4G/Y26.9/S17/USA/+AA7295	Shipper Name:	FISHER SCIENTIFIC COMPANY LLC
Cont1 Pkging Type:		Shipper Street Name:	2775 HORIZON RIDGE CT
Cont1 Const Mat:		Shipper City:	SUWANEE
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:		Shipper Postal:	30024-3592
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:		Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	39064596123020390645724812
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	SUWANEE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Mnfctr:				Origin State:	GEORGIA	
Cont1 Pkg Mnfct Dt:				Origin Postal:	30024	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:				Destination City:	ORLANDO	
C1 Pkg Dsign Pres.:				Destination State:	FLORIDA	
C1 Dsign Press UOM:				Destination Postal:	32827	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:	0	
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respntrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatais:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:						
Recommend Actions Taken:						

Original comments: Package was found on the dock wet. As I looked inside I notice 4 1gal bottles of isopropanol but 1 bottle had a loose cap New Comments:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>HMIR Historical Reports</u>						
Report No:	X-2018080555				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	07/21/2018				Report Submit Src:	XML
Time of Incident:	0045				Inc Multiple Rows:	No
Haz Class Code:	8				Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL				Mode Transport:	Highway
Commodity Short Nm:	COMPOUNDS CLEANING LIQU				Transport Phase:	UNLOADING
Commodity Long Nm:	COMPOUNDS CLEANING LIQUID				Incident Occrrnce:	
Trade Name:	containing Potassium				Mat Ship Approval?:	No
ID No:	NA1760				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	2				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	GEORGIA CHEMICAL EQUIPMENT CO INC
Cont1 Pkging Type:	Drum				Shipper Street Name:	1580 BEAVER RUIN RD
Cont1 Const Mat:	Plastic				Shipper City:	NORCROSS
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30093-2801
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	5693903569444795473
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	NORCROSS
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:					Origin Postal:	30093
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	FORT WALTON BEACH
C1 Pkg Dsign Pres.:					Destination State:	FLORIDA
C1 Dsign Press UOM:					Destination Postal:	32547
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	No
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:	No				Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:	No				Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	
Total Haz Hosp Inj:	0				HMIS Container Desc:	
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: BOX WAS FOUND ON DOCK WET. AS I LOOKED INSIDE THERE WAS 5GAL PLASTIC DRUM OF HOOD CLEANER WITH A LOOSE CAP New Comments:					
Recommend Actions Taken:						

HMIR Historical Reports

Report No:	X-2013090197	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	08/21/2013	Report Submit Src:	XML
Time of Incident:	1641	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT L	Transport Phase:	UNLOADING
Commodity Long Nm:	PAINT INCLUDING PAINT LACQUER ENAMEL STAIN SHELLAC SOLUTIONS VARNISH POLISH LIQUID FILLER AND LIQUID LACQUER BASE	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1263	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108-9373
How Failed Code:	305	CR Non US State:	
How Failed Desc:	Crushed	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:		Shipper Name:	N/A
Cont1 Pkging Type:	Box	Shipper Street Name:	ILLEGIBLE
Cont1 Const Mat:	Fiberboard	Shipper City:	NORCROSS
Cont1 Head Type:		Shipper State:	GA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Capacity:					Shipper Postal:	30071
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	111111111111111
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	NORCROSS
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:					Origin Postal:	30071
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	NORCROSS
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30071
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:		The pail was dropped during handling causing leakage. The leakage was contained and the package was repacked. Undamaged product was returned to the shipper. The damaged product was properly disposed of in accordance with Federal Regulations.				
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2012100412				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	10/02/2012				Report Submit Src:	XML
Time of Incident:	0800				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	ACETONE				Transport Phase:	IN TRANSIT
Commodity Long Nm:	ACETONE				Incident Occrrnce:	
Trade Name:	na				Mat Ship Approval?:	No
ID No:	UN1090				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1.3209				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	304				CR Non US State:	
How Failed Desc:	Cracked				CR Fed DOT ID:	265752
Failure Cause Code:	515				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Human Error				CR Country:	US
Ident. Markings:	4G/X10.9/S/12/USA/M4109				Shipper Name:	SIGMA-ALDRICH CORPORATION
Cont1 Pkging Type:					Shipper Street Name:	6000 N TEUTONIA AVE
Cont1 Const Mat:					Shipper City:	MILWAUKEE
Cont1 Head Type:					Shipper State:	WI
Cont1 Pkg Capacity:					Shipper Postal:	53209-3645
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	36553821317376
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	BROWN DEER
Cont1 Pkg Mnfctr:					Origin State:	WISCONSIN
Cont1 Pkg Mnfc Dt:					Origin Postal:	53209
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	ROSWELL
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30076
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:		The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.				

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014070404	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	06/26/2014	Report Submit Src:	XML
Time of Incident:	1717	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	ACETONITRILE	Transport Phase:	LOADING
Commodity Long Nm:	ACETONITRILE	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1648	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.264180	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108-9373
How Failed Code:	303	CR Non US State:	
How Failed Desc:	Burst or Ruptured	CR Fed DOT ID:	265752
Failure Cause Code:	502	CR Hazmat Reg ID:	051910551007S

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Failure Cause Desc:	Broken Component or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	ALDRICH CHEMICAL CO. LLC	
Cont1 Pkging Type:	Box				Shipper Street Name:	6000 N TEUTONIA AVE
Cont1 Const Mat:	Fiberboard				Shipper City:	MILWAUKEE
Cont1 Head Type:				Shipper State:	WI	
Cont1 Pkg Capacity:				Shipper Postal:	53209-3645	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	36553832746080	
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:	BROWN DEER	
Cont1 Pkg Mnfctr:				Origin State:	WISCONSIN	
Cont1 Pkg Mnfcct Dt:				Origin Postal:	53209	
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:	US	
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:				Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30322	
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:				Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:	0	
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No				Ship Air Subflight:	No
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazmat Injury:		No			HMIS Bulk Release:	No
Haz Hospital Empl:		0			HMIS Marine Pollutnt:	No
Haz Hospital Resp:		0			HMIS Radioactive:	No
Haz Hosp Gen Public:		0			HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:		0			HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:		0			HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:		0			HMIS Bulk Incident:	No
Haz Non Hosp Resp:		0			Undeclared Shipment:	No
Description of Events:		The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:		X-2018050755		Fed DOT Agency Nm:		
Report Type:		A hazardous material incident		Fed DOT Report No:		
Date of Incident:		04/29/2018		Report Submit Src:		XML
Time of Incident:		2200		Inc Multiple Rows:		No
Haz Class Code:		8		Inc Non US State:		
Hazardous Class:		CORROSIVE MATERIAL		Mode Transport:		Highway
Commodity Short Nm:		SODIUM HYDROXIDE SOLUTI		Transport Phase:		UNLOADING
Commodity Long Nm:		SODIUM HYDROXIDE SOLUTION		Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:		No
ID No:		UN1824		Mat Ship Approv No:		
Haz Waste Ind:		No		Undecl Hazmat Ship?:		No
Haz Waste EPA No:				Packaging Type:		Non-Bulk
HMIS Tox Inhalation?:		No		Packing Group:		II
TIH Hazard Zone:				Carrier Reporter:		FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:		0.0625		CR Street Name:		1000 FED EX DR
Unit of Measure:		Liquid - Gallon		CR City:		CORAOPOLIS
What Failed:		109		CR State:		PA
What Failed Desc:		Closure (e.g. Cap Top or Plug)		CR Postal Code:		15108-9373
How Failed Code:		308		CR Non US State:		
How Failed Desc:		Leaked		CR Fed DOT ID:		265752
Failure Cause Code:		526		CR Hazmat Reg ID:		051910551007S
Failure Cause Desc:		Loose Closure Component or Device		CR Country:		US
Ident. Markings:		NO MARKINGS GIVEN		Shipper Name:		CEVA LOGISTICS
Cont1 Pkging Type:		Drum		Shipper Street Name:		125 SOUTHSIDE CT
Cont1 Const Mat:		Metal other than steel or aluminum		Shipper City:		MCDONOUGH
Cont1 Head Type:				Shipper State:		GA
Cont1 Pkg Capacity:				Shipper Postal:		30253-7448
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:				Shipper Country:		US
C1 Pkg Amt UOM:				Shipper Waybill:		91607907452718
Cont1 Pkg No:				Ship Hazmat Reg ID:		
C1 Pkg NO Failed:				Origin City:		MCDONOUGH
Cont1 Pkg Mnfctr:				Origin State:		GEORGIA
Cont1 Pkg Mnfc Dt:				Origin Postal:		30253
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:				Origin Country:		US
C1 Test Const Mat:		Metal other than steel or aluminum		Destination City:		ATLANTA
C1 Pkg Dsign Pres.:				Destination State:		GEORGIA
C1 Dsign Press UOM:				Destination Postal:		30329
C1 Pkg Shell Thick:				Destination Non US:		
C1 Shell Thick UOM:				Destination Country:		US
C1 Head Thickness:				Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:				Cont2 Pkg Capacity:		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:		No		Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:		0
RAM Pkg Cert.:		FALSE		Haz NonHosp Old:		0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	NO MARKI
Total Haz Hosp Inj:	0				HMIS Container Desc:	
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:		Original comments: bucket or pail was found on dock wet. as I examined the pail notice liquid was leaking from cap New Comments:				

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2012120290	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	11/28/2012	Report Submit Src:	XML
Time of Incident:	2135	Inc Multiple Rows:	No
Haz Class Code:	3	Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	Mode Transport:	Highway
Commodity Short Nm:	METHANOL	Transport Phase:	LOADING
Commodity Long Nm:	METHANOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1230	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	2.6418	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	139	CR State:	PA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
What Failed Desc:	O-Ring or Seals				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:	4G/Y16/S/11USA/HEDWIN				Shipper Name:	FISHER SCIENTIFIC COMPANY LLC
Cont1 Pkging Type:					Shipper Street Name:	2775 HORIZON RIDGE CT
Cont1 Const Mat:					Shipper City:	SUWANEE
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30024-3592
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	39064579110074
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	SUWANEE
Cont1 Pkg Mnfrct:					Origin State:	GEORGIA
Cont1 Pkg Mnfrct Dt:					Origin Postal:	30024
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:					Destination City:	ORLANDO
C1 Pkg Dsign Pres.:					Destination State:	FLORIDA
C1 Dsign Press UOM:					Destination Postal:	32806
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:					Cont2 Pkg Capacity:	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfrct:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014040244	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	03/18/2014	Report Submit Src:	XML
Time of Incident:	1631	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC	Transport Phase:	LOADING
Commodity Long Nm:	CORROSIVE LIQUID BASIC INORGANIC N. O.S.	Incident Occrrnce:	
Trade Name:	Sodium Hydroxide Alk	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.1250	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	NALCO COMPANY LLC
Cont1 Pkging Type:	Drum	Shipper Street Name:	7701 HIGHWAY 90A
Cont1 Const Mat:	Plastic	Shipper City:	SUGAR LAND
Cont1 Head Type:		Shipper State:	TX
Cont1 Pkg Capacity:	0	Shipper Postal:	77478-2121
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	532835511007
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	SUGAR LAND
Cont1 Pkg Mnfctr:		Origin State:	TEXAS
Cont1 Pkg Mnfct Dt:		Origin Postal:	77478
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Plastic	Destination City:	ATLANTA
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30324
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvc Pres.:		Cont2 Pkg Capacity:	
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	
C1 Device Type:		Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:		Cont2 Pkg No:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Device Model: NRC No:				Cont2 Pkg No Failed:		
RAM Pkg Category:				Haz NonHosp Public: 0		
RAM Pkg Cert.: FALSE				Haz NonHosp Old: 0		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj: 0		
RAM Nuclide S:				Total Hazmat Injuries: 0		
RAM Transport Index:				Evacuation Indicator: No		
RAM UOM:				Public Evacuated: 0		
RAM Activity Rpted:				Employees Evac: 0		
RAM UOM Rpted:				Total Evacuated: 0		
RAM Activity: 0				Total Evacuation Hrs: 0		
RAM Activity UOM:				Major Artery Closed: No		
RAM Mat Safety:				Mjr Artery Hrs Closed: 0		
Spillage Result: Yes				Material Involved: No		
Fire Result: No				Estimated Speed: 0		
Explosion Result: No				Weather Conditions:		
Water Sewer Result: No				Vehicle Overturn: No		
Gas Dispersion: No				Vehicle Left Roadway: No		
Environment Damage: No				Passenger Aircraft: No		
No Release Result: No				Cargo Baggage:		
Fire EMS Report: No				Ship Non Transport: No		
Fire EMS EMS Report:				Ship Air First Flight: No		
Police Report: No				Ship Air Subflight: No		
Police Report No:				Ship Init Transport: No		
In House Cleanup: Yes				Ship Phase Transfer: No		
Other Cleanup: No				Contact Name: GEORGE FETSKO		
Damage > 500: No				Contact Title: HAZMAT - SAFETY ADVISOR		
Material Loss: 0				Contact Business: Fedex Ground Package System Inc.		
Carrier Damage: 0				Contact Street: 1000 Fedex Drive		
Property Damage: 0				Contact City: CORAOPOLIS		
Response Cost: 0				Contact State: PA		
Remediation Cost: 0				Contact Postal: 15108		
Damage Old Form: 0				Contact Non US St:		
Total Damages Amt: 0				Contact Country: US		
Hazmat Fatality: No				Inc. Report Prepared: Carrier		
Haz Fatal Employees: 0				HMIS Serious Incidnt: No		
Haz Fatal Respndrs: 0				HMIS Serious Fatality: No		
Haz Fatal Gen Public: 0				HMIS Serious Injury: No		
Tot Hazmat Fatalities: 0				HMIS Flight Plan: No		
Non Hazmat Fatality: No				HMIS Serious Evacs: No		
Non Hazmat Fatals: 0				HMIS Major Artery: No		
Hazmat Injury: No				HMIS Bulk Release: No		
Haz Hospital Empl: 0				HMIS Marine Pollutnt: No		
Haz Hospital Resp: 0				HMIS Radioactive: No		
Haz Hosp Gen Public: 0				HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt		
Haz Hosp Old Form: 0				HMIS Container Code: DRUM PLS		
Total Haz Hosp Inj: 0				HMIS Container Desc: Plastic drum		
Haz Non Hosp Empl: 0				HMIS Bulk Incident: No		
Haz Non Hosp Resp: 0				Undeclared Shipment: No		
Description of Events:		The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
HMIR Historical Reports						
Report No:	X-2017110282			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	10/17/2017			Report Submit Src:	XML	
Time of Incident:	0600			Inc Multiple Rows:	No	
Haz Class Code:	8			Inc Non US State:		
Hazardous Class:	CORROSIVE MATERIAL			Mode Transport:	Highway	
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI			Transport Phase:	LOADING	
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1824			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	

DB

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2017110188	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	10/15/2017	Report Submit Src:	XML
Time of Incident:	1355	Inc Multiple Rows:	No
Haz Class Code:	8	Inc Non US State:	
Hazardous Class:	CORROSIVE MATERIAL	Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI	Transport Phase:	LOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1824	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	CR Postal Code:	15108-9373
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	ECOLAB INC.
Cont1 Pkging Type:	Drum	Shipper Street Name:	125 SOUTHSIDE CT STE 100
Cont1 Const Mat:	Plastic	Shipper City:	MCDONOUGH
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30253-7448
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	9160790128842687
Cont1 Pkg No:		Ship Hazmat Reg ID:	
C1 Pkg NO Failed:		Origin City:	MCDONOUGH
Cont1 Pkg Mnfctr:		Origin State:	GEORGIA
Cont1 Pkg Mnfc Dt:		Origin Postal:	30253
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:		Origin Country:	US
C1 Test Const Mat:	Plastic	Destination City:	MCDONOUGH
C1 Pkg Dsign Pres.:		Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30253
C1 Pkg Shell Thick:		Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:		Cont2 Package Type:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Head Thick UOM: C1 Pkg Srvc Pres.: C1 Srvc Press UOM: C1 Valve/Device Fail?: No C1 Device Type: C1 Device Mnfctr: C1 Device Model: NRC No: Cont2 Const Mat: Cont2 Pkg Capacity: Cont2 Capacity UOM: Cont2 Pkg Amount: Cont2 Pkg Amt UOM: Cont2 Pkg No: Cont2 Pkg No Failed:						
RAM Pkg Category: RAM Pkg Cert.: FALSE RAM Pkg Cert. NBR: RAM Nuclide S: RAM Transport Index: RAM UOM: RAM Activity Rpted: RAM UOM Rpted: RAM Activity: 0 RAM Activity UOM: RAM Mat Safety: Spillage Result: Yes Fire Result: No Explosion Result: No Water Sewer Result: No Gas Dispersion: No Environment Damage: No No Release Result: No Fire EMS Report: No Fire EMS EMS Report: Police Report: No Police Report No: In House Cleanup: Yes Other Cleanup: No Damage > 500: No Material Loss: 0 Carrier Damage: 0 Property Damage: 0 Response Cost: 0 Remediation Cost: 0 Damage Old Form: 0 Total Damages Amt: 0 Hazmat Fatality: No Haz Fatal Employees: 0 Haz Fatal Respntrs: 0 Haz Fatal Gen Public: 0 Tot Hazmat Fatalities: 0 Non Hazmat Fatality: No Non Hazmat Fatals: 0 Hazmat Injury: No Haz Hospital Empl: 0 Haz Hospital Resp: 0 Haz Hosp Gen Public: 0 Haz Hosp Old Form: 0 Total Haz Hosp Inj: 0 Haz Non Hosp Empl: 0 Haz Non Hosp Resp: 0 Description of Events: Haz NonHosp Public: 0 Haz NonHosp Old: 0 Tot Haz Non Hosp Inj: 0 Total Hazmat Injuries: 0 Evacuation Indicator: No Public Evacuated: 0 Employees Evac: 0 Total Evacuated: 0 Total Evacuation Hrs: 0 Major Artery Closed: No Mjr Artery Hrs Closed: 0 Material Involved: No Estimated Speed: 0 Weather Conditions: Vehicle Overturn: No Vehicle Left Roadway: No Passenger Aircraft: No Cargo Baggage: Ship Non Transport: No Ship Air First Flight: No Ship Air Subflight: No Ship Init Transport: No Ship Phase Transfer: No Contact Name: GEORGE FETSKO Contact Title: HAZMAT - SAFETY ADVISOR Contact Business: Fedex Ground Package System Inc. Contact Street: 1000 Fedex Drive Contact City: CORAOPOLIS Contact State: PA Contact Postal: 15108 Contact Non US St: Contact Country: US Inc. Report Prepared: Carrier HMIS Serious Incidnt: No HMIS Serious Fatality: No HMIS Serious Injury: No HMIS Flight Plan: No HMIS Serious Evacs: No HMIS Major Artery: No HMIS Bulk Release: No HMIS Marine Pollutnt: No HMIS Radioactive: No HMIS Gen Pkg Type: OHMIR.Ref_Container.descr_txt HMIS Container Code: DRUM PLS HMIS Container Desc: Plastic drum HMIS Bulk Incident: No Undeclared Shipment: No						
Recommend Actions Taken:			The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.			
<u>7</u>	6 of 13	NE	0.12 / 612.03	1,013.74 / 1	6265 Atlanttic Blvd NORCROSS GA	HMIRS
Incident County:		GWINNETT				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
HMIR Historical Reports						
Report No:	X-2015100233				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	09/18/2015				Report Submit Src:	XML
Time of Incident:	2335				Inc Multiple Rows:	No
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT L				Transport Phase:	IN TRANSIT
Commodity Long Nm:	PAINT INCLUDING PAINT LACQUER ENAMEL STAIN SHELLAC SOLUTIONS VARNISH POLISH LIQUID FILLER AND LIQUID LACQUER BASE				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1263				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	I
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.1250				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	SHERWIN WILLIAMS DISTRIBUTION
Cont1 Pkging Type:	Box				Shipper Street Name:	930 SHERWIN PKWY
Cont1 Const Mat:	Fiberboard				Shipper City:	BUFORD
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:					Shipper Postal:	30518-5859
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	30652260776198
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	BUFORD
Cont1 Pkg Mnfctr:					Origin State:	GEORGIA
Cont1 Pkg Mnfct Dt:					Origin Postal:	30518
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	LAWRENCEVILLE
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30043
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:					The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.	
Recommend Actions Taken:						

7	7 of 13	NE	0.12 / 612.03	1,013.74 / 1	FedEx Ground Package System, Inc. 6265 Atlantic Blvd. Norcross GA 30071	TIER 2
Facility ID:	6795388				Filing Year:	2020(Tier2)
State Facility ID:					Filing Type:	302
						312
Max No of Occupant:	400				County:	Gwinnett
Manned Y/N:	YES				Latitude:	33.9437439
Has Doc(s):	True				Longitude:	-84.235592
Facility Name:		FedEx Ground - 301 - Norcross				
SIC Code:		4215				
NAICS Code:		492110				
Dun & Bradstreet Code:		18-868-3486				
Last Modified Date:		2021-02-25				
First Submit Date:		2021-02-25(Tier2)				
Data Submitted By:		Kyle Nelson, FedEx Authorized Representative, Gannett Fleming				
Contact 1 Name:		James Wolstenholme				
Contact 1 Cont Type:		Emergency Contact				
Contact 1 Email:		1037899@fedex.com				
Contact 1 24 Hr Phone:		404-787-9135				
Contact 1 Work Phone:		770-743-3400				
Contact 2 Name:		Natalie Owens				
Contact 2 Cont Type:		Tier II Information Contact				
Contact 2 Email:		natalie.owens@fedex.com				
Contact 2 24 Hr Phone:		412-313-6909				
Contact 2 Work Phone:		412-262-7347				
Contact 3 Name:		Anthony Spalvieri				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont 3 Cont Type:		Owner / Operator				
Cont 3 Email:		environmental@fedex.com				
Cont 3 24 Hr Phone:		412-859-2384				
Cont 3 Work Phone:		FedEx Ground Package System, Inc., 1000 FedEx Drive				
Mailing Address:		Moon Township				
Mailing City:		PA				
Mailing State:		15108				
Mailing Zip:						
Facility Note:						

FedEx Fac# 301

Chemical Info

Cas Number:	68476346	Pyrophoric Liq/Sol:	False
Max Daily Qty:	146,000	Pyrophoric Gas:	False
Avg Daily Qty:	146,000	Self Heating:	False
EHS:		Organic Peroxide:	False
Below Thresholds:		Corrosive to Metal:	False
Trade Secret:		Gas Under Pressure:	False
H:	0	Cont Wtr Emit Gas:	False
F:	2	Combustible Dust:	False
R:	0	Acute Toxicity:	True
S:	-	Skin Corrosion/Irr:	True
Solid:	False	Serious Eye Damage:	False
Liquid:	True	Resp/Skin Sensitiz:	False
Gas:	False	Germ Cell Mutagen:	False
Pure:	False	Carcinogenicity:	True
Mixture:	True	Reproductive Toxic:	False
Explosive:	False	Spc Trgt Organ Tox:	True
Flammable Gas/Liq:	True	Aspiration Hazard:	True
Oxidzr Liq/Sol/Gas:	False	Simple Asphyxiant:	False
Self Reactive:	False	Haz not o/w Class:	False
Chemical Name:	Diesel Fuel		
Contact Info:	Name: Joe Ballah		
	Contact Type: Fac. Emergency Coordinator		
	Email: 2062046@fedex.com		
	24-hour Phone :470-388-9303		
	Work Phone :770-743-3400		

Storage Pressure Temperature:

"Below ground tank"/"Ambient pressure"/"Ambient temperature"/"West Side of Distribution Building"/146,000(pounds) **Note: Many records provided by the department have a truncated [Storage Pressure Temperature T] field.

Chemical Info

Cas Number:	7664939	Pyrophoric Liq/Sol:	False
Max Daily Qty:	2,509	Pyrophoric Gas:	False
Avg Daily Qty:	2,509	Self Heating:	False
EHS:	True	Organic Peroxide:	False
Below Thresholds:		Corrosive to Metal:	True
Trade Secret:		Gas Under Pressure:	False
H:	3	Cont Wtr Emit Gas:	False
F:	0	Combustible Dust:	False
R:	0	Acute Toxicity:	False
S:	W	Skin Corrosion/Irr:	True
Solid:	False	Serious Eye Damage:	True
Liquid:	True	Resp/Skin Sensitiz:	False
Gas:	False	Germ Cell Mutagen:	False
Pure:	True	Carcinogenicity:	False
Mixture:	False	Reproductive Toxic:	False
Explosive:	False	Spc Trgt Organ Tox:	False
Flammable Gas/Liq:	False	Aspiration Hazard:	False
Oxidzr Liq/Sol/Gas:	False	Simple Asphyxiant:	False
Self Reactive:	False	Haz not o/w Class:	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Chemical Name:		Sulfuric Acid				
Contact Info:		Name: Joe Ballah Contact Type: Fac. Emergency Coordinator Email: 2062046@fedex.com 24-hour Phone :470-388-9303 Work Phone :770-743-3400				
Storage Pressure Temperature:						
"Battery"/"Ambient pressure"/"Ambient temperature"/"Near Maintenance / used Throughout"/2,509(pounds) **Note: Many records provided by the department have a truncated [Storage Pressure Temperature T] field.						
<u>Contact Info</u>						
Contact Type:		Emergency Contact				
Contact Name Title :		James Wolstenholme (Senior Manager)				
Contact Address:		6265 Atlantic Blvd				
Contact City:		Norcross				
Contact State:		GA				
Contact Zip:		30071				
Email:		1037899@fedex.com				
Phone:		404-787-9135 (24-hour) 770-743-3400 (Work)				
<u>Contact Info</u>						
Contact Type:		Facility Phone				
Contact Name Title :		FedEx Ground - 301 - Norcross				
Contact Address:						
Contact City:						
Contact State:						
Contact Zip:						
Email:						
Phone:		770-743-3400 (FP)				
<u>Contact Info</u>						
Contact Type:		Owner / Operator				
Contact Name Title :		Anthony Spalvieri (Assistant Secretary)				
Contact Address:		1000 FedEx Drive				
Contact City:		Moon Township				
Contact State:		PA				
Contact Zip:		15108				
Email:		environmental@fedex.com				
Phone:		412-859-2384 (Work)				
<u>Contact Info</u>						
Contact Type:		Tier II Information Contact				
Contact Name Title :		Natalie Owens (Environmental)				
Contact Address:		1000 FedEx Drive				
Contact City:		Moon Township				
Contact State:		PA				
Contact Zip:		15108				
Email:		natalie.owens@fedex.com				
Phone:		412-313-6909 (24-hour) 412-262-7347 (Work)				
<u>Contact Info</u>						
Contact Type:		Fac. Emergency Coordinator				
Contact Name Title :		Joe Ballah (Facility Maintenance Manager)				
Contact Address:		6265 ATLANTIC BOULEVARD				
Contact City:		Norcross				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Contact State:		GA				
Contact Zip:		30071				
Email:		2062046@fedex.com				
Phone:		470-388-9303 (24-hour)				
		770-743-3400 (Work)				
7	8 of 13	NE	0.12 / 612.03	1,013.74 / 1	FEDEX GROUND 6265 ATLANTIC BLVD NORCROSS GA 30071	RCRA VSQG
EPA Handler ID:		GAR000084616				
Gen Status Universe:		VSG				
Contact Name:		NATALIE OWENS				
Contact Address:		1000 , FEDEX DRIVE , , MOON TWP , PA, 15108 , US				
Contact Phone No and Ext:		412-262-7347				
Contact Email:		NATALIE.OWENS@FEDEX.COM				
Contact Country:		US				
County Name:		GWINNETT				
EPA Region:		04				
Land Type:		Private				
Receive Date:		20180809				
Location Latitude:		33.941564				
Location Longitude:		-84.232277				
<u>Violation/Evaluation Summary</u>						
Note:		NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).				
<u>Handler Summary</u>						
Importer Activity:		No				
Mixed Waste Generator:		No				
Transporter Activity:		No				
Transfer Facility:		No				
Onsite Burner Exemption:		No				
Furnace Exemption:		No				
Underground Injection Activity:		No				
Commercial TSD:		No				
Used Oil Transporter:		No				
Used Oil Transfer Facility:		No				
Used Oil Processor:		No				
Used Oil Refiner:		No				
Used Oil Burner:		No				
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		1				
Receive Date:		20180809				
Handler Name:		FEDEX GROUND				
Federal Waste Generator Code:		3				
Generator Code Description:		Very Small Quantity Generator				
Source Type:		Notification				
<u>Waste Code Details</u>						
Hazardous Waste Code:		D002				
Waste Code Description:		CORROSIVE WASTE				
Hazardous Waste Code:		D003				
Waste Code Description:		REACTIVE WASTE				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazardous Waste Code:		D004				
Waste Code Description:		ARSENIC				
Hazardous Waste Code:		D001				
Waste Code Description:		IGNITABLE WASTE				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:	Current Owner			Street No:	1000	
Type:	Private			Street 1:	FEDEX DRIVE	
Name:	FEDEX GROUND			Street 2:		
Date Became Current:				City:	MOON TWP	
Date Ended Current:				State:	PA	
Phone:				Country:	US	
Source Type:	Notification			Zip Code:	15108	
Owner/Operator Ind:	Current Operator			Street No:	1000	
Type:	Private			Street 1:	FEDEX DRIVE	
Name:	FEDEX GROUND			Street 2:		
Date Became Current:				City:	MOON TWP	
Date Ended Current:				State:	PA	
Phone:				Country:	US	
Source Type:	Notification			Zip Code:	15108	

7	9 of 13	NE	0.12 / 612.03	1,013.74 / 1	6265 Atlantic Blvd Norcross GA	HMIRS

Incident County: GWINNETT

HMIR Incident Reports

Report No:	X-2015030283	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2015-02-26	Report Submit Src:	XML
Time of Incident:	1000	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	COMPOUNDS, CLEANING LIQU	Transport Phase:	Unloading
Commodity Long Nm:	COMPOUNDS, CLEANING LIQUID	Incident Occrrnce:	
Trade Name:	ACETONEHEPTANE	Mat Ship Approval?:	No
ID No:	NA1993	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.5	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	PRINTERS SERVICES
Cont1 Pkging Type:	Box	Shipper Street Name:	7055 AMWILER INDUSTRIAL DR
Cont1 Const Mat:	Fiberboard	Shipper City:	DORAVILLE
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30360
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	30738232550734
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:		
C1 Test Const Mat:	Fiberboard			Destination City:	DECATUR	
C1 Pkg Dsign Pres.:	0			Destination State:	ALABAMA	
C1 Dsign Press UOM:				Destination Postal:	35601	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:	Can	
C1 Head Thick UOM:				Cont2 Const Mat:	Metal (any type)	
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:		0
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	BOX FBR	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box or carton	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:		The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>HMIR Incident Reports</u>						
Report No:	X-2016090646				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2016-08-25				Report Submit Src:	XML
Time of Incident:	2338				Inc Multiple Rows:	Yes
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,				Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.				Incident Occrrnce:	
Trade Name:	(contains Potassium				Mat Ship Approval?:	No
ID No:	UN3266				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.5				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/Yy21.1/S/16 Usa/+BZ0775				Shipper Name:	DIVERSITECH CORP
Cont1 Pkging Type:					Shipper Street Name:	3175 E PARK DR
Cont1 Const Mat:					Shipper City:	CONYERS
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30013-5773
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	701396650994
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:					Destination City:	BERKELEY LAKE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30096
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srv Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srv Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:	X-2016090646				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2016-08-25				Report Submit Src:	XML
Time of Incident:	2338				Inc Multiple Rows:	Yes
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,				Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.				Incident Occrrnce:	
Trade Name:	Contains potassium a				Mat Ship Approval?:	No
ID No:	UN3266				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1.5				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	312				CR Non US State:	
How Failed Desc:	Torn Off or Damaged				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	Diversitech Corp
Cont1 Pkging Type:	Box				Shipper Street Name:	2175 E PARK DR NE
Cont1 Const Mat:	Fiberboard				Shipper City:	Conyers
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30013

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	2506707701396650983
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg MnfcDt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	DULUTH
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30096
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2014110237				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2014-10-20				Report Submit Src:	XML
Time of Incident:	1835				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	METHANOL				Transport Phase:	Unloading
Commodity Long Nm:	METHANOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1230				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	3.7				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	135				CR State:	PA
What Failed Desc:	Loading or Unloading Lines				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	CARDINAL HEALTH
Cont1 Pkging Type:	Box				Shipper Street Name:	7611 BRANDON WOODS BLVD
Cont1 Const Mat:	Fiberboard				Shipper City:	Baltimore
Cont1 Head Type:					Shipper State:	MD
Cont1 Pkg Capacity:	0				Shipper Postal:	21226
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	173967192014633
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	No
RAM Transport Index:					Evacuation Indicator:	0
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2015060331	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2015-06-02	Report Submit Src:	XML
Time of Incident:	2305	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS, CORRO	Transport Phase:	In Transit
Commodity Long Nm:	FLAMMABLE LIQUIDS, CORROSIVE, N.O.S.	Incident Occrrnce:	
Trade Name:	TRIMETHYLBENZENE, AM	Mat Ship Approval?:	No
ID No:	UN2924	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	3.25	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Ident. Markings:			Shipper Name:			AXALTA COATING SYSTEMS
Cont1 Pkging Type:	Box		Shipper Street Name:			7961 Winchester rd
Cont1 Const Mat:	Fiberboard		Shipper City:			Front Royal
Cont1 Head Type:			Shipper State:			VA
Cont1 Pkg Capacity:	0		Shipper Postal:			22630
C1 Capacity UOM:			Shipper Non US St:			
Cont1 Pkg Amt:	0		Shipper Country:			US
C1 Pkg Amt UOM:			Shipper Waybill:			27875525191
Cont1 Pkg No:	0		Ship Hazmat Reg ID:			
C1 Pkg NO Failed:	0		Origin City:			
Cont1 Pkg Mnfctr:			Origin State:			
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00		Origin Postal:			
Cont1 Pkg Serial NO:			Origin Non US St:			
C1 Pkg Last Test Dt:	0-00-00 00:00:00		Origin Country:			
C1 Test Const Mat:	Fiberboard		Destination City:			CUMMING
C1 Pkg Dsign Pres.:	0		Destination State:			GEORGIA
C1 Dsign Press UOM:			Destination Postal:			30040
C1 Pkg Shell Thick:	0		Destination Non US:			
C1 Shell Thick UOM:			Destination Country:			US
C1 Head Thickness:	0		Cont2 Package Type:			Can
C1 Head Thick UOM:			Cont2 Const Mat:			Metal (any type)
C1 Pkg Srvc Pres.:	0		Cont2 Pkg Capacity:			0
C1 Srvc Press UOM:			Cont2 Capacity UOM:			
C1 Valve/Device Fail?:	No		Cont2 Pkg Amount:			0
C1 Device Type:			Cont2 Pkg Amt UOM:			
C1 Device Mnfctr:			Cont2 Pkg No:			0
C1 Device Model:			Cont2 Pkg No Failed:			0
NRC No:						
RAM Pkg Category:			Haz NonHosp Public:			0
RAM Pkg Cert.:	FALSE		Haz NonHosp Old:			
RAM Pkg Cert. NBR:			Tot Haz Non Hosp Inj:			
RAM Nuclide S:			Total Hazmat Injuries:			0
RAM Transport Index:			Evacuation Indicator:			No
RAM UOM:			Public Evacuated:			0
RAM Activity Rpted:	0		Employees Evac:			0
RAM UOM Rpted:			Total Evacuated:			0
RAM Activity:	0		Total Evacuation Hrs:			0
RAM Activity UOM:			Major Artery Closed:			No
RAM Mat Safety:			Mjr Artery Hrs Closed:			0
Spillage Result:	Yes		Material Involved:			No
Fire Result:	No		Estimated Speed:			0
Explosion Result:	No		Weather Conditions:			
Water Sewer Result:	No		Vehicle Overturn:			No
Gas Dispersion:	No		Vehicle Left Roadway:			No
Environment Damage:	No		Passenger Aircraft:			No
No Release Result:	No		Cargo Baggage:			
Fire EMS Report:	No		Ship Non Transport:			No
Fire EMS EMS Report:			Ship Air First Flight:			No
Police Report:	No		Ship Air Subflight:			No
Police Report No:			Ship Init Transport:			No
In House Cleanup:	Yes		Ship Phase Transfer:			No
Other Cleanup:	No		Contact Name:			GEORGE FETSKO
Damage > 500:	No		Contact Title:			HAZMAT - SAFETY ADVISOR
Material Loss:	0		Contact Business:			Fedex Ground Package System, Inc.
Carrier Damage:	0		Contact Street:			1000 Fedex Drive
Property Damage:	0		Contact City:			CORAOPOLIS
Response Cost:	0		Contact State:			PA
Remediation Cost:	0		Contact Postal:			15108
Damage Old Form:	0		Contact Non US St:			
Total Damages Amt:	0		Contact Country:			US
Hazmat Fatality:	No		Inc. Report Prepared:			Carrier
Haz Fatal Employees:	0		HMIS Serious Incidnt:			No
Haz Fatal Respndrs:	0		HMIS Serious Fatality:			No
Haz Fatal Gen Public:	0		HMIS Serious Injury:			No
Tot Hazmat Fatalities:	0		HMIS Flight Plan:			No
Non Hazmat Fatality:	No		HMIS Serious Evacs:			No
Non Hazmat Fatafs:	0		HMIS Major Artery:			No
Hazmat Injury:	No		HMIS Bulk Release:			No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2013040185				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2013-03-22				Report Submit Src:	XML
Time of Incident:	1730				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,				Transport Phase:	Loading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.				Incident Occrrnce:	
Trade Name:	contains Phosphates				Mat Ship Approval?:	No
ID No:	UN3266				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	2				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	A.B.C. COMPOUNDING COMPANY, IN
Cont1 Pkging Type:	Box				Shipper Street Name:	6970 JONESBORO RD
Cont1 Const Mat:	Fiberboard				Shipper City:	Lake City
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30260
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	31858262231010
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	SUWANEE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30024
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2016090684	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2016-08-29	Report Submit Src:	XML
Time of Incident:	2338	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,	Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.	Incident Occrrnce:	
Trade Name:	(sodium hydroxide)	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1	CR Street Name:	1000 Fedex Drive

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Unit of Measure:	Liquid - Gallon			CR City:	Moon Township	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)			CR Postal Code:	15108	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	Zep Inc	
Cont1 Pkging Type:	Box			Shipper Street Name:	105 Kendall Park Ln	
Cont1 Const Mat:	Fiberboard			Shipper City:	ATLANTA	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:	0			Shipper Postal:	30336	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	222733011470325	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	NORCROSS	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30071	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvs Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvs Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2013050256	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2013-04-16	Report Submit Src:	XML
Time of Incident:	1700	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	5.1	Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	Transport Phase:	Loading
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES, STABILIZED WITH ACIDS, WATER, AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN3149	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.039062	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G/Y6.1/S/13USA/AA4750	Shipper Name:	STERIS CORP
Cont1 Pkging Type:		Shipper Street Name:	8525 PAGE AVE
Cont1 Const Mat:		Shipper City:	Breckenridge Hills
Cont1 Head Type:		Shipper State:	MO
Cont1 Pkg Capacity:	0	Shipper Postal:	63114
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	63106970969350
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:		Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30329
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfrctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2012100412				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2012-10-02				Report Submit Src:	XML
Time of Incident:	0800				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Commodity Short Nm:	ACETONE				Transport Phase:	In Transit
Commodity Long Nm:	ACETONE				Incident Occrrnce:	
Trade Name:	na				Mat Ship Approval?:	No
ID No:	UN1090				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1.3209				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	304				CR Non US State:	
How Failed Desc:	Cracked				CR Fed DOT ID:	265752
Failure Cause Code:	515				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Human Error				CR Country:	US
Ident. Markings:	4G/X10.9/S/12/USA/M4109				Shipper Name:	SIGMA-ALDRICH
Cont1 Pkging Type:					Shipper Street Name:	6000 N TEUTONIA AVE
Cont1 Const Mat:					Shipper City:	Brown Deer
Cont1 Head Type:					Shipper State:	WI
Cont1 Pkg Capacity:	0				Shipper Postal:	53209
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	36553821317376
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:					Destination City:	ROSWELL
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30076
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2016060832	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2016-05-31	Report Submit Src:	XML
Time of Incident:	0018	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	PETROLEUM DISTILLATES, N	Transport Phase:	Unloading
Commodity Long Nm:	PETROLEUM DISTILLATES, N.O.S. OR PETROLEUM PRODUCTS, N.O.S.	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1268	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.007812	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	Test Equipment Dtributors
Cont1 Pkging Type:	Box	Shipper Street Name:	1959-D Parker Ct
Cont1 Const Mat:	Fiberboard	Shipper City:	Stone Mountain
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30087
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	2367824684910
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:	Fiberboard	Destination City:	PALMETTO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Dsgn Pres.:	0				Destination State:	FLORIDA
C1 Dsgn Press UOM:					Destination Postal:	34221
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report No:	X-2016060877				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2016-05-31				Report Submit Src:	XML
Time of Incident:	2345				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	ETHYL ALCOHOL				Transport Phase:	Loading
Commodity Long Nm:	ETHYL ALCOHOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1170				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.15				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	517				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Improper Preparation for Transportation				CR Country:	US
Ident. Markings:					Shipper Name:	VWR International
Cont1 Pkging Type:	Box				Shipper Street Name:	1050 satellite blvd
Cont1 Const Mat:	Fiberboard				Shipper City:	Suwanee
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30024
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	408394874704729
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	BLOOMINGDALE
C1 Pkg Dsign Pres.:	0				Destination State:	TENNESSEE
C1 Dsign Press UOM:					Destination Postal:	37660
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2015020161	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2015-01-22	Report Submit Src:	XML
Time of Incident:	1040	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS, N.O.S.	Transport Phase:	Loading
Commodity Long Nm:	FLAMMABLE LIQUIDS, N.O.S.	Incident Occrrnce:	
Trade Name:	ACETONEHEPTANE	Mat Ship Approval?:	No
ID No:	UN1993	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.52836	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108
How Failed Code:	309	CR Non US State:	
How Failed Desc:	Punctured	CR Fed DOT ID:	265752
Failure Cause Code:	515	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Human Error	CR Country:	US
Ident. Markings:		Shipper Name:	PRINTERS SERVICE
Cont1 Pkging Type:	Drum	Shipper Street Name:	7055 AMWILER INDUSTRIAL DR
Cont1 Const Mat:	Aluminum	Shipper City:	DORAVILLE
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30360
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	30738232546607
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Aluminum				Destination City:	ORLANDO
C1 Pkg Dsign Pres.:	0				Destination State:	FLORIDA
C1 Dsign Press UOM:					Destination Postal:	32805
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM METAL
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM MTL
Total Haz Hosp Inj:	0				HMIS Container Desc:	Metal drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:	X-2014090142				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2014-08-08				Report Submit Src:	XML
Time of Incident:	1700				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE SOLID, BASIC,				Transport Phase:	Loading
Commodity Long Nm:	CORROSIVE SOLID, BASIC, INORGANIC, N. O.S.				Incident Occrrnce:	
Trade Name:	sodium hydroxide				Mat Ship Approval?:	No
ID No:	UN3262				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	14				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Solid - Pound				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	309				CR Non US State:	
How Failed Desc:	Punctured				CR Fed DOT ID:	265752
Failure Cause Code:	516				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g., nails)				CR Country:	US
Ident. Markings:					Shipper Name:	ECOLAB/CEVA LOGISTICS
Cont1 Pkging Type:	Box				Shipper Street Name:	125 SOUTHSIDE CT
Cont1 Const Mat:	Fiberboard				Shipper City:	MCDONOUGH
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30253
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	916079075091895
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	LAWRENCEVILLE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30044
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2013060051	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2013-05-08	Report Submit Src:	XML
Time of Incident:	1705	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	ETHYL ALCOHOL	Transport Phase:	Loading
Commodity Long Nm:	ETHYL ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1170	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G/Y28/S/13USA/M4899	Shipper Name:	DECON LABORATORIES, INC
Cont1 Pkging Type:		Shipper Street Name:	460 GLENNIE CIR
Cont1 Const Mat:		Shipper City:	King Of Prussia

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Head Type:					Shipper State:	PA
Cont1 Pkg Capacity:	0				Shipper Postal:	19406
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	69577450056015
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2012100413				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2012-10-02				Report Submit Src:	XML
Time of Incident:	0900				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	ETHANOL OR ETHYL ALCOHOL				Transport Phase:	Unloading
Commodity Long Nm:	ETHANOL OR ETHYL ALCOHOL OR ETHANOL SOLUTIONS OR ETHYL ALCOHOL SOLUTIONS				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1170				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.007812				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/Y25/S/12USA/M5586				Shipper Name:	MERCEDES MEDICAL
Cont1 Pkging Type:					Shipper Street Name:	7590 COMMERCE CT
Cont1 Const Mat:					Shipper City:	Sarasota
Cont1 Head Type:					Shipper State:	FL
Cont1 Pkg Capacity:	0				Shipper Postal:	34243
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	33796370256076
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	CHAMBLEE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30341
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	Moon Township	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respntrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:				The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.		

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2012100414	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2012-10-02	Report Submit Src:	XML
Time of Incident:	0600	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, ACIDIC	Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, ACIDIC, ORGANIC, N. O.S.	Incident Occrrnce:	
Trade Name:	Isothiazolinone Micr	Mat Ship Approval?:	No
ID No:	UN3265	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.25	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	104	CR State:	PA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	309				CR Non US State:	
How Failed Desc:	Punctured				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:					Shipper Name:	NALCO
Cont1 Pkging Type:	Drum				Shipper Street Name:	125 NALCO WAY
Cont1 Const Mat:	Plastic				Shipper City:	Ellport
Cont1 Head Type:					Shipper State:	PA
Cont1 Pkg Capacity:	0				Shipper Postal:	16117
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	44537038098609
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30309
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM NON-METAL
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2012120290	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2012-11-28	Report Submit Src:	XML
Time of Incident:	2135	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	METHANOL	Transport Phase:	Loading
Commodity Long Nm:	METHANOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1230	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	2.6418	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	139	CR State:	PA
What Failed Desc:	O-Ring or Seals	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:	4G/Y16/S/11USA/HEDWIN	Shipper Name:	Fisher Scientific
Cont1 Pkging Type:		Shipper Street Name:	2775 Horizon Ridge Ct
Cont1 Const Mat:		Shipper City:	Suwanee
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30024
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	39064579110074
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:		Destination City:	ORLANDO
C1 Pkg Dsign Pres.:	0	Destination State:	FLORIDA
C1 Dsign Press UOM:		Destination Postal:	32806
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0	Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	0
C1 Device Type:		Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:		Cont2 Pkg No:	0
C1 Device Model:		Cont2 Pkg No Failed:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2016080616	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2016-07-29	Report Submit Src:	XML
Time of Incident:	1432	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	5.1	Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	Transport Phase:	In Transit
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES, STABILIZED WITH ACIDS, WATER, AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	Incident Occrrnce:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Trade Name:	stabilized				Mat Ship Approval?:	No
ID No:	UN3149				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	Medivators
Cont1 Pkging Type:	Box				Shipper Street Name:	14605 28th Ave Ne
Cont1 Const Mat:	Fiberboard				Shipper City:	Minneapolis
Cont1 Head Type:					Shipper State:	MN
Cont1 Pkg Capacity:	0				Shipper Postal:	55447
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	91101235088374
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2014060045	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2014-05-06	Report Submit Src:	XML
Time of Incident:	1638	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	PETROLEUM PRODUCTS, N.O.	Transport Phase:	Loading
Commodity Long Nm:	PETROLEUM PRODUCTS, N.O.S.	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1268	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.25	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	311	CR Non US State:	
How Failed Desc:	Structural	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	N/A
Cont1 Pkging Type:	Box	Shipper Street Name:	ILLEGIBLE
Cont1 Const Mat:	Fiberboard	Shipper City:	Norcross
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30071
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	111111111111111
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:	Fiberboard	Destination City:	NORCROSS
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30071
C1 Pkg Shell Thick:	0	Destination Non US:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfrctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	BOX FBR	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box or carton	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:	X-2014060047			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	2014-05-06			Report Submit Src:	XML	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Time of Incident:	1705				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	ACETONITRILE				Transport Phase:	Loading
Commodity Long Nm:	ACETONITRILE				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1648				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.26418				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	128				CR State:	PA
What Failed Desc:	Inner Packaging				CR Postal Code:	15108
How Failed Code:	304				CR Non US State:	
How Failed Desc:	Cracked				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:					Shipper Name:	ALDRICH CHEMICAL CO
Cont1 Pkging Type:	Box				Shipper Street Name:	6000 N TEUTONIA AVE
Cont1 Const Mat:	Fiberboard				Shipper City:	Brown Deer
Cont1 Head Type:					Shipper State:	WI
Cont1 Pkg Capacity:	0				Shipper Postal:	53209
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	36553831709185
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	CHAMBLEE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30341
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Police Report No:				Ship Init Transport:		No
In House Cleanup: Yes				Ship Phase Transfer:		No
Other Cleanup: No				Contact Name:		GEORGE FETSKO
Damage > 500: No				Contact Title:		HAZMAT - SAFETY ADVISOR
Material Loss: 0				Contact Business:		Fedex Ground Package System, Inc.
Carrier Damage: 0				Contact Street:		1000 Fedex Drive
Property Damage: 0				Contact City:		CORAOPOLIS
Response Cost: 0				Contact State:		PA
Remediation Cost: 0				Contact Postal:		15108
Damage Old Form: 0				Contact Non US St:		
Total Damages Amt: 0				Contact Country:		US
Hazmat Fatality: No				Inc. Report Prepared:		Carrier
Haz Fatal Employees: 0				HMIS Serious Incidnt:		No
Haz Fatal Respndrs: 0				HMIS Serious Fatality:		No
Haz Fatal Gen Public: 0				HMIS Serious Injury:		No
Tot Hazmat Fatalities: 0				HMIS Flight Plan:		No
Non Hazmat Fatality: No				HMIS Serious Evacs:		No
Non Hazmat FataIs: 0				HMIS Major Artery:		No
Hazmat Injury: No				HMIS Bulk Release:		No
Haz Hospital Empl: 0				HMIS Marine Pollutnt:		No
Haz Hospital Resp: 0				HMIS Radioactive:		No
Haz Hosp Gen Public: 0				HMIS Gen Pkg Type:		BOX FIBER
Haz Hosp Old Form: 0				HMIS Container Code:		BOX FBR
Total Haz Hosp Inj: 0				HMIS Container Desc:		Fiberboard box or carton
Haz Non Hosp Empl: 0				HMIS Bulk Incident:		No
Haz Non Hosp Resp: 0				Undeclared Shipment:		No
Description of Events:				The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.		
Recommend Actions Taken:						
HMIR Incident Reports						
Report No: X-2013060096				Fed DOT Agency Nm:		
Report Type: A hazardous material incident				Fed DOT Report No:		
Date of Incident: 2013-05-10				Report Submit Src: XML		
Time of Incident: 2130				Inc Multiple Rows: No		
Haz Class Code:				Inc Non US State:		
Hazardous Class: 3				Mode Transport: Highway		
Commodity Short Nm: GASOLINE INCLUDES GASOLI				Transport Phase: Unloading		
Commodity Long Nm: GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL, WITH NOT MORE THAN 10% ALCOHOL				Incident Occrrnce:		
Trade Name:				Mat Ship Approval?: No		
ID No: UN1203				Mat Ship Approv No:		
Haz Waste Ind: No				Undecl Hazmat Ship?: No		
Haz Waste EPA No:				Packaging Type: Non-Bulk		
HMIS Tox Inhalation?: No				Packing Group: II		
TIH Hazard Zone:				Carrier Reporter: Fedex Ground Package System, Inc.		
Qty Released: 0.25				CR Street Name: 1000 Fedex Drive		
Unit of Measure: Liquid - Gallon				CR City: Moon Township		
What Failed: 109				CR State: PA		
What Failed Desc: Closure (e.g., Cap, Top, or Plug)				CR Postal Code: 15108		
How Failed Code: 308				CR Non US State:		
How Failed Desc: Leaked				CR Fed DOT ID: 265752		
Failure Cause Code: 526				CR Hazmat Reg ID: 051910551007S		
Failure Cause Desc: Loose Closure, Component, or Device				CR Country: US		
Ident. Markings: 4G/Y31.6/S/10USA/+AA3579				Shipper Name: MOTIVA ENTERPRISE		
Cont1 Pkging Type:				Shipper Street Name: 4127 WINTERS CHAPEL RD		
Cont1 Const Mat:				Shipper City: DORAVILLE		
Cont1 Head Type:				Shipper State: GA		
Cont1 Pkg Capacity: 0				Shipper Postal: 30360		
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt: 0				Shipper Country: US		
C1 Pkg Amt UOM:				Shipper Waybill: 427541762800178		
Cont1 Pkg No: 0				Ship Hazmat Reg ID:		
C1 Pkg NO Failed: 0				Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	ABAC
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	31794
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>HMIR Incident Reports</u>						
Report No:	X-2014060105				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2014-05-12				Report Submit Src:	XML
Time of Incident:	1650				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT, L				Transport Phase:	Loading
Commodity Long Nm:	PAINT INCLUDING PAINT, LACQUER, ENAMEL, STAIN, SHELLAC SOLUTIONS, VARNISH, POLISH, LIQUID FILLER AND LIQUID LACQUER BASE				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1263				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	528				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Missing Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	Grainger
Cont1 Pkging Type:	Box				Shipper Street Name:	101 Southchase Blvd
Cont1 Const Mat:	Fiberboard				Shipper City:	Fountain Inn
Cont1 Head Type:					Shipper State:	SC
Cont1 Pkg Capacity:	0				Shipper Postal:	29644
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	132603475544352
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	DUNWOODY
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30346
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2014090144	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2014-08-14	Report Submit Src:	XML
Time of Incident:	1645	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	METHANOL	Transport Phase:	Loading
Commodity Long Nm:	METHANOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1230	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	4.22688	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108
How Failed Code:	304	CR Non US State:	
How Failed Desc:	Cracked	CR Fed DOT ID:	265752
Failure Cause Code:	502	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Broken Component or Device	CR Country:	US
Ident. Markings:		Shipper Name:	Sigma-Aldrich Inc
Cont1 Pkging Type:	Box	Shipper Street Name:	6000 N. Teutonia Ave
Cont1 Const Mat:	Fiberboard	Shipper City:	Brown Deer

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Head Type:					Shipper State:	WI
Cont1 Pkg Capacity:	0				Shipper Postal:	53209
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	36553833760191
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	SANDY SPRINGS
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30342
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2012110049				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2012-10-04				Report Submit Src:	XML
Time of Incident:	0730				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	ETHYL ALCOHOL				Transport Phase:	Loading
Commodity Long Nm:	ETHYL ALCOHOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1170				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	305				CR Non US State:	
How Failed Desc:	Crushed				CR Fed DOT ID:	265752
Failure Cause Code:	515				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Human Error				CR Country:	US
Ident. Markings:					Shipper Name:	DECON LABORATOIRES
Cont1 Pkging Type:	Jerrican				Shipper Street Name:	460 GLENNIE CIR
Cont1 Const Mat:	Plastic				Shipper City:	King Of Prussia
Cont1 Head Type:					Shipper State:	PA
Cont1 Pkg Capacity:	0				Shipper Postal:	19406
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	69577466150172
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	INSIDE CONTAIN
Haz Hosp Old Form:	0				HMIS Container Code:	CONT PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic container, no capacity or description given
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2012120361	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2012-12-04	Report Submit Src:	XML
Time of Incident:	2130	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS, N.O.S.	Transport Phase:	Unloading
Commodity Long Nm:	FLAMMABLE LIQUIDS, N.O.S.	Incident Occrrnce:	
Trade Name:	Acetone	Mat Ship Approval?:	No
ID No:	UN1993	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.007812	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	PRINTERS SVC	
Cont1 Pkging Type:	Box			Shipper Street Name:	7055 AMWILER INDUSTRIAL DR	
Cont1 Const Mat:	Fiberboard			Shipper City:	DORAVILLE	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:	0			Shipper Postal:	30360	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	30738232457873	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:		
C1 Test Const Mat:	Fiberboard			Destination City:	DALTON	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30720	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:	Can	
C1 Head Thick UOM:				Cont2 Const Mat:	Metal (any type)	
C1 Pkg Srvs Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvs Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	Moon Township	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2013010242	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2013-01-02	Report Submit Src:	XML
Time of Incident:	1630	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	ALCOHOLS, N.O.S.	Transport Phase:	Loading
Commodity Long Nm:	ALCOHOLS, N.O.S.	Incident Occrrnce:	
Trade Name:	Ethanol/Methanol	Mat Ship Approval?:	No
ID No:	UN1987	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.26418	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108
How Failed Code:	305	CR Non US State:	
How Failed Desc:	Crushed	CR Fed DOT ID:	265752
Failure Cause Code:	515	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Human Error	CR Country:	US
Ident. Markings:		Shipper Name:	LEICA BIOSYSTEMS RICHMOND,
Cont1 Pkging Type:	Box	Shipper Street Name:	5205 RT 12
Cont1 Const Mat:	Fiberboard	Shipper City:	Richmond
Cont1 Head Type:		Shipper State:	IL
Cont1 Pkg Capacity:	0	Shipper Postal:	60071
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	60226515879166
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:	Fiberboard	Destination City:	ALPHARETTA
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30005
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	Bottle
C1 Head Thick UOM:		Cont2 Const Mat:	Plastic
C1 Pkg Srv Pres.:	0	Cont2 Pkg Capacity:	0
C1 Srv Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	0
C1 Device Type:		Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:		Cont2 Pkg No:	0
C1 Device Model:		Cont2 Pkg No Failed:	0
NRC No:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:					The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.	

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2012100097	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2012-09-12	Report Submit Src:	XML
Time of Incident:	2200	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	NITRIC ACID OTHER THAN R	Transport Phase:	Unloading
Commodity Long Nm:	NITRIC ACID OTHER THAN RED FUMING, WITH AT LEAST 65 PERCENT, BUT NOT MORE THAN 70 PERCENT NITRIC ACID	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN2031	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.26418				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	303				CR Non US State:	
How Failed Desc:	Burst or Ruptured				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:					Shipper Name:	Fedex Ground Rocky Mountain
Cont1 Pkging Type:	Box				Shipper Street Name:	2410 UNITED DRIVE
Cont1 Const Mat:	Fiberboard				Shipper City:	GREENVILLE
Cont1 Head Type:					Shipper State:	NC
Cont1 Pkg Capacity:	0				Shipper Postal:	27834
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	889027825009116
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	SUWANEE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30024
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2014050177	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2014-04-15	Report Submit Src:	XML
Time of Incident:	1623	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	5.2	Mode Transport:	Highway
Commodity Short Nm:	ORGANIC PEROXIDE TYPE F,	Transport Phase:	Unloading
Commodity Long Nm:	ORGANIC PEROXIDE TYPE F, LIQUID	Incident Occrrnce:	
Trade Name:	(Persisept)	Mat Ship Approval?:	No
ID No:	UN3109	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0125	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G/Y5.7/S/14/USA/+BR9244	Shipper Name:	Triple S/OHL
Cont1 Pkgng Type:		Shipper Street Name:	900 Kriner Rd
Cont1 Const Mat:		Shipper City:	Chambersburg
Cont1 Head Type:		Shipper State:	PA
Cont1 Pkg Capacity:	0	Shipper Postal:	17202
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	530702383345
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:		Destination City:	ROSWELL
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30076
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0	Cont2 Pkg Capacity:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:	X-2015040260				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2015-03-19				Report Submit Src:	XML
Time of Incident:	2345				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	ETHANOL OR ETHYL ALCOHOL				Transport Phase:	In Transit

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Commodity Long Nm:		ETHANOL OR ETHYL ALCOHOL OR ETHANOL SOLUTIONS OR ETHYL ALCOHOL SOLUTIONS		Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1170			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	Fedex Ground Package System, Inc.	
Qty Released:	1			CR Street Name:	1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon			CR City:	Moon Township	
What Failed:	104			CR State:	PA	
What Failed Desc:	Body			CR Postal Code:	15108	
How Failed Code:	309			CR Non US State:		
How Failed Desc:	Punctured			CR Fed DOT ID:	265752	
Failure Cause Code:	511			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Dropped			CR Country:	US	
Ident. Markings:				Shipper Name:	RICHARD ALLAN SCIENTIFIC	
Cont1 Pkging Type:	Box			Shipper Street Name:	4481 CAMPUS DR	
Cont1 Const Mat:	Fiberboard			Shipper City:	Kalamazoo	
Cont1 Head Type:				Shipper State:	MI	
Cont1 Pkg Capacity:	0			Shipper Postal:	49008	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	49002119935067	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:		
C1 Test Const Mat:	Fiberboard			Destination City:	ATLANTA	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30322	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2013050158				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2013-04-10				Report Submit Src:	XML
Time of Incident:	1630				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	5.1				Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE				Transport Phase:	Loading
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES, STABILIZED WITH ACIDS, WATER, AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN3149				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.5				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/Y26.3/S/13USA/+AA4759				Shipper Name:	MAR COR PURIFICATION
Cont1 Pkging Type:					Shipper Street Name:	14550 28TH AVE N
Cont1 Const Mat:					Shipper City:	Minneapolis
Cont1 Head Type:					Shipper State:	MN
Cont1 Pkg Capacity:	0				Shipper Postal:	55447
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	753963334393666
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	ROSWELL
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30076
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>HMIR Incident Reports</u>						
Report No:	X-2016110579				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2016-10-26				Report Submit Src:	XML
Time of Incident:	2042				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, ACIDIC				Transport Phase:	In Transit
Commodity Long Nm:	CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S.				Incident Occrrnce:	
Trade Name:	(Phosporic & Hydroch				Mat Ship Approval?:	No
ID No:	UN3264				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.007812				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	Swisher Hygiene
Cont1 Pkging Type:	Box				Shipper Street Name:	516 Monceaux Rd
Cont1 Const Mat:	Fiberboard				Shipper City:	Lawrenceville
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30046
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	73610265470058758
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	LAWRENCEVILLE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30046
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:	X-2016120062				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2016-11-02				Report Submit Src:	XML
Time of Incident:	2155				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	GASOLINE INCLUDES GASOLI				Transport Phase:	Loading
Commodity Long Nm:	GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL, WITH NOT MORE THAN 10% ALCOHOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1203				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.007812				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4g/y28/s/15 usa/+BR9196				Shipper Name:	Motiva Enterprises
Cont1 Pkging Type:					Shipper Street Name:	4127 Winters Chapel Rd
Cont1 Const Mat:					Shipper City:	DORAVILLE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30360
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	4275417665207850618
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:					Destination City:	TIFTON
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	31794
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2014020279				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2014-02-04				Report Submit Src:	XML
Time of Incident:	1700				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	5.1				Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE				Transport Phase:	Loading
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES, STABILIZED WITH ACIDS, WATER, AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID				Incident Occrrnce:	
Trade Name:	stabilized				Mat Ship Approval?:	No
ID No:	UN3149				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	REPROCESSING PRODUCTS CORP
Cont1 Pkging Type:	Box				Shipper Street Name:	3984 QUEBEC AVE N
Cont1 Const Mat:	Fiberboard				Shipper City:	Crystal
Cont1 Head Type:					Shipper State:	MN
Cont1 Pkg Capacity:	0				Shipper Postal:	55427
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	915475935242949
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfcct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	SANDY SPRINGS
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30350
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2014020310	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2014-02-06	Report Submit Src:	XML
Time of Incident:	1630	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	ACETONITRILE	Transport Phase:	Loading
Commodity Long Nm:	ACETONITRILE	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1648	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1.05672	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
What Failed:	104			CR State:	PA	
What Failed Desc:	Body			CR Postal Code:	15108	
How Failed Code:	304			CR Non US State:		
How Failed Desc:	Cracked			CR Fed DOT ID:	265752	
Failure Cause Code:	502			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Broken Component or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	Sigma Aldrich	
Cont1 Pkging Type:	Box			Shipper Street Name:	6000 N Teutonia Ave	
Cont1 Const Mat:	Fiberboard			Shipper City:	Brown Deer	
Cont1 Head Type:				Shipper State:	WI	
Cont1 Pkg Capacity:	0			Shipper Postal:	53209	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	36553829915987	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfcct Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:		
C1 Test Const Mat:	Fiberboard			Destination City:	ATLANTA	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30322	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2013090197	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2013-08-21	Report Submit Src:	XML
Time of Incident:	1641	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT, L	Transport Phase:	Unloading
Commodity Long Nm:	PAINT INCLUDING PAINT, LACQUER, ENAMEL, STAIN, SHELLAC SOLUTIONS, VARNISH, POLISH, LIQUID FILLER AND LIQUID LACQUER BASE	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1263	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108
How Failed Code:	305	CR Non US State:	
How Failed Desc:	Crushed	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:		Shipper Name:	N/A
Cont1 Pkging Type:	Box	Shipper Street Name:	ILLEGIBLE
Cont1 Const Mat:	Fiberboard	Shipper City:	Norcross
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30071
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	111111111111111
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:	Fiberboard	Destination City:	NORCROSS
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30071
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	Can
C1 Head Thick UOM:		Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvc Pres.:	0	Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:		Cont2 Capacity UOM:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The pail was dropped during handling causing leakage. The leakage was contained and the package was repacked. Undamaged product was returned to the shipper. The damaged product was properly disposed of in accordance with Federal Regulations.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2014040244	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2014-03-18	Report Submit Src:	XML
Time of Incident:	1631	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,	Transport Phase:	Loading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC,	Incident Occrrnce:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Trade Name:	N.O.S.				Mat Ship Approval?:	No
ID No:	Sodium Hydroxide, Alk				Mat Ship Approv No:	
Haz Waste Ind:	UN3266				Undecl Hazmat Ship?:	No
Haz Waste EPA No:	No				Packaging Type:	Non-Bulk
HMS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	NALCO COMPANY
Cont1 Pkging Type:	Drum				Shipper Street Name:	7701 HIGHWAY 90A
Cont1 Const Mat:	Plastic				Shipper City:	Sugar Land
Cont1 Head Type:					Shipper State:	TX
Cont1 Pkg Capacity:	0				Shipper Postal:	77478
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	532835511007
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg MnfcDt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Plastic				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30324
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Material Loss:	0				Contact Business: Fedex Ground Package System, Inc.	
Carrier Damage:	0				Contact Street: 1000 Fedex Drive	
Property Damage:	0				Contact City: CORAOPOLIS	
Response Cost:	0				Contact State: PA	
Remediation Cost:	0				Contact Postal: 15108	
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country: US	
Hazmat Fatality:	No				Inc. Report Prepared: Carrier	
Haz Fatal Employees:	0				HMIS Serious Incidnt: No	
Haz Fatal Respndrs:	0				HMIS Serious Fatality: No	
Haz Fatal Gen Public:	0				HMIS Serious Injury: No	
Tot Hazmat Fatalities:	0				HMIS Flight Plan: No	
Non Hazmat Fatality:	No				HMIS Serious Evacs: No	
Non Hazmat FataIs:	0				HMIS Major Artery: No	
Hazmat Injury:	No				HMIS Bulk Release: No	
Haz Hospital Empl:	0				HMIS Marine Pollutnt: No	
Haz Hospital Resp:	0				HMIS Radioactive: No	
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type: DRUM NON-METAL	
Haz Hosp Old Form:	0				HMIS Container Code: DRUM PLS	
Total Haz Hosp Inj:	0				HMIS Container Desc: Plastic drum	
Haz Non Hosp Empl:	0				HMIS Bulk Incident: No	
Haz Non Hosp Resp:	0				Undeclared Shipment: No	
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2012120262	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2012-11-26	Report Submit Src:	XML
Time of Incident:	1632	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL	Transport Phase:	Unloading
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1219	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.039062	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	139	CR State:	PA
What Failed Desc:	O-Ring or Seals	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:		Shipper Name:	ACUTE CARE/CAT KITS
Cont1 Pkging Type:	Box	Shipper Street Name:	12225 WORLD TRADE DR
Cont1 Const Mat:	Fiberboard	Shipper City:	SAN DIEGO
Cont1 Head Type:		Shipper State:	CA
Cont1 Pkg Capacity:	0	Shipper Postal:	92128
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	62974362592636
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:	Fiberboard	Destination City:	BERKELEY LAKE
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30096

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No: X-2012090263
Report Type: A hazardous material incident

Fed DOT Agency Nm:
Fed DOT Report No:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Date of Incident:	2012-08-28				Report Submit Src:	XML
Time of Incident:	2330				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL				Transport Phase:	Unloading
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1219				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.26418				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	305				CR Non US State:	
How Failed Desc:	Crushed				CR Fed DOT ID:	265752
Failure Cause Code:	515				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Human Error				CR Country:	US
Ident. Markings:	4G/Y11.5/S/11				Shipper Name:	Xzilon Inc
Cont1 Pkging Type:					Shipper Street Name:	3384 W Osborn Rd
Cont1 Const Mat:					Shipper City:	Phoenix
Cont1 Head Type:					Shipper State:	AZ
Cont1 Pkg Capacity:	0				Shipper Postal:	85017
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	709667230302850
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	LOGANVILLE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30052
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2012100028	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2012-09-06	Report Submit Src:	XML
Time of Incident:	2100	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	PENTANES	Transport Phase:	Unloading
Commodity Long Nm:	PENTANES	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1265	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.26418	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108
How Failed Code:	304	CR Non US State:	
How Failed Desc:	Cracked	CR Fed DOT ID:	265752
Failure Cause Code:	502	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Broken Component or Device	CR Country:	US
Ident. Markings:	4G/X10.9/S/12/USA/M4109	Shipper Name:	sigma-aldrich inc
Cont1 Pkging Type:		Shipper Street Name:	6000 N Tuetonia Avenue
Cont1 Const Mat:		Shipper City:	Brown Deer
Cont1 Head Type:		Shipper State:	WI
Cont1 Pkg Capacity:	0	Shipper Postal:	53209
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	36553821007246
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:		0
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:		0
RAM Transport Index:				Evacuation Indicator:		No
RAM UOM:				Public Evacuated:		0
RAM Activity Rpted:	0			Employees Evac:		0
RAM UOM Rpted:				Total Evacuated:		0
RAM Activity:	0			Total Evacuation Hrs:		0
RAM Activity UOM:				Major Artery Closed:		No
RAM Mat Safety:				Mjr Artery Hrs Closed:		0
Spillage Result:	Yes			Material Involved:		No
Fire Result:	No			Estimated Speed:		0
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:		No
Gas Dispersion:	No			Vehicle Left Roadway:		No
Environment Damage:	No			Passenger Aircraft:		No
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:		No
Fire EMS EMS Report:				Ship Air First Flight:		No
Police Report:	No			Ship Air Subflight:		No
Police Report No:				Ship Init Transport:		No
In House Cleanup:	Yes			Ship Phase Transfer:		No
Other Cleanup:	No			Contact Name:		GEORGE FETSKO
Damage > 500:	No			Contact Title:		SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0			Contact Business:		Fedex Ground Package System, Inc.
Carrier Damage:	0			Contact Street:		1000 Fedex Drive
Property Damage:	0			Contact City:		Moon Township
Response Cost:	0			Contact State:		PA
Remediation Cost:	0			Contact Postal:		15108
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:		US
Hazmat Fatality:	No			Inc. Report Prepared:		Carrier
Haz Fatal Employees:	0			HMIS Serious Incidnt:		No
Haz Fatal Respndrs:	0			HMIS Serious Fatality:		No
Haz Fatal Gen Public:	0			HMIS Serious Injury:		No
Tot Hazmat Fatalities:	0			HMIS Flight Plan:		No
Non Hazmat Fatality:	No			HMIS Serious Evacs:		No
Non Hazmat Fatals:	0			HMIS Major Artery:		No
Hazmat Injury:	No			HMIS Bulk Release:		No
Haz Hospital Empl:	0			HMIS Marine Pollutnt:		No
Haz Hospital Resp:	0			HMIS Radioactive:		No
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:		BOX FIBER
Haz Hosp Old Form:	0			HMIS Container Code:		4G
Total Haz Hosp Inj:	0			HMIS Container Desc:		Fiberboard box
Haz Non Hosp Empl:	0			HMIS Bulk Incident:		No
Haz Non Hosp Resp:	0			Undeclared Shipment:		No
Description of Events:		The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>HMIR Incident Reports</u>						
Report No:	X-2016040256				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2016-03-11				Report Submit Src:	XML
Time of Incident:	1016				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	ADHESIVES, CONTAINING A				Transport Phase:	In Transit
Commodity Long Nm:	ADHESIVES, CONTAINING A FLAMMABLE LIQUID				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1133				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.007812				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/Y12.5/S/14				Shipper Name:	Deckrite LLC
Cont1 Pkging Type:					Shipper Street Name:	3912 e progress street
Cont1 Const Mat:					Shipper City:	NORTH LITTLE ROCK
Cont1 Head Type:					Shipper State:	AR
Cont1 Pkg Capacity:	0				Shipper Postal:	72114
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	60750426625
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	DORAVILLE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30360
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srv Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srv Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2016090346				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2016-08-22				Report Submit Src:	XML
Time of Incident:	2024				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	5.1				Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE				Transport Phase:	Unloading
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES, STABILIZED WITH ACIDS, WATER, AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID				Incident Occrrnce:	
Trade Name:	stabilized				Mat Ship Approval?:	No
ID No:	UN3149				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.007812				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:					Shipper Name:	Medivator Inc
Cont1 Pkging Type:	Box				Shipper Street Name:	14605 28TH AVE N

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Const Mat:	Fiberboard				Shipper City:	Minneapolis
Cont1 Head Type:					Shipper State:	MN
Cont1 Pkg Capacity:	0				Shipper Postal:	55447
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	91101235082389
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2012100044				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2012-09-06				Report Submit Src:	XML
Time of Incident:	2130				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	HYDROCHLORIC ACID, SOLUT				Transport Phase:	Unloading
Commodity Long Nm:	HYDROCHLORIC ACID, SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1789				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.52836				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	305				CR Non US State:	
How Failed Desc:	Crushed				CR Fed DOT ID:	265752
Failure Cause Code:	534				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Too Much Weight on Package				CR Country:	US
Ident. Markings:	4G/Y32/S/12				Shipper Name:	VWR International LLC
Cont1 Pkging Type:					Shipper Street Name:	1050 Satellite Blvd
Cont1 Const Mat:					Shipper City:	Suwanee
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30024
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	408394871018027
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:					Destination City:	COLUMBUS
C1 Pkg Dsign Pres.:	0				Destination State:	MISSISSIPPI
C1 Dsign Press UOM:					Destination Postal:	39701
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	Moon Township	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:		The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:	X-2012100064			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	2012-09-07			Report Submit Src:	XML	
Time of Incident:	2247			Inc Multiple Rows:	No	
Haz Class Code:				Inc Non US State:		
Hazardous Class:	3			Mode Transport:	Highway	
Commodity Short Nm:	HEXANES			Transport Phase:	Loading	
Commodity Long Nm:	HEXANES			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1208			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	Fedex Ground Package System, Inc.	
Qty Released:	0.52836			CR Street Name:	1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon			CR City:	Moon Township	
What Failed:	104			CR State:	PA	
What Failed Desc:	Body			CR Postal Code:	15108	
How Failed Code:	303			CR Non US State:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
How Failed Desc:	Burst or Ruptured				CR Fed DOT ID: 265752	
Failure Cause Code:	511				CR Hazmat Reg ID: 051910551007S	
Failure Cause Desc:	Dropped				CR Country: US	
Ident. Markings:	4G/Y28.1/S/12				Shipper Name: Thermo Fisher Scientific	
Cont1 Pkging Type:					Shipper Street Name: 2775 horizon ridge ct	
Cont1 Const Mat:					Shipper City: Suwanee	
Cont1 Head Type:					Shipper State: GA	
Cont1 Pkg Capacity:	0				Shipper Postal: 30024	
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country: US	
C1 Pkg Amt UOM:					Shipper Waybill: 39064577779242	
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City: GULFPORT	
C1 Pkg Dsign Pres.:	0				Destination State: MISSISSIPPI	
C1 Dsign Press UOM:					Destination Postal: 39501	
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country: US	
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srv Pres.:	0				Cont2 Pkg Capacity: 0	
C1 Srv Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount: 0	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No: 0	
C1 Device Model:					Cont2 Pkg No Failed: 0	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public: 0	
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries: 0	
RAM Transport Index:					Evacuation Indicator: No	
RAM UOM:					Public Evacuated: 0	
RAM Activity Rpted:	0				Employees Evac: 0	
RAM UOM Rpted:					Total Evacuated: 0	
RAM Activity:	0				Total Evacuation Hrs: 0	
RAM Activity UOM:					Major Artery Closed: No	
RAM Mat Safety:					Mjr Artery Hrs Closed: 0	
Spillage Result:	Yes				Material Involved: No	
Fire Result:	No				Estimated Speed: 0	
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn: No	
Gas Dispersion:	No				Vehicle Left Roadway: No	
Environment Damage:	No				Passenger Aircraft: No	
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport: No	
Fire EMS EMS Report:					Ship Air First Flight: No	
Police Report:	No				Ship Air Subflight: No	
Police Report No:					Ship Init Transport: No	
In House Cleanup:	Yes				Ship Phase Transfer: No	
Other Cleanup:	No				Contact Name: GEORGE FETSKO	
Damage > 500:	No				Contact Title: SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0				Contact Business: Fedex Ground Package System, Inc.	
Carrier Damage:	0				Contact Street: 1000 Fedex Drive	
Property Damage:	0				Contact City: Moon Township	
Response Cost:	0				Contact State: PA	
Remediation Cost:	0				Contact Postal: 15108	
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country: US	
Hazmat Fatality:	No				Inc. Report Prepared: Carrier	
Haz Fatal Employees:	0				HMIS Serious Incidnt: No	
Haz Fatal Respntrs:	0				HMIS Serious Fatality: No	
Haz Fatal Gen Public:	0				HMIS Serious Injury: No	
Tot Hazmat Fatalities:	0				HMIS Flight Plan: No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2012110225	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2012-10-19	Report Submit Src:	XML
Time of Incident:	1430	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS, N.O.S.	Transport Phase:	Unloading
Commodity Long Nm:	FLAMMABLE LIQUIDS, N.O.S.	Incident Occrrnce:	
Trade Name:	XYLENE ETHYLBENZENE	Mat Ship Approval?:	No
ID No:	UN1993	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.066045	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	CERTIFIED LABS
Cont1 Pkging Type:	Box	Shipper Street Name:	2730 CARL RD
Cont1 Const Mat:	Fiberboard	Shipper City:	Irving
Cont1 Head Type:		Shipper State:	TX
Cont1 Pkg Capacity:	0	Shipper Postal:	75062
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	76974570463783
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:	Fiberboard	Destination City:	CUMMING
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30041
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	Bottle
C1 Head Thick UOM:		Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0	Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	0
C1 Device Type:		Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:		Cont2 Pkg No:	0
C1 Device Model:		Cont2 Pkg No Failed:	0
NRC No:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:					The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.	

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2013040173	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2013-03-21	Report Submit Src:	XML
Time of Incident:	1645	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	5.1	Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	Transport Phase:	Loading
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES, STABILIZED WITH ACIDS, WATER, AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	Incident Occrrnce:	
Trade Name:	stabilized	Mat Ship Approval?:	No
ID No:	UN3149	Mat Ship Approv No:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.026418				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	Mar Cor Purification
Cont1 Pkging Type:	Box				Shipper Street Name:	14550 28th Ave N
Cont1 Const Mat:	Fiberboard				Shipper City:	Minneapolis
Cont1 Head Type:					Shipper State:	MN
Cont1 Pkg Capacity:	0				Shipper Postal:	55447
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	753963334386910
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30309
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	BOX FBR	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box or carton	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2016030412	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2016-02-23	Report Submit Src:	XML
Time of Incident:	1046	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	METHANOL	Transport Phase:	In Transit
Commodity Long Nm:	METHANOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1230	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.007812	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	VWR International llc
Cont1 Pkging Type:	Box	Shipper Street Name:	1050 Satellite blvd nw
Cont1 Const Mat:	Fiberboard	Shipper City:	Suwanee
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30024
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	408394874378036
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:	Fiberboard	Destination City:	HIALEAH
C1 Pkg Dsign Pres.:	0	Destination State:	FLORIDA
C1 Dsign Press UOM:		Destination Postal:	33014
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	Bottle

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respntrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	BOX FBR	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box or carton	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:						

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2014050261	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2014-04-21	Report Submit Src:	XML
Time of Incident:	1816	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazardous Class:	5.1				Mode Transport: Highway	
Commodity Short Nm:	TRICHLOROISOCYANURIC ACI				Transport Phase: Loading	
Commodity Long Nm:	TRICHLOROISOCYANURIC ACID, DRY				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?: No	
ID No:	UN2468				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?: No	
Haz Waste EPA No:					Packaging Type: Non-Bulk	
HMIS Tox Inhalation?:	No				Packing Group: II	
TIH Hazard Zone:					Carrier Reporter: Fedex Ground Package System, Inc.	
Qty Released:	1				CR Street Name: 1000 Fedex Drive	
Unit of Measure:	Solid - Pound				CR City: Moon Township	
What Failed:	109				CR State: PA	
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code: 15108	
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID: 265752	
Failure Cause Code:	526				CR Hazmat Reg ID: 051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country: US	
Ident. Markings:					Shipper Name: BIOLAB, INC	
Cont1 Pkging Type:	Box				Shipper Street Name: 1350 LESTER RD NW	
Cont1 Const Mat:	Fiberboard				Shipper City: Conyers	
Cont1 Head Type:					Shipper State: GA	
Cont1 Pkg Capacity:	0				Shipper Postal: 30012	
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country: US	
C1 Pkg Amt UOM:					Shipper Waybill: 423630401673489	
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City: SUWANEE	
C1 Pkg Dsign Pres.:	0				Destination State: GEORGIA	
C1 Dsign Press UOM:					Destination Postal: 30024	
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country: US	
C1 Head Thickness:	0				Cont2 Package Type: Can	
C1 Head Thick UOM:					Cont2 Const Mat: Plastic	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity: 0	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount: 0	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No: 0	
C1 Device Model:					Cont2 Pkg No Failed: 0	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public: 0	
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries: 0	
RAM Transport Index:					Evacuation Indicator: No	
RAM UOM:					Public Evacuated: 0	
RAM Activity Rpted:	0				Employees Evac: 0	
RAM UOM Rpted:					Total Evacuated: 0	
RAM Activity:	0				Total Evacuation Hrs: 0	
RAM Activity UOM:					Major Artery Closed: No	
RAM Mat Safety:					Mjr Artery Hrs Closed: 0	
Spillage Result:	Yes				Material Involved: No	
Fire Result:	No				Estimated Speed: 0	
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn: No	
Gas Dispersion:	No				Vehicle Left Roadway: No	
Environment Damage:	No				Passenger Aircraft: No	
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport: No	
Fire EMS EMS Report:					Ship Air First Flight: No	
Police Report:	No				Ship Air Subflight: No	
Police Report No:					Ship Init Transport: No	
In House Cleanup:	Yes				Ship Phase Transfer: No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2014020161				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2014-01-24				Report Submit Src:	XML
Time of Incident:	1625				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	COMPOUNDS, CLEANING LIQU				Transport Phase:	Loading
Commodity Long Nm:	COMPOUNDS, CLEANING LIQUID				Incident Occrrnce:	
Trade Name:	acetone				Mat Ship Approval?:	No
ID No:	NA1993				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	309				CR Non US State:	
How Failed Desc:	Punctured				CR Fed DOT ID:	265752
Failure Cause Code:	516				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g., nails)				CR Country:	US
Ident. Markings:					Shipper Name:	PRINTERS SVC
Cont1 Pkging Type:	Drum				Shipper Street Name:	7055 AMWILER INDUSTRIAL DR
Cont1 Const Mat:	Aluminum				Shipper City:	DORAVILLE
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30360
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	30738232506229
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Test Const Mat:	Aluminum				Destination City:	CONYERS
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30013
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM METAL
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM MTL
Total Haz Hosp Inj:	0				HMIS Container Desc:	Metal drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report No:	X-2015070182				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2015-06-15				Report Submit Src:	XML
Time of Incident:	1035				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	5.1				Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE, AQUEO				Transport Phase:	In Transit
Commodity Long Nm:	HYDROGEN PEROXIDE, AQUEOUS SOLUTIONS WITH NOT LESS THAN 20 PERCENT BUT NOT MORE THAN 40 PERCENT HYDROGEN PEROXIDE (STABILIZED AS NECESSARY)				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN2014				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.5				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/Y19.7/S/15/USA/+BZ0854				Shipper Name:	NATIONAL DISCOUNT POOL
Cont1 Pkging Type:					Shipper Street Name:	8920 58th pl
Cont1 Const Mat:					Shipper City:	Kenosha
Cont1 Head Type:					Shipper State:	WI
Cont1 Pkg Capacity:	0				Shipper Postal:	53144
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	37332887696
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	LAWRENCEVILLE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30045
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2013030227	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2013-02-25	Report Submit Src:	XML
Time of Incident:	1654	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,	Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.	Incident Occrrnce:	
Trade Name:	contains Phosphates	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	2	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108
How Failed Code:	305	CR Non US State:	
How Failed Desc:	Crushed	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:		Shipper Name:	A.B.C. COMPOUNDING COMPANY
Cont1 Pkging Type:	Box	Shipper Street Name:	6970 JONESBORO RD
Cont1 Const Mat:	Fiberboard	Shipper City:	Lake City
Cont1 Head Type:		Shipper State:	GA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Capacity:	0				Shipper Postal:	30260
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	31858262223176
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	SUWANEE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30024
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2018090371				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2018-08-27				Report Submit Src:	XML
Time of Incident:	2000				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	FORMIC ACID WITH MORE TH				Transport Phase:	Unloading
Commodity Long Nm:	FORMIC ACID WITH MORE THAN 85% ACID BY MASS				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1779				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/X9/S/18/USA/M4109				Shipper Name:	SIGMA-ALDRICH
Cont1 Pkgg Type:	Box				Shipper Street Name:	6000 N TEUTONIA AVENUE
Cont1 Const Mat:	Fiberboard				Shipper City:	MILWAUKEE
Cont1 Head Type:					Shipper State:	WI
Cont1 Pkg Capacity:	0				Shipper Postal:	53209
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	365538036553874598869
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	TUCKER
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30084
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srv Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srv Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: PACKAGE WAS FOUND WET ON DOCK. AS I LOOKED INSIDE THERE WAS A BOTTLE OF FORMIC ACID WITH A LOOSE CAP New Comments:					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2018040130	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2018-03-12	Report Submit Src:	XML
Time of Incident:	2345	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL	Transport Phase:	Unloading
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1219	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB		
Failure Cause Desc:	Loose Closure, Component, or Device			CR Country:	US			
Ident. Markings:	4G/Y26.9/S/17/USA/+AA7295			Shipper Name:	Fisher Scientific			
Cont1 Pkging Type:				Shipper Street Name:	2775 Horizon Ridge Ct			
Cont1 Const Mat:				Shipper City:	Suwanee			
Cont1 Head Type:				Shipper State:	GA			
Cont1 Pkg Capacity:	0			Shipper Postal:	30024			
C1 Capacity UOM:				Shipper Non US St:				
Cont1 Pkg Amt:	0			Shipper Country:	US			
C1 Pkg Amt UOM:				Shipper Waybill:	39064596123020390645724812			
Cont1 Pkg No:	0			Ship Hazmat Reg ID:				
C1 Pkg NO Failed:	0			Origin City:				
Cont1 Pkg Mnfctr:				Origin State:				
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00			Origin Postal:				
Cont1 Pkg Serial NO:				Origin Non US St:				
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:				
C1 Test Const Mat:				Destination City:	ORLANDO			
C1 Pkg Dsign Pres.:	0			Destination State:	FLORIDA			
C1 Dsign Press UOM:				Destination Postal:	32827			
C1 Pkg Shell Thick:	0			Destination Non US:				
C1 Shell Thick UOM:				Destination Country:	US			
C1 Head Thickness:	0			Cont2 Package Type:				
C1 Head Thick UOM:				Cont2 Const Mat:				
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0			
C1 Srvc Press UOM:				Cont2 Capacity UOM:				
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0			
C1 Device Type:				Cont2 Pkg Amt UOM:				
C1 Device Mnfctr:				Cont2 Pkg No:	0			
C1 Device Model:				Cont2 Pkg No Failed:	0			
NRC No:								
RAM Pkg Category:				Haz NonHosp Public:	0			
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:				
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:				
RAM Nuclide S:				Total Hazmat Injuries:	0			
RAM Transport Index:				Evacuation Indicator:	No			
RAM UOM:				Public Evacuated:	0			
RAM Activity Rpted:	0			Employees Evac:	0			
RAM UOM Rpted:				Total Evacuated:	0			
RAM Activity:	0			Total Evacuation Hrs:	0			
RAM Activity UOM:				Major Artery Closed:	No			
RAM Mat Safety:				Mjr Artery Hrs Closed:	0			
Spillage Result:	Yes			Material Involved:	No			
Fire Result:	No			Estimated Speed:	0			
Explosion Result:	No			Weather Conditions:				
Water Sewer Result:	No			Vehicle Overturn:	No			
Gas Dispersion:	No			Vehicle Left Roadway:	No			
Environment Damage:	No			Passenger Aircraft:	No			
No Release Result:	No			Cargo Baggage:				
Fire EMS Report:	No			Ship Non Transport:	No			
Fire EMS EMS Report:				Ship Air First Flight:	No			
Police Report:	No			Ship Air Subflight:	No			
Police Report No:				Ship Init Transport:	No			
In House Cleanup:	Yes			Ship Phase Transfer:	No			
Other Cleanup:	No			Contact Name:	GEORGE FETSKO			
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR			
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.			
Carrier Damage:	0			Contact Street:	1000 Fedex Drive			
Property Damage:	0			Contact City:	CORAOPOLIS			
Response Cost:	0			Contact State:	PA			
Remediation Cost:	0			Contact Postal:	15108			
Damage Old Form:	0			Contact Non US St:				
Total Damages Amt:	0			Contact Country:	US			
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier			
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No			
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No			
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No			
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No			
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No			
Non Hazmat Fatafs:	0			HMIS Major Artery:	No			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: Package was found on the dock wet. As I looked inside I notice 4 1gal bottles of isopropanol but 1 bottle had a loose cap New Comments:					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2018040290				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2018-03-21				Report Submit Src:	XML
Time of Incident:	2200				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,				Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.				Incident Occrrnce:	
Trade Name:	CONTAINS SODIUM MET				Mat Ship Approval?:	No
ID No:	UN3266				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	A.B.C. COMPOUNDING COMPANY, IN
Cont1 Pkging Type:	Drum				Shipper Street Name:	2001 Deere Dr SE
Cont1 Const Mat:	Metal other than steel or aluminum				Shipper City:	Conyers
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30013
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	318582412826165842
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Metal other than steel or aluminum				Destination City:	SUWANEE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30024
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	CONTAINER
Haz Hosp Old Form:	0				HMIS Container Code:	CONT
Total Haz Hosp Inj:	0				HMIS Container Desc:	Container, no description given (do not use if at all possible)
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:		Original comments: ONE BOTTLE HAD A LOOSE CAP New Comments:				
Recommend Actions Taken:						

HMIR Incident Reports

Report No:	X-2017100130	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2017-09-13	Report Submit Src:	XML
Time of Incident:	1044	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	DISINFECTANTS, LIQUID, C	Transport Phase:	Loading
Commodity Long Nm:	DISINFECTANTS, LIQUID, CORROSIVE N.O. S.	Incident Occrrnce:	
Trade Name:	(quatemary ammonium	Mat Ship Approval?:	No
ID No:	UN1903	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.52836	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)			CR Postal Code:	15108	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device			CR Country:	US	
Ident. Markings:	4G/y23.9/s/17/usa/+BR10195			Shipper Name:	NXKEM USA LLC	
Cont1 Pkgng Type:				Shipper Street Name:	7855 N Faulkner Rd	
Cont1 Const Mat:				Shipper City:	Milwaukee	
Cont1 Head Type:				Shipper State:	WI	
Cont1 Pkg Capacity:	0			Shipper Postal:	53224	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	172416830172118	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:	US	
C1 Test Const Mat:				Destination City:	NORCROSS	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30071	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No

Description of Events:

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2014090158	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2014-08-15	Report Submit Src:	XML
Time of Incident:	1746	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	ACETONE	Transport Phase:	Loading
Commodity Long Nm:	ACETONE	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1090	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.25	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	N/A
Cont1 Pkging Type:	Box	Shipper Street Name:	ILLEGIBLE
Cont1 Const Mat:	Fiberboard	Shipper City:	Norcross
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30071
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	111111111111111
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:	Fiberboard	Destination City:	NORCROSS
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30071
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	Can
C1 Head Thick UOM:		Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvs Pres.:	0	Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	0
C1 Device Type:		Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:		Cont2 Pkg No:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Device Model:				Cont2 Pkg No Failed:		0
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:		0
RAM Pkg Cert.:		FALSE	Haz NonHosp Old:			
RAM Pkg Cert. NBR:			Tot Haz Non Hosp Inj:			
RAM Nuclide S:			Total Hazmat Injuries:		0	
RAM Transport Index:			Evacuation Indicator:		No	
RAM UOM:			Public Evacuated:		0	
RAM Activity Rpted:		0	Employees Evac:		0	
RAM UOM Rpted:			Total Evacuated:		0	
RAM Activity:		0	Total Evacuation Hrs:		0	
RAM Activity UOM:			Major Artery Closed:		No	
RAM Mat Safety:			Mjr Artery Hrs Closed:		0	
Spillage Result:		Yes	Material Involved:		No	
Fire Result:		No	Estimated Speed:		0	
Explosion Result:		No	Weather Conditions:			
Water Sewer Result:		No	Vehicle Overturn:		No	
Gas Dispersion:		No	Vehicle Left Roadway:		No	
Environment Damage:		No	Passenger Aircraft:		No	
No Release Result:		No	Cargo Baggage:			
Fire EMS Report:		No	Ship Non Transport:		No	
Fire EMS EMS Report:			Ship Air First Flight:		No	
Police Report:		No	Ship Air Subflight:		No	
Police Report No:			Ship Init Transport:		No	
In House Cleanup:		Yes	Ship Phase Transfer:		No	
Other Cleanup:		No	Contact Name:		GEORGE FETSKO	
Damage > 500:		No	Contact Title:		HAZMAT - SAFETY ADVISOR	
Material Loss:		0	Contact Business:		Fedex Ground Package System, Inc.	
Carrier Damage:		0	Contact Street:		1000 Fedex Drive	
Property Damage:		0	Contact City:		CORAOPOLIS	
Response Cost:		0	Contact State:		PA	
Remediation Cost:		0	Contact Postal:		15108	
Damage Old Form:		0	Contact Non US St:			
Total Damages Amt:		0	Contact Country:		US	
Hazmat Fatality:		No	Inc. Report Prepared:		Carrier	
Haz Fatal Employees:		0	HMIS Serious Incidnt:		No	
Haz Fatal Respndrs:		0	HMIS Serious Fatality:		No	
Haz Fatal Gen Public:		0	HMIS Serious Injury:		No	
Tot Hazmat Fatalities:		0	HMIS Flight Plan:		No	
Non Hazmat Fatality:		No	HMIS Serious Evacs:		No	
Non Hazmat Fatals:		0	HMIS Major Artery:		No	
Hazmat Injury:		No	HMIS Bulk Release:		No	
Haz Hospital Empl:		0	HMIS Marine Pollutnt:		No	
Haz Hospital Resp:		0	HMIS Radioactive:		No	
Haz Hosp Gen Public:		0	HMIS Gen Pkg Type:		BOX FIBER	
Haz Hosp Old Form:		0	HMIS Container Code:		BOX FBR	
Total Haz Hosp Inj:		0	HMIS Container Desc:		Fiberboard box or carton	
Haz Non Hosp Empl:		0	HMIS Bulk Incident:		No	
Haz Non Hosp Resp:		0	Undeclared Shipment:		No	
Description of Events:		The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:		X-2014100088		Fed DOT Agency Nm:		
Report Type:		A hazardous material incident		Fed DOT Report No:		
Date of Incident:		2014-09-08		Report Submit Src:		XML
Time of Incident:		2200		Inc Multiple Rows:		No
Haz Class Code:				Inc Non US State:		
Hazardous Class:		3		Mode Transport:		Highway
Commodity Short Nm:		ISOPROPANOL OR ISOPROPYL		Transport Phase:		In Transit
Commodity Long Nm:		ISOPROPANOL OR ISOPROPYL ALCOHOL		Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:		No
ID No:		UN1219		Mat Ship Approv No:		
Haz Waste Ind:		No		Undecl Hazmat Ship?:		No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/Y5.2/S/16/USA/+ AI4406				Shipper Name:	MCKESSON HBOC COMPANY
Cont1 Pkging Type:					Shipper Street Name:	2975 EVERGREEN DR
Cont1 Const Mat:					Shipper City:	Berkeley Lake
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30096
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	30816977808942
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	MILWAUKEE
C1 Pkg Dsign Pres.:	0				Destination State:	WISCONSIN
C1 Dsign Press UOM:					Destination Postal:	53205
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatafs:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2013110321	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2013-11-01	Report Submit Src:	XML
Time of Incident:	1635	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	ETHANOL SOLUTIONS	Transport Phase:	Loading
Commodity Long Nm:	ETHANOL SOLUTIONS	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1170	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108
How Failed Code:	309	CR Non US State:	
How Failed Desc:	Punctured	CR Fed DOT ID:	265752
Failure Cause Code:	522	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Inadequate Procedures	CR Country:	US
Ident. Markings:		Shipper Name:	Univar USA
Cont1 Pkging Type:	Drum	Shipper Street Name:	1 Alchemy Place
Cont1 Const Mat:	Aluminum	Shipper City:	Atlanta
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30360
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	23940115003552
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:	Aluminum	Destination City:	SPRING HILL
C1 Pkg Dsign Pres.:	0	Destination State:	TENNESSEE
C1 Dsign Press UOM:		Destination Postal:	37174
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfrctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM METAL
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM MTL
Total Haz Hosp Inj:	0				HMIS Container Desc:	Metal drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						
						The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2014070404				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2014-06-26				Report Submit Src:	XML
Time of Incident:	1717				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Commodity Short Nm:	ACETONITRILE				Transport Phase:	Loading
Commodity Long Nm:	ACETONITRILE				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1648				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.26418				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	303				CR Non US State:	
How Failed Desc:	Burst or Ruptured				CR Fed DOT ID:	265752
Failure Cause Code:	502				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Broken Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	ALDRICH CHEMICAL CO
Cont1 Pkging Type:	Box				Shipper Street Name:	6000 N TEUTONIA AVE
Cont1 Const Mat:	Fiberboard				Shipper City:	Brown Deer
Cont1 Head Type:					Shipper State:	WI
Cont1 Pkg Capacity:	0				Shipper Postal:	53209
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	36553832746080
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfcct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2014080098	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2014-07-10	Report Submit Src:	XML
Time of Incident:	1655	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS, N.O.S.	Transport Phase:	Loading
Commodity Long Nm:	FLAMMABLE LIQUIDS, N.O.S.	Incident Occrrnce:	
Trade Name:	Alcohol Solution	Mat Ship Approval?:	No
ID No:	UN1993	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	N/A
Cont1 Pkging Type:	Box	Shipper Street Name:	ILLEGIBLE
Cont1 Const Mat:	Fiberboard	Shipper City:	Norcross
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30071
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	111111111111113
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:	Fiberboard	Destination City:	NORCROSS
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Dsign Press UOM:					Destination Postal:	30071
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:			The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.			

Recommend Actions Taken:

HMIR Incident Reports

Report No: X-2018120223

Fed DOT Agency Nm:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2018-11-07				Report Submit Src:	XML
Time of Incident:	1900				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI				Transport Phase:	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	ECOLAB/CEVA LOGISTICS
Cont1 Pkging Type:	Drum				Shipper Street Name:	125 SOUTHSIDE CT
Cont1 Const Mat:	Plastic				Shipper City:	MCDONOUGH
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30253
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	916079075465184
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30340
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srv Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srv Pres UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatafs:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	CONTAINER	
Haz Hosp Old Form:	0			HMIS Container Code:	CONT	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Container, no description given (do not use if at all possible)	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	Original comments: PACKAGE FOUND WITH LOOSE CAP AND LEAKING New Comments:					
Recommend Actions Taken:						

HMIR Incident Reports

Report No:	X-2019050628	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2019-04-15	Report Submit Src:	XML
Time of Incident:	2200	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL	Transport Phase:	Unloading
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1219	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.375	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G/Y19.4/S/19USA/+AB2733	Shipper Name:	Fedex Ground
Cont1 Pkging Type:	Box	Shipper Street Name:	6265 Atlantic Blvd
Cont1 Const Mat:	Fiberboard	Shipper City:	NORCROSS
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30071
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	8890301889030110696496
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	FLORENCE
C1 Pkg Dsign Pres.:	0				Destination State:	KENTUCKY
C1 Dsign Press UOM:					Destination Postal:	41042
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:		0
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:		0
RAM Transport Index:				Evacuation Indicator:		No
RAM UOM:				Public Evacuated:		0
RAM Activity Rpted:	0			Employees Evac:		0
RAM UOM Rpted:				Total Evacuated:		0
RAM Activity:	0			Total Evacuation Hrs:		0
RAM Activity UOM:				Major Artery Closed:		No
RAM Mat Safety:				Mjr Artery Hrs Closed:		0
Spillage Result:	Yes			Material Involved:		No
Fire Result:	No			Estimated Speed:		0
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:		No
Gas Dispersion:	No			Vehicle Left Roadway:		No
Environment Damage:	No			Passenger Aircraft:		No
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:		No
Fire EMS EMS Report:				Ship Air First Flight:		No
Police Report:	No			Ship Air Subflight:		No
Police Report No:				Ship Init Transport:		No
In House Cleanup:	Yes			Ship Phase Transfer:		No
Other Cleanup:	No			Contact Name:		GEORGE FETSKO
Damage > 500:	No			Contact Title:		HAZMAT - SAFETY ADVISOR
Material Loss:	0			Contact Business:		Fedex Ground Package System, Inc.
Carrier Damage:	0			Contact Street:		1000 Fedex Drive
Property Damage:	0			Contact City:		CORAOPOLIS
Response Cost:	0			Contact State:		PA
Remediation Cost:	0			Contact Postal:		15108
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:		US
Hazmat Fatality:	No			Inc. Report Prepared:		Carrier
Haz Fatal Employees:	0			HMIS Serious Incidnt:		No
Haz Fatal Respndrs:	0			HMIS Serious Fatality:		No
Haz Fatal Gen Public:	0			HMIS Serious Injury:		No
Tot Hazmat Fatalities:	0			HMIS Flight Plan:		No
Non Hazmat Fatality:	No			HMIS Serious Evacs:		No
Non Hazmat Fatals:	0			HMIS Major Artery:		No
Hazmat Injury:	No			HMIS Bulk Release:		No
Haz Hospital Empl:	0			HMIS Marine Pollutnt:		No
Haz Hospital Resp:	0			HMIS Radioactive:		No
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:		BOX FIBER
Haz Hosp Old Form:	0			HMIS Container Code:		4G
Total Haz Hosp Inj:	0			HMIS Container Desc:		Fiberboard box
Haz Non Hosp Empl:	0			HMIS Bulk Incident:		No
Haz Non Hosp Resp:	0			Undeclared Shipment:		No
Description of Events:				The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>HMIR Incident Reports</u>						
Report No:	X-2017120249				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2017-11-15				Report Submit Src:	XML
Time of Incident:	0830				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI				Transport Phase:	In Transit
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.2				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	ECL-Kay
Cont1 Pkging Type:	Box				Shipper Street Name:	90 Piedmont Ind Drive
Cont1 Const Mat:	Fiberboard				Shipper City:	WINSTON SALEM
Cont1 Head Type:					Shipper State:	NC
Cont1 Pkg Capacity:	0				Shipper Postal:	27107
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	7577716757771683020470
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2017120331	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2017-11-24	Report Submit Src:	XML
Time of Incident:	1700	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	5.1	Mode Transport:	Highway
Commodity Short Nm:	CALCIUM HYPOCHLORITE, HY	Transport Phase:	Unloading
Commodity Long Nm:	CALCIUM HYPOCHLORITE, HYDRATED OR CALCIUM HYPOCHLORITE, HYDRATED MIXTURES, WITH NOT LESS THAN 5.5 PERCENT BUT NOT MORE THAN 16 PERCENT WATER	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN2880	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	Yes
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	15	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Solid - Pound	CR City:	Moon Township
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108
How Failed Code:	303	CR Non US State:	
How Failed Desc:	Burst or Ruptured	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	Ecolab
Cont1 Pkging Type:	Drum	Shipper Street Name:	125 Southside Ct
Cont1 Const Mat:	Metal other than steel or aluminum	Shipper City:	MCDONOUGH

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30253
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	889030132953331
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Metal other than steel or aluminum				Destination City:	ORMOND BEACH
C1 Pkg Dsign Pres.:	0				Destination State:	FLORIDA
C1 Dsign Press UOM:					Destination Postal:	32174
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM METAL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM MTL
Total Haz Hosp Inj:	0				HMIS Container Desc:	Metal drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	Yes
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2018040299				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2018-03-22				Report Submit Src:	XML
Time of Incident:	1400				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,				Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.				Incident Occrrnce:	
Trade Name:	sodium hydroxide				Mat Ship Approval?:	No
ID No:	UN3266				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.1875				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	A.B.C. COMPOUNDING COMPANY, IN
Cont1 Pkging Type:	Jerrican				Shipper Street Name:	2001 Deere Dr SE
Cont1 Const Mat:	Steel				Shipper City:	Conyers
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	1				Shipper Postal:	30013
C1 Capacity UOM:	LGA				Shipper Non US St:	
Cont1 Pkg Amt:	1				Shipper Country:	US
C1 Pkg Amt UOM:	LGA				Shipper Waybill:	318582412826165864
Cont1 Pkg No:	4				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	4				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Steel				Destination City:	SUWANEE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30024
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	CONTAINER
Haz Hosp Old Form:	0				HMIS Container Code:	CONT
Total Haz Hosp Inj:	0				HMIS Container Desc:	Container, no description given (do not use if at all possible)
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

Original comments: BOX WAS FOUND ON DOCK WET. AS I LOOKED INSIDE THE BOX THERE WERE 4 1GAL JUGS OF BRANSON GP FORMULATED CLEANING CONCENTRATE. ALL 4 JUGS HAD LOOSE CAPS. New Comments:

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2020060782	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2020-01-13	Report Submit Src:	XML
Time of Incident:	1800	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	Transport Phase:	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1824	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	1H				Shipper Name:	ECOLAB/CEVA LOGISTICS
Cont1 Pkging Type:	Drum				Shipper Street Name:	125 SOUTHSIDE CT
Cont1 Const Mat:	Plastic				Shipper City:	MCDONOUGH
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30253
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	9160790916079077319881
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	DULUTH
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30096
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM NON-METAL
Haz Hosp Old Form:	0				HMIS Container Code:	1H1
Total Haz Hosp Inj:	0				HMIS Container Desc:	Non-removable head plastic drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:	NO COMMENTS PROVIDED.					

HMIR Incident Reports

Report No:	X-2014110030	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2014-10-01	Report Submit Src:	XML
Time of Incident:	1730	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	POTASSIUM HYDROXIDE, SOL	Transport Phase:	Loading
Commodity Long Nm:	POTASSIUM HYDROXIDE, SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1814	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	5.000927	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108
How Failed Code:	309	CR Non US State:	
How Failed Desc:	Punctured	CR Fed DOT ID:	265752
Failure Cause Code:	516	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g., nails)	CR Country:	US
Ident. Markings:		Shipper Name:	STERIS CORPORATION
Cont1 Pkging Type:	Drum	Shipper Street Name:	8525 PAGE AVE
Cont1 Const Mat:	Plastic	Shipper City:	Breckenridge Hills
Cont1 Head Type:		Shipper State:	MO
Cont1 Pkg Capacity:	0	Shipper Postal:	63114-6014
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	63106975098390
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	US
C1 Test Const Mat:	Plastic	Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30329
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0	Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	0
C1 Device Type:		Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:		Cont2 Pkg No:	0
C1 Device Model:		Cont2 Pkg No Failed:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM NON-METAL
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2019110582				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2019-09-03				Report Submit Src:	XML
Time of Incident:	2200				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT, L				Transport Phase:	Unloading
Commodity Long Nm:	PAINT INCLUDING PAINT, LACQUER, ENAMEL, STAIN, SHELLAC SOLUTIONS, VARNISH, POLISH, LIQUID FILLER AND LIQUID LACQUER BASE				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
ID No:	UN1263				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	Fedex Ground
Cont1 Pkging Type:	Drum				Shipper Street Name:	6265 Atlantic Blvd.
Cont1 Const Mat:	Steel				Shipper City:	NORCROSS
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30071
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	8890301889030124738601
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Steel				Destination City:	SMYRNA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30082
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM METAL
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM MTL
Total Haz Hosp Inj:	0				HMIS Container Desc:	Metal drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2018050216	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2018-04-16	Report Submit Src:	XML
Time of Incident:	1730	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,	Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.	Incident Occrrnce:	
Trade Name:	(Contains potassuim	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G/Y19.4/S/18USA/+BZ1194	Shipper Name:	DIVERSITECH CORP.
Cont1 Pkging Type:	Box	Shipper Street Name:	2175 EAST PARK DR.
Cont1 Const Mat:	Fiberboard	Shipper City:	CONYERS
Cont1 Head Type:	Removable	Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30013
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	2506707434102111520
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	US
C1 Test Const Mat:	Fiberboard	Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30329
C1 Pkg Shell Thick:	0	Destination Non US:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfrctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatafs:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	Original comments: BOX WAS FOUND ON DOCK WET. AS I LOOKED INSIDE THERE WERE 4 1GAL BOTTLE OF TRIPLE D UNIVERSAL CLEANER BUT 2 BOTTLES HAD LOOSE CAPS New Comments:					
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:	X-2018060119			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	2018-05-09			Report Submit Src:	XML	
Time of Incident:	1500			Inc Multiple Rows:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Class Code:			Inc Non US State:			
Hazardous Class:	3			Mode Transport:	Highway	
Commodity Short Nm:	ETHANOL SOLUTIONS			Transport Phase:	Unloading	
Commodity Long Nm:	ETHANOL SOLUTIONS			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1170			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	Fedex Ground Package System, Inc.	
Qty Released:	0.1875			CR Street Name:	1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)			CR Postal Code:	15108	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device			CR Country:	US	
Ident. Markings:	4G/Y20.0/S/18,USA/AA8398			Shipper Name:	StatLab Medical Products	
Cont1 Pkging Type:	Box			Shipper Street Name:	2090 Commerce Drive	
Cont1 Const Mat:	Fiberboard			Shipper City:	MCKINNEY	
Cont1 Head Type:				Shipper State:	TX	
Cont1 Pkg Capacity:	0			Shipper Postal:	75069	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	1009093100909319999144	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	ATLANTA	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30309	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srv Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srv Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:			Haz NonHosp Public:			0
RAM Pkg Cert.:	FALSE		Haz NonHosp Old:			
RAM Pkg Cert. NBR:			Tot Haz Non Hosp Inj:			
RAM Nuclide S:			Total Hazmat Injuries:	0		
RAM Transport Index:			Evacuation Indicator:	No		
RAM UOM:			Public Evacuated:	0		
RAM Activity Rpted:	0		Employees Evac:	0		
RAM UOM Rpted:			Total Evacuated:	0		
RAM Activity:	0		Total Evacuation Hrs:	0		
RAM Activity UOM:			Major Artery Closed:	No		
RAM Mat Safety:			Mjr Artery Hrs Closed:	0		
Spillage Result:	Yes		Material Involved:	No		
Fire Result:	No		Estimated Speed:	0		
Explosion Result:	No		Weather Conditions:			
Water Sewer Result:	No		Vehicle Overturn:	No		
Gas Dispersion:	No		Vehicle Left Roadway:	No		
Environment Damage:	No		Passenger Aircraft:	No		
No Release Result:	No		Cargo Baggage:			
Fire EMS Report:	No		Ship Non Transport:	No		
Fire EMS EMS Report:			Ship Air First Flight:	No		
Police Report:	No		Ship Air Subflight:	No		
Police Report No:			Ship Init Transport:	No		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: BOX WAS FOUND ON DOCK WET. AS I LOOKED INSIDE THERE WERE 4 1GAL BOTTLES OF 100% REAGENT ALCOHOL BUT 1 BOTTLE HAD A LOOSE CAP. New Comments:					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2018120570				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2018-12-01				Report Submit Src:	XML
Time of Incident:	1700				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	FORMIC ACID WITH MORE TH				Transport Phase:	Unloading
Commodity Long Nm:	FORMIC ACID WITH MORE THAN 85% ACID BY MASS				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1779				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM, INC.
Qty Released:	0.125				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/X9/S/18/USA/M4109				Shipper Name:	Fedex Ground
Cont1 Pkging Type:	Box				Shipper Street Name:	Atlantic Blvd.
Cont1 Const Mat:	Fiberboard				Shipper City:	NORCROSS
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30071
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	889030133554766
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Test Const Mat:	Fiberboard				Destination City:	MILWAUKEE
C1 Pkg Dsign Pres.:	0				Destination State:	WISCONSIN
C1 Dsign Press UOM:					Destination Postal:	53209
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: BOX WAS FOUND WET ON DOCK. AS I LOOKED INSIDE THERE WAS A PLASTIC OF FORMIC ACID WITH A LOOSE CAP New Comments:					
Recommend Actions Taken:						

HMIR Incident Reports

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report No:	X-2017120286				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2017-11-21				Report Submit Src:	XML
Time of Incident:	0745				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, ACIDIC				Transport Phase:	Loading
Commodity Long Nm:	CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S.				Incident Occrrnce:	
Trade Name:	Phosphoric Acid, Hyd				Mat Ship Approval?:	No
ID No:	UN3264				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.25				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	Zep Nass GDC
Cont1 Pkging Type:	Box				Shipper Street Name:	71 Business Park Dr
Cont1 Const Mat:	Fiberboard				Shipper City:	Cartersville
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30121
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	486166002436745
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30324
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2018020267	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2018-01-24	Report Submit Src:	XML
Time of Incident:	0800	Inc Multiple Rows:	Yes
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	Transport Phase:	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1824	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G/Y24.7/S/17/USA/M4172	Shipper Name:	ECL-KAY
Cont1 Pkging Type:		Shipper Street Name:	90 PIEDMONT INDUSTRIAL DR
Cont1 Const Mat:		Shipper City:	WINSTON SALEM
Cont1 Head Type:		Shipper State:	NC
Cont1 Pkg Capacity:	0	Shipper Postal:	27107
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	7577716757771683146880
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

Original comments: PACKAGE WAS FOUND ON DOCK WET. SO I LOOK INSIDE THE BOX. APO N OPENING THE BOX THERE WAS 4 1GAL JUGS OF MACHINE WAREWASHI NG DETERGENT IN THE BOX BUT 2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
OF THE 1 GAL JUGS HAD LOOSE CAP S New Comments:						
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:	X-2018020267				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2018-01-24				Report Submit Src:	XML
Time of Incident:	0800				Inc Multiple Rows:	Yes
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI				Transport Phase:	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/Y24.7/S/17/USA/M4172				Shipper Name:	ECL-KAY
Cont1 Pkging Type:					Shipper Street Name:	90 PIEDMONT INDUSTRIAL DR
Cont1 Const Mat:					Shipper City:	WINSTON SALEM
Cont1 Head Type:					Shipper State:	NC
Cont1 Pkg Capacity:	0				Shipper Postal:	27107
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	7577716757771683146897
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:	No			Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatafs:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	Original comments: PACKAGE WAS FOUND ON DOCK WET. SO I LOOK INSIDE THE BOX. APO N OPENING THE BOX THERE WAS 4 1GAL JUGS OF MACHINE WAREWASHI NG DETERGENT IN THE BOX BUT 2 OFTHE 1GAL JUGS HAD LOOSE CAP S New Comments:					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2018050753	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2018-04-29	Report Submit Src:	XML
Time of Incident:	2300	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	Transport Phase:	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1824	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	NO MARKINGS GIVEN	Shipper Name:	ECOLAB/CEVA LOGISTICS
Cont1 Pkging Type:	Jerrican	Shipper Street Name:	125 SOUTHSIDE CT
Cont1 Const Mat:	Plastic	Shipper City:	MCDONOUGH
Cont1 Head Type:		Shipper State:	GA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Capacity:	0				Shipper Postal:	30253
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	916079074527821
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	
Haz Hosp Old Form:	0				HMIS Container Code:	NO MARKI

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Total Haz Hosp Inj:	0				HMIS Container Desc:	
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:		Original comments: Bucket of pail was found wet on dock. as I examined the pail I notice liquid leaking from cap New Comments:				
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:	X-2018050790				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2018-05-02				Report Submit Src:	XML
Time of Incident:	2302				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	DIESEL FUEL				Transport Phase:	Unloading
Commodity Long Nm:	DIESEL FUEL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1202				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625				CR Street Name:	1000 FEDEX DRIVE
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/Y28/S/15USA/+BR9196				Shipper Name:	INDIVIDUAL-NOT A COMPANY
Cont1 Pkging Type:	Box				Shipper Street Name:	4172 WINTERS CHAPEL RD
Cont1 Const Mat:	Fiberboard				Shipper City:	POMPANO BEACH
Cont1 Head Type:					Shipper State:	FL
Cont1 Pkg Capacity:	0				Shipper Postal:	33069-4108
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	4275417734283189073
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	TIFTON
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	31794
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: WHEN I GOT THE PACKAGE IT WAS WET. SO WHEN I OPENED IT TWO O F THE CONTAINERS WERE WET. New Comments:					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2020020488	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2019-10-15	Report Submit Src:	XML
Time of Incident:	2154	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT, L	Transport Phase:	Unloading
Commodity Long Nm:	PAINT INCLUDING PAINT, LACQUER, ENAMEL, STAIN, SHELLAC SOLUTIONS, VARNISH, POLISH, LIQUID FILLER AND LIQUID LACQUER BASE	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1263	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.75	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Failure Cause Code:	526				CR Hazmat Reg ID: 051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country: US	
Ident. Markings:					Shipper Name: NEW YORK BLOWER CO	
Cont1 Pkging Type:	Box				Shipper Street Name: 171 Factory Street	
Cont1 Const Mat:	Fiberboard				Shipper City: LA PORTE	
Cont1 Head Type:					Shipper State: IN	
Cont1 Pkg Capacity:	0				Shipper Postal: 46350	
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country: US	
C1 Pkg Amt UOM:					Shipper Waybill: 1307393465543705933	
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country: US	
C1 Test Const Mat:	Fiberboard				Destination City: ATLANTA	
C1 Pkg Dsign Pres.:	0				Destination State: GEORGIA	
C1 Dsign Press UOM:					Destination Postal: 30340	
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country: US	
C1 Head Thickness:	0				Cont2 Package Type: Can	
C1 Head Thick UOM:					Cont2 Const Mat: Metal (any type)	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity: 0	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount: 0	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No: 0	
C1 Device Model:					Cont2 Pkg No Failed: 0	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public: 0	
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries: 0	
RAM Transport Index:					Evacuation Indicator: No	
RAM UOM:					Public Evacuated: 0	
RAM Activity Rpted:	0				Employees Evac: 0	
RAM UOM Rpted:					Total Evacuated: 0	
RAM Activity:	0				Total Evacuation Hrs: 0	
RAM Activity UOM:					Major Artery Closed: No	
RAM Mat Safety:					Mjr Artery Hrs Closed: 0	
Spillage Result:	Yes				Material Involved: No	
Fire Result:	No				Estimated Speed: 0	
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn: No	
Gas Dispersion:	No				Vehicle Left Roadway: No	
Environment Damage:	No				Passenger Aircraft: No	
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport: No	
Fire EMS EMS Report:					Ship Air First Flight: No	
Police Report:	No				Ship Air Subflight: No	
Police Report No:					Ship Init Transport: No	
In House Cleanup:	Yes				Ship Phase Transfer: No	
Other Cleanup:	No				Contact Name: GEORGE FETSKO	
Damage > 500:	No				Contact Title: HAZMAT - SAFETY ADVISOR	
Material Loss:	0				Contact Business: Fedex Ground Package System, Inc.	
Carrier Damage:	0				Contact Street: 1000 Fedex Drive	
Property Damage:	0				Contact City: CORAOPOLIS	
Response Cost:	0				Contact State: PA	
Remediation Cost:	0				Contact Postal: 15108	
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country: US	
Hazmat Fatality:	No				Inc. Report Prepared: Carrier	
Haz Fatal Employees:	0				HMIS Serious Incidnt: No	
Haz Fatal Respndrs:	0				HMIS Serious Fatality: No	
Haz Fatal Gen Public:	0				HMIS Serious Injury: No	
Tot Hazmat Fatalities:	0				HMIS Flight Plan: No	
Non Hazmat Fatality:	No				HMIS Serious Evacs: No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non Hazmat Fatal:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2020080129				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2020-02-05				Report Submit Src:	XML
Time of Incident:	2000				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT, L				Transport Phase:	Unloading
Commodity Long Nm:	PAINT INCLUDING PAINT, LACQUER, ENAMEL, STAIN, SHELLAC SOLUTIONS, VARNISH, POLISH, LIQUID FILLER AND LIQUID LACQUER BASE				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1263				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G				Shipper Name:	Manhattan Laminates
Cont1 Pkging Type:	Box				Shipper Street Name:	5115 35TH ST
Cont1 Const Mat:	Fiberboard				Shipper City:	LONG ISLAND CITY
Cont1 Head Type:					Shipper State:	NY
Cont1 Pkg Capacity:	0				Shipper Postal:	11101
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	3703501390067820125
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ROSWELL
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30076
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:	NO COMMENTS PROVIDED.					

HMIR Incident Reports

Report No:	X-2015090258	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2015-08-20	Report Submit Src:	XML
Time of Incident:	1000	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	5.1	Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE, AQUEO	Transport Phase:	In Transit
Commodity Long Nm:	HYDROGEN PEROXIDE, AQUEOUS SOLUTIONS WITH NOT LESS THAN 20 PERCENT BUT NOT MORE THAN 40 PERCENT HYDROGEN PEROXIDE (STABILIZED AS NECESSARY)	Incident Occrrnce:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN2014			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	Fedex Ground Package System, Inc.	
Qty Released:	5			CR Street Name:	1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon			CR City:	Moon Township	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)			CR Postal Code:	15108	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device			CR Country:	US	
Ident. Markings:	4G/Y24.5/S/15 USA/M6295			Shipper Name:	BRAINERD LLC	
Cont1 Pkging Type:				Shipper Street Name:	1600 S WILSON AVE	
Cont1 Const Mat:				Shipper City:	Dunn	
Cont1 Head Type:				Shipper State:	NC	
Cont1 Pkg Capacity:	0			Shipper Postal:	28334	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	774300073770	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:		
C1 Test Const Mat:				Destination City:	LOGANVILLE	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30052	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2018110353	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2018-10-18	Report Submit Src:	XML
Time of Incident:	1300	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	Transport Phase:	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1824	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	NO MARKINGS GIVEN	Shipper Name:	ECOLAB/CEVA LOGISTICS
Cont1 Pkging Type:	Drum	Shipper Street Name:	125 SOUTHSIDE CT
Cont1 Const Mat:	Plastic	Shipper City:	MCDONOUGH
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30253
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	916079075414663
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	US
C1 Test Const Mat:	Plastic	Destination City:	DULUTH
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30096
C1 Pkg Shell Thick:	0	Destination Non US:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB	
C1 Shell Thick UOM:	0	No			Destination Country:	US	
C1 Head Thickness:					Cont2 Package Type:		
C1 Head Thick UOM:	Cont2 Const Mat:						
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:					Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	0				Cont2 Pkg Amount:	0	
C1 Device Type:					Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:					Cont2 Pkg No:	0	
C1 Device Model:					Cont2 Pkg No Failed:	0	
NRC No:							
RAM Pkg Category:	FALSE				Haz NonHosp Public:	0	
RAM Pkg Cert.:					Haz NonHosp Old:		
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:		
RAM Nuclide S:					Total Hazmat Injuries:	0	
RAM Transport Index:					Evacuation Indicator:	No	
RAM UOM:					Public Evacuated:	0	
RAM Activity Rpted:					0	Employees Evac:	0
RAM UOM Rpted:					0	Total Evacuated:	0
RAM Activity:					0	Total Evacuation Hrs:	0
RAM Activity UOM:						Major Artery Closed:	No
RAM Mat Safety:		Mjr Artery Hrs Closed:	0				
Spillage Result:	Yes				Material Involved:	No	
Fire Result:	No				Estimated Speed:	0	
Explosion Result:	No				Weather Conditions:		
Water Sewer Result:	No				Vehicle Overturn:	No	
Gas Dispersion:	No				Vehicle Left Roadway:	No	
Environment Damage:	No				Passenger Aircraft:	No	
No Release Result:	No				Cargo Baggage:		
Fire EMS Report:	No				Ship Non Transport:	No	
Fire EMS EMS Report:					Ship Air First Flight:	No	
Police Report:	No				Ship Air Subflight:	No	
Police Report No:					Ship Init Transport:	No	
In House Cleanup:	Yes				Ship Phase Transfer:	No	
Other Cleanup:	No				Contact Name:	GEORGE FETSKO	
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0				Contact Street:	1000 Fedex Drive	
Property Damage:	0				Contact City:	CORAOPOLIS	
Response Cost:	0				Contact State:	PA	
Remediation Cost:	0				Contact Postal:	15108	
Damage Old Form:	0				Contact Non US St:		
Total Damages Amt:	0				Contact Country:	US	
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No	
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No	
Non Hazmat Fatafs:	0				HMIS Major Artery:	No	
Hazmat Injury:	No				HMIS Bulk Release:	No	
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0				HMIS Radioactive:	No	
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:		
Haz Hosp Old Form:	0				HMIS Container Code:	NO MARKI	
Total Haz Hosp Inj:	0				HMIS Container Desc:		
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0				Undeclared Shipment:	No	
Description of Events:	Original comments: pail was found on dock wet. I examined the pail and notice the cap was loose New Comments:						
Recommend Actions Taken:							

HMIR Incident Reports

Report No:	X-2017120296	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2017-11-24	Report Submit Src:	XML
Time of Incident:	1930	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,				Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.				Incident Occrrnce:	
Trade Name:	potassium hydroxide				Mat Ship Approval?:	No
ID No:	UN3266				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	Yes
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1.75				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	Diversitech
Cont1 Pkging Type:	Box				Shipper Street Name:	6650 Sugarloaf Pkwy
Cont1 Const Mat:	Fiberboard				Shipper City:	Duluth
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30097
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	889030132853297
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	DULUTH
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30097
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	Yes
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2020080181	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2020-02-11	Report Submit Src:	XML
Time of Incident:	1900	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL	Transport Phase:	Unloading
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1219	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.75	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G	Shipper Name:	AMERICAN ACESS CARE-ATLANTA
Cont1 Pkging Type:	Box	Shipper Street Name:	250 E PONCE DE LEON AVE STE 100
Cont1 Const Mat:	Fiberboard	Shipper City:	DECATUR
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30030
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	5720466777471593266
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Test Const Mat:	Fiberboard				Destination City:	MCDONOUGH
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30253
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:	NO COMMENTS PROVIDED.					

HMIR Incident Reports

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report No:	X-2020080182				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2020-02-11				Report Submit Src:	XML
Time of Incident:	1930				Inc Multiple Rows:	Yes
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI				Transport Phase:	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	1H				Shipper Name:	DONGNEA BANGNEA
Cont1 Pkging Type:	Drum				Shipper Street Name:	3042 OAKCLIFF RD, STE 104
Cont1 Const Mat:	Plastic				Shipper City:	ATLANTA
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30340
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	9160790916079077575744
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	MCDONOUGH
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30253
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM NON-METAL
Haz Hosp Old Form:	0				HMIS Container Code:	1H1
Total Haz Hosp Inj:	0				HMIS Container Desc:	Non-removable head plastic drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:	NO COMMENTS PROVIDED.					

HMIR Incident Reports

Report No:	X-2020060299	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2019-12-16	Report Submit Src:	XML
Time of Incident:	2300	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,	Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.	Incident Occrrnce:	
Trade Name:	Sodium hydroxide	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.5	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
How Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G/Y19.4/S/19USA/+CP1206	Shipper Name:	ZEP INC-NASS
Cont1 Pkging Type:	Box	Shipper Street Name:	71 BUSINESS PARK DR
Cont1 Const Mat:	Fiberboard	Shipper City:	CARTERSVILLE
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30121
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	2227330222733020765016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30338
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
		container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:		NO COMMENTS PROVIDED.				
<u>HMIR Incident Reports</u>						
Report No:	X-2019120530			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	2019-09-20			Report Submit Src:	XML	
Time of Incident:	2142			Inc Multiple Rows:	No	
Haz Class Code:				Inc Non US State:		
Hazardous Class:	8			Mode Transport:	Highway	
Commodity Short Nm:	CORROSIVE LIQUIDS, N.O.S.			Transport Phase:	Unloading	
Commodity Long Nm:	CORROSIVE LIQUIDS, N.O.S.			Incident Occrrnce:		
Trade Name:	SODIUM HYDROXIDE			Mat Ship Approval?:	No	
ID No:	UN1760			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	Fedex Ground Package System, Inc.	
Qty Released:	0.25			CR Street Name:	1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)			CR Postal Code:	15108	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device			CR Country:	US	
Ident. Markings:	4G/Y19.3/S/19USA/+CO2214			Shipper Name:	BETCO	
Cont1 Pkging Type:	Box			Shipper Street Name:	400 Van Camp Rd	
Cont1 Const Mat:	Fiberboard			Shipper City:	BOWLING GREEN	
Cont1 Head Type:				Shipper State:	OH	
Cont1 Pkg Capacity:	0			Shipper Postal:	43402	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	6186957123430177321	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	NORCROSS	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30092	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2014100247	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2014-09-17	Report Submit Src:	XML
Time of Incident:	1800	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	METHANOL	Transport Phase:	Loading
Commodity Long Nm:	METHANOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1230	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1.05672	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108
How Failed Code:	305	CR Non US State:	
How Failed Desc:	Crushed	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:	4G/X10.9/S/13/USA/M4109	Shipper Name:	SIGMA-ALDRICH CORPORATION
Cont1 Pkging Type:		Shipper Street Name:	6000 N TEUTONIA AVE
Cont1 Const Mat:		Shipper City:	MILWAUKEE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Head Type:					Shipper State:	WI
Cont1 Pkg Capacity:	0				Shipper Postal:	53209-3645
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	36553834415601
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:	X-2019080858				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2019-07-25				Report Submit Src:	XML
Time of Incident:	2100				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,				Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.				Incident Occrrnce:	
Trade Name:	potassium hydroxide				Mat Ship Approval?:	No
ID No:	UN3266				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/Y24.9//S/19USA/+CA0080				Shipper Name:	NARCO
Cont1 Pkging Type:	Box				Shipper Street Name:	519 Huffines Blvd
Cont1 Const Mat:	Fiberboard				Shipper City:	THE COLONY
Cont1 Head Type:					Shipper State:	TX
Cont1 Pkg Capacity:	0				Shipper Postal:	75056
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	760860788535244490
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	NORCROSS
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30092
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM UOM: RAM Activity Rpted: 0 RAM UOM Rpted: RAM Activity: 0 RAM Activity UOM: RAM Mat Safety: Spillage Result: Yes Fire Result: No Explosion Result: No Water Sewer Result: No Gas Dispersion: No Environment Damage: No No Release Result: No Fire EMS Report: No Fire EMS EMS Report: Police Report: No Police Report No: In House Cleanup: Yes Other Cleanup: No Damage > 500: No Material Loss: 0 Carrier Damage: 0 Property Damage: 0 Response Cost: 0 Remediation Cost: 0 Damage Old Form: 0 Total Damages Amt: 0 Hazmat Fatality: No Haz Fatal Employees: 0 Haz Fatal Respndrs: 0 Haz Fatal Gen Public: 0 Tot Hazmat Fatalities: 0 Non Hazmat Fatality: No Non Hazmat Fatals: 0 Hazmat Injury: No Haz Hospital Empl: 0 Haz Hospital Resp: 0 Haz Hosp Gen Public: 0 Haz Hosp Old Form: 0 Total Haz Hosp Inj: 0 Haz Non Hosp Empl: 0 Haz Non Hosp Resp: 0 Description of Events: Public Evacuated: 0 Employees Evac: 0 Total Evacuated: 0 Total Evacuation Hrs: 0 Major Artery Closed: No Mjr Artery Hrs Closed: 0 Material Involved: No Estimated Speed: 0 Weather Conditions: Vehicle Overturn: No Vehicle Left Roadway: No Passenger Aircraft: No Cargo Baggage: Ship Non Transport: No Ship Air First Flight: No Ship Air Subflight: No Ship Init Transport: No Ship Phase Transfer: No Contact Name: GEORGE FETSKO Contact Title: HAZMAT - SAFETY ADVISOR Contact Business: Fedex Ground Package System, Inc. Contact Street: 1000 Fedex Drive Contact City: CORAOPOLIS Contact State: PA Contact Postal: 15108 Contact Non US St: Contact Country: US Inc. Report Prepared: Carrier HMIS Serious Incidnt: No HMIS Serious Fatality: No HMIS Serious Injury: No HMIS Flight Plan: No HMIS Serious Evacs: No HMIS Major Artery: No HMIS Bulk Release: No HMIS Marine Pollutnt: No HMIS Radioactive: No HMIS Gen Pkg Type: BOX FIBER HMIS Container Code: 4G HMIS Container Desc: Fiberboard box HMIS Bulk Incident: No Undeclared Shipment: No The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.						
Recommend Actions Taken:						
HMIR Incident Reports						
Report No: X-2018030168 Report Type: A hazardous material incident Date of Incident: 2018-02-17 Time of Incident: 0700 Haz Class Code: Hazardous Class: 8 Commodity Short Nm: SODIUM HYDROXIDE, SOLUTI Commodity Long Nm: SODIUM HYDROXIDE, SOLUTION Trade Name: ID No: UN1824 Haz Waste Ind: No Haz Waste EPA No: HMIS Tox Inhalation?: No TIH Hazard Zone: Qty Released: 0.25 Unit of Measure: Liquid - Gallon What Failed: 109 What Failed Desc: Closure (e.g., Cap, Top, or Plug) How Failed Code: 308 Fed DOT Agency Nm: Fed DOT Report No: Report Submit Src: XML Inc Multiple Rows: No Inc Non US State: Mode Transport: Highway Transport Phase: Unloading Incident Occrrnce: Mat Ship Approval?: No Mat Ship Approv No: Undecl Hazmat Ship?: No Packaging Type: Non-Bulk Packing Group: II Carrier Reporter: Fedex Ground Package System, Inc. CR Street Name: 1000 Fedex Drive CR City: Moon Township CR State: PA CR Postal Code: 15108 CR Non US State:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
How Failed Desc:	Leaked				CR Fed DOT ID: 265752	
Failure Cause Code:	526				CR Hazmat Reg ID: 051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country: US	
Ident. Markings:	4G/Y24.7/S/17/USA/M4172				Shipper Name: ECL-KAY	
Cont1 Pkging Type:	Box				Shipper Street Name: 90 PIEDMONT INDUSTRIAL DR	
Cont1 Const Mat:	Fiberboard				Shipper City: WINSTON SALEM	
Cont1 Head Type:					Shipper State: NC	
Cont1 Pkg Capacity:	0				Shipper Postal: 27107	
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country: US	
C1 Pkg Amt UOM:					Shipper Waybill: 757771683187746	
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfcct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country: US	
C1 Test Const Mat:	Fiberboard				Destination City: ATLANTA	
C1 Pkg Dsign Pres.:	0				Destination State: GEORGIA	
C1 Dsign Press UOM:					Destination Postal: 30329	
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country: US	
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity: 0	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount: 0	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No: 0	
C1 Device Model:					Cont2 Pkg No Failed: 0	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public: 0	
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries: 0	
RAM Transport Index:					Evacuation Indicator: No	
RAM UOM:					Public Evacuated: 0	
RAM Activity Rpted:	0				Employees Evac: 0	
RAM UOM Rpted:					Total Evacuated: 0	
RAM Activity:	0				Total Evacuation Hrs: 0	
RAM Activity UOM:					Major Artery Closed: No	
RAM Mat Safety:					Mjr Artery Hrs Closed: 0	
Spillage Result:	Yes				Material Involved: No	
Fire Result:	No				Estimated Speed: 0	
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn: No	
Gas Dispersion:	No				Vehicle Left Roadway: No	
Environment Damage:	No				Passenger Aircraft: No	
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport: No	
Fire EMS EMS Report:					Ship Air First Flight: No	
Police Report:	No				Ship Air Subflight: No	
Police Report No:					Ship Init Transport: No	
In House Cleanup:	Yes				Ship Phase Transfer: No	
Other Cleanup:	No				Contact Name: GEORGE FETSKO	
Damage > 500:	No				Contact Title: HAZMAT - SAFETY ADVISOR	
Material Loss:	0				Contact Business: Fedex Ground Package System, Inc.	
Carrier Damage:	0				Contact Street: 1000 Fedex Drive	
Property Damage:	0				Contact City: CORAOPOLIS	
Response Cost:	0				Contact State: PA	
Remediation Cost:	0				Contact Postal: 15108	
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country: US	
Hazmat Fatality:	No				Inc. Report Prepared: Carrier	
Haz Fatal Employees:	0				HMIS Serious Incidnt: No	
Haz Fatal Respndrs:	0				HMIS Serious Fatality: No	
Haz Fatal Gen Public:	0				HMIS Serious Injury: No	
Tot Hazmat Fatalities:	0				HMIS Flight Plan: No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: WET BOX WAS FOUND ON THE DOCK. AS I LOOKED INSIDE THE BOX THERE WAS 4 1GAL JUGS OF MACHINE WAREWASHING DETERGENT BUT 3 OF THEM HAD LOOSE CAPS New Comments:					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2018080306				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2018-07-05				Report Submit Src:	XML
Time of Incident:	2200				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	5.1				Mode Transport:	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE				Transport Phase:	Unloading
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES, STABILIZED WITH ACIDS, WATER, AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN3149				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/Y14.8/S/18 USA/+AA5566				Shipper Name:	MEDIVATORS
Cont1 Pkging Type:	Box				Shipper Street Name:	14605 28TH AVENUE N
Cont1 Const Mat:	Fiberboard				Shipper City:	MINNEAPOLIS
Cont1 Head Type:					Shipper State:	MN
Cont1 Pkg Capacity:	0				Shipper Postal:	55447
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	911012437364387935
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	TUCKER
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30084
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.: FALSE				Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted: 0				Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity: 0				Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result: Yes				Material Involved:	No	
Fire Result: No				Estimated Speed:	0	
Explosion Result: No				Weather Conditions:		
Water Sewer Result: No				Vehicle Overturn:	No	
Gas Dispersion: No				Vehicle Left Roadway:	No	
Environment Damage: No				Passenger Aircraft:	No	
No Release Result: No				Cargo Baggage:		
Fire EMS Report: No				Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report: No				Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup: Yes				Ship Phase Transfer:	No	
Other Cleanup: No				Contact Name:	GEORGE FETSKO	
Damage > 500: No				Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss: 0				Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage: 0				Contact Street:	1000 Fedex Drive	
Property Damage: 0				Contact City:	CORAOPOLIS	
Response Cost: 0				Contact State:	PA	
Remediation Cost: 0				Contact Postal:	15108	
Damage Old Form: 0				Contact Non US St:		
Total Damages Amt: 0				Contact Country:	US	
Hazmat Fatality: No				Inc. Report Prepared:	Carrier	
Haz Fatal Employees: 0				HMIS Serious Incidnt:	No	
Haz Fatal Respndrs: 0				HMIS Serious Fatality:	No	
Haz Fatal Gen Public: 0				HMIS Serious Injury:	No	
Tot Hazmat Fatalities: 0				HMIS Flight Plan:	No	
Non Hazmat Fatality: No				HMIS Serious Evacs:	No	
Non Hazmat Fatals: 0				HMIS Major Artery:	No	
Hazmat Injury: No				HMIS Bulk Release:	No	
Haz Hospital Empl: 0				HMIS Marine Pollutnt:	No	
Haz Hospital Resp: 0				HMIS Radioactive:	No	
Haz Hosp Gen Public: 0				HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form: 0				HMIS Container Code:	4G	
Total Haz Hosp Inj: 0				HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl: 0				HMIS Bulk Incident:	No	
Haz Non Hosp Resp: 0				Undeclared Shipment:	No	
Description of Events:		Original comments: Box was found on dock wet. As I looked inside there was 2 inner packages both boxes had 2 bottles of Rapicide PA inside of it. 1 box had no damage the 2nd box had 2 damage bottles with loose caps New Comments:				
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:		X-2017090510		Fed DOT Agency Nm:		
Report Type:		A hazardous material incident		Fed DOT Report No:		
Date of Incident:		2017-08-21		Report Submit Src:		XML
Time of Incident:		1018		Inc Multiple Rows:		No
Haz Class Code:				Inc Non US State:		
Hazardous Class:		8		Mode Transport:		Highway
Commodity Short Nm:		SODIUM HYDROXIDE, SOLUTI		Transport Phase:		In Transit
Commodity Long Nm:		SODIUM HYDROXIDE, SOLUTION		Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:		No
ID No:		UN1824		Mat Ship Approv No:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Waste Ind:	No				Undecl Hazmat Ship?: No	
Haz Waste EPA No:					Packaging Type: Non-Bulk	
HMIS Tox Inhalation?:	No				Packing Group: II	
TIH Hazard Zone:					Carrier Reporter: Fedex Ground Package System, Inc.	
Qty Released:	5				CR Street Name: 1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon				CR City: Moon Township	
What Failed:	109				CR State: PA	
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code: 15108	
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID: 265752	
Failure Cause Code:	526				CR Hazmat Reg ID: 051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country: US	
Ident. Markings:					Shipper Name: Ecolab	
Cont1 Pkgg Type:	Drum				Shipper Street Name: 124 Southside Ct	
Cont1 Const Mat:	Plastic				Shipper City: MCDONOUGH	
Cont1 Head Type:					Shipper State: GA	
Cont1 Pkg Capacity:	0				Shipper Postal: 30253	
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country: US	
C1 Pkg Amt UOM:					Shipper Waybill: 916079073204099	
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country: US	
C1 Test Const Mat:	Plastic				Destination City: ATLANTA	
C1 Pkg Dsign Pres.:	0				Destination State: GEORGIA	
C1 Dsign Press UOM:					Destination Postal: 30319	
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country: US	
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity: 0	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount: 0	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No: 0	
C1 Device Model:					Cont2 Pkg No Failed: 0	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public: 0	
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries: 0	
RAM Transport Index:					Evacuation Indicator: No	
RAM UOM:					Public Evacuated: 0	
RAM Activity Rpted:	0				Employees Evac: 0	
RAM UOM Rpted:					Total Evacuated: 0	
RAM Activity:	0				Total Evacuation Hrs: 0	
RAM Activity UOM:					Major Artery Closed: No	
RAM Mat Safety:					Mjr Artery Hrs Closed: 0	
Spillage Result:	Yes				Material Involved: No	
Fire Result:	No				Estimated Speed: 0	
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn: No	
Gas Dispersion:	No				Vehicle Left Roadway: No	
Environment Damage:	No				Passenger Aircraft: No	
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport: No	
Fire EMS EMS Report:					Ship Air First Flight: No	
Police Report:	No				Ship Air Subflight: No	
Police Report No:					Ship Init Transport: No	
In House Cleanup:	Yes				Ship Phase Transfer: No	
Other Cleanup:	No				Contact Name: GEORGE FETSKO	
Damage > 500:	No				Contact Title: HAZMAT - SAFETY ADVISOR	
Material Loss:	0				Contact Business: Fedex Ground Package System, Inc.	
Carrier Damage:	0				Contact Street: 1000 Fedex Drive	
Property Damage:	0				Contact City: CORAOPOLIS	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	DRUM NON-METAL	
Haz Hosp Old Form:	0			HMIS Container Code:	DRUM PLS	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Plastic drum	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2019120531	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2019-09-20	Report Submit Src:	XML
Time of Incident:	2203	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS, N.O.S.	Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUIDS, N.O.S.	Incident Occrrnce:	
Trade Name:	SODIUM HYDROXIDE	Mat Ship Approval?:	No
ID No:	UN1760	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.25	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G/Y19.3/S/19USA/+C02214	Shipper Name:	BETCO
Cont1 Pkging Type:	Box	Shipper Street Name:	400 Van Camp Rd
Cont1 Const Mat:	Fiberboard	Shipper City:	BOWLING GREEN
Cont1 Head Type:		Shipper State:	OH
Cont1 Pkg Capacity:	0	Shipper Postal:	43402
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	6186957123430177332
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	US
C1 Test Const Mat:	Fiberboard	Destination City:	NORCROSS
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30092
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2019120561	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2019-09-23	Report Submit Src:	XML
Time of Incident:	2150	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazardous Class:	3				Mode Transport: Highway	
Commodity Short Nm:	ACETONE				Transport Phase: Unloading	
Commodity Long Nm:	ACETONE				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?: No	
ID No:	UN1090				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?: No	
Haz Waste EPA No:					Packaging Type: Non-Bulk	
HMIS Tox Inhalation?:	No				Packing Group: II	
TIH Hazard Zone:					Carrier Reporter: Fedex Ground Package System, Inc.	
Qty Released:	0.25				CR Street Name: 1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon				CR City: CORAOPOLIS	
What Failed:	109				CR State: PA	
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code: 15108	
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID: 265752	
Failure Cause Code:	526				CR Hazmat Reg ID: 051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country: US	
Ident. Markings:	4G/Y26/S/19USA/+BR10450				Shipper Name: CHEMENCE INC	
Cont1 Pkging Type:	Box				Shipper Street Name: 185 Bluegrass Valley Pkwy	
Cont1 Const Mat:	Fiberboard				Shipper City: ALPHARETTA	
Cont1 Head Type:					Shipper State: GA	
Cont1 Pkg Capacity:	0				Shipper Postal: 30005	
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country: US	
C1 Pkg Amt UOM:					Shipper Waybill: 9814311116704465439	
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country: US	
C1 Test Const Mat:	Fiberboard				Destination City: PINEVILLE	
C1 Pkg Dsign Pres.:	0				Destination State: NORTH CAROLINA	
C1 Dsign Press UOM:					Destination Postal: 28134	
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country: US	
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity: 0	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount: 0	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No: 0	
C1 Device Model:					Cont2 Pkg No Failed: 0	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public: 0	
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries: 0	
RAM Transport Index:					Evacuation Indicator: No	
RAM UOM:					Public Evacuated: 0	
RAM Activity Rpted:	0				Employees Evac: 0	
RAM UOM Rpted:					Total Evacuated: 0	
RAM Activity:	0				Total Evacuation Hrs: 0	
RAM Activity UOM:					Major Artery Closed: No	
RAM Mat Safety:					Mjr Artery Hrs Closed: 0	
Spillage Result:	Yes				Material Involved: No	
Fire Result:	No				Estimated Speed: 0	
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn: No	
Gas Dispersion:	No				Vehicle Left Roadway: No	
Environment Damage:	No				Passenger Aircraft: No	
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport: No	
Fire EMS EMS Report:					Ship Air First Flight: No	
Police Report:	No				Ship Air Subflight: No	
Police Report No:					Ship Init Transport: No	
In House Cleanup:	Yes				Ship Phase Transfer: No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2017120235			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	2017-11-16			Report Submit Src:	XML	
Time of Incident:	0001			Inc Multiple Rows:	No	
Haz Class Code:				Inc Non US State:		
Hazardous Class:	8			Mode Transport:	Highway	
Commodity Short Nm:	POTASSIUM HYDROXIDE, SOL			Transport Phase:	Loading	
Commodity Long Nm:	POTASSIUM HYDROXIDE, SOLUTION			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1814			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	Fedex Ground Package System, Inc.	
Qty Released:	0.1			CR Street Name:	1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon			CR City:	Moon Township	
What Failed:	104			CR State:	PA	
What Failed Desc:	Body			CR Postal Code:	15108	
How Failed Code:	309			CR Non US State:		
How Failed Desc:	Punctured			CR Fed DOT ID:	265752	
Failure Cause Code:	511			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Dropped			CR Country:	US	
Ident. Markings:				Shipper Name:	VWR International	
Cont1 Pkging Type:	Jerrican			Shipper Street Name:	1050 Satellite Blvd	
Cont1 Const Mat:	Plastic			Shipper City:	Suwanee	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:	0			Shipper Postal:	30024	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	4083948739681535394	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg MnfcDt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:		
C1 Test Const Mat:	Plastic			Destination City:	CLEARWATER	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Dsign Pres.:	0				Destination State:	FLORIDA
C1 Dsign Press UOM:					Destination Postal:	33762
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM NON-METAL
Haz Hosp Old Form:	0				HMIS Container Code:	PAIL PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report No:	X-2017120248				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2017-11-15				Report Submit Src:	XML
Time of Incident:	0830				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI				Transport Phase:	In Transit
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.1				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	ECL-Kay
Cont1 Pkging Type:	Box				Shipper Street Name:	90 Piedmont Ind Dr
Cont1 Const Mat:	Fiberboard				Shipper City:	WINSTON SALEM
Cont1 Head Type:					Shipper State:	NC
Cont1 Pkg Capacity:	0				Shipper Postal:	27107
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	7577716757771683020456
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfcct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2018010282	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2017-12-29	Report Submit Src:	XML
Time of Incident:	1934	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS, N.O.S.	Transport Phase:	Loading
Commodity Long Nm:	FLAMMABLE LIQUIDS, N.O.S.	Incident Occrrnce:	
Trade Name:	(Methyl Alcohol Nitr	Mat Ship Approval?:	No
ID No:	UN1993	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	110	CR State:	PA
What Failed Desc:	Cover	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G/Y24/S/17 USA/+CO1300	Shipper Name:	Sig Mfg Inc
Cont1 Pkging Type:		Shipper Street Name:	401 S Front St.
Cont1 Const Mat:		Shipper City:	MONTEZUMA
Cont1 Head Type:		Shipper State:	IA
Cont1 Pkg Capacity:	0	Shipper Postal:	50171
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	525081725018479076
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:					Destination City:	SNELLVILLE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30078
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.						
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:	X-2017110330				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2017-10-19				Report Submit Src:	XML
Time of Incident:	1810				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI				Transport Phase:	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	ECOLAB
Cont1 Pkging Type:	Drum				Shipper Street Name:	125 Southdale Ct
Cont1 Const Mat:	Plastic				Shipper City:	MCDONOUGH
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30253
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	889030128842663
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	MCDONOUGH
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30253
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatafs:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	DRUM NON-METAL	
Haz Hosp Old Form:	0			HMIS Container Code:	DRUM PLS	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Plastic drum	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2017090186			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	2017-08-16			Report Submit Src:	XML	
Time of Incident:	1500			Inc Multiple Rows:	No	
Haz Class Code:				Inc Non US State:		
Hazardous Class:	3			Mode Transport:	Highway	
Commodity Short Nm:	GASOLINE INCLUDES GASOLI			Transport Phase:	Unloading	
Commodity Long Nm:	GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL, WITH NOT MORE THAN 10% ALCOHOL			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1203			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	Fedex Ground Package System, Inc.	
Qty Released:	0.26418			CR Street Name:	1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon			CR City:	Moon Township	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)			CR Postal Code:	15108	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	Motivia Enterprise	
Cont1 Pkging Type:	Box			Shipper Street Name:	4127 Winters Chapel Rd	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Const Mat:	Fiberboard				Shipper City:	DORAVILLE
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30360
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	4275417998030122906948
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	TIFTON
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	31794
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2015090016				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2014-08-29				Report Submit Src:	XML
Time of Incident:	1100				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,				Transport Phase:	In Transit
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.				Incident Occrrnce:	
Trade Name:	(Contains potassuim				Mat Ship Approval?:	No
ID No:	UN3266				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	5				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	517				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Improper Preparation for Transportation				CR Country:	US
Ident. Markings:	4G/Y21.1/S/15 USA/+BZ0775				Shipper Name:	Diversitech corp
Cont1 Pkging Type:					Shipper Street Name:	2175 e Park Dr
Cont1 Const Mat:					Shipper City:	Conyers
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30013
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	645431699508
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg MnfcDt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2017120093			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	2017-11-08			Report Submit Src:	XML	
Time of Incident:	0925			Inc Multiple Rows:	No	
Haz Class Code:				Inc Non US State:		
Hazardous Class:	5.1			Mode Transport:	Highway	
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE			Transport Phase:	Loading	
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES, STABILIZED WITH ACIDS, WATER, AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID			Incident Occrrnce:		
Trade Name:	stabilized			Mat Ship Approval?:	No	
ID No:	UN3149			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	Fedex Ground Package System, Inc.	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Qty Released:	0.026418				CR Street Name: 1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon				CR City: Moon Township	
What Failed:	109				CR State: PA	
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code: 15108	
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID: 265752	
Failure Cause Code:	526				CR Hazmat Reg ID: 051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country: US	
Ident. Markings:					Shipper Name: Medivators Inc	
Cont1 Pkging Type:	Box				Shipper Street Name: 14605 28th Avenue N	
Cont1 Const Mat:	Fiberboard				Shipper City: Minneapolis	
Cont1 Head Type:					Shipper State: MN	
Cont1 Pkg Capacity:	0				Shipper Postal: 55447	
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country: US	
C1 Pkg Amt UOM:					Shipper Waybill: 91101235447379	
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City: TUCKER	
C1 Pkg Dsign Pres.:	0				Destination State: GEORGIA	
C1 Dsign Press UOM:					Destination Postal: 30084	
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country: US	
C1 Head Thickness:	0				Cont2 Package Type: Can	
C1 Head Thick UOM:					Cont2 Const Mat: Plastic	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity: 0	
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount: 0	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No: 0	
C1 Device Model:					Cont2 Pkg No Failed: 0	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public: 0	
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries: 0	
RAM Transport Index:					Evacuation Indicator: No	
RAM UOM:					Public Evacuated: 0	
RAM Activity Rpted:	0				Employees Evac: 0	
RAM UOM Rpted:					Total Evacuated: 0	
RAM Activity:	0				Total Evacuation Hrs: 0	
RAM Activity UOM:					Major Artery Closed: No	
RAM Mat Safety:					Mjr Artery Hrs Closed: 0	
Spillage Result:	Yes				Material Involved: No	
Fire Result:	No				Estimated Speed: 0	
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn: No	
Gas Dispersion:	No				Vehicle Left Roadway: No	
Environment Damage:	No				Passenger Aircraft: No	
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport: No	
Fire EMS EMS Report:					Ship Air First Flight: No	
Police Report:	No				Ship Air Subflight: No	
Police Report No:					Ship Init Transport: No	
In House Cleanup:	Yes				Ship Phase Transfer: No	
Other Cleanup:	No				Contact Name: GEORGE FETSKO	
Damage > 500:	No				Contact Title: HAZMAT - SAFETY ADVISOR	
Material Loss:	0				Contact Business: Fedex Ground Package System, Inc.	
Carrier Damage:	0				Contact Street: 1000 Fedex Drive	
Property Damage:	0				Contact City: CORAOPOLIS	
Response Cost:	0				Contact State: PA	
Remediation Cost:	0				Contact Postal: 15108	
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country: US	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazmat Fatality:	No				Inc. Report Prepared: Carrier	
Haz Fatal Employees:	0				HMIS Serious Incidnt: No	
Haz Fatal Respndrs:	0				HMIS Serious Fatality: No	
Haz Fatal Gen Public:	0				HMIS Serious Injury: No	
Tot Hazmat Fatalities:	0				HMIS Flight Plan: No	
Non Hazmat Fatality:	No				HMIS Serious Evacs: No	
Non Hazmat Fatafs:	0				HMIS Major Artery: No	
Hazmat Injury:	No				HMIS Bulk Release: No	
Haz Hospital Empl:	0				HMIS Marine Pollutnt: No	
Haz Hospital Resp:	0				HMIS Radioactive: No	
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type: BOX FIBER	
Haz Hosp Old Form:	0				HMIS Container Code: BOX FBR	
Total Haz Hosp Inj:	0				HMIS Container Desc: Fiberboard box or carton	
Haz Non Hosp Empl:	0				HMIS Bulk Incident: No	
Haz Non Hosp Resp:	0				Undeclared Shipment: No	
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2017080451	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2017-07-20	Report Submit Src:	XML
Time of Incident:	1000	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	ETHYL ALCOHOL SOLUTIONS	Transport Phase:	Unloading
Commodity Long Nm:	ETHYL ALCOHOL SOLUTIONS	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1170	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	3.75	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	Alex C Fergusson Co
Cont1 Pkging Type:	Box	Shipper Street Name:	5121 Coffey Ave
Cont1 Const Mat:	Fiberboard	Shipper City:	Chambersburg
Cont1 Head Type:		Shipper State:	PA
Cont1 Pkg Capacity:	0	Shipper Postal:	17201
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	1078449664565473472
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:	Fiberboard	Destination City:	NORCROSS
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30093
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	Bottle
C1 Head Thick UOM:		Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0	Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No: 0		
C1 Device Model:				Cont2 Pkg No Failed: 0		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public: 0		
RAM Pkg Cert.: FALSE				Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries: 0		
RAM Transport Index:				Evacuation Indicator: No		
RAM UOM:				Public Evacuated: 0		
RAM Activity Rpted: 0				Employees Evac: 0		
RAM UOM Rpted:				Total Evacuated: 0		
RAM Activity: 0				Total Evacuation Hrs: 0		
RAM Activity UOM:				Major Artery Closed: No		
RAM Mat Safety:				Mjr Artery Hrs Closed: 0		
Spillage Result: Yes				Material Involved: No		
Fire Result: No				Estimated Speed: 0		
Explosion Result: No				Weather Conditions:		
Water Sewer Result: No				Vehicle Overturn: No		
Gas Dispersion: No				Vehicle Left Roadway: No		
Environment Damage: No				Passenger Aircraft: No		
No Release Result: No				Cargo Baggage:		
Fire EMS Report: No				Ship Non Transport: No		
Fire EMS EMS Report:				Ship Air First Flight: No		
Police Report: No				Ship Air Subflight: No		
Police Report No:				Ship Init Transport: No		
In House Cleanup: Yes				Ship Phase Transfer: No		
Other Cleanup: No				Contact Name: GEORGE FETSKO		
Damage > 500: No				Contact Title: HAZMAT - SAFETY ADVISOR		
Material Loss: 0				Contact Business: Fedex Ground Package System, Inc.		
Carrier Damage: 0				Contact Street: 1000 Fedex Drive		
Property Damage: 0				Contact City: CORAOPOLIS		
Response Cost: 0				Contact State: PA		
Remediation Cost: 0				Contact Postal: 15108		
Damage Old Form: 0				Contact Non US St:		
Total Damages Amt: 0				Contact Country: US		
Hazmat Fatality: No				Inc. Report Prepared: Carrier		
Haz Fatal Employees: 0				HMIS Serious Incidnt: No		
Haz Fatal Respndrs: 0				HMIS Serious Fatality: No		
Haz Fatal Gen Public: 0				HMIS Serious Injury: No		
Tot Hazmat Fatalities: 0				HMIS Flight Plan: No		
Non Hazmat Fatality: No				HMIS Serious Evacs: No		
Non Hazmat FataIs: 0				HMIS Major Artery: No		
Hazmat Injury: No				HMIS Bulk Release: No		
Haz Hospital Empl: 0				HMIS Marine Pollutnt: No		
Haz Hospital Resp: 0				HMIS Radioactive: No		
Haz Hosp Gen Public: 0				HMIS Gen Pkg Type: BOX FIBER		
Haz Hosp Old Form: 0				HMIS Container Code: BOX FBR		
Total Haz Hosp Inj: 0				HMIS Container Desc: Fiberboard box or carton		
Haz Non Hosp Empl: 0				HMIS Bulk Incident: No		
Haz Non Hosp Resp: 0				Undeclared Shipment: No		
Description of Events:		The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:		X-2017090210		Fed DOT Agency Nm:		
Report Type:		A hazardous material incident		Fed DOT Report No:		
Date of Incident:		2017-08-16		Report Submit Src: XML		
Time of Incident:		0647		Inc Multiple Rows: No		
Haz Class Code:				Inc Non US State:		
Hazardous Class:		8		Mode Transport: Highway		
Commodity Short Nm:		SODIUM HYDROXIDE, SOLUTI		Transport Phase: Unloading		
Commodity Long Nm:		SODIUM HYDROXIDE, SOLUTION		Incident Occrrnce:		
Trade Name:				Mat Ship Approval?: No		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.26418				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:					Shipper Name:	ECL-Kay
Cont1 Pkging Type:	Box				Shipper Street Name:	90 Piedmont Ind Dr
Cont1 Const Mat:	Fiberboard				Shipper City:	Winston Salem
Cont1 Head Type:					Shipper State:	NC
Cont1 Pkg Capacity:	0				Shipper Postal:	27107
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	75777167577716828313
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	DULUTH
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30096
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2017090379	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2017-08-23	Report Submit Src:	XML
Time of Incident:	0405	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	5.2	Mode Transport:	Highway
Commodity Short Nm:	ORGANIC PEROXIDE TYPE F,	Transport Phase:	Loading
Commodity Long Nm:	ORGANIC PEROXIDE TYPE F, LIQUID	Incident Occrrnce:	
Trade Name:	peracetic acid	Mat Ship Approval?:	No
ID No:	UN3109	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	104	CR State:	PA
What Failed Desc:	Body	CR Postal Code:	15108
How Failed Code:	309	CR Non US State:	
How Failed Desc:	Punctured	CR Fed DOT ID:	265752
Failure Cause Code:	516	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g., nails)	CR Country:	US
Ident. Markings:		Shipper Name:	Zep Inc
Cont1 Pkging Type:	Jerrican	Shipper Street Name:	71 Business Park Ct
Cont1 Const Mat:	Plastic	Shipper City:	Cartersville
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30121
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	486166002143162
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	US
C1 Test Const Mat:	Plastic	Destination City:	TUCKER
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30084
C1 Pkg Shell Thick:	0	Destination Non US:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM NON-METAL
Haz Hosp Old Form:	0				HMIS Container Code:	PAIL PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						

The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No: X-2013100391
Report Type: A hazardous material incident

Fed DOT Agency Nm:
Fed DOT Report No:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Date of Incident:	2013-09-30				Report Submit Src:	XML
Time of Incident:	1633				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	PETROLEUM DISTILLATES, N				Transport Phase:	Loading
Commodity Long Nm:	PETROLEUM DISTILLATES, N.O.S. OR PETROLEUM PRODUCTS, N.O.S.				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1268				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	4				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	304				CR Non US State:	
How Failed Desc:	Cracked				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:					Shipper Name:	Volvo Penta
Cont1 Pkging Type:	Drum				Shipper Street Name:	3020 Evergreen Dr
Cont1 Const Mat:	Plastic				Shipper City:	Berkeley Lake
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30096
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	342519570209063
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Plastic				Destination City:	BEND
C1 Pkg Dsign Pres.:	0				Destination State:	OREGON
C1 Dsign Press UOM:					Destination Postal:	97702
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srv Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srv Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	Moon Township
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM NON-METAL
Haz Hosp Old Form:	0				HMIS Container Code:	DRUM PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic drum
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2019020517	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2019-01-23	Report Submit Src:	XML
Time of Incident:	1800	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	Transport Phase:	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1824	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	ECOLAB/CEVA LOGISTICS
Cont1 Pkging Type:	Drum	Shipper Street Name:	125 SOUTHSIDE CT
Cont1 Const Mat:	Plastic	Shipper City:	MCDONOUGH
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30253
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	916079075812681
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	CONTAINER
Haz Hosp Old Form:	0				HMIS Container Code:	CONT
Total Haz Hosp Inj:	0				HMIS Container Desc:	Container, no description given (do not use if at all possible)
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:		Original comments: PLASTIC PAIL WAS ON DOCK WET. I EXAMINED THE PAIL TO FIND A LOOSE CAP New Comments:				
Recommend Actions Taken:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>HMIR Incident Reports</u>						
Report No:	X-2019020518				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2019-01-23				Report Submit Src:	XML
Time of Incident:	2000				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL				Transport Phase:	Unloading
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1219				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	Krayden
Cont1 Pkging Type:	Box				Shipper Street Name:	18330 Sutter Blvd
Cont1 Const Mat:	Fiberboard				Shipper City:	MORGAN HILL
Cont1 Head Type:					Shipper State:	CA
Cont1 Pkg Capacity:	0				Shipper Postal:	95037
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	950932473500111239
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	NORCROSS
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30071
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	Plastic
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatafs:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	BOX FBR	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box or carton	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	Original comments: BOX WAS FOUNDED ON DOCK WET. AS I LOOKED INSIDE THE I SEE 3 BOTTLES OF ALPHA 857 New Comments:					
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:	X-2017100409			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	2017-09-28			Report Submit Src:	XML	
Time of Incident:	1503			Inc Multiple Rows:	No	
Haz Class Code:				Inc Non US State:		
Hazardous Class:	3			Mode Transport:	Highway	
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL			Transport Phase:	In Transit	
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1219			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	Fedex Ground Package System, Inc.	
Qty Released:	0.039062			CR Street Name:	1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon			CR City:	Moon Township	
What Failed:	104			CR State:	PA	
What Failed Desc:	Body			CR Postal Code:	15108	
How Failed Code:	309			CR Non US State:		
How Failed Desc:	Punctured			CR Fed DOT ID:	265752	
Failure Cause Code:	516			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g., nails)			CR Country:	US	
Ident. Markings:	4g/y24/s/17			Shipper Name:	LEHMAN INC	
Cont1 Pkging Type:				Shipper Street Name:	1585 GREENLEAF	
Cont1 Const Mat:				Shipper City:	Elk Grove Village	
Cont1 Head Type:				Shipper State:	IL	
Cont1 Pkg Capacity:	0			Shipper Postal:	60007	
C1 Capacity UOM:				Shipper Non US St:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	277958664566639300
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfr:					Origin State:	
Cont1 Pkg Mnfr Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	NORCROSS
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30071
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Non Hosp Resp: 0		Undeclared Shipment: No				
Description of Events:		The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:		X-2017110064		Fed DOT Agency Nm:		
Report Type:		A hazardous material incident		Fed DOT Report No:		
Date of Incident:		2017-10-06		Report Submit Src:		XML
Time of Incident:		0018		Inc Multiple Rows:		No
Haz Class Code:				Inc Non US State:		
Hazardous Class:		8		Mode Transport:		Highway
Commodity Short Nm:		HYPOCHLORITE SOLUTIONS		Transport Phase:		Loading
Commodity Long Nm:		HYPOCHLORITE SOLUTIONS		Incident Occrrnce:		
Trade Name:				Mat Ship Approval?: No		
ID No:		UN1791		Mat Ship Approv No:		
Haz Waste Ind:		No		Undecl Hazmat Ship?: No		
Haz Waste EPA No:				Packaging Type: Non-Bulk		
HMIS Tox Inhalation?:		No		Packing Group: II		
TIH Hazard Zone:				Carrier Reporter: Fedex Ground Package System, Inc.		
Qty Released:		0.26418		CR Street Name: 1000 Fedex Drive		
Unit of Measure:		Liquid - Gallon		CR City: Moon Township		
What Failed:		109		CR State: PA		
What Failed Desc:		Closure (e.g., Cap, Top, or Plug)		CR Postal Code: 15108		
How Failed Code:		308		CR Non US State:		
How Failed Desc:		Leaked		CR Fed DOT ID: 265752		
Failure Cause Code:		526		CR Hazmat Reg ID: 051910551007S		
Failure Cause Desc:		Loose Closure, Component, or Device		CR Country: US		
Ident. Markings:				Shipper Name: ecolabs		
Cont1 Pkging Type:		Jerrican		Shipper Street Name: 125 southdale ct		
Cont1 Const Mat:		Plastic		Shipper City: MCDONOUGH		
Cont1 Head Type:				Shipper State: GA		
Cont1 Pkg Capacity:		0		Shipper Postal: 30253		
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:		0		Shipper Country: US		
C1 Pkg Amt UOM:				Shipper Waybill: 916079072035144		
Cont1 Pkg No:		0		Ship Hazmat Reg ID:		
C1 Pkg NO Failed:		0		Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfc Dt:		0-00-00 00:00:00		Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:		0-00-00 00:00:00		Origin Country:		
C1 Test Const Mat:		Plastic		Destination City: ORMOND BEACH		
C1 Pkg Dsign Pres.:		0		Destination State: FLORIDA		
C1 Dsign Press UOM:				Destination Postal: 32174		
C1 Pkg Shell Thick:		0		Destination Non US:		
C1 Shell Thick UOM:				Destination Country: US		
C1 Head Thickness:		0		Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:		0		Cont2 Pkg Capacity: 0		
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:		No		Cont2 Pkg Amount: 0		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No: 0		
C1 Device Model:				Cont2 Pkg No Failed: 0		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public: 0		
RAM Pkg Cert.:		FALSE		Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries: 0		
RAM Transport Index:				Evacuation Indicator: No		
RAM UOM:				Public Evacuated: 0		
RAM Activity Rpted:		0		Employees Evac: 0		
RAM UOM Rpted:				Total Evacuated: 0		
RAM Activity:		0		Total Evacuation Hrs: 0		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Activity UOM:				Major Artery Closed:		No
RAM Mat Safety:				Mjr Artery Hrs Closed:		0
Spillage Result:	Yes			Material Involved:		No
Fire Result:	No			Estimated Speed:		0
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:		No
Gas Dispersion:	No			Vehicle Left Roadway:		No
Environment Damage:	No			Passenger Aircraft:		No
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:		No
Fire EMS EMS Report:				Ship Air First Flight:		No
Police Report:	No			Ship Air Subflight:		No
Police Report No:				Ship Init Transport:		No
In House Cleanup:	Yes			Ship Phase Transfer:		No
Other Cleanup:	No			Contact Name:		GEORGE FETSKO
Damage > 500:	No			Contact Title:		HAZMAT - SAFETY ADVISOR
Material Loss:	0			Contact Business:		Fedex Ground Package System, Inc.
Carrier Damage:	0			Contact Street:		1000 Fedex Drive
Property Damage:	0			Contact City:		CORAOPOLIS
Response Cost:	0			Contact State:		PA
Remediation Cost:	0			Contact Postal:		15108
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:		US
Hazmat Fatality:	No			Inc. Report Prepared:		Carrier
Haz Fatal Employees:	0			HMIS Serious Incidnt:		No
Haz Fatal Respndrs:	0			HMIS Serious Fatality:		No
Haz Fatal Gen Public:	0			HMIS Serious Injury:		No
Tot Hazmat Fatalities:	0			HMIS Flight Plan:		No
Non Hazmat Fatality:	No			HMIS Serious Evacs:		No
Non Hazmat Fatals:	0			HMIS Major Artery:		No
Hazmat Injury:	No			HMIS Bulk Release:		No
Haz Hospital Empl:	0			HMIS Marine Pollutnt:		No
Haz Hospital Resp:	0			HMIS Radioactive:		No
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:		DRUM NON-METAL
Haz Hosp Old Form:	0			HMIS Container Code:		PAIL PLS
Total Haz Hosp Inj:	0			HMIS Container Desc:		Plastic pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:				HMIS Bulk Incident:		No
Haz Non Hosp Resp:				Undeclared Shipment:		No
Description of Events:				The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.		

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2013100392	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2013-09-30	Report Submit Src:	XML
Time of Incident:	1646	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	PETROLEUM DISTILLATES, N	Transport Phase:	Loading
Commodity Long Nm:	PETROLEUM DISTILLATES, N.O.S. OR PETROLEUM PRODUCTS, N.O.S.	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1268	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.25	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Failure Cause Desc:	Loose Closure, Component, or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	N/A	
Cont1 Pkging Type:	Box			Shipper Street Name:	illegible	
Cont1 Const Mat:	Fiberboard			Shipper City:	Norcross	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:	0			Shipper Postal:	30071	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	111111111111111	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:		
C1 Test Const Mat:	Fiberboard			Destination City:	NORCROSS	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30071	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	Moon Township	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatafs:	0			HMIS Major Arterv:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2014100096				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2014-09-09				Report Submit Src:	XML
Time of Incident:	1700				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	NITRIC ACID OTHER THAN R				Transport Phase:	In Transit
Commodity Long Nm:	NITRIC ACID OTHER THAN RED FUMING, WITH AT LEAST 65 PERCENT, BUT NOT MORE THAN 70 PERCENT NITRIC ACID				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN2031				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	304				CR Non US State:	
How Failed Desc:	Cracked				CR Fed DOT ID:	265752
Failure Cause Code:	502				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Broken Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	DUDA DIESEL
Cont1 Pkging Type:	Box				Shipper Street Name:	1112 Brooks st
Cont1 Const Mat:	Fiberboard				Shipper City:	Decatur
Cont1 Head Type:					Shipper State:	AL
Cont1 Pkg Capacity:	0				Shipper Postal:	35601
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	78009656188
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Fiberboard				Destination City:	LAWRENCEVILLE
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30043
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Bottle
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:					The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.	

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2019020519	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2019-01-23	Report Submit Src:	XML
Time of Incident:	2300	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	HYDROCHLORIC ACID	Transport Phase:	Unloading
Commodity Long Nm:	HYDROCHLORIC ACID	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1789	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Qty Released:	0.375				CR Street Name: 1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon				CR City: CORAOPOLIS	
What Failed:	109				CR State: PA	
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code: 15108	
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID: 265752	
Failure Cause Code:	526				CR Hazmat Reg ID: 051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country: US	
Ident. Markings:	4G/Y20.0/S/18USA/+AA8398				Shipper Name: StatLab Medical Products	
Cont1 Pkging Type:					Shipper Street Name: 2090 Commerce Drive	
Cont1 Const Mat:					Shipper City: MCKINNEY	
Cont1 Head Type:					Shipper State: TX	
Cont1 Pkg Capacity:	0				Shipper Postal: 75069	
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country: US	
C1 Pkg Amt UOM:					Shipper Waybill: 1009931100909310620627	
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country: US	
C1 Test Const Mat:					Destination City: DECATUR	
C1 Pkg Dsign Pres.:	0				Destination State: GEORGIA	
C1 Dsign Press UOM:					Destination Postal: 30033	
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country: US	
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srv Pres.:	0				Cont2 Pkg Capacity: 0	
C1 Srv Pres UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount: 0	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No: 0	
C1 Device Model:					Cont2 Pkg No Failed: 0	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public: 0	
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries: 0	
RAM Transport Index:					Evacuation Indicator: No	
RAM UOM:					Public Evacuated: 0	
RAM Activity Rpted:	0				Employees Evac: 0	
RAM UOM Rpted:					Total Evacuated: 0	
RAM Activity:	0				Total Evacuation Hrs: 0	
RAM Activity UOM:					Major Artery Closed: No	
RAM Mat Safety:					Mjr Artery Hrs Closed: 0	
Spillage Result:	Yes				Material Involved: No	
Fire Result:	No				Estimated Speed: 0	
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn: No	
Gas Dispersion:	No				Vehicle Left Roadway: No	
Environment Damage:	No				Passenger Aircraft: No	
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport: No	
Fire EMS EMS Report:					Ship Air First Flight: No	
Police Report:	No				Ship Air Subflight: No	
Police Report No:					Ship Init Transport: No	
In House Cleanup:	Yes				Ship Phase Transfer: No	
Other Cleanup:	No				Contact Name: GEORGE FETSKO	
Damage > 500:	No				Contact Title: HAZMAT - SAFETY ADVISOR	
Material Loss:	0				Contact Business: Fedex Ground Package System, Inc.	
Carrier Damage:	0				Contact Street: 1000 Fedex Drive	
Property Damage:	0				Contact City: CORAOPOLIS	
Response Cost:	0				Contact State: PA	
Remediation Cost:	0				Contact Postal: 15108	
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country: US	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazmat Fatality:	No				Inc. Report Prepared: Carrier	
Haz Fatal Employees:	0				HMIS Serious Incidnt: No	
Haz Fatal Respndrs:	0				HMIS Serious Fatality: No	
Haz Fatal Gen Public:	0				HMIS Serious Injury: No	
Tot Hazmat Fatalities:	0				HMIS Flight Plan: No	
Non Hazmat Fatality:	No				HMIS Serious Evacs: No	
Non Hazmat Fatals:	0				HMIS Major Artery: No	
Hazmat Injury:	No				HMIS Bulk Release: No	
Haz Hospital Empl:	0				HMIS Marine Pollutnt: No	
Haz Hospital Resp:	0				HMIS Radioactive: No	
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type: BOX FIBER	
Haz Hosp Old Form:	0				HMIS Container Code: 4G	
Total Haz Hosp Inj:	0				HMIS Container Desc: Fiberboard box	
Haz Non Hosp Empl:	0				HMIS Bulk Incident: No	
Haz Non Hosp Resp:	0				Undeclared Shipment: No	
Description of Events:	Original comments: Box was founded on dock wet, as I looked inside the box there was 4 1-gal of decal stat with loose caps New Comments:					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2018080555	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2018-07-21	Report Submit Src:	XML
Time of Incident:	0045	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	COMPOUNDS, CLEANING LIQU	Transport Phase:	Unloading
Commodity Long Nm:	COMPOUNDS, CLEANING LIQUID	Incident Occrrnce:	
Trade Name:	containing Potassium	Mat Ship Approval?:	No
ID No:	NA1760	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	2	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	GCE/Soap Warehouse Brand
Cont1 Pkging Type:	Drum	Shipper Street Name:	1580 Beaver Ruin Road
Cont1 Const Mat:	Plastic	Shipper City:	NORCROSS
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30093
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	5693903569444795473
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg MnfcDt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	US
C1 Test Const Mat:	Plastic	Destination City:	FORT WALTON BEACH
C1 Pkg Dsign Pres.:	0	Destination State:	FLORIDA
C1 Dsign Press UOM:		Destination Postal:	32547
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0	Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	0
C1 Device Type:		Cont2 Pkg Amt UOM:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Device Mnfctr:			Cont2 Pkg No:		0	
C1 Device Model:			Cont2 Pkg No Failed:		0	
NRC No:						
RAM Pkg Category:			Haz NonHosp Public:		0	
RAM Pkg Cert.: FALSE			Haz NonHosp Old:			
RAM Pkg Cert. NBR:			Tot Haz Non Hosp Inj:			
RAM Nuclide S:			Total Hazmat Injuries:		0	
RAM Transport Index:			Evacuation Indicator:		No	
RAM UOM:			Public Evacuated:		0	
RAM Activity Rpted: 0			Employees Evac:		0	
RAM UOM Rpted:			Total Evacuated:		0	
RAM Activity: 0			Total Evacuation Hrs:		0	
RAM Activity UOM:			Major Artery Closed:		No	
RAM Mat Safety:			Mjr Artery Hrs Closed:		0	
Spillage Result: Yes			Material Involved:		No	
Fire Result: No			Estimated Speed:		0	
Explosion Result: No			Weather Conditions:			
Water Sewer Result: No			Vehicle Overturn:		No	
Gas Dispersion: No			Vehicle Left Roadway:		No	
Environment Damage: No			Passenger Aircraft:		No	
No Release Result: No			Cargo Baggage:			
Fire EMS Report: No			Ship Non Transport:		No	
Fire EMS EMS Report:			Ship Air First Flight:		No	
Police Report: No			Ship Air Subflight:		No	
Police Report No:			Ship Init Transport:		No	
In House Cleanup: Yes			Ship Phase Transfer:		No	
Other Cleanup: No			Contact Name:		GEORGE FETSKO	
Damage > 500: No			Contact Title:		HAZMAT - SAFETY ADVISOR	
Material Loss: 0			Contact Business:		Fedex Ground Package System, Inc.	
Carrier Damage: 0			Contact Street:		1000 Fedex Drive	
Property Damage: 0			Contact City:		CORAOPOLIS	
Response Cost: 0			Contact State:		PA	
Remediation Cost: 0			Contact Postal:		15108	
Damage Old Form: 0			Contact Non US St:			
Total Damages Amt: 0			Contact Country:		US	
Hazmat Fatality: No			Inc. Report Prepared:		Carrier	
Haz Fatal Employees: 0			HMIS Serious Incidnt:		No	
Haz Fatal Respntrs: 0			HMIS Serious Fatality:		No	
Haz Fatal Gen Public: 0			HMIS Serious Injury:		No	
Tot Hazmat Fatalities: 0			HMIS Flight Plan:		No	
Non Hazmat Fatality: No			HMIS Serious Evacs:		No	
Non Hazmat Fatals: 0			HMIS Major Artery:		No	
Hazmat Injury: No			HMIS Bulk Release:		No	
Haz Hospital Empl: 0			HMIS Marine Pollutnt:		No	
Haz Hospital Resp: 0			HMIS Radioactive:		No	
Haz Hosp Gen Public: 0			HMIS Gen Pkg Type:			
Haz Hosp Old Form: 0			HMIS Container Code:			
Total Haz Hosp Inj: 0			HMIS Container Desc:			
Haz Non Hosp Empl: 0			HMIS Bulk Incident:		No	
Haz Non Hosp Resp: 0			Undeclared Shipment:		No	
Description of Events:			Original comments: BOX WAS FOUND ON DOCK WET. AS I LOOKED INSIDE THERE WAS 5GAL PLASTIC DRUM OF HOOD CLEANER WITH A LOOSE CAP New Comments:			

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2017090211	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2017-08-17	Report Submit Src:	XML
Time of Incident:	1203	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	ETHANOL SOLUTIONS	Transport Phase:	Unloading
Commodity Long Nm:	ETHANOL SOLUTIONS	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1170	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.26418				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:					Shipper Name:	Decon Labs
Cont1 Pkging Type:	Jerrican				Shipper Street Name:	464 Glennie Circle
Cont1 Const Mat:	Plastic				Shipper City:	King Of Prussia
Cont1 Head Type:					Shipper State:	PA
Cont1 Pkg Capacity:	0				Shipper Postal:	19406
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	695774779988220985
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM NON-METAL
Haz Hosp Old Form:	0				HMIS Container Code:	PAIL PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2017110282	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2017-10-17	Report Submit Src:	XML
Time of Incident:	0600	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	Transport Phase:	Loading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1824	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.023438	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	309	CR Non US State:	
How Failed Desc:	Punctured	CR Fed DOT ID:	265752
Failure Cause Code:	516	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g., nails)	CR Country:	US
Ident. Markings:	4g/y24.7/s/17/usa/m4172	Shipper Name:	ecl-kay
Cont1 Pkgng Type:		Shipper Street Name:	90 piedmont industrial dr
Cont1 Const Mat:		Shipper City:	WINSTON SALEM
Cont1 Head Type:		Shipper State:	NC
Cont1 Pkg Capacity:	0	Shipper Postal:	27107
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	757771682960838
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:		Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30329
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srv Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srv Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2018090052				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2018-08-13				Report Submit Src:	XML
Time of Incident:	2017				Inc Multiple Rows:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Class Code:			Inc Non US State:			
Hazardous Class:	3			Mode Transport:	Highway	
Commodity Short Nm:	COMPOUNDS, CLEANING LIQU			Transport Phase:	Unloading	
Commodity Long Nm:	COMPOUNDS, CLEANING LIQUID			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	NA1993			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	Fedex Ground Package System, Inc.	
Qty Released:	1			CR Street Name:	1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon			CR City:	CORAOPOLIS	
What Failed:	140			CR State:	PA	
What Failed Desc:	Outer Frame			CR Postal Code:	15108	
How Failed Code:	309			CR Non US State:		
How Failed Desc:	Punctured			CR Fed DOT ID:	265752	
Failure Cause Code:	511			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Dropped			CR Country:	US	
Ident. Markings:	4G/Y30/S/17 USA/+CM0042			Shipper Name:	FedEx Ground	
Cont1 Pkging Type:	Box			Shipper Street Name:	6265 Atlantic Blvd	
Cont1 Const Mat:	Fiberboard			Shipper City:	NORCROSS	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:	0			Shipper Postal:	30071	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	307382889090122517253	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:	US	
C1 Test Const Mat:	Fiberboard			Destination City:	ATLANTA	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30360	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srv Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srv Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:			Haz NonHosp Public:			0
RAM Pkg Cert.:	FALSE		Haz NonHosp Old:			
RAM Pkg Cert. NBR:			Tot Haz Non Hosp Inj:			
RAM Nuclide S:			Total Hazmat Injuries:	0		
RAM Transport Index:			Evacuation Indicator:	No		
RAM UOM:			Public Evacuated:	0		
RAM Activity Rpted:	0		Employees Evac:	0		
RAM UOM Rpted:			Total Evacuated:	0		
RAM Activity:	0		Total Evacuation Hrs:	0		
RAM Activity UOM:			Major Artery Closed:	No		
RAM Mat Safety:			Mjr Artery Hrs Closed:	0		
Spillage Result:	Yes		Material Involved:	No		
Fire Result:	No		Estimated Speed:	0		
Explosion Result:	No		Weather Conditions:			
Water Sewer Result:	No		Vehicle Overturn:	No		
Gas Dispersion:	No		Vehicle Left Roadway:	No		
Environment Damage:	No		Passenger Aircraft:	No		
No Release Result:	No		Cargo Baggage:			
Fire EMS Report:	No		Ship Non Transport:	No		
Fire EMS EMS Report:			Ship Air First Flight:	No		
Police Report:	No		Ship Air Subflight:	No		
Police Report No:			Ship Init Transport:	No		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: pails were punctured during the unload process New Comments:					
Recommend Actions Taken:						

HMIR Incident Reports

Report No:	X-2017110188	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2017-10-15	Report Submit Src:	XML
Time of Incident:	1355	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	Transport Phase:	Loading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1824	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	ecolab
Cont1 Pkging Type:	Drum	Shipper Street Name:	125 southdale ct
Cont1 Const Mat:	Plastic	Shipper City:	MCDONOUGH
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30253
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	9160790128842687
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfcct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	US
C1 Test Const Mat:	Plastic	Destination City:	MCDONOUGH
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Dsign Press UOM: C1 Pkg Shell Thick: 0 C1 Shell Thick UOM: C1 Head Thickness: 0 C1 Head Thick UOM: C1 Pkg Srvc Pres.: 0 C1 Srvc Press UOM: C1 Valve/Device Fail?: No C1 Device Type: C1 Device Mnfctr: C1 Device Model: NRC No:						Destination Postal: 30253 Destination Non US: Destination Country: US Cont2 Package Type: Cont2 Const Mat: Cont2 Pkg Capacity: 0 Cont2 Capacity UOM: Cont2 Pkg Amount: 0 Cont2 Pkg Amt UOM: Cont2 Pkg No: 0 Cont2 Pkg No Failed: 0
RAM Pkg Category: RAM Pkg Cert.: FALSE RAM Pkg Cert. NBR: RAM Nuclide S: RAM Transport Index: RAM UOM: RAM Activity Rpted: 0 RAM UOM Rpted: RAM Activity: 0 RAM Activity UOM: RAM Mat Safety: Spillage Result: Yes Fire Result: No Explosion Result: No Water Sewer Result: No Gas Dispersion: No Environment Damage: No No Release Result: No Fire EMS Report: No Fire EMS EMS Report: Police Report: No Police Report No: In House Cleanup: Yes Other Cleanup: No Damage > 500: No Material Loss: 0 Carrier Damage: 0 Property Damage: 0 Response Cost: 0 Remediation Cost: 0 Damage Old Form: 0 Total Damages Amt: 0 Hazmat Fatality: No Haz Fatal Employees: 0 Haz Fatal Respntrs: 0 Haz Fatal Gen Public: 0 Tot Hazmat Fatalities: 0 Non Hazmat Fatality: No Non Hazmat Fatals: 0 Hazmat Injury: No Haz Hospital Empl: 0 Haz Hospital Resp: 0 Haz Hosp Gen Public: 0 Haz Hosp Old Form: 0 Total Haz Hosp Inj: 0 Haz Non Hosp Empl: 0 Haz Non Hosp Resp: 0 Description of Events:						Haz NonHosp Public: 0 Haz NonHosp Old: Tot Haz Non Hosp Inj: Total Hazmat Injuries: 0 Evacuation Indicator: No Public Evacuated: 0 Employees Evac: 0 Total Evacuated: 0 Total Evacuation Hrs: 0 Major Artery Closed: No Mjr Artery Hrs Closed: 0 Material Involved: No Estimated Speed: 0 Weather Conditions: Vehicle Overturn: No Vehicle Left Roadway: No Passenger Aircraft: No Cargo Baggage: Ship Non Transport: No Ship Air First Flight: No Ship Air Subflight: No Ship Init Transport: No Ship Phase Transfer: No Contact Name: GEORGE FETSKO Contact Title: HAZMAT - SAFETY ADVISOR Contact Business: Fedex Ground Package System, Inc. Contact Street: 1000 Fedex Drive Contact City: CORAOPOLIS Contact State: PA Contact Postal: 15108 Contact Non US St: Contact Country: US Inc. Report Prepared: Carrier HMIS Serious Incidnt: No HMIS Serious Fatality: No HMIS Serious Injury: No HMIS Flight Plan: No HMIS Serious Evacs: No HMIS Major Artery: No HMIS Bulk Release: No HMIS Marine Pollutnt: No HMIS Radioactive: No HMIS Gen Pkg Type: DRUM NON-METAL HMIS Container Code: DRUM PLS HMIS Container Desc: Plastic drum HMIS Bulk Incident: No Undeclared Shipment: No
Recommend Actions Taken:						The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

HMIR Incident Reports

Report No: X-2013120187

Fed DOT Agency Nm:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	2013-11-15			Report Submit Src:	XML	
Time of Incident:	1648			Inc Multiple Rows:	No	
Haz Class Code:				Inc Non US State:		
Hazardous Class:	3			Mode Transport:	Highway	
Commodity Short Nm:	GASOLINE INCLUDES GASOLI			Transport Phase:	Unloading	
Commodity Long Nm:	GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL, WITH NOT MORE THAN 10% ALCOHOL			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1203			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	Fedex Ground Package System, Inc.	
Qty Released:	0.25			CR Street Name:	1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon			CR City:	Moon Township	
What Failed:	104			CR State:	PA	
What Failed Desc:	Body			CR Postal Code:	15108	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	Motiva Enterprises LLC	
Cont1 Pkging Type:	Box			Shipper Street Name:	4127 Winter Chapel Rd	
Cont1 Const Mat:	Fiberboard			Shipper City:	DORAVILLE	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:	0			Shipper Postal:	30360	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	427541762800284	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:		
C1 Test Const Mat:	Fiberboard			Destination City:	ABAC	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	31794	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:	Can	
C1 Head Thick UOM:				Cont2 Const Mat:	Metal (any type)	
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2014010030	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2013-12-05	Report Submit Src:	XML
Time of Incident:	1659	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,	Transport Phase:	Loading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.	Incident Occrrnce:	
Trade Name:	Sodium Hydroxide, Al	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	NALCO COMPANY
Cont1 Pkging Type:	Jerrican	Shipper Street Name:	7701 HIGHWAY 90A
Cont1 Const Mat:	Plastic	Shipper City:	Sugar Land
Cont1 Head Type:		Shipper State:	TX
Cont1 Pkg Capacity:	0	Shipper Postal:	77478
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	532835499631

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Plastic				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30324
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	INSIDE CONTAIN
Haz Hosp Old Form:	0				HMIS Container Code:	CONT PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic container, no capacity or description given
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Description of Events:		The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2017080188			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	2017-07-12			Report Submit Src:	XML	
Time of Incident:	0556			Inc Multiple Rows:	No	
Haz Class Code:				Inc Non US State:		
Hazardous Class:	8			Mode Transport:	Highway	
Commodity Short Nm:	CORROSIVE LIQUID, ACIDIC			Transport Phase:	Loading	
Commodity Long Nm:	CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S.			Incident Occrrnce:		
Trade Name:	(PHOSPHORIC ACID, HY			Mat Ship Approval?:	No	
ID No:	UN3264			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	
Haz Waste EPA No:				Packaging Type:	Non-Bulk	
HMIS Tox Inhalation?:	No			Packing Group:	II	
TIH Hazard Zone:				Carrier Reporter:	Fedex Ground Package System, Inc.	
Qty Released:	1			CR Street Name:	1000 Fedex Drive	
Unit of Measure:	Liquid - Gallon			CR City:	Moon Township	
What Failed:	109			CR State:	PA	
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)			CR Postal Code:	15108	
How Failed Code:	308			CR Non US State:		
How Failed Desc:	Leaked			CR Fed DOT ID:	265752	
Failure Cause Code:	526			CR Hazmat Reg ID:	051910551007S	
Failure Cause Desc:	Loose Closure, Component, or Device			CR Country:	US	
Ident. Markings:				Shipper Name:	ZEP INC	
Cont1 Pkging Type:	Box			Shipper Street Name:	71 BUSINESS PARK DR	
Cont1 Const Mat:	Fiberboard			Shipper City:	Cartersville	
Cont1 Head Type:				Shipper State:	GA	
Cont1 Pkg Capacity:	0			Shipper Postal:	30121	
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:	0			Shipper Country:	US	
C1 Pkg Amt UOM:				Shipper Waybill:	496166002012970	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:		
C1 Test Const Mat:	Fiberboard			Destination City:	TUCKER	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	30084	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:	Bottle	
C1 Head Thick UOM:				Cont2 Const Mat:	Plastic	
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Activity UOM:			Major Artery Closed:			No
RAM Mat Safety:			Mjr Artery Hrs Closed:			0
Spillage Result:			Material Involved:			No
Fire Result:			Estimated Speed:			0
Explosion Result:			Weather Conditions:			
Water Sewer Result:			Vehicle Overturn:			No
Gas Dispersion:			Vehicle Left Roadway:			No
Environment Damage:			Passenger Aircraft:			No
No Release Result:			Cargo Baggage:			
Fire EMS Report:			Ship Non Transport:			No
Fire EMS EMS Report:			Ship Air First Flight:			No
Police Report:			Ship Air Subflight:			No
Police Report No:			Ship Init Transport:			No
In House Cleanup:			Ship Phase Transfer:			No
Other Cleanup:			Contact Name:			GEORGE FETSKO
Damage > 500:			Contact Title:			HAZMAT - SAFETY ADVISOR
Material Loss:			Contact Business:			Fedex Ground Package System, Inc.
Carrier Damage:			Contact Street:			1000 Fedex Drive
Property Damage:			Contact City:			CORAOPOLIS
Response Cost:			Contact State:			PA
Remediation Cost:			Contact Postal:			15108
Damage Old Form:			Contact Non US St:			
Total Damages Amt:			Contact Country:			US
Hazmat Fatality:			Inc. Report Prepared:			Carrier
Haz Fatal Employees:			HMIS Serious Incidnt:			No
Haz Fatal Respntrs:			HMIS Serious Fatality:			No
Haz Fatal Gen Public:			HMIS Serious Injury:			No
Tot Hazmat Fatalities:			HMIS Flight Plan:			No
Non Hazmat Fatality:			HMIS Serious Evacs:			No
Non Hazmat Fatals:			HMIS Major Artery:			No
Hazmat Injury:			HMIS Bulk Release:			No
Haz Hospital Empl:			HMIS Marine Pollutnt:			No
Haz Hospital Resp:			HMIS Radioactive:			No
Haz Hosp Gen Public:			HMIS Gen Pkg Type:			BOX FIBER
Haz Hosp Old Form:			HMIS Container Code:			BOX FBR
Total Haz Hosp Inj:			HMIS Container Desc:			Fiberboard box or carton
Haz Non Hosp Empl:			HMIS Bulk Incident:			No
Haz Non Hosp Resp:			Undeclared Shipment:			No
Description of Events:			The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.			

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2017110063	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2017-10-06	Report Submit Src:	XML
Time of Incident:	0012	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	METHANOL	Transport Phase:	Loading
Commodity Long Nm:	METHANOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1230	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.001308	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:	4g/y25/s/16/usa/m5586	Shipper Name:	mckesson medical durgical

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkging Type:					Shipper Street Name:	1005 satellite blvd
Cont1 Const Mat:					Shipper City:	Suwanee
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30024
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	1146899664833599331
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	CLARKSVILLE
C1 Pkg Dsign Pres.:	0				Destination State:	TENNESSEE
C1 Dsign Press UOM:					Destination Postal:	37040
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2017110270				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2017-10-17				Report Submit Src:	XML
Time of Incident:	0107				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI				Transport Phase:	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.003904				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4g/y24..7/s/17/usa/m4172				Shipper Name:	ecl-kay
Cont1 Pkging Type:					Shipper Street Name:	90 piedmot industrial dr
Cont1 Const Mat:					Shipper City:	Winston Salem
Cont1 Head Type:					Shipper State:	NC
Cont1 Pkg Capacity:	0				Shipper Postal:	27107
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	757771682960821
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:					Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respntrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:				The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.		

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2017120081	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2017-11-07	Report Submit Src:	XML
Time of Incident:	2330	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	BATTERY FLUID, ACID	Transport Phase:	Unloading
Commodity Long Nm:	BATTERY FLUID, ACID	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN2796	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.25	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	Carolina Handling
Cont1 Pkging Type:	Jerrican				Shipper Street Name:	1955 Montreal Rd
Cont1 Const Mat:	Plastic				Shipper City:	Tucker
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30084
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	148805889030131148738
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	
C1 Test Const Mat:	Plastic				Destination City:	DINSMORE
C1 Pkg Dsign Pres.:	0				Destination State:	FLORIDA
C1 Dsign Press UOM:					Destination Postal:	32219
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	DRUM NON-METAL
Haz Hosp Old Form:	0				HMIS Container Code:	PAIL PLS
Total Haz Hosp Inj:	0				HMIS Container Desc:	Plastic pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2020060222	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2019-12-16	Report Submit Src:	XML
Time of Incident:	2300	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,	Transport Phase:	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.	Incident Occrrnce:	
Trade Name:	Sodium hydroxide	Mat Ship Approval?:	No
ID No:	UN3266	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.5	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G/Y19.4/S/19USA/+CP1206	Shipper Name:	ZEP INC-NASS
Cont1 Pkging Type:	Box	Shipper Street Name:	71 BUSINESS PARK DR
Cont1 Const Mat:	Fiberboard	Shipper City:	CARTERSVILLE
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30121
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	2227330222733020765016
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	US
C1 Test Const Mat:	Fiberboard	Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30338
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0	Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	0
C1 Device Type:		Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:		Cont2 Pkg No:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	HAZMAT - SAFETY ADVISOR	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	CORAOPOLIS	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatals:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:	NO COMMENTS PROVIDED.					
HMIR Incident Reports						
Report No:	X-2014060207			Fed DOT Agency Nm:		
Report Type:	A hazardous material incident			Fed DOT Report No:		
Date of Incident:	2014-05-16			Report Submit Src:	XML	
Time of Incident:	2351			Inc Multiple Rows:	No	
Haz Class Code:				Inc Non US State:		
Hazardous Class:	3			Mode Transport:	Highway	
Commodity Short Nm:	ETHANOL SOLUTIONS			Transport Phase:	Loading	
Commodity Long Nm:	ETHANOL SOLUTIONS			Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:	No	
ID No:	UN1170			Mat Ship Approv No:		
Haz Waste Ind:	No			Undecl Hazmat Ship?:	No	

DB

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respndrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat Fatafs:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	BOX FBR	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box or carton	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2018120555	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2018-11-30	Report Submit Src:	XML
Time of Incident:	2200	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	8	Mode Transport:	Highway
Commodity Short Nm:	SPIRITS OF SALT	Transport Phase:	Unloading
Commodity Long Nm:	SPIRITS OF SALT	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1789	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	NO MARKINGS GIVEN	Shipper Name:	StatLab Medical Products
Cont1 Pkging Type:	Jerrican	Shipper Street Name:	2090 Commerce Drive
Cont1 Const Mat:	Plastic	Shipper City:	MCKINNEY
Cont1 Head Type:		Shipper State:	TX
Cont1 Pkg Capacity:	0	Shipper Postal:	75069
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	100909310465839
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	US
C1 Test Const Mat:	Plastic	Destination City:	DULUTH
C1 Pkg Dsign Pres.:	0	Destination State:	GEORGIA
C1 Dsign Press UOM:		Destination Postal:	30097
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfrctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	
Haz Hosp Old Form:	0				HMIS Container Code:	NO MARKI
Total Haz Hosp Inj:	0				HMIS Container Desc:	
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						
					Original comments: PACKAGE WAS FOUND ON DOCK WET. AS I LOOKED INSIDE THERE WAS A PLASTIC BAG WITH A LOOSE CAP New Comments:	
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2018070572				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2018-06-25				Report Submit Src:	XML
Time of Incident:	2203				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	ETHYL ALCOHOL				Transport Phase:	Unloading

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Commodity Long Nm:	ETHYL ALCOHOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1170				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:					Shipper Name:	Decon Labs, Inc.
Cont1 Pkging Type:	Jerrican				Shipper Street Name:	460 GLENNIE CIR
Cont1 Const Mat:	Plastic				Shipper City:	KING OF PRUSSIA
Cont1 Head Type:					Shipper State:	PA
Cont1 Pkg Capacity:	0				Shipper Postal:	19406
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	695774781486004510
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Plastic				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30322
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Material Loss:	0				Contact Business: Fedex Ground Package System, Inc.	
Carrier Damage:	0				Contact Street: 1000 Fedex Drive	
Property Damage:	0				Contact City: CORAOPOLIS	
Response Cost:	0				Contact State: PA	
Remediation Cost:	0				Contact Postal: 15108	
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country: US	
Hazmat Fatality:	No				Inc. Report Prepared: Carrier	
Haz Fatal Employees:	0				HMIS Serious Incidnt: No	
Haz Fatal Respndrs:	0				HMIS Serious Fatality: No	
Haz Fatal Gen Public:	0				HMIS Serious Injury: No	
Tot Hazmat Fatalities:	0				HMIS Flight Plan: No	
Non Hazmat Fatality:	No				HMIS Serious Evacs: No	
Non Hazmat FataIs:	0				HMIS Major Artery: No	
Hazmat Injury:	No				HMIS Bulk Release: No	
Haz Hospital Empl:	0				HMIS Marine Pollutnt: No	
Haz Hospital Resp:	0				HMIS Radioactive: No	
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type: CONTAINER	
Haz Hosp Old Form:	0				HMIS Container Code: CONT	
Total Haz Hosp Inj:	0				HMIS Container Desc: Container, no description given (do not use if at all possible)	
Haz Non Hosp Empl:	0				HMIS Bulk Incident: No	
Haz Non Hosp Resp:	0				Undeclared Shipment: No	
Description of Events:	Original comments: BOX WAS FOUND ON DOCK WET. AS I LOOKED INSIDE THERE WERE 4 1 GAL BOTTLES OF ETHANOL 2 HAD LOOSE CAPS THE OTHER 2 WAS OK New Comments:					
Recommend Actions Taken:						

HMIR Incident Reports

Report No:	X-2018070591	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2018-06-26	Report Submit Src:	XML
Time of Incident:	2100	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	METHANOL	Transport Phase:	Unloading
Commodity Long Nm:	METHANOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1230	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.125	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	CORAOPOLIS
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G/Y6.4/S/17 USA/aa4303	Shipper Name:	Fisher Scientific
Cont1 Pkging Type:		Shipper Street Name:	Shepard
Cont1 Const Mat:		Shipper City:	SUWANEE
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30024
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	39064596123020390645736071
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	US
C1 Test Const Mat:		Destination City:	JACKSON
C1 Pkg Dsgn Pres.:	0	Destination State:	MISSISSIPPI
C1 Dsgn Press UOM:		Destination Postal:	39216

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatafs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:		Original comments: BOX WAS FOUND ON FLOOR WET. AS I LOOKED INSIDE THERE WAS 1 B OTTLE METHANOL WITH A LOOSE CAP New Comments:				
Recommend Actions Taken:						

HMIR Incident Reports

Report No:	X-2018050755	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2018-04-29	Report Submit Src:	XML

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Time of Incident:	2200				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	8				Mode Transport:	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI				Transport Phase:	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1824				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	NO MARKINGS GIVEN				Shipper Name:	ECOLAB/CEVA LOGISTICS
Cont1 Pkging Type:	Drum				Shipper Street Name:	125 SOUTHSIDE CT
Cont1 Const Mat:	Metal other than steel or aluminum				Shipper City:	MCDONOUGH
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30253
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	91607907452718
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Metal other than steel or aluminum				Destination City:	ATLANTA
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30329
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Police Report No:				Ship Init Transport:		No
In House Cleanup:				Ship Phase Transfer:		No
Other Cleanup:				Contact Name:		GEORGE FETSKO
Damage > 500:				Contact Title:		HAZMAT - SAFETY ADVISOR
Material Loss:				Contact Business:		Fedex Ground Package System, Inc.
Carrier Damage:				Contact Street:		1000 Fedex Drive
Property Damage:				Contact City:		CORAOPOLIS
Response Cost:				Contact State:		PA
Remediation Cost:				Contact Postal:		15108
Damage Old Form:				Contact Non US St:		
Total Damages Amt:				Contact Country:		US
Hazmat Fatality:				Inc. Report Prepared:		Carrier
Haz Fatal Employees:				HMIS Serious Incidnt:		No
Haz Fatal Respndrs:				HMIS Serious Fatality:		No
Haz Fatal Gen Public:				HMIS Serious Injury:		No
Tot Hazmat Fatalities:				HMIS Flight Plan:		No
Non Hazmat Fatality:				HMIS Serious Evacs:		No
Non Hazmat Fatais:				HMIS Major Artery:		No
Hazmat Injury:				HMIS Bulk Release:		No
Haz Hospital Empl:				HMIS Marine Pollutnt:		No
Haz Hospital Resp:				HMIS Radioactive:		No
Haz Hosp Gen Public:				HMIS Gen Pkg Type:		
Haz Hosp Old Form:				HMIS Container Code:		NO MARKI
Total Haz Hosp Inj:				HMIS Container Desc:		
Haz Non Hosp Empl:				HMIS Bulk Incident:		No
Haz Non Hosp Resp:				Undeclared Shipment:		No
Description of Events:			Original comments: bucket or pail was found on dock wet. as I examined the pail notice liquid was leaking from cap New Comments:			
Recommend Actions Taken:						
<u>HMIR Incident Reports</u>						
Report No:		X-2018050771		Fed DOT Agency Nm:		
Report Type:		A hazardous material incident		Fed DOT Report No:		
Date of Incident:		2018-05-01		Report Submit Src:		XML
Time of Incident:		2300		Inc Multiple Rows:		No
Haz Class Code:				Inc Non US State:		
Hazardous Class:		3		Mode Transport:		Highway
Commodity Short Nm:		PRINTING INK, FLAMMABLE		Transport Phase:		Unloading
Commodity Long Nm:		PRINTING INK, FLAMMABLE OR PRINTING INK RELATED MATERIAL (INCLUDING PRINTING INK THINNING OR REDUCING COMPOUND), FLAMMABLE		Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:		No
ID No:		UN1210		Mat Ship Approv No:		
Haz Waste Ind:		No		Undecl Hazmat Ship?:		No
Haz Waste EPA No:				Packaging Type:		Non-Bulk
HMIS Tox Inhalation?:		No		Packing Group:		II
TIH Hazard Zone:				Carrier Reporter:		Fedex Ground Package System, Inc.
Qty Released:		0.0625		CR Street Name:		1000 Fedex Drive
Unit of Measure:		Liquid - Gallon		CR City:		CORAOPOLIS
What Failed:		109		CR State:		PA
What Failed Desc:		Closure (e.g., Cap, Top, or Plug)		CR Postal Code:		15108
How Failed Code:		308		CR Non US State:		
How Failed Desc:		Leaked		CR Fed DOT ID:		265752
Failure Cause Code:		526		CR Hazmat Reg ID:		051910551007S
Failure Cause Desc:		Loose Closure, Component, or Device		CR Country:		US
Ident. Markings:		NO MARKINGS GIVEN		Shipper Name:		Printers Service
Cont1 Pkging Type:		Jerrican		Shipper Street Name:		7055 Amwiler Industrial dr.
Cont1 Const Mat:		Aluminum		Shipper City:		ATLANTA
Cont1 Head Type:				Shipper State:		GA
Cont1 Pkg Capacity:		0		Shipper Postal:		30360
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:		0		Shipper Country:		US
C1 Pkg Amt UOM:				Shipper Waybill:		30738232666947
Cont1 Pkg No:		0		Ship Hazmat Reg ID:		
C1 Pkg NO Failed:		0		Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Aluminum				Destination City:	SANFORD
C1 Pkg Dsign Pres.:	0				Destination State:	FLORIDA
C1 Dsign Press UOM:					Destination Postal:	32771
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat FataIs:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	
Haz Hosp Old Form:	0				HMIS Container Code:	NO MARKI
Total Haz Hosp Inj:	0				HMIS Container Desc:	
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:						
Recommend Actions Taken:						

Original comments: BOX WAS FOUND WET ON DOCK. AS I LOOKED INSIDE THERE WAS 2 1G AL CANS OF METERING ROLLER CLEANER WITH LOOSE CAPS New Comments:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>HMIR Incident Reports</u>						
Report No:	X-2017110329				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2017-10-19				Report Submit Src:	XML
Time of Incident:	0411				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	ETHANOL OR ETHYL ALCOHOL				Transport Phase:	Loading
Commodity Long Nm:	ETHANOL OR ETHYL ALCOHOL OR ETHANOL SOLUTIONS OR ETHYL ALCOHOL SOLUTIONS				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1170				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.039062				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	Moon Township
What Failed:	104				CR State:	PA
What Failed Desc:	Body				CR Postal Code:	15108
How Failed Code:	305				CR Non US State:	
How Failed Desc:	Crushed				CR Fed DOT ID:	265752
Failure Cause Code:	511				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped				CR Country:	US
Ident. Markings:	4G/X1.5/S/11/USA/AA0747				Shipper Name:	KMX Chemical
Cont1 Pkging Type:					Shipper Street Name:	30474 ENERGY DR
Cont1 Const Mat:					Shipper City:	New Church
Cont1 Head Type:					Shipper State:	VA
Cont1 Pkg Capacity:	0				Shipper Postal:	23415
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	244767760003918
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:					Destination City:	CUMMING
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30040
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						
HMIR Incident Reports						
Report No:	X-2018050789				Fed DOT Agency Nm:	
Report Type:	A hazardous material incident				Fed DOT Report No:	
Date of Incident:	2018-05-02				Report Submit Src:	XML
Time of Incident:	2301				Inc Multiple Rows:	No
Haz Class Code:					Inc Non US State:	
Hazardous Class:	3				Mode Transport:	Highway
Commodity Short Nm:	GASOLINE INCLUDES GASOLI				Transport Phase:	Unloading
Commodity Long Nm:	GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL, WITH NOT MORE THAN 10% ALCOHOL				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1203				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	No
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.0625				CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)				CR Postal Code:	15108
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device				CR Country:	US
Ident. Markings:	4G/Y28/S/15USA/+BR9196				Shipper Name:	INDIVIDUAL- NOT A COMPANY
Cont1 Pkging Type:	Box				Shipper Street Name:	4127 Winters Chapel Rd.
Cont1 Const Mat:	Fiberboard				Shipper City:	Atlanta

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Head Type:					Shipper State:	GA
Cont1 Pkg Capacity:	0				Shipper Postal:	30360
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	4275417734283189062
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	TIFTON
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	31794
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	
C1 Head Thick UOM:					Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respntrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hosp Old Form:	0				HMIS Container Code:	4G
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	Original comments: WHEN I GOT THE PACKAGE THE BOX WAS WET. SO I OPENED THE PACK AGE AND SO THAT TWO CONTAINERS OF GASOLINE WAS LEAKING. New Comments:					
Recommend Actions Taken:						

7	10 of 13	NE	0.12 / 612.03	1,013.74 / 1	6265 Atlantic Blvd Norcross GA	HMIRS

Incident County: GWINNETT

HMIR Incident Reports

Report No:	X-2012120289	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2012-11-28	Report Submit Src:	XML
Time of Incident:	2130	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	METHANOL	Transport Phase:	Loading
Commodity Long Nm:	METHANOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1230	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	2.6418	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	303	CR Non US State:	
How Failed Desc:	Burst or Ruptured	CR Fed DOT ID:	265752
Failure Cause Code:	511	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Dropped	CR Country:	US
Ident. Markings:	4G/Y16/S/11USA/HEDWIN	Shipper Name:	Fisher Scientific
Cont1 Pkging Type:		Shipper Street Name:	2775 Horizon Ridge Ct
Cont1 Const Mat:		Shipper City:	Suwanee
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30024
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US
C1 Pkg Amt UOM:		Shipper Waybill:	39064579110081
Cont1 Pkg No:	0	Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0	Origin City:	
Cont1 Pkg Mnfctr:		Origin State:	
Cont1 Pkg Mnfc Dt:	0-00-00 00:00:00	Origin Postal:	
Cont1 Pkg Serial NO:		Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	Origin Country:	
C1 Test Const Mat:		Destination City:	ORLANDO
C1 Pkg Dsign Pres.:	0	Destination State:	FLORIDA
C1 Dsign Press UOM:		Destination Postal:	32806
C1 Pkg Shell Thick:	0	Destination Non US:	
C1 Shell Thick UOM:		Destination Country:	US
C1 Head Thickness:	0	Cont2 Package Type:	
C1 Head Thick UOM:		Cont2 Const Mat:	
C1 Pkg Srvc Pres.:	0	Cont2 Pkg Capacity:	0
C1 Srvc Press UOM:		Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No	Cont2 Pkg Amount:	0
C1 Device Type:		Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:		Cont2 Pkg No:	0
C1 Device Model:		Cont2 Pkg No Failed:	0
NRC No:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:				FALSE	Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:				0	Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:				0	Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:				Yes	Material Involved:	No
Fire Result:				No	Estimated Speed:	0
Explosion Result:				No	Weather Conditions:	
Water Sewer Result:				No	Vehicle Overturn:	No
Gas Dispersion:				No	Vehicle Left Roadway:	No
Environment Damage:				No	Passenger Aircraft:	No
No Release Result:				No	Cargo Baggage:	
Fire EMS Report:				No	Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:				No	Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:				Yes	Ship Phase Transfer:	No
Other Cleanup:				No	Contact Name:	GEORGE FETSKO
Damage > 500:				No	Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:				0	Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:				0	Contact Street:	1000 Fedex Drive
Property Damage:				0	Contact City:	Moon Township
Response Cost:				0	Contact State:	PA
Remediation Cost:				0	Contact Postal:	15108
Damage Old Form:				0	Contact Non US St:	
Total Damages Amt:				0	Contact Country:	US
Hazmat Fatality:				No	Inc. Report Prepared:	Carrier
Haz Fatal Employees:				0	HMIS Serious Incidnt:	No
Haz Fatal Respndrs:				0	HMIS Serious Fatality:	No
Haz Fatal Gen Public:				0	HMIS Serious Injury:	No
Tot Hazmat Fatalities:				0	HMIS Flight Plan:	No
Non Hazmat Fatality:				No	HMIS Serious Evacs:	No
Non Hazmat FataIs:				0	HMIS Major Artery:	No
Hazmat Injury:				No	HMIS Bulk Release:	No
Haz Hospital Empl:				0	HMIS Marine Pollutnt:	No
Haz Hospital Resp:				0	HMIS Radioactive:	No
Haz Hosp Gen Public:				0	HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:				0	HMIS Container Code:	4G
Total Haz Hosp Inj:				0	HMIS Container Desc:	Fiberboard box
Haz Non Hosp Empl:				0	HMIS Bulk Incident:	No
Haz Non Hosp Resp:				0	Undeclared Shipment:	No
Description of Events:				The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.		
Recommend Actions Taken:						

7	11 of 13	NE	0.12 / 612.03	1,013.74 / 1	6265 Atlantic Blvd ATLANTA GA	HMIRS

Incident County: FULTON

HMIR Incident Reports

Report No:	X-2014090185	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2014-08-19	Report Submit Src:	XML
Time of Incident:	2333	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	ETHANOL SOLUTIONS	Transport Phase:	Loading

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Commodity Long Nm:		ETHANOL SOLUTIONS		Incident Occrrnce:		
Trade Name:				Mat Ship Approval?:		
ID No:		UN1170		Mat Ship Approv No:		
Haz Waste Ind:		No		Undecl Hazmat Ship?:		
Haz Waste EPA No:				Packaging Type:		
HMIS Tox Inhalation?:		No		Packing Group:		
TIH Hazard Zone:				Carrier Reporter:		
Qty Released:		1		CR Street Name:		
Unit of Measure:		Liquid - Gallon		CR City:		
What Failed:		109		CR State:		
What Failed Desc:		Closure (e.g., Cap, Top, or Plug)		CR Postal Code:		
How Failed Code:		308		CR Non US State:		
How Failed Desc:		Leaked		CR Fed DOT ID:		
Failure Cause Code:		526		CR Hazmat Reg ID:		
Failure Cause Desc:		Loose Closure, Component, or Device		CR Country:		
Ident. Markings:				Shipper Name:		
Cont1 Pkging Type:		Box		Shipper Street Name:		
Cont1 Const Mat:		Fiberboard		Shipper City:		
Cont1 Head Type:				Shipper State:		
Cont1 Pkg Capacity:		0		Shipper Postal:		
C1 Capacity UOM:				Shipper Non US St:		
Cont1 Pkg Amt:		0		Shipper Country:		
C1 Pkg Amt UOM:				Shipper Waybill:		
Cont1 Pkg No:		0		Ship Hazmat Reg ID:		
C1 Pkg NO Failed:		0		Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfct Dt:		0-00-00 00:00:00		Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:		0-00-00 00:00:00		Origin Country:		
C1 Test Const Mat:		Fiberboard		Destination City:		
C1 Pkg Dsign Pres.:		0		Destination State:		
C1 Dsign Press UOM:				Destination Postal:		
C1 Pkg Shell Thick:		0		Destination Non US:		
C1 Shell Thick UOM:				Destination Country:		
C1 Head Thickness:		0		Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvs Pres.:		0		Cont2 Pkg Capacity:		
C1 Srvs Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:		No		Cont2 Pkg Amount:		
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:		
C1 Device Model:				Cont2 Pkg No Failed:		
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:		
RAM Pkg Cert.:		FALSE		Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:		
RAM Transport Index:				Evacuation Indicator:		
RAM UOM:				Public Evacuated:		
RAM Activity Rpted:		0		Employees Evac:		
RAM UOM Rpted:				Total Evacuated:		
RAM Activity:		0		Total Evacuation Hrs:		
RAM Activity UOM:				Major Artery Closed:		
RAM Mat Safety:				Mjr Artery Hrs Closed:		
Spillage Result:		Yes		Material Involved:		
Fire Result:		No		Estimated Speed:		
Explosion Result:		No		Weather Conditions:		
Water Sewer Result:		No		Vehicle Overturn:		
Gas Dispersion:		No		Vehicle Left Roadway:		
Environment Damage:		No		Passenger Aircraft:		
No Release Result:		No		Cargo Baggage:		
Fire EMS Report:		No		Ship Non Transport:		
Fire EMS EMS Report:				Ship Air First Flight:		
Police Report:		No		Ship Air Subflight:		
Police Report No:				Ship Init Transport:		
In House Cleanup:		Yes		Ship Phase Transfer:		
Other Cleanup:		No		Contact Name:		
				GEORGE FETSKO		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatais:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	No
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						

7	12 of 13	NE	0.12 / 612.03	1,013.74 / 1	6265 Atlanta Blvd Norcross GA	HMIRS

Incident County: GWINNETT

HMIR Incident Reports

Report No:	X-2013090143	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2013-08-15	Report Submit Src:	XML
Time of Incident:	1635	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	GASOLINE INCLUDES GASOLI	Transport Phase:	Unloading
Commodity Long Nm:	GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL, WITH NOT MORE THAN 10% ALCOHOL	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1203	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	No
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	0.25	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:	4G/Y31.6/S/10USA/+AA3579	Shipper Name:	Motiva Enterprises
Cont1 Pkging Type:		Shipper Street Name:	4127 Winters Chapel Road
Cont1 Const Mat:		Shipper City:	DORAVILLE
Cont1 Head Type:		Shipper State:	GA
Cont1 Pkg Capacity:	0	Shipper Postal:	30360
C1 Capacity UOM:		Shipper Non US St:	
Cont1 Pkg Amt:	0	Shipper Country:	US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
C1 Pkg Amt UOM:				Shipper Waybill:	427541762800215	
Cont1 Pkg No:	0			Ship Hazmat Reg ID:		
C1 Pkg NO Failed:	0			Origin City:		
Cont1 Pkg Mnfctr:				Origin State:		
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00			Origin Postal:		
Cont1 Pkg Serial NO:				Origin Non US St:		
C1 Pkg Last Test Dt:	0-00-00 00:00:00			Origin Country:		
C1 Test Const Mat:				Destination City:	ABAC	
C1 Pkg Dsign Pres.:	0			Destination State:	GEORGIA	
C1 Dsign Press UOM:				Destination Postal:	31794	
C1 Pkg Shell Thick:	0			Destination Non US:		
C1 Shell Thick UOM:				Destination Country:	US	
C1 Head Thickness:	0			Cont2 Package Type:		
C1 Head Thick UOM:				Cont2 Const Mat:		
C1 Pkg Srvc Pres.:	0			Cont2 Pkg Capacity:	0	
C1 Srvc Press UOM:				Cont2 Capacity UOM:		
C1 Valve/Device Fail?:	No			Cont2 Pkg Amount:	0	
C1 Device Type:				Cont2 Pkg Amt UOM:		
C1 Device Mnfctr:				Cont2 Pkg No:	0	
C1 Device Model:				Cont2 Pkg No Failed:	0	
NRC No:						
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:	FALSE			Haz NonHosp Old:		
RAM Pkg Cert. NBR:				Tot Haz Non Hosp Inj:		
RAM Nuclide S:				Total Hazmat Injuries:	0	
RAM Transport Index:				Evacuation Indicator:	No	
RAM UOM:				Public Evacuated:	0	
RAM Activity Rpted:	0			Employees Evac:	0	
RAM UOM Rpted:				Total Evacuated:	0	
RAM Activity:	0			Total Evacuation Hrs:	0	
RAM Activity UOM:				Major Artery Closed:	No	
RAM Mat Safety:				Mjr Artery Hrs Closed:	0	
Spillage Result:	Yes			Material Involved:	No	
Fire Result:	No			Estimated Speed:	0	
Explosion Result:	No			Weather Conditions:		
Water Sewer Result:	No			Vehicle Overturn:	No	
Gas Dispersion:	No			Vehicle Left Roadway:	No	
Environment Damage:	No			Passenger Aircraft:	No	
No Release Result:	No			Cargo Baggage:		
Fire EMS Report:	No			Ship Non Transport:	No	
Fire EMS EMS Report:				Ship Air First Flight:	No	
Police Report:	No			Ship Air Subflight:	No	
Police Report No:				Ship Init Transport:	No	
In House Cleanup:	Yes			Ship Phase Transfer:	No	
Other Cleanup:	No			Contact Name:	GEORGE FETSKO	
Damage > 500:	No			Contact Title:	SAFETY PROCESS SPECIALIST I - HAZMAT	
Material Loss:	0			Contact Business:	Fedex Ground Package System, Inc.	
Carrier Damage:	0			Contact Street:	1000 Fedex Drive	
Property Damage:	0			Contact City:	Moon Township	
Response Cost:	0			Contact State:	PA	
Remediation Cost:	0			Contact Postal:	15108	
Damage Old Form:	0			Contact Non US St:		
Total Damages Amt:	0			Contact Country:	US	
Hazmat Fatality:	No			Inc. Report Prepared:	Carrier	
Haz Fatal Employees:	0			HMIS Serious Incidnt:	No	
Haz Fatal Respntrs:	0			HMIS Serious Fatality:	No	
Haz Fatal Gen Public:	0			HMIS Serious Injury:	No	
Tot Hazmat Fatalities:	0			HMIS Flight Plan:	No	
Non Hazmat Fatality:	No			HMIS Serious Evacs:	No	
Non Hazmat FataIs:	0			HMIS Major Artery:	No	
Hazmat Injury:	No			HMIS Bulk Release:	No	
Haz Hospital Empl:	0			HMIS Marine Pollutnt:	No	
Haz Hospital Resp:	0			HMIS Radioactive:	No	
Haz Hosp Gen Public:	0			HMIS Gen Pkg Type:	BOX FIBER	
Haz Hosp Old Form:	0			HMIS Container Code:	4G	
Total Haz Hosp Inj:	0			HMIS Container Desc:	Fiberboard box	
Haz Non Hosp Empl:	0			HMIS Bulk Incident:	No	
Haz Non Hosp Resp:	0			Undeclared Shipment:	No	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Description of Events:		The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.				
Recommend Actions Taken:						
7	13 of 13	NE	0.12 / 612.03	1,013.74 / 1	6265 Atlanttic Blvd NORCROSS GA	HMIRS

Incident County: GWINNETT

HMIR Incident Reports

Report No: X-2015100233
Report Type: A hazardous material incident
Date of Incident: 2015-09-18
Time of Incident: 2335
Haz Class Code:
Hazardous Class: 3
Commodity Short Nm: PAINT INCLUDING PAINT, L
Commodity Long Nm: PAINT INCLUDING PAINT, LACQUER, ENAMEL, STAIN, SHELLAC SOLUTIONS, VARNISH, POLISH, LIQUID FILLER AND LIQUID LACQUER BASE

Fed DOT Agency Nm:
Fed DOT Report No:
Report Submit Src: XML
Inc Multiple Rows: No
Inc Non US State:
Mode Transport: Highway
Transport Phase: In Transit
Incident Occrrnce:

Trade Name:
ID No: UN1263
Haz Waste Ind: No
Haz Waste EPA No:
HMIS Tox Inhalation?: No
TIH Hazard Zone:
Qty Released: 0.125
Unit of Measure: Liquid - Gallon
What Failed: 109
What Failed Desc: Closure (e.g., Cap, Top, or Plug)
How Failed Code: 308
How Failed Desc: Leaked
Failure Cause Code: 526
Failure Cause Desc: Loose Closure, Component, or Device
Ident. Markings:
Cont1 Pkging Type: Box
Cont1 Const Mat: Fiberboard
Cont1 Head Type:
Cont1 Pkg Capacity: 0
C1 Capacity UOM:
Cont1 Pkg Amt: 0
C1 Pkg Amt UOM:
Cont1 Pkg No: 0
C1 Pkg NO Failed: 0
Cont1 Pkg Mnfctr:
Cont1 Pkg Mnfct Dt: 0-00-00 00:00:00
Cont1 Pkg Serial NO:
C1 Pkg Last Test Dt: 0-00-00 00:00:00
C1 Test Const Mat: Fiberboard
C1 Pkg Dsign Pres.: 0
C1 Dsign Press UOM:
C1 Pkg Shell Thick: 0
C1 Shell Thick UOM:
C1 Head Thickness: 0
C1 Head Thick UOM:
C1 Pkg Srvs Pres.: 0
C1 Srvs Press UOM:
C1 Valve/Device Fail?: No
C1 Device Type:
C1 Device Mnfctr:
C1 Device Model:
NRC No:

Mat Ship Approval?: No
Mat Ship Approv No:
Undecl Hazmat Ship?: No
Packaging Type: Non-Bulk
Packing Group: I
Carrier Reporter: Fedex Ground Package System, Inc.
CR Street Name: 1000 Fedex Drive
CR City: Moon Township
CR State: PA
CR Postal Code: 15108
CR Non US State:
CR Fed DOT ID: 265752
CR Hazmat Reg ID: 051910551007S
CR Country: US
Shipper Name: Sherwin Williams
Shipper Street Name: 930 Sherwin Pkwy
Shipper City: Buford
Shipper State: GA
Shipper Postal: 30518
Shipper Non US St:
Shipper Country: US
Shipper Waybill: 30652260776198
Ship Hazmat Reg ID:
Origin City:
Origin State:
Origin Postal:
Origin Non US St:
Origin Country: US
Destination City: LAWRENCEVILLE
Destination State: GEORGIA
Destination Postal: 30043
Destination Non US:
Destination Country: US
Cont2 Package Type: Can
Cont2 Const Mat: Metal (any type)
Cont2 Pkg Capacity: 0
Cont2 Capacity UOM:
Cont2 Pkg Amount: 0
Cont2 Pkg Amt UOM:
Cont2 Pkg No: 0
Cont2 Pkg No Failed: 0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAM Pkg Category:				Haz NonHosp Public:	0	
RAM Pkg Cert.:				FALSE	Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:				0	Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:				0	Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:				Yes	Material Involved:	No
Fire Result:				No	Estimated Speed:	0
Explosion Result:				No	Weather Conditions:	
Water Sewer Result:				No	Vehicle Overturn:	No
Gas Dispersion:				No	Vehicle Left Roadway:	No
Environment Damage:				No	Passenger Aircraft:	No
No Release Result:				No	Cargo Baggage:	
Fire EMS Report:				No	Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:				No	Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:				Yes	Ship Phase Transfer:	No
Other Cleanup:				No	Contact Name:	GEORGE FETSKO
Damage > 500:				No	Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:				0	Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:				0	Contact Street:	1000 Fedex Drive
Property Damage:				0	Contact City:	CORAOPOLIS
Response Cost:				0	Contact State:	PA
Remediation Cost:				0	Contact Postal:	15108
Damage Old Form:				0	Contact Non US St:	
Total Damages Amt:				0	Contact Country:	US
Hazmat Fatality:				No	Inc. Report Prepared:	Carrier
Haz Fatal Employees:				0	HMIS Serious Incidnt:	No
Haz Fatal Respndrs:				0	HMIS Serious Fatality:	No
Haz Fatal Gen Public:				0	HMIS Serious Injury:	No
Tot Hazmat Fatalities:				0	HMIS Flight Plan:	No
Non Hazmat Fatality:				No	HMIS Serious Evacs:	No
Non Hazmat Fatals:				0	HMIS Major Artery:	No
Hazmat Injury:				No	HMIS Bulk Release:	No
Haz Hospital Empl:				0	HMIS Marine Pollutnt:	No
Haz Hospital Resp:				0	HMIS Radioactive:	No
Haz Hosp Gen Public:				0	HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:				0	HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:				0	HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:				0	HMIS Bulk Incident:	No
Haz Non Hosp Resp:				0	Undeclared Shipment:	No
Description of Events:				The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.		
Recommend Actions Taken:						

<u>8</u>	1 of 1	ESE	0.12 / 614.85	997.45 / -15	6265 Atlantic Ave. Norcross GA	SPILLS
Complaint ID:	71472			Concern1 Code:	OS1	
Source Facility ID:				Primary Concern:	Oil spill	
Pers Recd ID:				Concern1 Rules:		
Associate ID:				Concern1 OCGA:		
Login ID:				Concern2 Code:		
Entry Person ID:				Secondary Concern:		
Status:	Closed			Concern2 Rules:		
Active?:				Concern2 OCGA:		
Dt Complaint Cl:	07/04/2013 00:00:00			Source Facility Name:	FedEx Ground	
Date Received:	07/01/2013 17:25:03			Source City:	Norcross	
Caller Represents:	EX Environmental			Source County:		
Owner Assign Date:	07/01/2013 00:00:00			Source State:	Georgia	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Owner Accept Date: 07/01/2013 00:00:00 Investigation Date: FUI Need: Resolved?: Refer 2: Ten Day Follow Up?: Caller Name: Mike Dowger Caller Middle Name: Caller City: Exton Caller County: Caller State: Pennsylvania Caller Postal Code: 19341 Caller Phone: Call Primary Phone: Prim Phone Type: Secondary Phone: Sec Phone Type: Caller Email: Caller Street: 505 Eagle View Blvd. Caller Street2: Caller Other Phone: Call Other Ph Type: Program Code: Program: Source Street: 6265 Atlantic Ave. Complaint Directions: Review Comments: Complaint Location: 6265 Atlantic Ave. Complaint Nature:						
Source Postal Code: Source Email: Source Street2: Src Primary Phone: Src Prim Ph Type: Source Sec Phone: Src Sec Ph Type: Src Other Phone: Src Other Ph Type: Src Contact Name: Oscar Latham Branch Code: PCB-ERT Current Office: Emergency Response Team Branch Active?: Yes Prog Branch Code: Program Branch: Prog Branch Active: Comp County ID: Complaint County: Gwinnett Current Owner: Scarbary, Jacki Approved Date: Date Entered: 07/01/2013 17:30:19 Entered by: Treadwell, Ken Received by: Treadwell, Ken Review by: Campbell, Jerry						

Caller reports a 20 gallon oil spill due to a blown engine on truck. The ran into a retention pond on the property. EPNS of Vermont hired for cleanup.

Page#1328613 EPD D/O J. Scarbary @ 1735.

EPD D/O J. Scarbary briefed @ 1737.

Spills Details

Event ID:		Investigator:	JScarbary
Entry by ID:		Entry Date:	07/02/2013 00:00:00
Investigator ID:		Follow Up Needed?:	
Event Code:		Active?:	
Event:		Code Desc:	Initial Investigation
Event Date: 07/01/2013 00:00:00		Entered by:	Scarbary, Jacki
Comments:			

1740 hrs: Received page from GEMA - called to confirm receipt.

1745 hrs: Spoke with Mike Dowger, EP&S, to verify details of spill: A FedEx tractor trailer truck at the Norcross FedEx facility blew an engine and spilled ~ 20 gallons of oil. The oil ran onto the concrete parking lot and a small amount into a retention pond on the property causing a slight sheen on the water. Oil will be remediated in retention pond with booms and pads. EP&S of Vermont responsible for cleanup.

-Recommend closure of file with no further action.

9	1 of 2	SSE	0.12 / 627.82	1,006.45 / -6	6562 Atlantic Blvd NORCROSS GA	HMIRS

Incident County: GWINNETT

HMIR Historical Reports

Report No:	X-2018010135	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	12/21/2017	Report Submit Src:	XML
Time of Incident:	0005	Inc Multiple Rows:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Class Code:	3				Inc Non US State:	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID				Mode Transport:	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT L				Transport Phase:	UNLOADING
Commodity Long Nm:	PAINT INCLUDING PAINT LACQUER ENAMEL STAIN SHELLAC SOLUTIONS VARNISH POLISH LIQUID FILLER AND LIQUID LACQUER BASE				Incident Occrrnce:	
Trade Name:					Mat Ship Approval?:	No
ID No:	UN1263				Mat Ship Approv No:	
Haz Waste Ind:	No				Undecl Hazmat Ship?:	Yes
Haz Waste EPA No:					Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No				Packing Group:	II
TIH Hazard Zone:					Carrier Reporter:	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1				CR Street Name:	1000 FED EX DR
Unit of Measure:	Liquid - Gallon				CR City:	CORAOPOLIS
What Failed:	109				CR State:	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)				CR Postal Code:	15108-9373
How Failed Code:	308				CR Non US State:	
How Failed Desc:	Leaked				CR Fed DOT ID:	265752
Failure Cause Code:	526				CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure Component or Device				CR Country:	US
Ident. Markings:					Shipper Name:	AIR SOURCE ONE LP
Cont1 Pkging Type:	Box				Shipper Street Name:	2702 N NICHOLS ST STE A
Cont1 Const Mat:	Fiberboard				Shipper City:	FORT WORTH
Cont1 Head Type:					Shipper State:	TX
Cont1 Pkg Capacity:					Shipper Postal:	76106-7243
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:					Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	6776818723769051286
Cont1 Pkg No:					Ship Hazmat Reg ID:	
C1 Pkg NO Failed:					Origin City:	FORT WORTH
Cont1 Pkg Mnfctr:					Origin State:	TEXAS
Cont1 Pkg Mnfc Dt:					Origin Postal:	76106
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:					Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	NORCROSS
C1 Pkg Dsign Pres.:					Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30071
C1 Pkg Shell Thick:					Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:					Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvc Pres.:					Cont2 Pkg Capacity:	
C1 Srvc Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	
C1 Device Model:					Cont2 Pkg No Failed:	
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	0
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	0
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:					Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:					Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fire EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	Yes
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						

<u>9</u>	2 of 2	SSE	0.12 / 627.82	1,006.45 / -6	6562 Atlantic Blvd NORCROSS GA	HMIRS

Incident County: GWINNETT

HMIR Incident Reports

Report No:	X-2018010135	Fed DOT Agency Nm:	
Report Type:	A hazardous material incident	Fed DOT Report No:	
Date of Incident:	2017-12-21	Report Submit Src:	XML
Time of Incident:	0005	Inc Multiple Rows:	No
Haz Class Code:		Inc Non US State:	
Hazardous Class:	3	Mode Transport:	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT, L	Transport Phase:	Unloading
Commodity Long Nm:	PAINT INCLUDING PAINT, LACQUER, ENAMEL, STAIN, SHELLAC SOLUTIONS, VARNISH, POLISH, LIQUID FILLER AND LIQUID LACQUER BASE	Incident Occrrnce:	
Trade Name:		Mat Ship Approval?:	No
ID No:	UN1263	Mat Ship Approv No:	
Haz Waste Ind:	No	Undecl Hazmat Ship?:	Yes
Haz Waste EPA No:		Packaging Type:	Non-Bulk
HMIS Tox Inhalation?:	No	Packing Group:	II
TIH Hazard Zone:		Carrier Reporter:	Fedex Ground Package System, Inc.
Qty Released:	1	CR Street Name:	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	CR City:	Moon Township
What Failed:	109	CR State:	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	CR Postal Code:	15108
How Failed Code:	308	CR Non US State:	
How Failed Desc:	Leaked	CR Fed DOT ID:	265752
Failure Cause Code:	526	CR Hazmat Reg ID:	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	CR Country:	US
Ident. Markings:		Shipper Name:	Air Source One

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Cont1 Pkging Type:	Box				Shipper Street Name:	2702 NORTH NICHOLS STREET
Cont1 Const Mat:	Fiberboard				Shipper City:	Fort Worth
Cont1 Head Type:					Shipper State:	TX
Cont1 Pkg Capacity:	0				Shipper Postal:	76106
C1 Capacity UOM:					Shipper Non US St:	
Cont1 Pkg Amt:	0				Shipper Country:	US
C1 Pkg Amt UOM:					Shipper Waybill:	6776818723769051286
Cont1 Pkg No:	0				Ship Hazmat Reg ID:	
C1 Pkg NO Failed:	0				Origin City:	
Cont1 Pkg Mnfctr:					Origin State:	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00				Origin Postal:	
Cont1 Pkg Serial NO:					Origin Non US St:	
C1 Pkg Last Test Dt:	0-00-00 00:00:00				Origin Country:	US
C1 Test Const Mat:	Fiberboard				Destination City:	NORCROSS
C1 Pkg Dsign Pres.:	0				Destination State:	GEORGIA
C1 Dsign Press UOM:					Destination Postal:	30071
C1 Pkg Shell Thick:	0				Destination Non US:	
C1 Shell Thick UOM:					Destination Country:	US
C1 Head Thickness:	0				Cont2 Package Type:	Can
C1 Head Thick UOM:					Cont2 Const Mat:	Metal (any type)
C1 Pkg Srvs Pres.:	0				Cont2 Pkg Capacity:	0
C1 Srvs Press UOM:					Cont2 Capacity UOM:	
C1 Valve/Device Fail?:	No				Cont2 Pkg Amount:	0
C1 Device Type:					Cont2 Pkg Amt UOM:	
C1 Device Mnfctr:					Cont2 Pkg No:	0
C1 Device Model:					Cont2 Pkg No Failed:	0
NRC No:						
RAM Pkg Category:					Haz NonHosp Public:	0
RAM Pkg Cert.:	FALSE				Haz NonHosp Old:	
RAM Pkg Cert. NBR:					Tot Haz Non Hosp Inj:	
RAM Nuclide S:					Total Hazmat Injuries:	0
RAM Transport Index:					Evacuation Indicator:	No
RAM UOM:					Public Evacuated:	0
RAM Activity Rpted:	0				Employees Evac:	0
RAM UOM Rpted:					Total Evacuated:	0
RAM Activity:	0				Total Evacuation Hrs:	0
RAM Activity UOM:					Major Artery Closed:	No
RAM Mat Safety:					Mjr Artery Hrs Closed:	0
Spillage Result:	Yes				Material Involved:	No
Fire Result:	No				Estimated Speed:	0
Explosion Result:	No				Weather Conditions:	
Water Sewer Result:	No				Vehicle Overturn:	No
Gas Dispersion:	No				Vehicle Left Roadway:	No
Environment Damage:	No				Passenger Aircraft:	No
No Release Result:	No				Cargo Baggage:	
Fire EMS Report:	No				Ship Non Transport:	No
Fire EMS EMS Report:					Ship Air First Flight:	No
Police Report:	No				Ship Air Subflight:	No
Police Report No:					Ship Init Transport:	No
In House Cleanup:	Yes				Ship Phase Transfer:	No
Other Cleanup:	No				Contact Name:	GEORGE FETSKO
Damage > 500:	No				Contact Title:	HAZMAT - SAFETY ADVISOR
Material Loss:	0				Contact Business:	Fedex Ground Package System, Inc.
Carrier Damage:	0				Contact Street:	1000 Fedex Drive
Property Damage:	0				Contact City:	CORAOPOLIS
Response Cost:	0				Contact State:	PA
Remediation Cost:	0				Contact Postal:	15108
Damage Old Form:	0				Contact Non US St:	
Total Damages Amt:	0				Contact Country:	US
Hazmat Fatality:	No				Inc. Report Prepared:	Carrier
Haz Fatal Employees:	0				HMIS Serious Incidnt:	No
Haz Fatal Respndrs:	0				HMIS Serious Fatality:	No
Haz Fatal Gen Public:	0				HMIS Serious Injury:	No
Tot Hazmat Fatalities:	0				HMIS Flight Plan:	No
Non Hazmat Fatality:	No				HMIS Serious Evacs:	No
Non Hazmat Fatals:	0				HMIS Major Artery:	No
Hazmat Injury:	No				HMIS Bulk Release:	No
Haz Hospital Empl:	0				HMIS Marine Pollutnt:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Haz Hospital Resp:	0				HMIS Radioactive:	No
Haz Hosp Gen Public:	0				HMIS Gen Pkg Type:	BOX FIBER
Haz Hosp Old Form:	0				HMIS Container Code:	BOX FBR
Total Haz Hosp Inj:	0				HMIS Container Desc:	Fiberboard box or carton
Haz Non Hosp Empl:	0				HMIS Bulk Incident:	No
Haz Non Hosp Resp:	0				Undeclared Shipment:	Yes
Description of Events:	The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.					
Recommend Actions Taken:						

10	1 of 3	WSW	0.12 / 645.39	1,000.72 / -12	M D HODGES ENTERPRISES INC 3033 ADRIATIC COURT NORCROSS GA 30071	RCRA NON GEN

EPA Handler ID: GAR000009902
Gen Status Universe: No Report
Contact Name: JAMES VAUGHN
Contact Address: 300 GREAT SOUTHWEST PKWY SW , , ATLANTA , GA, 30336 , US
Contact Phone No and Ext: 404-691-4007
Contact Email:
Contact Country: US
County Name: GWINNETT
EPA Region: 04
Land Type: Municipal
Receive Date: 19980122
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19980122
Handler Name: M D HODGES ENTERPRISES INC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: D001

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Waste Code Description:		IGNITABLE WASTE				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:	Current Owner			Street No:		
Type:	Municipal			Street 1:	300 GREAT SOUTHWEST PKWY SW	
Name:	M D HODGES ENTERPRISES INC			Street 2:		
Date Became Current:				City:	ATLANTA	
Date Ended Current:				State:	GA	
Phone:	404-691-4007			Country:		
Source Type:	Notification			Zip Code:	30336	
10	2 of 3	WSW	0.12 / 645.39	1,000.72 / -12	M D HODGES ENTERPRISES INC 3033 ADRIATIC COURT EAST POINT GA	UST
Facility ID:	9067298					
County:	Fulton					
State:						
Note:	Documents related to facilities in Georgia can be searched on the Georgia EPD Online System (GEOS) for Permitting, Compliance and Facility Information: https://geos.epd.georgia.gov/GA/GEOS/Public/Client/GA_GEOS/Public/Pages/PublicApplicationList.aspx					
<u>Underground Storage Tank Data</u>						
Tank Status:	Removed from Ground					
Legacy Tank No:	1					
Tank Constr Descr:	Not Marked/Unknown					
Content Descr:	Other					
Pipe Descr:	Not Marked					
Pipe Type:						
Tank Capacity:	1000					
Tank Overfill Date:						
Tank Overfill Exempt:						
Tank Spill Exempt:						
Tank Spill Instl Dt:						
Tank Overfill Type:						
Tank Install Date:	11/25/1996					
10	3 of 3	WSW	0.12 / 645.39	1,000.72 / -12	M D HODGES ENTERPRISES INC 3033 ADRIATIC COURT EAST POINT GA 30311	LUST
Facility ID:	9067298					
County:	Fulton					
Cleanup Status:	NFA - Clean Closure					
Confirm Release Date:						
No Further Action Date:	7/17/1998					
Project Manager:	EPD Migration					
Site Code Description:	Owner/Operator funded site					
Project Name:	UST - CLOSURE - M D HODGES ENTERPRISES INC					
11	1 of 5	SE	0.14 / 758.04	1,001.12 / -11	Panolam Industries 6300 Atlantic Boulevard Norcross GA 30071-	DELISTED SHWS
HSI ID:	10532			Funding Source:	P	
SL No:				Fund Source Desc:	Private	
ID:				Max Fund LE/SE:		
Parcel No:				LF:		
Listed Status:	DELISTED			Unit:	Reuland	
Listed:	No			CO:	Williams, B.	
List Date:				Geologist:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Delist Date: 5/15/2003 Class: VRP Date: Brownfield Date: Source Date: 2/27/2001 Soil Date: 2/27/2001 Groundwater Date: 2/27/2001 HWTF Projected Src: 0 HWTF Proj Soil: 0 HWTF Projected GW: 0 HWTF Proj Total: 0 HWTF Loc Gov Actual Exp Obl: 0 SW No: Source Status: RRS1 Source Stat Desc: Type 1 Risk Reduction Standards - default residential standards Soil Status: RRS1 Soil Status Desc: Type 1 Risk Reduction Standards - default residential standards Groundwater Status: RRS1 Groundwater Status Desc: Type 1 Risk Reduction Standards - default residential standards Overall Status: RRS1 Overall Status Desc: Type 1 Risk Reduction Standards - default residential standards Latitude: Longitude: Source: Delisted by HSI with Address (By Date); Delisted by HSI with Address - LW Delist HSRA Buddy: Site Addr 2: County: Gwinnett Quad Name: Latitude(D): Latitude(M): Latitude(S): Longitude(D): Longitude(M): Longitude(S):						
11	2 of 5	SE	0.14 / 758.04	1,001.12 / -11	PANOLAM INDUSTRIES FACILITY - PARCEL 5 6300 ATLANTIC BOULEVARD NORCROSS GA 30071-	HSRA NOTIF
Notif ID: 4115 Non HSRA Unit: REULAND Non HSRA CO: WILLIAMS HSRA CO: WILLIAMS HSRA Unit: HSI: No HSI No: 10532 Pre RQSM Cleanup: FALSE Deferred on Site Scoring: FALSE Additional Data Requested: FALSE VRP Deferral: FALSE Comments: NON-HIS LTR MAILED 2/15/17: Supplemental Notification FOR HIS 10532. Remains Delisted Date Received: 10/14/2004 Date Assigned: 10/15/2004 Date Back: Date to Director: 2/16/2017 Date LTR: 2/14/2017 County: GWINNETT						
11	3 of 5	SE	0.14 / 758.04	1,001.12 / -11	PANOLAM INDUSTRIES, INC. 6300 ATLANTIC BLVD NORCROSS GA	HSRA NOTIF
Notif ID: 3004 Non HSRA Unit: S.FRAZIER Non HSRA CO: KLOET HSRA CO: WILLIAMS HSRA Unit: HSI: Yes HSI No: 10532 Pre RQSM Cleanup: FALSE Deferred on Site Scoring: FALSE Additional Data Requested: FALSE VRP Deferral: FALSE Comments: ASSIGNED 5-27-98 HSI#10532 2/14/17 Date Received: 3/12/1997 Date Assigned: 3/24/1997 Date Back: Date to Director: 3/26/1999 Date LTR: County: GWINNETT						
11	4 of 5	SE	0.14 / 758.04	1,001.12 / -11	PANOLAM INDUSTRIES, INC. 6300 ATLANTIC BLVD., NW NORCROSS GA 30071-	HSRA NOTIF

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Notif ID:	6507				Date Received: 11/7/2016	
Non HSRA Unit:	HAYES				Date Assigned: 11/9/2016	
Non HSRA CO:	WILLIAMS				Date Back:	
HSRA CO:	WILLIAMS				Date to Director:	
HSRA Unit:	HAYES				Date LTR: 2/14/2017	
HSI:	Yes				County: GWINNETT	
HSI No:	10532					
Pre RQSM Cleanup:	FALSE					
Deferred on Site Scoring:	FALSE					
Additional Data Requested:	FALSE					
VRP Deferral:	FALSE					
Comments:	NON-HSI LTR MAILED 2/15/17: Supplemental Notification FOR HSI 10532. Remains Delisted					

11	5 of 5	SE	0.14 / 758.04	1,001.12 / -11	Panoram Industries 6300 Atlantic Boulevard Norcross GA 30071-	SHWS
ID:	471				Property Owner: Peter Lawson	
HSI ID:	10532				Fac Owner Title: Vice President/General Manager	
Overall Status:	RRS1				Address: 2410 Paces Ferry, Suite 200	
Delist date:	5/15/2003				City: Atlanta	
List Date:	3/26/1999				State: GA	
Listed:	FALSE				Zip: 30339	
LF:					Phone: (770) 368-2330	
Rank:					Lat Deg: 33	
Scored By:	Wayne Hausser				Lat Min: 56	
Score Date:	1/16/1998				Lat Sec: 20	
GW Score:	2.53				Long Deg: 84	
OS Score:	21.48				Long Min: 14	
USGS Quadrant N:	Norcross				Long Sec: 05	
VRP Date:					Lat Decimal Degree: 33.93888888888889	
BF Date:					Lat Degree Minutes: 0.938888888888889	
HSRA Buddy:	Williams, B.				Lat Degree Seconds: 0.333333333333333	
Geologist:					Lon Decimal Degree: 84.2347222222222	
Groundwater Status:	RRS1				Lon Degree Minutes: 0.234722222222222	
Unit:	Reuland				Lon Decimal Second: 0.0833333333333333	
Source Status:	RRS1				Lon DSH: 14.0833333333333	
Soil Status:	RRS1				Lat DMH: 56.3333333333333	
CO:	Williams, B.				Site City: Norcross	
County:	Gwinnett				Site ZIP: 30071-	
Company:	Panoram Industries					
Site Summary:						
Gndwater Stat Desc:	Type 1 Risk Reduction Standards - default residential standards					
Soil Status Desc:	Type 1 Risk Reduction Standards - default residential standards					
Comments:						
Investigation Cleanup Funding:						

Groundwater Pathway

CAS No:	50000	Section 1D:	Formaldehyde
Chem Name:	Formaldehyde	Section 2D:	2
Section A:	5	Section 3D Desc:	
Section 1B:	0	Section 3D:	4
Section 2B:	3	Section 1E:	1
Section C:	2	Section 2E:	16

On-Site Exposure

CAS No:	50000	Section 2D:	2
Chem Name:	Formaldehyde	Section 3D Desc:	
Section A:	4	Section 3D:	4
Section B:	25	Section 1E:	8
Section C:	4	Section 2E:	0
Section 1D:	Formaldehyde		
Code Guide Doc:	https://epd.georgia.gov/sites/epd.georgia.gov/files/related_files/site_page/RQSMManual.pdf		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Property Owner Information

Prop Owner: MD Hodges Enterprises, Inc.
Address: 300 Great Southwest Parkway
City: Atlanta
State: GA
ZIP: 30336
Phone: (404) 691-4007
Prop Owner 2:
Address 2:
City 2:
State 2:
ZIP 2:
Phone 2:

Prop Owner 3:
Address 3:
City 3:
State 3:
ZIP 3:
Phone 3:
Prop Owner 4:
Address 4:
City 4:
State 4:
Zip 4:
Phone 4:

Property Contact Information

Contact Person: Rick Allagood
Contact Title: Plant Technical Director
Contact Comp: Panolam Industries
Contact Addr: 6300 Atlantic Parkway
Contact City: Norcross
Contact State: GA
Contact ZIP: 30071
Contact Phone: (770) 368-2330

Contact Person 2:
Contact Title 2:
Contact Comp 2:
Contact Addr 2:
Contact City 2:
Contact State 2:
Contact ZIP 2:
Contact Phone 2:

12	1 of 1	SW	0.16 / 839.20	1,002.54 / -10	CREATIVE SYSTEMS GROUP INC 3015 ADRIATIC CT NORCROSS GA 30071	RCRA NON GEN

EPA Handler ID: GAD981217177
Gen Status Universe: No Report
Contact Name: BILL TOLAR
Contact Address: 3015 ADRIATIC CT , , NORCROSS , GA, 30071 , US
Contact Phone No and Ext: 404-448-2022
Contact Email:
Contact Country: US
County Name: GWINNETT
EPA Region: 04
Land Type:
Receive Date: 20080418
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Apr, 2022.

Evaluation Details

Evaluation Start Date: 20080409
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Transporter Activity:		No				
Transfer Facility:		No				
Onsite Burner Exemption:		No				
Furnace Exemption:		No				
Underground Injection Activity:		No				
Commercial TSD:		No				
Used Oil Transporter:		No				
Used Oil Transfer Facility:		No				
Used Oil Processor:		No				
Used Oil Refiner:		No				
Used Oil Burner:		No				
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		2				
Receive Date:		20080418				
Handler Name:		CREATIVE SYSTEMS GROUP INC				
Source Type:		Notification				
Federal Waste Generator Code:		N				
Generator Code Description:		Not a Generator, Verified				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		1				
Receive Date:		19860707				
Handler Name:		CREATIVE SYSTEMS GROUP INC				
Source Type:		Notification				
Federal Waste Generator Code:		2				
Generator Code Description:		Small Quantity Generator				
<u>Waste Code Details</u>						
Hazardous Waste Code:		D001				
Waste Code Description:		IGNITABLE WASTE				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:		Current Owner			Street No:	
Type:		Private			Street 1:	OWNERSTREET
Name:		TOLAR BILL			Street 2:	
Date Became Current:					City:	OWNERCITY
Date Ended Current:					State:	WY
Phone:		404-555-1212			Country:	
Source Type:		Notification			Zip Code:	99999
Owner/Operator Ind:		Current Operator			Street No:	
Type:		Private			Street 1:	OPERSTREET
Name:		OPERNAME			Street 2:	
Date Became Current:					City:	OPERCITY
Date Ended Current:					State:	WY
Phone:		404-555-1212			Country:	
Source Type:		Notification			Zip Code:	99999
<u>Historical Handler Details</u>						
Receive Dt:		19860707				
Generator Code Description:		Small Quantity Generator				
Handler Name:		CREATIVE SYSTEMS GROUP INC				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
13	1 of 1	SW	0.16 / 841.07	1,002.54 / -10	LUCENT TECHNOLOGIES INC 3017 ADRIATIC CT NORCROSS GA 30071	RCRA NON GEN

EPA Handler ID: GAD984311258
Gen Status Universe: No Report
Contact Name: LISA SCHUBERT
Contact Address: 131 MORRISTOWN RD RM B2223 , , BASKING RIDGE , NJ, 07920 , US
Contact Phone No and Ext: 908-630-2701
Contact Email:
Contact Country: US
County Name: GWINNETT
EPA Region: 04
Land Type: Private
Receive Date: 19961119
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19961119
Handler Name: LUCENT TECHNOLOGIES INC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazardous Waste Code:		D009				
Waste Code Description:		MERCURY				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:	Current Owner			Street No:		
Type:	Private			Street 1:	600 MOUNTAIN AVE	
Name:	LUCENT TECHNOLOGIES INC			Street 2:		
Date Became Current:				City:	MURRAY HILL	
Date Ended Current:				State:	NJ	
Phone:	908-582-3000			Country:		
Source Type:	Notification			Zip Code:	07374-0636	
14	1 of 1	SSE	0.16 / 847.53	1,006.54 / -6	NORDSON CORP 6755 JIMMY CARTER BLVD NORCROSS GA 30071	RCRA NON GEN
EPA Handler ID:		GAD981219736				
Gen Status Universe:		No Report				
Contact Name:		BETH BARBER				
Contact Address:		6755 , JIMMY CARTER BLVD , , NORCROSS , GA, 30071 , US				
Contact Phone No and Ext:		404-985-4074				
Contact Email:						
Contact Country:		US				
County Name:		GWINNETT				
EPA Region:		04				
Land Type:						
Receive Date:		20090528				
Location Latitude:						
Location Longitude:						
<u>Violation/Evaluation Summary</u>						
Note:		VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Apr, 2022.				
<u>Violation Details</u>						
Found Violation:		Yes				
Citation:						
Violation Short Description:		Generators - General				
Violation Type:		262.A				
Violation Determined Date:		19900629				
Scheduled Compliance Date:						
Return to Compliance:		Observed				
Actual Return to Compl:		19900810				
Violation Responsible Agency:		State				
<u>Enforcement Details</u>						
Enforcement Type:		120				
Enforcement Type Description:		WRITTEN INFORMAL				
Enforcement Action Date:		19900709				
Enf Disposition Status:						
Disposition Status Date:						
Enforcement Lead Agency:		State				
Proposed Penalty Amount:						
Final Amount:						
Paid Amount:						
<u>Evaluation Details</u>						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Evaluation Start Date:		19900501				
Evaluation Type Description:		NON-FINANCIAL RECORD REVIEW				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		19900629				
Evaluation Type Description:		COMPLIANCE EVALUATION INSPECTION ON-SITE				
Violation Short Description:		Generators - General				
Return to Compliance Date:		19900810				
Evaluation Agency:		State				
<u>Handler Summary</u>						
Importer Activity:		No				
Mixed Waste Generator:		No				
Transporter Activity:		No				
Transfer Facility:		No				
Onsite Burner Exemption:		No				
Furnace Exemption:		No				
Underground Injection Activity:		No				
Commercial TSD:		No				
Used Oil Transporter:		No				
Used Oil Transfer Facility:		No				
Used Oil Processor:		No				
Used Oil Refiner:		No				
Used Oil Burner:		No				
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		2				
Receive Date:		20090528				
Handler Name:		NORDSON CORP				
Source Type:		Notification				
Federal Waste Generator Code:		N				
Generator Code Description:		Not a Generator, Verified				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		1				
Receive Date:		19860909				
Handler Name:		NORDSON CORP				
Source Type:		Notification				
Federal Waste Generator Code:		2				
Generator Code Description:		Small Quantity Generator				
<u>Waste Code Details</u>						
Hazardous Waste Code:		D001				
Waste Code Description:		IGNITABLE WASTE				
Hazardous Waste Code:		F001				
Waste Code Description:		THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.				
Hazardous Waste Code:		F003				
Waste Code Description:		THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.						
Hazardous Waste Code:		F005				
Waste Code Description:		THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:		Current Owner		Street No:		
Type:		Private		Street 1:		OWNERSTREET
Name:		LILO FINK MBH		Street 2:		
Date Became Current:				City:		OWNERCITY
Date Ended Current:				State:		WY
Phone:		404-555-1212		Country:		
Source Type:		Notification		Zip Code:		99999
Owner/Operator Ind:		Current Operator		Street No:		
Type:		Private		Street 1:		OPERSTREET
Name:		OPERNAME		Street 2:		
Date Became Current:				City:		OPERCITY
Date Ended Current:				State:		WY
Phone:		404-555-1212		Country:		
Source Type:		Notification		Zip Code:		99999
<u>Historical Handler Details</u>						
Receive Dt:		19860909				
Generator Code Description:		Small Quantity Generator				
Handler Name:		NORDSON CORP				
15	1 of 1	SW	0.16 / 848.95	1,001.53 / -11	THE HANSON GROUP LLC 3044 ADRIATIC CT PEACHTREE CORNERS GA 30071	RCRA LQG
EPA Handler ID:		GAR000091785				
Gen Status Universe:		Large Quantity Generator				
Contact Name:		JACQUES GOUWS				
Contact Address:		3044 , ADRIATIC CT , , PEACHTREE CORNERS , GA, 30071 , US				
Contact Phone No and Ext:		770-495-9554				
Contact Email:		JGOUWS@HANSONCO.NET				
Contact Country:		US				
County Name:		GWINNETT				
EPA Region:		04				
Land Type:		Private				
Receive Date:		20210125				
Location Latitude:		33.939768				
Location Longitude:		-84.239717				
<u>Violation/Evaluation Summary</u>						
Note:		NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).				
<u>Handler Summary</u>						
Importer Activity:		No				

450

[erisinfo.com](#) | Environmental Risk Information Services

Order No: 22051600831

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Mixed Waste Generator:		No				
Transporter Activity:		No				
Transfer Facility:		No				
Onsite Burner Exemption:		No				
Furnace Exemption:		No				
Underground Injection Activity:		No				
Commercial TSD:		No				
Used Oil Transporter:		No				
Used Oil Transfer Facility:		No				
Used Oil Processor:		No				
Used Oil Refiner:		No				
Used Oil Burner:		No				
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		1				
Receive Date:		20210125				
Handler Name:		THE HANSON GROUP LLC				
Federal Waste Generator Code:		1				
Generator Code Description:		Large Quantity Generator				
Source Type:		Notification				
<u>Waste Code Details</u>						
Hazardous Waste Code:		D001				
Waste Code Description:		IGNITABLE WASTE				
Hazardous Waste Code:		D009				
Waste Code Description:		MERCURY				
Hazardous Waste Code:		F003				
Waste Code Description:		THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.				
Hazardous Waste Code:		F005				
Waste Code Description:		THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:		Current Operator		Street No:	3044	
Type:		Private		Street 1:	ADRIATIC CT	
Name:		WALLACE LEE HANSON		Street 2:		
Date Became Current:		20140101		City:	PEACHTREE CORNERS	
Date Ended Current:				State:	GA	
Phone:		770-495-9554		Country:	US	
Source Type:		Notification		Zip Code:	30071	
Owner/Operator Ind:		Current Owner		Street No:	3044	
Type:		Private		Street 1:	ADRIATIC CT	
Name:		WALLACE LEE HANSON		Street 2:		
Date Became Current:		20140101		City:	PEACHTREE CORNERS	
Date Ended Current:				State:	GA	
Phone:		770-495-9554		Country:	US	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Source Type:	Notification			Zip Code:	30071	

16	1 of 1	SW	0.17 / 893.72	1,003.88 / -8	ARCHITECTURAL SIENINE INC 3040 ADRIATIC COURT NORCROSS GA 30071	RCRA NON GEN

EPA Handler ID: GAR000007526
Gen Status Universe: No Report
Contact Name: BILL TOLAR
Contact Address: 3040 ADRIATIC COURT , , NORCROSS , GA, 30071 , US
Contact Phone No and Ext: 770-448-2026
Contact Email:
Contact Country: US
County Name: GWINNETT
EPA Region: 04
Land Type: Private
Receive Date: 20130512
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Apr, 2022.

Violation Details

Found Violation: Yes
Citation: SR - 262.34(c)(1)(ii)
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 20040121
Scheduled Compliance Date: 20040401
Return to Compliance: Documented
Actual Return to Compl: 20040309
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20040301
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 20040121
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 20040309
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Transfer Facility:		No				
Onsite Burner Exemption:		No				
Furnace Exemption:		No				
Underground Injection Activity:		No				
Commercial TSD:		No				
Used Oil Transporter:		No				
Used Oil Transfer Facility:		No				
Used Oil Processor:		No				
Used Oil Refiner:		No				
Used Oil Burner:		No				
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19950517
Handler Name: ARCHITECTURAL SIENINE INC
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20130512
Handler Name: ARCHITECTURAL SIENINE INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Private	Street 1:	3040 ADRIATIC COURT
Name:	TOLAR BILL	Street 2:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Date Became Current:				City:	NORCROSS	
Date Ended Current:				State:	GA	
Phone:	770-448-2026			Country:		
Source Type:	Notification			Zip Code:	30071	
Owner/Operator Ind:				Street No:		
Type:	Current Owner			Street 1:	3040 ADRIATIC COURT	
Name:	Private			Street 2:		
Date Became Current:	TOLAR BILL			City:	NORCROSS	
Date Ended Current:				State:	GA	
Phone:	770-448-2026			Country:		
Source Type:	Implementer			Zip Code:	30071	
<u>Historical Handler Details</u>						
Receive Dt:		19950517				
Generator Code Description:		Small Quantity Generator				
Handler Name:		ARCHITECTURAL SIENINE INC				

17	1 of 3	NNW	0.23 / 1,204.74	988.54 / -24	WYANDOTTE PAINT PRODUCTS CO 6369 OLD PEACHTREE RD NORCROSS GA 30071	CERCLIS
Site ID:	0401382			RNPL Status Code:	N	
Site EPA ID:	GAD003480183			NPL Status:	Not on the NPL	
Site Street Address 2:				RFED Facility Code:	N	
Site County Name:	GWINNETT			RFED Facility Desc:	Not a Federal Facility	
Site FIPS Code:	13135			USGS Hydro Unit No.:	03130001	
Region Code:	04			Site Cong. Dist. Code:	09	
Site SMSA No.:	0520			ROT Desc:	Other	
Site Prim. Latitude:	33D55M51S			FR NPL Update No.:		
Site Prim. Longitude:	084D13M54S			RFRA Code:		
Lat Long Source:						
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information					

CERCLIS Assess History

OU ID:	00	RALT Short Name:	State (Fund)
Act Code ID:	001	Act Start Date:	
RAT Code:	PA	Act Complete Date:	12/30/1985 00:00:00
RAT Short Name:	PA	AGT Order No.:	130
RAT Name:	PRELIMINARY ASSESSMENT	SH OU:	
RAT Hist. Only Flag:		SH Code:	
RAT NSI Indicator:	B	SH Seq:	
RAT Level:	1	SH Start Date:	
RAT DEF OU:	00	SH Complete Date:	
RFBS Code:	P	SH Lead:	
SPA Code:	13		
RAT Def:	Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.		
Site Desc:			
Site Alias:			

CERCLIS Assess History

OU ID:		00	RALT Short Name:		EPA Fund
Act Code ID:		001	Act Start Date:		
RAT Code:		SI	Act Complete Date:		12/31/1988 00:00:00
RAT Short Name:		SI	AGT Order No.:		160
RAT Name:		SITE INSPECTION	SH OU:		
RAT Hist. Only Flag:			SH Code:		
RAT NSI Indicator:		B	SH Seq:		
RAT Level:		1	SH Start Date:		
RAT DEF OU:		00	SH Complete Date:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RFBS Code:	P				SH Lead:	
SPA Code:	13					
RAT Def:		The process of collecting site data and samples to characterize the severity of the hazard for the hazard ranking score and/or enforcement support.				
Site Desc:						
Site Alias:						
<u>CERCLIS Assess History</u>						
OU ID:	00				RALT Short Name:	EPA In-House
Act Code ID:	001				Act Start Date:	
RAT Code:	VS				Act Complete Date:	12/31/1988 00:00:00
RAT Short Name:	ARCH SITE				AGT Order No.:	1500
RAT Name:	ARCHIVE SITE				SH OU:	
RAT Hist. Only Flag:					SH Code:	
RAT NSI Indicator:	B				SH Seq:	
RAT Level:	1				SH Start Date:	
RAT DEF OU:	00				SH Complete Date:	
RFBS Code:					SH Lead:	
SPA Code:	13					
RAT Def:		The decision is made that no further activity is planned at the site.				
Site Desc:						
Site Alias:						
<u>CERCLIS Assess History</u>						
OU ID:	00				RALT Short Name:	EPA Fund
Act Code ID:	001				Act Start Date:	
RAT Code:	DS				Act Complete Date:	8/1/1980 00:00:00
RAT Short Name:	DISCVRY				AGT Order No.:	10
RAT Name:	DISCOVERY				SH OU:	
RAT Hist. Only Flag:					SH Code:	
RAT NSI Indicator:	B				SH Seq:	
RAT Level:	1				SH Start Date:	
RAT DEF OU:	00				SH Complete Date:	
RFBS Code:					SH Lead:	
SPA Code:	13					
RAT Def:		The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.				
Site Desc:						
Site Alias:						
<u>CERCLIS Assess History</u>						
OU ID:	00				RALT Short Name:	
Act Code ID:					Act Start Date:	
RAT Code:					Act Complete Date:	
RAT Short Name:					AGT Order No.:	0
RAT Name:					SH OU:	
RAT Hist. Only Flag:					SH Code:	
RAT NSI Indicator:					SH Seq:	
RAT Level:					SH Start Date:	
RAT DEF OU:					SH Complete Date:	
RFBS Code:					SH Lead:	
SPA Code:						
RAT Def:						
Site Desc:		No description available				
Site Alias:		WYANDOTTE PAINT PRODUCTS CO.,GWINNETT,GA,;				
17	2 of 3	NNW	0.23 / 1,204.74	988.54 / -24	WYANDOTTE PAINT PRODUCTS CO 6369 OLD PEACHTREE RD NORCROSS GA 30071	CERCLIS NFRAP

17

2 of 3

NNW

0.23 /
1,204.74988.54 /
-24WYANDOTTE PAINT PRODUCTS
CO
6369 OLD PEACHTREE RD
NORCROSS GA 30071CERCLIS
NFRAP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Site ID:	401382			Site FIPS Code:	13135	
Site EPA ID:	GAD003480183			Region Code:	4	
Site Parent ID:				Site Cong. Dist. Code:	9	
Site County Name:	GWINNETT			Federal Facility:		
Parent Site Name:						

CERCLIS-NFRAP Assess History

OU ID:	0	Act Start Date:	
Act Code ID:	1	Act Complete Date:	8/1/1980
RAT Code:	DS	AGT Order No.:	10
RAT Short Name:	DISCVRY	SH OU:	
RAT Name:	DISCOVERY	SH Code:	
RAT Hist. Only Flag:		SH Seq:	
RAT NSI Indicator:	B	SH Start Date:	
RAT Level:	1	SH Complete Date:	
RAT DEF OU:	00	SH Lead:	
RFBS Code:		SH Qual:	
SPA Code:	13	RAQ Act. Qual Short:	
RALT Short Name:	EPA Fund	RNPL Status Code:	N
RAT Def:	The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

CERCLIS-NFRAP Assess History

OU ID:	0	Act Start Date:	
Act Code ID:	1	Act Complete Date:	12/31/1988
RAT Code:	VS	AGT Order No.:	1500
RAT Short Name:	ARCH SITE	SH OU:	
RAT Name:	ARCHIVE SITE	SH Code:	
RAT Hist. Only Flag:		SH Seq:	
RAT NSI Indicator:	B	SH Start Date:	
RAT Level:	1	SH Complete Date:	
RAT DEF OU:	00	SH Lead:	
RFBS Code:		SH Qual:	
SPA Code:	13	RAQ Act. Qual Short:	
RALT Short Name:	EPA In-House	RNPL Status Code:	N
RAT Def:	The decision is made that no further activity is planned at the site.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

CERCLIS-NFRAP Assess History

OU ID:	0	Act Start Date:	
Act Code ID:	1	Act Complete Date:	12/30/1985
RAT Code:	PA	AGT Order No.:	130
RAT Short Name:	PA	SH OU:	
RAT Name:	PRELIMINARY ASSESSMENT	SH Code:	
RAT Hist. Only Flag:		SH Seq:	
RAT NSI Indicator:	B	SH Start Date:	
RAT Level:	1	SH Complete Date:	
RAT DEF OU:	00	SH Lead:	
RFBS Code:	P	SH Qual:	
SPA Code:	13	RAQ Act. Qual Short:	NFRAP
RALT Short Name:	State (Fund)	RNPL Status Code:	N
RAT Def:	Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

CERCLIS-NFRAP Assess History

OU ID:	0	Act Start Date:	
Act Code ID:	1	Act Complete Date:	12/31/1988
RAT Code:	SI	AGT Order No.:	160

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
RAT Short Name: SI RAT Name: SITE INSPECTION RAT Hist. Only Flag: RAT NSI Indicator: B RAT Level: 1 RAT DEF OU: 00 RFBS Code: P SPA Code: 13 RALT Short Name: EPA Fund RAT Def: The process of collecting site data and samples to characterize the severity of the hazard for the hazard ranking score and/or enforcement support. RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information						
SH OU: SH Code: SH Seq: SH Start Date: SH Complete Date: SH Lead: SH Qual: RAQ Act. Qual Short: NFRAP RNPL Status Code: N						

17	3 of 3	NNW	0.23 / 1,204.74	988.54 / -24	FERRO CORPORATION - NORCROSS SITE 6369 PEACHTREE ST NORCROSS GA 30071	RCRA VSQG

EPA Handler ID: GAD003480183
Gen Status Universe: VSG
Contact Name: AARON WILLIAMS
Contact Address: 6369 , PEACHTREE ST , , NORCROSS , GA, 30071 , US
Contact Phone No and Ext: 470-273-3374
Contact Email: AARON.WILLIAMS@FERRO.COM
Contact Country: US
County Name: GWINNETT
EPA Region: 04
Land Type: Private
Receive Date: 20210118
Location Latitude: 33.935937
Location Longitude: -84.218532

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Apr, 2022.

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19900626
Scheduled Compliance Date:
Return to Compliance: Observed
Actual Return to Compl: 19900723
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 19900706
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Citation:						
Violation Short Description:		Generators - General				
Violation Type:		262.A				
Violation Determined Date:		19880210				
Scheduled Compliance Date:		19880509				
Return to Compliance:		Observed				
Actual Return to Compl:		19881121				
Violation Responsible Agency:		State				
<u>Enforcement Details</u>						
Enforcement Type:		120				
Enforcement Type Description:		WRITTEN INFORMAL				
Enforcement Action Date:		19880411				
Enf Disposition Status:						
Disposition Status Date:						
Enforcement Lead Agency:		State				
Proposed Penalty Amount:						
Final Amount:						
Paid Amount:						
<u>Violation Details</u>						
Found Violation:		Yes				
Citation:						
Violation Short Description:		Generators - General				
Violation Type:		262.A				
Violation Determined Date:		20131108				
Scheduled Compliance Date:						
Return to Compliance:		Documented				
Actual Return to Compl:		20141125				
Violation Responsible Agency:		EPA				
<u>Violation Details</u>						
Found Violation:		Yes				
Citation:						
Violation Short Description:		Universal Waste - Small Quantity Handlers				
Violation Type:		273.B				
Violation Determined Date:		20120619				
Scheduled Compliance Date:		20120813				
Return to Compliance:		Documented				
Actual Return to Compl:		20120905				
Violation Responsible Agency:		State				
<u>Enforcement Details</u>						
Enforcement Type:		120				
Enforcement Type Description:		WRITTEN INFORMAL				
Enforcement Action Date:		20120712				
Enf Disposition Status:						
Disposition Status Date:						
Enforcement Lead Agency:		State				
Proposed Penalty Amount:						
Final Amount:						
Paid Amount:						
<u>Violation Details</u>						
Found Violation:		Yes				
Citation:						
Violation Short Description:		TSD IS-Preparedness and Prevention				
Violation Type:		265.C				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Violation Determined Date:		20131108				
Scheduled Compliance Date:						
Return to Compliance:		Documented				
Actual Return to Compl:		20141125				
Violation Responsible Agency:		EPA				
<u>Violation Details</u>						
Found Violation:		Yes				
Citation:		SR - 262.34(c)(1)(ii)				
Violation Short Description:		Generators - General				
Violation Type:		262.A				
Violation Determined Date:		20011113				
Scheduled Compliance Date:		20020103				
Return to Compliance:		Documented				
Actual Return to Compl:		20011219				
Violation Responsible Agency:		State				
<u>Enforcement Details</u>						
Enforcement Type:		120				
Enforcement Type Description:		WRITTEN INFORMAL				
Enforcement Action Date:		20011207				
Enf Disposition Status:						
Disposition Status Date:						
Enforcement Lead Agency:		State				
Proposed Penalty Amount:						
Final Amount:						
Paid Amount:						
<u>Violation Details</u>						
Found Violation:		Yes				
Citation:						
Violation Short Description:		Generators - Pre-transport				
Violation Type:		262.C				
Violation Determined Date:		20120619				
Scheduled Compliance Date:		20120813				
Return to Compliance:		Documented				
Actual Return to Compl:		20120905				
Violation Responsible Agency:		State				
<u>Enforcement Details</u>						
Enforcement Type:		120				
Enforcement Type Description:		WRITTEN INFORMAL				
Enforcement Action Date:		20120712				
Enf Disposition Status:						
Disposition Status Date:						
Enforcement Lead Agency:		State				
Proposed Penalty Amount:						
Final Amount:						
Paid Amount:						
<u>Violation Details</u>						
Found Violation:		Yes				
Citation:						
Violation Short Description:		LDR - General				
Violation Type:		268.A				
Violation Determined Date:		19880210				
Scheduled Compliance Date:		19880509				
Return to Compliance:		Observed				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Actual Return to Compl:		19881121				
Violation Responsible Agency:		State				
<u>Enforcement Details</u>						
Enforcement Type:		120				
Enforcement Type Description:		WRITTEN INFORMAL				
Enforcement Action Date:		19880411				
Enf Disposition Status:						
Disposition Status Date:						
Enforcement Lead Agency:		State				
Proposed Penalty Amount:						
Final Amount:						
Paid Amount:						
<u>Violation Details</u>						
Found Violation:		Yes				
Citation:						
Violation Short Description:		TSD IS-Container Use and Management				
Violation Type:		265.I				
Violation Determined Date:		20120619				
Scheduled Compliance Date:		20120813				
Return to Compliance:		Documented				
Actual Return to Compl:		20120905				
Violation Responsible Agency:		State				
<u>Enforcement Details</u>						
Enforcement Type:		120				
Enforcement Type Description:		WRITTEN INFORMAL				
Enforcement Action Date:		20120712				
Enf Disposition Status:						
Disposition Status Date:						
Enforcement Lead Agency:		State				
Proposed Penalty Amount:						
Final Amount:						
Paid Amount:						
<u>Violation Details</u>						
Found Violation:		Yes				
Citation:						
Violation Short Description:		LDR - General				
Violation Type:		268.A				
Violation Determined Date:		19900626				
Scheduled Compliance Date:						
Return to Compliance:		Observed				
Actual Return to Compl:		19900723				
Violation Responsible Agency:		State				
<u>Enforcement Details</u>						
Enforcement Type:		120				
Enforcement Type Description:		WRITTEN INFORMAL				
Enforcement Action Date:		19900706				
Enf Disposition Status:						
Disposition Status Date:						
Enforcement Lead Agency:		State				
Proposed Penalty Amount:						
Final Amount:						
Paid Amount:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>Evaluation Details</u>						
Evaluation Start Date:		19880210				
Evaluation Type Description:		FOCUSED COMPLIANCE INSPECTION				
Violation Short Description:		LDR - General				
Return to Compliance Date:		19881121				
Evaluation Agency:		State				
Evaluation Start Date:		20040112				
Evaluation Type Description:		COMPLIANCE EVALUATION INSPECTION ON-SITE				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		19900821				
Evaluation Type Description:		NON-FINANCIAL RECORD REVIEW				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		20000127				
Evaluation Type Description:		COMPLIANCE EVALUATION INSPECTION ON-SITE				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		20131108				
Evaluation Type Description:		COMPLIANCE EVALUATION INSPECTION ON-SITE				
Violation Short Description:		Generators - General				
Return to Compliance Date:		20141125				
Evaluation Agency:		EPA				
Evaluation Start Date:		20000127				
Evaluation Type Description:		FOCUSED COMPLIANCE INSPECTION				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		19860703				
Evaluation Type Description:		NON-FINANCIAL RECORD REVIEW				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		20120619				
Evaluation Type Description:		COMPLIANCE EVALUATION INSPECTION ON-SITE				
Violation Short Description:		TSD IS-Container Use and Management				
Return to Compliance Date:		20120905				
Evaluation Agency:		State				
Evaluation Start Date:		19920628				
Evaluation Type Description:		NON-FINANCIAL RECORD REVIEW				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		19980728				
Evaluation Type Description:		COMPLIANCE EVALUATION INSPECTION ON-SITE				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		20011113				
Evaluation Type Description:		COMPLIANCE EVALUATION INSPECTION ON-SITE				
Violation Short Description:		Generators - General				
Return to Compliance Date:		20011219				
Evaluation Agency:		State				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Evaluation Start Date: Evaluation Type Description: Violation Short Description: Return to Compliance Date: Evaluation Agency:		20010221 FOCUSED COMPLIANCE INSPECTION State				
Evaluation Start Date: Evaluation Type Description: Violation Short Description: Return to Compliance Date: Evaluation Agency:		20120619 COMPLIANCE EVALUATION INSPECTION ON-SITE Universal Waste - Small Quantity Handlers 20120905 State				
Evaluation Start Date: Evaluation Type Description: Violation Short Description: Return to Compliance Date: Evaluation Agency:		19880907 NON-FINANCIAL RECORD REVIEW State				
Evaluation Start Date: Evaluation Type Description: Violation Short Description: Return to Compliance Date: Evaluation Agency:		19980526 NON-FINANCIAL RECORD REVIEW State				
Evaluation Start Date: Evaluation Type Description: Violation Short Description: Return to Compliance Date: Evaluation Agency:		19920830 NON-FINANCIAL RECORD REVIEW State				
Evaluation Start Date: Evaluation Type Description: Violation Short Description: Return to Compliance Date: Evaluation Agency:		20150526 FOCUSED COMPLIANCE INSPECTION State				
Evaluation Start Date: Evaluation Type Description: Violation Short Description: Return to Compliance Date: Evaluation Agency:		20131108 COMPLIANCE EVALUATION INSPECTION ON-SITE TSD IS-Preparedness and Prevention 20141125 EPA				
Evaluation Start Date: Evaluation Type Description: Violation Short Description: Return to Compliance Date: Evaluation Agency:		19980722 FOCUSED COMPLIANCE INSPECTION State				
Evaluation Start Date: Evaluation Type Description: Violation Short Description: Return to Compliance Date: Evaluation Agency:		20120619 COMPLIANCE EVALUATION INSPECTION ON-SITE Generators - Pre-transport 20120905 State				
Evaluation Start Date: Evaluation Type Description: Violation Short Description: Return to Compliance Date: Evaluation Agency:		20150526 COMPLIANCE EVALUATION INSPECTION ON-SITE State				
Evaluation Start Date: Evaluation Type Description: Violation Short Description: Return to Compliance Date: Evaluation Agency:		19950828 COMPLIANCE EVALUATION INSPECTION ON-SITE State				
Evaluation Start Date: Evaluation Type Description: Violation Short Description:		19960524 FOCUSED COMPLIANCE INSPECTION				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Return to Compliance Date:		State				
Evaluation Agency:						
Evaluation Start Date:		19900626				
Evaluation Type Description:		FOCUSED COMPLIANCE INSPECTION				
Violation Short Description:		LDR - General				
Return to Compliance Date:		19900723				
Evaluation Agency:		State				
Evaluation Start Date:		19970325				
Evaluation Type Description:		FOCUSED COMPLIANCE INSPECTION				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		19960417				
Evaluation Type Description:		NON-FINANCIAL RECORD REVIEW				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		20011113				
Evaluation Type Description:		FOCUSED COMPLIANCE INSPECTION				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		19900626				
Evaluation Type Description:		FOCUSED COMPLIANCE INSPECTION				
Violation Short Description:		Generators - General				
Return to Compliance Date:		19900723				
Evaluation Agency:		State				
Evaluation Start Date:		20010221				
Evaluation Type Description:		COMPLIANCE EVALUATION INSPECTION ON-SITE				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		19990625				
Evaluation Type Description:		FOCUSED COMPLIANCE INSPECTION				
Violation Short Description:						
Return to Compliance Date:						
Evaluation Agency:		State				
Evaluation Start Date:		19880210				
Evaluation Type Description:		FOCUSED COMPLIANCE INSPECTION				
Violation Short Description:		Generators - General				
Return to Compliance Date:		19881121				
Evaluation Agency:		State				
 <u>Handler Summary</u>						
Importer Activity:		No				
Mixed Waste Generator:		No				
Transporter Activity:		No				
Transfer Facility:		No				
Onsite Burner Exemption:		No				
Furnace Exemption:		No				
Underground Injection Activity:		No				
Commercial TSD:		No				
Used Oil Transporter:		No				
Used Oil Transfer Facility:		No				
Used Oil Processor:		No				
Used Oil Refiner:		No				
Used Oil Burner:		No				
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20020705
Handler Name: AKZO NOBEL COATINGS INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20201209
Handler Name: FERRO CORPORATION - NORCROSS SITE
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.	
					<u>Hazardous Waste Handler Details</u>	
					Sequence No: 3	
					Receive Date: 19960215	
					Handler Name: AKZO NOBEL COATINGS INC	
					Federal Waste Generator Code: 1	
					Generator Code Description: Large Quantity Generator	
					Source Type: Annual/Biennial Report	
					<u>Hazardous Waste Handler Details</u>	
					Sequence No: 1	
					Receive Date: 20040127	
					Handler Name: AKZO NOBEL COATINGS INC	
					Federal Waste Generator Code: N	
					Generator Code Description: Not a Generator, Verified	
					Source Type: Implementer	
					<u>Hazardous Waste Handler Details</u>	
					Sequence No: 2	
					Receive Date: 20010209	
					Handler Name: AKZO NOBEL COATINGS INC	
					Federal Waste Generator Code: 1	
					Generator Code Description: Large Quantity Generator	
					Source Type: Notification	
					<u>Hazardous Waste Handler Details</u>	
					Sequence No: 4	
					Receive Date: 20050505	
					Handler Name: AKZO NOBEL COATINGS	
					Federal Waste Generator Code: N	
					Generator Code Description: Not a Generator, Verified	
					Source Type: Notification	
					<u>Waste Code Details</u>	
					Hazardous Waste Code: D035	
					Waste Code Description: METHYL ETHYL KETONE	
					Hazardous Waste Code: F003	
					Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.	
					Hazardous Waste Code: F005	
					Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.	
					Hazardous Waste Code: D001	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Waste Code Description:		IGNITABLE WASTE				
<u>Hazardous Waste Handler Details</u>						
Sequence No:	4					
Receive Date:	19981210					
Handler Name:	AKZP NOBEL COATINGS, INC.					
Federal Waste Generator Code:	1					
Generator Code Description:	Large Quantity Generator					
Source Type:	Annual/Biennial Report					
<u>Hazardous Waste Handler Details</u>						
Sequence No:	5					
Receive Date:	20100621					
Handler Name:	NUBIOLA					
Federal Waste Generator Code:	2					
Generator Code Description:	Small Quantity Generator					
Source Type:	Notification					
<u>Waste Code Details</u>						
Hazardous Waste Code:	D006					
Waste Code Description:	CADMIUM					
Hazardous Waste Code:	D007					
Waste Code Description:	CHROMIUM					
Hazardous Waste Code:	D008					
Waste Code Description:	LEAD					
Hazardous Waste Code:	D001					
Waste Code Description:	IGNITABLE WASTE					
<u>Hazardous Waste Handler Details</u>						
Sequence No:	5					
Receive Date:	20010328					
Handler Name:	AKZO NOBEL COATING, INC					
Federal Waste Generator Code:	1					
Generator Code Description:	Large Quantity Generator					
Source Type:	Annual/Biennial Report					
<u>Hazardous Waste Handler Details</u>						
Sequence No:	7					
Receive Date:	20210118					
Handler Name:	FERRO CORPORATION - NORCROSS SITE					
Federal Waste Generator Code:	3					
Generator Code Description:	Very Small Quantity Generator					
Source Type:	Notification					
<u>Waste Code Details</u>						
Hazardous Waste Code:	D006					
Waste Code Description:	CADMIUM					
Hazardous Waste Code:	D007					
Waste Code Description:	CHROMIUM					
Hazardous Waste Code:	D008					
Waste Code Description:	LEAD					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hazardous Waste Code:		D009				
Waste Code Description:		MERCURY				
Hazardous Waste Code:		F003				
Waste Code Description:		THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.				
Hazardous Waste Code:		D001				
Waste Code Description:		IGNITABLE WASTE				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		2				
Receive Date:		19920113				
Handler Name:		AKZO COATINGS INC				
Federal Waste Generator Code:		1				
Generator Code Description:		Large Quantity Generator				
Source Type:		Annual/Biennial Report				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		6				
Receive Date:		20020220				
Handler Name:		AKZO NOBEL COATINGS, INC.				
Federal Waste Generator Code:		1				
Generator Code Description:		Large Quantity Generator				
Source Type:		Annual/Biennial Report				
<u>Waste Code Details</u>						
Hazardous Waste Code:		F003				
Waste Code Description:		THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.				
Hazardous Waste Code:		F005				
Waste Code Description:		THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.				
Hazardous Waste Code:		D001				
Waste Code Description:		IGNITABLE WASTE				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		7				
Receive Date:		20040501				
Handler Name:		AKZO NOBEL COATINGS				
Federal Waste Generator Code:		1				
Generator Code Description:		Large Quantity Generator				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Source Type:		Annual/Biennial Report				
<u>Waste Code Details</u>						
Hazardous Waste Code:		D035				
Waste Code Description:		METHYL ETHYL KETONE				
Hazardous Waste Code:		F003				
Waste Code Description:		THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.				
Hazardous Waste Code:		F005				
Waste Code Description:		THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.				
Hazardous Waste Code:		D001				
Waste Code Description:		IGNITABLE WASTE				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		1				
Receive Date:		19951017				
Handler Name:		AKZO NOBEL COATINGS INC				
Federal Waste Generator Code:		1				
Generator Code Description:		Large Quantity Generator				
Source Type:		Notification				
<u>Hazardous Waste Handler Details</u>						
Sequence No:		1				
Receive Date:		19900228				
Handler Name:		AKZO COATINGS INC				
Federal Waste Generator Code:		1				
Generator Code Description:		Large Quantity Generator				
Source Type:		Annual/Biennial Report				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:		Current Operator			Street No:	
Type:		Private			Street 1:	
Name:		OPERNAME			Street 2:	
Date Became Current:					City:	
Date Ended Current:					State:	
Phone:		404-555-1212			Country:	
Source Type:		Implementer			Zip Code:	
Owner/Operator Ind:		Current Owner			Street No:	
Type:		Private			Street 1:	
Name:		NUBIOLA			Street 2:	
Date Became Current:		20020101			City:	
Date Ended Current:					State:	
Phone:		770-277-8819			Country:	
Source Type:		Notification			Zip Code:	
Owner/Operator Ind:		Current Owner			Street No:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Type: Name: Date Became Current: Date Ended Current: Phone: Source Type:	Private FERRO CORPORATION 216-875-5600 Notification			Street 1: Street 2: City: State: Country: Zip Code:	PARKLAND BOULEVARD MAYFIELD OH US 44124	
Owner/Operator Ind: Type: Name: Date Became Current: Date Ended Current: Phone: Source Type:	Current Owner Private AKZO NOBEL COATINGS, INC. 19570101 Annual/Biennial Report			Street No: Street 1: Street 2: City: State: Country: Zip Code:	 US	
Owner/Operator Ind: Type: Name: Date Became Current: Date Ended Current: Phone: Source Type:	Current Operator Private AKZO NOBEL COATINGS 19950315 Annual/Biennial Report			Street No: Street 1: Street 2: City: State: Country: Zip Code:	 US	
Owner/Operator Ind: Type: Name: Date Became Current: Date Ended Current: Phone: Source Type:	Current Owner Private AKZO NOBEL INC 312-906-7500 Implementer			Street No: Street 1: Street 2: City: State: Country: Zip Code:	 300 S RIVERSIDE PLAZA CHICAGO IL 60606	
Owner/Operator Ind: Type: Name: Date Became Current: Date Ended Current: Phone: Source Type:	Current Owner Private AKZO NOBEL COATINGS 19950315 Annual/Biennial Report			Street No: Street 1: Street 2: City: State: Country: Zip Code:	 5555 SPALDING DR NORCROSS GA US 30092	
Owner/Operator Ind: Type: Name: Date Became Current: Date Ended Current: Phone: Source Type:	Current Operator Private NUBIOLA 20020101 Notification			Street No: Street 1: Street 2: City: State: Country: Zip Code:	 GA US	
Owner/Operator Ind: Type: Name: Date Became Current: Date Ended Current: Phone: Source Type:	Current Owner Private AKZO NOBEL INC 312-906-7500 Notification			Street No: Street 1: Street 2: City: State: Country: Zip Code:	 300 S RIVERSIDE PLAZA CHICAGO IL 60606	
Owner/Operator Ind: Type: Name: Date Became Current: Date Ended Current: Phone: Source Type:	Current Operator Private AKZO NOBEL COATINGS, INC. 19570101 Annual/Biennial Report			Street No: Street 1: Street 2: City: State: Country: Zip Code:	 US	
Owner/Operator Ind: Type: Name: Date Became Current: Date Ended Current: Phone:	Current Operator Private OPERNAME 404-555-1212			Street No: Street 1: Street 2: City: State: Country:	 OPERSTREET OPERCITY WY	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Source Type:		Notification		Zip Code:	99999	
Owner/Operator Ind:		Current Operator		Street No:	6369	
Type:		Private		Street 1:	PEACHTREE ST.	
Name:		FERRO CORPORATION - NORCROSS SITE		Street 2:		
Date Became Current:				City:	NORCROSS	
Date Ended Current:				State:	GA	
Phone:				Country:	US	
Source Type:		Notification		Zip Code:	30071	

Historical Handler Details

Receive Dt: 19951017
Generator Code Description: Large Quantity Generator
Handler Name: AKZO NOBEL COATINGS INC

Receive Dt: 19960215
Generator Code Description: Large Quantity Generator
Handler Name: AKZO NOBEL COATINGS INC

Receive Dt: 20100621
Generator Code Description: Small Quantity Generator
Handler Name: NUBIOLA

Receive Dt: 19920113
Generator Code Description: Large Quantity Generator
Handler Name: AKZO COATINGS INC

Receive Dt: 20040127
Generator Code Description: Not a Generator, Verified
Handler Name: AKZO NOBEL COATINGS INC

Receive Dt: 20040501
Generator Code Description: Large Quantity Generator
Handler Name: AKZO NOBEL COATINGS

Receive Dt: 19981210
Generator Code Description: Large Quantity Generator
Handler Name: AKZO NOBEL COATINGS, INC.

Receive Dt: 20020220
Generator Code Description: Large Quantity Generator
Handler Name: AKZO NOBEL COATINGS, INC.

Receive Dt: 20010209
Generator Code Description: Large Quantity Generator
Handler Name: AKZO NOBEL COATINGS INC

Receive Dt: 19900228
Generator Code Description: Large Quantity Generator
Handler Name: AKZO COATINGS INC

Receive Dt: 20050505
Generator Code Description: Not a Generator, Verified
Handler Name: AKZO NOBEL COATINGS

Receive Dt: 20201209
Generator Code Description: Small Quantity Generator
Handler Name: FERRO CORPORATION - NORCROSS SITE

Receive Dt: 20020705
Generator Code Description: Large Quantity Generator
Handler Name: AKZO NOBEL COATINGS INC

Receive Dt: 20010328
Generator Code Description: Large Quantity Generator
Handler Name: AKZO NOBEL COATING, INC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
18	1 of 1	SSE	0.23 / 1,208.09	1,009.02 / -3	BRANDONS PRINTING 6725 JIMMY CARTER BLVD NORCROSS GA 30071	RCRA NON GEN

EPA Handler ID: GA0000187815
Gen Status Universe: No Report
Contact Name: JAY BYARS
Contact Address: 120 , TECHNOLOGY PKWY , , NORCROSS , GA, 30092 , US
Contact Phone No and Ext: 678-684-1823
Contact Email:
Contact Country: US
County Name: GWINNETT
EPA Region: 04
Land Type: Private
Receive Date: 20080512
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Apr, 2022.

Evaluation Details

Evaluation Start Date: 20080116
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19940127
Handler Name: BRANDONS PRINTING
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Code: F001
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20080512
Handler Name: BRANDONS PRINTING
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Private	Street 1:	6725 JIMMY CARTER BLVD
Name:	BYARS JEROME	Street 2:	
Date Became Current:		City:	NORCROSS
Date Ended Current:		State:	GA
Phone:	404-368-0150	Country:	
Source Type:	Notification	Zip Code:	30071

Historical Handler Details

Receive Dt: 19940127
Generator Code Description: Small Quantity Generator
Handler Name: BRANDONS PRINTING

19	1 of 1	NW	0.24 / 1,262.07	1,003.23 / -9	PIB CIRCLE-K 6385 Peachtree Industrial Blvd Peachtree Corners GA	UST

Facility ID: 10002810
County: Gwinnett
State:
Note: Documents related to facilities in Georgia can be searched on the Georgia EPD Online System (GEOS) for Permitting, Compliance and Facility Information:
https://geos.epd.georgia.gov/GA/GEOS/Public/Client/GA_GEOS/Public/Pages/PublicApplicationList.aspx

Underground Storage Tank Data

Tank Status: Currently in Use
Legacy Tank No: 1B
Tank Constr Descr: Composite Double Walled
Content Descr: Premium
Pipe Descr: Double-Walled Fiberglass
Pipe Type: Pressurized
Tank Capacity: 5000
Tank Overfill Date: 5/15/2018
Tank Overfill Exempt: FALSE
Tank Spill Exempt: FALSE
Tank Spill Instl Dt: 5/15/2018
Tank Overfill Type: Ball Float
Tank Install Date: 5/15/2018

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tank Status:		Currently in Use				
Legacy Tank No:		2A				
Tank Constr Descr:		Composite Double Walled				
Content Descr:		Diesel				
Pipe Descr:		Double-Walled Fiberglass				
Pipe Type:		Pressurized				
Tank Capacity:		5000				
Tank Overfill Date:		5/15/2018				
Tank Overfill Exempt:		FALSE				
Tank Spill Exempt:		FALSE				
Tank Spill Instl Dt:		5/15/2018				
Tank Overfill Type:		Flapper Valve				
Tank Install Date:		5/15/2018				
Tank Status:		Currently in Use				
Legacy Tank No:		1A				
Tank Constr Descr:		Composite Double Walled				
Content Descr:		Regular				
Pipe Descr:		Double-Walled Fiberglass				
Pipe Type:		Pressurized				
Tank Capacity:		15000				
Tank Overfill Date:		5/15/2018				
Tank Overfill Exempt:		FALSE				
Tank Spill Exempt:		FALSE				
Tank Spill Instl Dt:		5/15/2018				
Tank Overfill Type:		Flapper Valve				
Tank Install Date:		5/15/2018				
Tank Status:		Currently in Use				
Legacy Tank No:		2B				
Tank Constr Descr:		Composite Double Walled				
Content Descr:		E-85				
Pipe Descr:		Double-Walled Fiberglass				
Pipe Type:		Pressurized				
Tank Capacity:		5000				
Tank Overfill Date:		5/15/2018				
Tank Overfill Exempt:		FALSE				
Tank Spill Exempt:		FALSE				
Tank Spill Instl Dt:		5/15/2018				
Tank Overfill Type:		Flapper Valve				
Tank Install Date:		5/15/2018				

Facility Owner (Revised Jul 2021)

Lemir ID:	333606	State:	GA
County:	Gwinnett	Zip Code:	30338
Facility Status:	Active	Responsibility:	RO
Location Status:	Active	Start Date:	12/11/2018 4:46:20 PM
First Name:	Omar	End Date:	
Last Name:	Pasha	Area Code:	770
Mailing City:	Dunwoody	Phone:	9015600
Mailing Address:	1858 Independence Square		
Location Name:	PIB CIRCLE-K		
Email:	opasha@bellsouth.net		
Company Name:	P2 Properties, LLC		
Lemir ID:	333606	State:	GA
County:	Gwinnett	Zip Code:	30338
Facility Status:	Active	Responsibility:	RO
Location Status:	Active	Start Date:	12/11/2018 4:46:20 PM
First Name:	Omar	End Date:	
Last Name:	Pasha	Area Code:	
Mailing City:	Dunwoody	Phone:	
Mailing Address:	1858 Independence Square		
Location Name:	PIB CIRCLE-K		
Email:	opasha@bellsouth.net		
Company Name:	P2 Properties, LLC		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
20	1 of 8	WNW	0.24 / 1,275.39	1,008.00 / -4	COURTESY CLEANERS 6405-C PEACHTREE IND. BLVD NORCROSS GA 30092	RCRA NON GEN

EPA Handler ID: GAD984289215
Gen Status Universe: No Report
Contact Name: LEE BAGEL
Contact Address: 6405-C , PEACHTREE IND. BLVD , , NORCROSS , GA, 30092 , US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: GWINNETT
EPA Region: 04
Land Type: Private
Receive Date: 20030826
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Apr 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19910312
Handler Name: COURTESY CLEANERS
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Sequence No: 2
Receive Date: 20030826
Handler Name: COURTESY CLEANERS
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: UNKNOWN
Date Became Current: 19000101
Date Ended Current:
Phone:
Source Type: Notification

Street No:
Street 1:
Street 2:
City:
State:
Country:
Zip Code:

Owner/Operator Ind: Current Owner
Type: Private
Name: WILLIAM HANSMAN
Date Became Current:
Date Ended Current:
Phone: 404-948-6758
Source Type: Notification

Street No:
Street 1: 1305 WALDON DRIVE
Street 2:
City: AUSTELL
State: GA
Country:
Zip Code: 30001

Historical Handler Details

Receive Dt: 19910312
Generator Code Description: Small Quantity Generator
Handler Name: COURTESY CLEANERS

20	2 of 8	WNW	0.24 / 1,275.39	1,008.00 / -4	CSF DEVELOPMENT CORP 6405 PEACHTREE IND BLVD STE B NORCROSS GA 30092	RCRA NON GEN

EPA Handler ID: GAR000008870
Gen Status Universe: No Report
Contact Name:
Contact Address: US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: GWINNETT
EPA Region: 04
Land Type: Private
Receive Date: 19991108
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Apr, 2022.

Evaluation Details

Evaluation Start Date: 19990311
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19991108
Handler Name: CSF DEVELOPMENT CORP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990930
Handler Name: CSF DEVELOPMENT CORP
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: U210
Waste Code Description: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Private	Street 1:	5275 TRIANGLE PKWY STE 150
Name:	CSF DEVELOPMENT CORP	Street 2:	
Date Became Current:		City:	NORCROSS
Date Ended Current:		State:	GA
Phone:	770-448-3532	Country:	
Source Type:	Notification	Zip Code:	30092

Historical Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Receive Dt: Generator Code Description: Handler Name:		19990930 Not a Generator, Verified CSF DEVELOPMENT CORP				

20	3 of 8	WNW	0.24 / 1,275.39	1,008.00 / -4	PLATINUM REAL ESTATE PARTNERS LLC 6405 PEACHTREE IND BLVD NORCROSS GA	UST

Facility ID: 670143
County: Gwinnett
State:
Note: Documents related to facilities in Georgia can be searched on the Georgia EPD Online System (GEOS) for Permitting, Compliance and Facility Information:
https://geos.epd.georgia.gov/GA/GEOS/Public/Client/GA_GEOS/Public/Pages/PublicApplicationList.aspx

Underground Storage Tank Data

Tank Status: Currently in Use
Legacy Tank No: 1
Tank Constr Descr: Steel-Impressed Current
Content Descr: Gas (Historical Use)
Pipe Descr: Fiberglass Reinforced Plastic
Pipe Type: Pressurized
Tank Capacity: 15000
Tank Overfill Date: 6/1/1991
Tank Overfill Exempt:
Tank Spill Exempt:
Tank Spill Instl Dt: 3/1/1994
Tank Overfill Type:
Tank Install Date: 5/1/1981

Tank Status: Currently in Use
Legacy Tank No: 2
Tank Constr Descr: Steel-Impressed Current
Content Descr: Gas (Historical Use)
Pipe Descr: Fiberglass Reinforced Plastic
Pipe Type: Pressurized
Tank Capacity: 15000
Tank Overfill Date: 6/1/1991
Tank Overfill Exempt:
Tank Spill Exempt:
Tank Spill Instl Dt: 3/1/1994
Tank Overfill Type:
Tank Install Date: 5/1/1981

Tank Status: Currently in Use
Legacy Tank No: 3
Tank Constr Descr: Steel-Impressed Current
Content Descr: Gas (Historical Use)
Pipe Descr: Fiberglass Reinforced Plastic
Pipe Type: Pressurized
Tank Capacity: 15000
Tank Overfill Date: 6/1/1991
Tank Overfill Exempt:
Tank Spill Exempt:
Tank Spill Instl Dt: 3/1/1994
Tank Overfill Type:
Tank Install Date: 5/1/1981

Tank Status: Currently in Use
Legacy Tank No: 5
Tank Constr Descr: Steel-Impressed Current
Content Descr: Gas (Historical Use)
Pipe Descr: Fiberglass Reinforced Plastic
Pipe Type: Pressurized

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tank Capacity:		15000				
Tank Overfill Date:		6/1/1991				
Tank Overfill Exempt:						
Tank Spill Exempt:						
Tank Spill Instl Dt:		3/1/1994				
Tank Overfill Type:						
Tank Install Date:		5/1/1981				
Tank Status:		Currently in Use				
Legacy Tank No:		4				
Tank Constr Descr:		Steel-Impressed Current				
Content Descr:		Gas (Historical Use)				
Pipe Descr:		Fiberglass Reinforced Plastic				
Pipe Type:		Pressurized				
Tank Capacity:		6000				
Tank Overfill Date:		6/1/1991				
Tank Overfill Exempt:						
Tank Spill Exempt:						
Tank Spill Instl Dt:		3/1/1994				
Tank Overfill Type:						
Tank Install Date:		5/1/1981				
<u>Facility Owner (Revised Jul 2021)</u>						
Lemir ID:	143270			State:	GA	
County:	Gwinnett			Zip Code:	30092	
Facility Status:	Active			Responsiblity:	RO	
Location Status:	Active			Start Date:		
First Name:	NADIYA			End Date:		
Last Name:	ALIBHAI			Area Code:	404	
Mailing City:	Norcross			Phone:	5421258	
Mailing Address:	6405 Peachtree Industrial Blvd					
Location Name:	PLATINUM REAL ESTATE PARTNERS LLC; ASID: 1906					
Email:	ali786noor@gmail.com					
Company Name:						
Lemir ID:	143270			State:	GA	
County:	Gwinnett			Zip Code:	30092	
Facility Status:	Active			Responsiblity:	RO	
Location Status:	Active			Start Date:		
First Name:	NADIYA			End Date:		
Last Name:	ALIBHAI			Area Code:		
Mailing City:	Norcross			Phone:		
Mailing Address:	6405 Peachtree Industrial Blvd					
Location Name:	PLATINUM REAL ESTATE PARTNERS LLC; ASID: 1906					
Email:	ali786noor@gmail.com					
Company Name:						
Lemir ID:	143270			State:	GA	
County:	Gwinnett			Zip Code:	30092	
Facility Status:	Active			Responsiblity:	RO	
Location Status:	Active			Start Date:	6/14/2019 10:23:04 AM	
First Name:	Nadiya			End Date:		
Last Name:	Alibhai			Area Code:	404	
Mailing City:	NORCROSS			Phone:	9324954	
Mailing Address:	6405 PEACHTREE IND BLVD					
Location Name:	PLATINUM REAL ESTATE PARTNERS LLC; ASID: 1906					
Email:	TANISHADAMANI11@GMAIL.COM					
Company Name:	PLATINUM REAL ESTATE PARTNERS LLC					
<u>Payments & Obligations</u>						
Location Name:	PLATINUM REAL ESTATE PARTNERS LLC					
Obligated Amount:	57561.46					
County:	Gwinnett					
Agreement No:	2020-GUST-CAB-300892					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Agreement Type:		GUST – Reimbursement				
Payment Amount:		57561.46				
<u>Payments & Obligations</u>						
Location Name:		PLATINUM REAL ESTATE PARTNERS LLC				
Obligated Amount:		25374.29				
County:		Gwinnett				
Agreement No:		2017-GUST-UST-122642				
Agreement Type:		GUST – Reimbursement				
Payment Amount:		25374.29				
20	4 of 8	WNW	0.24 / 1,275.39	1,008.00 / -4	PLATINUM REAL ESTATE PARTNERS LLC 6405 PEACHTREE IND BLVD NORCROSS GA 30092	LUST
Facility ID:		670143				
County:		Gwinnett				
Cleanup Status:		NFA - No Further Action				
Confirm Release Date:		2/6/1996				
No Further Action Date:		5/22/1997				
Project Manager:		Stephen Burris				
Site Code Description:		Potential GUST trust fund reimbursement site				
Project Name:		UST - 1 - PLATINUM REAL ESTATE PARTNERS LLC				
20	5 of 8	WNW	0.24 / 1,275.39	1,008.00 / -4	European Cleaners 6405 Peachtree Industrial Boulevard Norcross GA 30092	DRYCLEANERS
County:		Gwinnett				
20	6 of 8	WNW	0.24 / 1,275.39	1,008.00 / -4	PLATINUM REAL ESTATE PARTNERS LLC (formerly Conv Square) 6405 PEACHTREE INDUSTRIAL BLVD NORCROSS GA 30092-	HSRA NOTIF
Notif ID:		6523		Date Received:		1/13/2017
Non HSRA Unit:		HAYES		Date Assigned:		1/18/2017
Non HSRA CO:		LUCAS		Date Back:		
HSRA CO:		LUCAS		Date to Director:		
HSRA Unit:		HAYES		Date LTR:		9/18/2020
HSI:		No		County:		GWINNETT
HSI No:		0				
Pre RQSM Cleanup:		FALSE				
Deferred on Site Scoring:		FALSE				
Additional Data Requested:		FALSE				
VRP Deferral:		FALSE				
Comments:		To Alaeddini 1/19/17. To Lucas 8-25-17. Add'l info due 6-30-2018				
20	7 of 8	WNW	0.24 / 1,275.39	1,008.00 / -4	CONVENIENCE SQUARE-6405 PCHTREE IND BLVD 6405 PEACHTREE INDUSTRIAL BOULEVARD NORCROSS GA	HSRA NOTIF
Notif ID:		2666		Date Received:		3/20/1995
Non HSRA Unit:		WOODALL		Date Assigned:		3/23/1995

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non HSRA CO: DEGOLIAN HSRA CO: HSRA Unit: HSI: No HSI No: 0 Pre RQSM Cleanup: FALSE Deferred on Site Scoring: FALSE Additional Data Requested: FALSE VRP Deferral: FALSE Comments:						
Date Back: Date to Director: Date LTR: 5/12/1995 County: GWINNETT						
20	8 of 8	WNW	0.24 / 1,275.39	1,008.00 / -4	PLATINUM REAL ESTATE PARTNERS LLC 6405 PEACHTREE IND BLVD NORCROSS GA 30092	LUST
Facility ID: 670143 County: Gwinnett Cleanup Status: In Remediation Confirm Release Date: 11/23/2016 No Further Action Date: Project Manager: Stephen Burris Site Code Description: Eligible GUST trust fund reimbursement site Project Name: UST - 2 - PLATINUM REAL ESTATE PARTNERS LLC						
21	1 of 1	W	0.34 / 1,811.55	970.06 / -42	MAYER ELECTRIC SUPPLY 6460 PEACHTREE IND BLVD NORCROSS GA 30071	LUST
Facility ID: 9067098 County: Gwinnett Cleanup Status: NFA - Clean Closure Confirm Release Date: No Further Action Date: 10/27/2010 Project Manager: Kelly Adams Site Code Description: Owner/Operator funded site Project Name: UST - CLOSURE - MAYER ELECTRIC SUPPLY						
22	1 of 3	WNW	0.40 / 2,136.90	957.36 / -55	Overlook Bay Apartments 6520 Hilldale Dr. Norcross GA 30092	NON HSI
NHSI Letter Date: Release Notif Date: Date: File: Contaminants: Additional Info:						
Groundwater Score: 7.3 On-Site Exp Score: 0 County: Gwinnett Latitude: 33.95 Longitude: -84.0361						
22	2 of 3	WNW	0.40 / 2,136.90	957.36 / -55	OVERLOOK BAY APARTMENTS 6520 HILLDALE DRIVE NORCROSS GA	HSRA NOTIF
Notif ID: 2427 Non HSRA Unit: WOODALL Non HSRA CO: SHUMATE HSRA CO: HSRA Unit: HSI: No HSI No: 0 Pre RQSM Cleanup: TRUE Deferred on Site Scoring: FALSE						
Date Received: 12/14/1994 Date Assigned: 12/16/1994 Date Back: Date to Director: Date LTR: 1/27/1995 County: GWINNETT						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Additional Data Requested:		FALSE				
VRP Deferral:		FALSE				
Comments:						
22	3 of 3	WNW	0.40 / 2,136.90	957.36 / -55	THE FIELDS AT PEACHTREE CORNERS APARTMENTS 6520 HILLANDALE DRIVE NORCROSS GA 30092-	HSRA NOTIF
Notif ID:		6646		Date Received:	4/30/2018	
Non HSRA Unit:		HAYES		Date Assigned:	5/1/2018	
Non HSRA CO:		LUCAS		Date Back:		
HSRA CO:		LUCAS		Date to Director:		
HSRA Unit:		HAYES		Date LTR:	8/17/2018	
HSI:		No		County:	GWINNETT	
HSI No:		0				
Pre RQSM Cleanup:		TRUE				
Deferred on Site Scoring:		FALSE				
Additional Data Requested:		FALSE				
VRP Deferral:		FALSE				
Comments:		To Lucas 5-1-18. Previous RN from mid-90s (Overlook Bay). Adjacent to 6405 Peachtree Ind Blvd RN.				
23	1 of 1	SSW	0.42 / 2,232.53	1,000.62 / -12	WMI BJ landfill PH3&4 JONES MILL RD DORAVILLE GA	LANDFILLS
Permit No:		067-027D(SL)		County Name:	GWINNETT	
HSI ID:		NA		Area:	0	
DHSI ID:		NA		Perimeter:	0	
DR0110 No:		449		Polygoni:	0	
DR0110 No ID:		259		Scale:	0	
Permit Issued:		09/26/1984		Angle:	1	
Date Ceased:		4/9/1999		Lat:	33.9349269796666	
Private Site:		TRUE		Long:	-84.2387369251257	
LPB:		Yes		Phone Area:	770	
Site Occ:		NL		Phone No:	4483997	
Operating Status:		2				
Operating Status Desc:		Closed. The disposal facility has closed and met all the regulatory closure requirements.				
Fac Type:		MSWL				
Fac Type Desc:		Municipal Solid Waste (putrescible waste) Landfill. Accepts solid wastes from homes, industries, commercial buildings, or institutional facilities. These are landfills which have installed liners and leachate collection systems on permitted acreage, as required under federal subtitle D regulations.				
GW Monitoring Required:		Y				
GW Monitoring Desc:		Ground-water monitoring is required and installation has been approved.				
Coord Source:		dr0020				
Coord Method:		G				
Coord Method Desc:		The landfills from DR00-20 were collected using GPS receivers				
24	1 of 1	SSW	0.43 / 2,246.64	1,001.43 / -11	WMI BJ Landfill Expansion JONES MILL RD DORAVILLE GA	LANDFILLS
Permit No:		067-025D(SL)		County Name:	GWINNETT	
HSI ID:		NA		Area:	0	
DHSI ID:		NA		Perimeter:	0	
DR0110 No:		202		Polygoni:	0	
DR0110 No ID:		258		Scale:	0	
Permit Issued:				Angle:	1	
Date Ceased:		1/1/1985		Lat:	33.9348953503935	
Private Site:		TRUE		Long:	-84.2387850681533	
LPB:		Yes		Phone Area:	404	
Site Occ:		NL		Phone No:	8590800	
Operating Status:		2				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Operating Status Desc:		Closed. The disposal facility has closed and met all the regulatory closure requirements.				
Fac Type:		SL				
Fac Type Desc:		Sanitary Waste (putrescible waste) landfill (older designation).				
GW Monitoring Required:		N				
GW Monitoring Desc:		Ground-water monitoring is not required. The landfill closed prior to the beginning of monitoring requirements.				
Coord Source:		dr0020				
Coord Method:		G				
Coord Method Desc:		The landfills from DR00-20 were collected using GPS receivers				
25	1 of 1	WSW	0.44 / 2,300.28	1,040.10 / 28	WASTE ELIMINATOR INC. 3025 Jones Mill Rd Norcross GA 30071	SWF/LF
Permit No:		067-041P(MRF)		Data Source:		Solid Waste Handling Permit
County:						
<u>Handling Permits (Current as of Jan 16, 2020)</u>						
Status:		Active		State:		GA
Address:		3025 Jones Mill Rd		Zip:		30071
City:		Norcross				
Facility Name:		WASTE ELIMINATOR INC.				
Site Property Type:		Regulated Entity				
Environmental Interest Identifier:		067-041P(MRF); ST-CR-333334				
26	1 of 3	SSE	0.58 / 3,087.68	1,051.72 / 39	Southern Pipe Coating Operation (Former) 6420 Corley Road Norcross GA 30071-	DELISTED SHWS
HSI ID:		10757		Funding Source:		P
SL No:				Fund Source Desc:		Private
ID:				Max Fund LE/SE:		
Parcel No:				LF:		
Listed Status:		DELISTED		Unit:		Brownlee
Listed:		No		CO:		Chew
List Date:				Geologist:		Collins
Delist Date:		6/24/2013		HSRA Buddy:		Chew
Class:		II		Site Addr 2:		
VRP Date:				County:		Gwinnett
Brownfield Date:				Quad Name:		
Source Date:		3/12/2013		Latitude(D):		
Soil Date:		3/12/2013		Latitude(M):		
Groundwater Date:		3/12/2013		Latitude(S):		
HWTF Projected Src:		0		Longitude(D):		
HWTF Proj Soil:		0		Longitude(M):		
HWTF Projected GW:		0		Longitude(S):		
HWTF Proj Total:		0				
HWTF Loc Gov Actual Exp Obl:		0				
SW No:						
Source Status:		RRS1				
Source Stat Desc:		Type 1 Risk Reduction Standards - default residential standards				
Soil Status:		RRS1				
Soil Status Desc:		Type 1 Risk Reduction Standards - default residential standards				
Groundwater Status:		RRS1				
Groundwater Status Desc:		Type 1 Risk Reduction Standards - default residential standards				
Overall Status:		RRS1				
Overall Status Desc:		Type 1 Risk Reduction Standards - default residential standards				
Latitude:						
Longitude:						
Source:		Delisted by HSI with Address (By Date); Delisted by HSI with Address - LW Delist				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
26	2 of 3	SSE	0.58 / 3,087.68	1,051.72 / 39	SOUTHERN PIPE COATING OPERATION (FORMER) 6420 CORLEY ROAD NORCROSS GA	HSRA NOTIF
Notif ID: 3804 Non HSRA Unit: KHALEIGHI Non HSRA CO: ROWE HSRA CO: NORWOOD HSRA Unit: HSI: Yes HSI No: 10757 Pre RQSM Cleanup: FALSE Deferred on Site Scoring: FALSE Additional Data Requested: FALSE VRP Deferral: FALSE Comments: SITE # 10757 Date Received: 2/8/2002 Date Assigned: 2/15/2002 Date Back: 7/26/2002 Date to Director: Date LTR: 3/19/2003 County: GWINNETT						
26	3 of 3	SSE	0.58 / 3,087.68	1,051.72 / 39	Southern Pipe Coating Operation (Former) 6420 Corley Road Norcross GA 30071-	SHWS
ID: 676 HSI ID: 10757 Overall Status: RRS1 Delist date: 6/24/2013 List Date: 3/11/2003 Listed: FALSE LF: Rank: 13 Scored By: Kelly Norwood Score Date: 3/7/2003 GW Score: 10.16 OS Score: 18.52 USGS Quadrant N: VRP Date: 6/22/2012 BF Date: HSRA Buddy: Fischer Geologist: Fischer Groundwater Status: RRS1 Unit: Brownlee Source Status: RRS1 Soil Status: RRS1 CO: Fischer County: Gwinnett Company: L. B. Foster Company Site Summary: Gndwater Stat Desc: Type 1 Risk Reduction Standards - default residential standards Soil Status Desc: Type 1 Risk Reduction Standards - default residential standards Comments: Investigation Cleanup Funding: Property Owner: Southern Pipe Coating Operation (Former) Fac Owner Title: no on-site contact given Address: 415 Holiday Drive City: Pittsburgh State: PA Zip: 15220 Phone: (412) 928-3402 Lat Deg: 33 Lat Min: 55 Lat Sec: 48 Long Deg: 84 Long Min: 14 Long Sec: 09 Lat Decimal Degree: 33.93 Lat Degree Minutes: 0.93 Lat Degree Seconds: 0.8 Lon Decimal Degree: 84.23583333333333 Lon Degree Minutes: 0.2358333333333333 Lon Decimal Second: 0.15 Lon DSH: 14.15 Lat DMH: 55.8 Site City: Norcross Site ZIP: 30071-						
<u>Groundwater Pathway</u> CAS No: 75014 Chem Name: Vinyl chloride Section A: 45 Section 1B: 0 Section 2B: 0 Section C: 0 Section 1D: Vinyl chloride Section 2D: 16 Section 3D Desc: Section 3D: 4 Section 1E: 4 Section 2E: 1						
<u>On-Site Exposure</u>						
CAS No:	75014			Section 2D:	16	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Chem Name: Vinyl chloride Section 3D Desc: Section 3D: 4 Section B: 15 Section 1E: 6 Section C: 5 Section 2E: 0 Section 1D: Vinyl chloride Code Guide Doc: https://epd.georgia.gov/sites/epd.georgia.gov/files/related_files/site_page/RQSMManual.pdf						
Property Owner Information						
Prop Owner: Corley Road, LLC c/o James Morton Prop Owner 3: Address: 1349 West Peachtree Street Address 3: City: Atlanta City 3: State: GA State 3: ZIP: 30309 ZIP 3: Phone: 404.966.5133 Phone 3: Prop Owner 2: Address 2: City 2: State 2: ZIP 2: Phone 2: Prop Owner 4: Address 4: City 4: State 4: Zip 4: Phone 4:						
Property Contact Information						
Contact Person: Joan Sasine Contact Person 2: Contact Title: Contact Comp 2: Contact Addr 2: Contact City 2: Contact State 2: Contact ZIP 2: Contact Phone 2: Contact Title: Contact Comp 2: Contact Addr 2: Contact City 2: Contact State 2: Contact ZIP 2: Contact Phone 2:						
27	1 of 1	NNW	0.65 / 3,418.74	951.30 / -61	MR. CLEAN (FORMER) 3375 HOLCOMB BRIDGE ROAD NORCROSS GA 30092-	HSRA NOTIF
Notif ID: 6385 Date Received: 10/28/2015 Non HSRA Unit: METZGER Date Assigned: 10/29/2015 Non HSRA CO: BEAVERS Date Back: HSRA CO: BEAVERS Date to Director: HSRA Unit: METZGER Date LTR: 12/22/2015 HSI: No County: GWINNETT HSI No: 0 Pre RQSM Cleanup: TRUE Deferred on Site Scoring: FALSE Additional Data Requested: FALSE VRP Deferral: FALSE Comments: MAILED NON-HSI LETTER 12/22/2015						
28	1 of 1	NE	0.66 / 3,497.75	1,000.02 / -12	Harris Beauty Supply Co. 6341 or 6041 Peachtree Industrial Blvd. Norcross GA 30092	NON HSI
NHSI Letter Date: Groundwater Score: 1.54 Release Notif Date: On-Site Exp Score: 16.11 Date: County: Gwinnett File: Latitude: Contaminants: Longitude: Additional Info:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
29	1 of 1	WSW	0.68 / 3,587.35	1,023.88 / 12	BAY COLONY BUSINESS CENTER 6621 BAY CIRCLE NORCROSS GA	HSRA NOTIF
Notif ID: 2749				Date Received:	8/18/1995	
Non HSRA Unit: WOODALL				Date Assigned:	8/23/1995	
Non HSRA CO: BROWNLEE				Date Back:		
HSRA CO:				Date to Director:		
HSRA Unit:				Date LTR:	11/27/1995	
HSI: No				County:	GWINNETT	
HSI No: 0						
Pre RQSM Cleanup:		FALSE				
Deferred on Site Scoring:		FALSE				
Additional Data Requested:		FALSE				
VRP Deferral:		FALSE				
Comments:						
30	1 of 2	N	0.69 / 3,661.03	929.94 / -82	Market Place Shopping Ctr. 6135 Peachtree Pkwy. Norcross GA 30092	NON HSI
NHSI Letter Date:				Groundwater Score:	3.25	
Release Notif Date:				On-Site Exp Score:	20.00	
Date: Nov-98				County:	Gwinnett	
File:				Latitude:	33.9526	
Contaminants:				Longitude:	84.2364	
Additional Info:						
30	2 of 2	N	0.69 / 3,661.03	929.94 / -82	MARKET PLACE SHOPPING CENTER 6135 PEACHTREE PARKWAY NORCROSS GA	HSRA NOTIF
Notif ID: 2954				Date Received:	12/4/1997	
Non HSRA Unit: HENDRICKS				Date Assigned:	1/27/1998	
Non HSRA CO: CHEN				Date Back:		
HSRA CO: CHEN				Date to Director:		
HSRA Unit:				Date LTR:	10/7/1998	
HSI: No				County:	GWINNETT	
HSI No: 0						
Pre RQSM Cleanup:		FALSE				
Deferred on Site Scoring:		FALSE				
Additional Data Requested:		FALSE				
VRP Deferral:		FALSE				
Comments:						
31	1 of 2	NNW	0.70 / 3,682.44	965.29 / -47	Elegant Cleaners 3380 Holcomb Bridge Road Norcross GA 30092	NON HSI
NHSI Letter Date:				Groundwater Score:	6.50	
Release Notif Date:				On-Site Exp Score:	19.26	
Date: Dec-08				County:	Gwinnett	
File:				Latitude:	33.950833	
Contaminants: PCE				Longitude:	84.240833	
Additional Info:						
31	2 of 2	NNW	0.70 / 3,682.44	965.29 / -47	ELEGANT CLEANERS 3380 HOLCOMB BRIDGE ROAD NORCROSS GA 30092-	HSRA NOTIF
Notif ID: 4737				Date Received:	12/15/2008	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non HSRA Unit: BROWNLEE Non HSRA CO: HAN HSRA CO: HAN HSRA Unit: BROWNLEE HSI: No HSI No: 0 Pre RQSM Cleanup: FALSE Deferred on Site Scoring: FALSE Additional Data Requested: FALSE VRP Deferral: FALSE Comments: NON HSI LETTER MAILED 12/24/2008						
					Date Assigned: 12/16/2008 Date Back: Date to Director: Date LTR: 12/22/2008 County: GWINNETT	
32	1 of 2	WNW	0.77 / 4,063.41	983.74 / -29	Post Corners Apartments 3341 Peachtree Corners Circle, NW Norcross GA 30092	NON HSI
NHSI Letter Date: Release Notif Date: Date: May-04 File: Contaminants: tetrachloroethylene Additional Info:						
					Groundwater Score: 6.50 On-Site Exp Score: 17.78 County: Gwinnett Latitude: 33.975000 Longitude: 84.250000	
32	2 of 2	WNW	0.77 / 4,063.41	983.74 / -29	POST CORNERS APARTMENTS 3341 PEACHTREE CORNER CIRCLE NW NORCROSS GA	HSRA NOTIF
Notif ID: 4047 Non HSRA Unit: CLEARY Non HSRA CO: DAVIS HSRA CO: DAVIS HSRA Unit: HSI: No HSI No: 0 Pre RQSM Cleanup: FALSE Deferred on Site Scoring: FALSE Additional Data Requested: FALSE VRP Deferral: FALSE Comments: NON HSI LETTER MAILED 5/24/2004						
					Date Received: 4/27/2004 Date Assigned: 5/6/2004 Date Back: Date to Director: Date LTR: 5/24/2004 County: GWINNETT	
33	1 of 3	SSE	0.79 / 4,161.27	1,067.88 / 56	AKZO Coatings, Inc. 6369 Old Peachtree Rd. Norcross GA 30071	NON HSI
NHSI Letter Date: Release Notif Date: Date: File: Contaminants: tetrachloroethylene Additional Info:						
					Groundwater Score: 0.60 On-Site Exp Score: 0 County: Gwinnett Latitude: 33.930 Longitude: -84.231	
33	2 of 3	SSE	0.79 / 4,161.27	1,067.88 / 56	WYANDOFFE PAINT PRODUCTS 6369 OLD PEACHTREE RD NORCROSS GA 30071-	HSRA NOTIF
Notif ID: 5388 Non HSRA Unit: Non HSRA CO: HSRA CO: HSRA Unit:						
					Date Received: 5/11/1994 Date Assigned: Date Back: Date to Director: Date LTR: 5/11/1994	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
HSI: HSI No: Pre RQSM Cleanup: Deferred on Site Scoring: Additional Data Requested: VRP Deferral: Comments:	No 0 FALSE FALSE FALSE FALSE RQSM SCORE DATE				County: GWINNETT	
33	3 of 3	SSE	0.79 / 4,161.27	1,067.88 / 56	AKZO COATINGS, INC. 6369 OLD PEACHTREE RD. NORCROSS GA	HSRA NOTIF
Notif ID: Non HSRA Unit: Non HSRA CO: HSRA CO: HSRA Unit: HSI: HSI No: Pre RQSM Cleanup: Deferred on Site Scoring: Additional Data Requested: VRP Deferral: Comments:	2576 WOODALL GERMAN No 0 FALSE FALSE FALSE FALSE			Date Received: Date Assigned: Date Back: Date to Director: Date LTR: County:	3/22/1994 6/29/1994 GWINNETT	
34	1 of 1	SSE	0.87 / 4,599.91	1,081.50 / 69	Properties of Stephen E. Champ 6354 Buford Highway Norcross GA 30093	NON HSI
NHSI Letter Date: Release Notif Date: Date: File: Contaminants: Additional Info:	Oct-05 chloroform			Groundwater Score: On-Site Exp Score: County: Latitude: Longitude:	1.00 18.80 Gwinnett 33.930000 84.233889	
35	1 of 1	SSE	0.88 / 4,624.93	1,079.97 / 68	STEPHEN E. CHAMP PROPERTY 6354 BUFORD HIGHWAY GA	HSRA NOTIF
Notif ID: Non HSRA Unit: Non HSRA CO: HSRA CO: HSRA Unit: HSI: HSI No: Pre RQSM Cleanup: Deferred on Site Scoring: Additional Data Requested: VRP Deferral: Comments:	4274 YARDUMIAN SLIWINSKI ROSS No 0 FALSE FALSE FALSE FALSE			Date Received: Date Assigned: Date Back: Date to Director: Date LTR: County:	9/14/2005 9/15/2005 10/25/2005 11/4/2005 GWINNETT	
36	1 of 1	WSW	0.88 / 4,627.49	987.97 / -24	PEACHTREE INDUSTRIAL MERCURY SPILL 6767 PEACHTREE INDUSTRIAL BOULEVARD NORCROSS GA	HSRA NOTIF
Notif ID: Non HSRA Unit: Non HSRA CO:	3160 CLEARY HETRICK			Date Received: Date Assigned: Date Back:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
HSRA CO: HSRA Unit: HSI: No HSI No: 0 Pre RQSM Cleanup: FALSE Deferred on Site Scoring: FALSE Additional Data Requested: FALSE VRP Deferral: FALSE Comments: EPA/RAT96						
				Date to Director: Date LTR: 8/12/1997 County: GWINNETT		
37	1 of 2	NE	0.98 / 5,156.73	1,025.36 / 13	Tennant Company (Former) 5805 Peachtree Corners East Norcross GA 30092	NON HSI
NHSI Letter Date: Release Notif Date: Date: Apr-06 File: Contaminants: Tetrachloroethene Additional Info:						
				Groundwater Score: 6.50 On-Site Exp Score: 14.80 County: Gwinnett Latitude: 33.953889 Longitude: 84.227778		
37	2 of 2	NE	0.98 / 5,156.73	1,025.36 / 13	TENNANT COMPANY PROPERTY (FORMER) 5805 PEACHTREE CORNERS EAST NORCROSS GA 30092-	HSRA NOTIF
Notif ID: 4319 Non HSRA Unit: REULAND Non HSRA CO: HSRA CO: WILLIAMS, B HSRA Unit: HSI: No HSI No: 0 Pre RQSM Cleanup: FALSE Deferred on Site Scoring: FALSE Additional Data Requested: FALSE VRP Deferral: FALSE Comments: ASSIGNED TO REULAND ON 03-13-2006 / NON HSI 04-18-2006 (B.WILLIAMS)						
				Date Received: 2/3/2006 Date Assigned: 2/9/2006 Date Back: Date to Director: Date LTR: 4/18/2006 County: GWINNETT		

Unplottable Summary

Total: 0 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID

No unplottable records were found that may be relevant for the search criteria.

Unplottable Report

No unplottable records were found that may be relevant for the search criteria.

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13 and E1527-21, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

Formerly Utilized Sites Remedial Action Program:

[DOE FUSRAP](#)

The U.S. Department of Energy (DOE) established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from the Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations. The DOE Office of Legacy Management (LM) established long-term surveillance and maintenance (LTS&M) requirements for remediated FUSRAP sites. DOE evaluates the final site conditions of a remediated site on the basis of risk for different future uses. DOE then confirms that LTS&M requirements will maintain protectiveness.

Government Publication Date: Mar 4, 2017

National Priority List:

[NPL](#)

Sites on the United States Environmental Protection Agency (EPA)'s National Priorities List of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. The NPL, which EPA is required to update at least once a year, is based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Mar 30, 2022

National Priority List - Proposed:

[PROPOSED NPL](#)

Sites proposed - by the EPA, the state agency, or concerned citizens - for addition to the NPL due to contamination by hazardous waste and identified by the Environmental Protection Agency (EPA) as a candidate for cleanup because it poses a risk to human health and/or the environment. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Mar 30, 2022

Deleted NPL:

[DELETED NPL](#)

Sites deleted from the United States Environmental Protection Agency (EPA)'s National Priorities List. The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425(e), sites may be deleted from the NPL where no further response is appropriate. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Mar 30, 2022

SEMS List 8R Active Site Inventory:[SEMS](#)

The Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted.

Government Publication Date: Feb 24, 2022

Inventory of Open Dumps, June 1985:[ODI](#)

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

SEMS List 8R Archive Sites:[SEMS ARCHIVE](#)

The Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time.

Government Publication Date: Feb 24, 2022

Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS:[CERCLIS](#)

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

EPA Report on the Status of Open Dumps on Indian Lands:[IODI](#)

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

CERCLIS - No Further Remedial Action Planned:[CERCLIS NFRAP](#)

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens:[CERCLIS LIENS](#)

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action:[RCRA CORRACTS](#)

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Apr 11, 2022

RCRA non-CORRACTS TSD Facilities:[RCRA TSD](#)

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites listed as treatment, storage and/or disposal facilities of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Government Publication Date: Apr 11, 2022

RCRA Generator List:[RCRA LQG](#)

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste.

Government Publication Date: Apr 11, 2022

RCRA Small Quantity Generators List:[RCRA SQG](#)

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month.

Government Publication Date: Apr 11, 2022

RCRA Very Small Quantity Generators List:[RCRA VSQG](#)

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Apr 11, 2022

RCRA Non-Generators:[RCRA NON GEN](#)

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Apr 11, 2022

RCRA Sites with Controls:[RCRA CONTROLS](#)

List of Resource Conservation and Recovery Act (RCRA) facilities with institutional controls in place. RCRA gives the U.S. Environmental Protection Agency (EPA) the authority to control hazardous waste from the "cradle-to-grave." This includes the generation, transportation, treatment, storage, and disposal of hazardous waste. RCRA also set forth a framework for the management of non-hazardous solid wastes. The 1986 amendments to RCRA enabled EPA to address environmental problems that could result from underground tanks storing petroleum and other hazardous substances.

Government Publication Date: Apr 11, 2022

Federal Engineering Controls-ECs:[FED ENG](#)

Engineering controls (ECs) encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Dec 30, 2021

Federal Institutional Controls-ICs:[FED INST](#)

Institutional controls are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's (United States Environmental Protection Agency) expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site.

Government Publication Date: Dec 30, 2021

Land Use Control Information System:[LUCIS](#)

The LUCIS database is maintained by the U.S. Department of the Navy and contains information for former Base Realignment and Closure (BRAC) properties across the United States.

Government Publication Date: Sep 1, 2006

Institutional Control Boundaries at NPL sites:[NPL IC](#)

Boundaries of Institutional Control areas at sites on the United States Environmental Protection Agency (EPA)'s National Priorities List, or Proposed or Deleted, made available by the EPA's Shared Enterprise Geodata and Services (SEGS). United States Environmental Protection Agency (EPA)'s National Priorities List of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. Institutional controls are non-engineered instruments such as administrative and legal controls that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy.

Government Publication Date: Mar 30, 2022

Emergency Response Notification System:[ERNS 1982 TO 1986](#)

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System:[ERNS 1987 TO 1989](#)

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System:[ERNS](#)

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Dec 31, 2021

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database:[FED BROWNFIELDS](#)

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Aug 20, 2021

FEMA Underground Storage Tank Listing:[FEMA UST](#)

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Facility Response Plan:[FRP](#)

List of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Dec 2, 2020

Historical Gas Stations:[HIST GAS STATIONS](#)

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries:

REFN

List of petroleum refineries from the U.S. Energy Information Administration (EIA) Refinery Capacity Report. Includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year located in the 50 States, the District of Columbia, Puerto Rico, the Virgin Islands, Guam, and other U.S. possessions. Survey locations adjusted using public data.

Government Publication Date: Feb 4, 2022

Petroleum Product and Crude Oil Rail Terminals:

BULK TERMINAL

List of petroleum product and crude oil rail terminals made available by the U.S. Energy Information Administration (EIA). Includes operable bulk petroleum product terminals located in the 50 States and the District of Columbia with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil that were active between 2017 and 2018. Petroleum product terminals comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings. Survey locations adjusted using public data.

Government Publication Date: Feb 4, 2022

LIEN on Property:

SEMS LIEN

The EPA Superfund Enterprise Management System (SEMS) provides LIEN information on properties under the EPA Superfund Program.

Government Publication Date: Feb 24, 2022

Superfund Decision Documents:

SUPERFUND ROD

This database contains a listing of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD), along with other associated memos and files. This information is maintained and made available by the US EPA (Environmental Protection Agency).

Government Publication Date: Nov 16, 2021

State**Hazardous Site Inventory:**

SHWS

The Hazardous Site Inventory (HSI) is a list of sites in Georgia where there has been a known or suspected release of a regulated substance above a reportable quantity and which have yet to show they meet state clean-up standards found in the Rules for Hazardous Site Response. The HSI is compiled and published by the Environmental Protection Division (EPD) of the Georgia Department of Natural Resources (DNR). This database is state equivalent CERCLIS.

Government Publication Date: Jul 1, 2021

Delisted Hazardous Site Inventory Listing:

DELISTED SHWS

Maintained by the Environmental Protection Division (EPD) of the Georgia Department of Natural Resources, this is a listing of sites which have, over the years, been delisted from the Georgia Hazardous Site Inventory (HSI).

Government Publication Date: Jul 1, 2021

Removed Sites Hazard Site Inventory & Delisted:

REMOVED HSI

A list of sites that have been removed from the Georgia Department of Natural Resources (DNR) Hazard Site Inventory (HSI) and the Delisted Hazard Site Inventory.

Government Publication Date: Jul 1, 2021

Hazard Evaluation Score (Non-Hazardous Site Inventory):

NON HSI

The Non HSI or Non-Hazardous Site Inventory is information taken from public sources and gathered and compiled by Rindt-McDuff Associates (RMA). Sites on this inventory were not included on the official Georgia State Hazardous Site Inventory because their Hazard Evaluation Score does not exceed the threshold levels. There is no guarantee of the accuracy of the data from RMA. This database is state equivalent CERCLIS.

Government Publication Date: Jul 31, 2014

Hazardous Site Response Notifications:

HSRA NOTIF

List of Hazardous Site Response Act (HSRA) Release Notification sites made available by the Georgia Environmental Protection Division (EPD). Under the Rules for Hazardous Site Response, Chapter 391-3-19, the HSRA requires property owners who discover the release of regulated contaminants in soil or groundwater to report to the Georgia EPD. A Release Notification is submitted by the property owner to the Response & Remediation Program (RRP); the RRP may or may not issue a Non-HSI Letter or an HSI Listing Letter based on the information gathered from the Release Notification and site visits.

Government Publication Date: Apr 4, 2022

Solid Waste Disposal Facilities:

SWF/LF

Facilities permitted by the Solid Waste Management Program in the Environmental Protection Division (EPD) of the Georgia Department of Natural Resources. Includes solid waste collection operations, solid waste disposal facilities (including inert), solid waste transfer stations, closed and in-closure landfills, and collection and transfer stations.

Government Publication Date: Jul 17, 2020

Historic and Current Landfills through 1999:

LANDFILLS

A list of current and historic landfills made available by the Georgia Department of Natural Resources Environmental Protection Division (EPD), Geologic Survey Branch. Includes permitted, regulated landfills, others are older landfills that elected to close when it became a regulatory requirement of the state of Georgia to obtain a solid waste disposal permit.

Government Publication Date: Dec 31, 1999

Leaking Underground Storage Tanks:

LUST

A list of Leaking Underground Storage Tanks (LUSTs). The Underground Storage Tank (UST) Management Program is responsible for ensuring operational compliance and cleanup of leaks from registered UST systems.

Government Publication Date: Jan 6, 2022

Delisted Leaking Storage Tanks:

DELISTED LST

This database contains a list of leaking storage tank sites that were removed from the Underground Storage Tank (UST) Management Program.

Government Publication Date: Jan 6, 2022

Underground Storage Tanks:

UST

A list of Underground Storage Tanks including information on owner, facility and tank details. This data is collected by the Underground Storage Tank Management Program in the Environmental Protection Division (EPD) of the Georgia Department of Natural Resources (DNR).

Government Publication Date: Jan 6, 2022

Delisted Storage Tanks:

DTNK

A list of sites which once appeared on - and have since been removed from - the list of storage tanks made available by the Underground Storage Tank Management Program in the Environmental Protection Division (EPD) of the Georgia Department of Natural Resources (DNR).

Government Publication Date: Jan 6, 2022

Institutional Controls (Public Record List):

INST

Georgia does not have a centralized database which provides detailed information on the specific instruments used to establish institutional controls (ICs). Institutional control requirements vary depending upon the regulatory status of the property, the time period when the limitation of liability was issued, and the nature of the risk reduction certification. This list includes sites at which formal institutional controls are required: properties listed on the Hazardous Site Inventory (HSI) which are not certified to residential risk reduction standards. The IC may follow the requirements of the Rules for Hazardous Site Response, or for more recent decisions, may use environmental covenants. This public record list is maintained by the Environmental Protection Division (EPD) of the Georgia Department of Natural Resources.

Government Publication Date: Mar 24, 2022

Uniform Environmental Covenants:

AUL

List of properties subject to Uniform Environmental Covenants (UECs), made available by the Environmental Protection Division (EPD) of the Georgia Department of Natural Resources. Certain properties within Georgia have been designated as needing corrective action due to the presence of hazardous wastes, hazardous constituents, or hazardous substances regulated under state law. In some instances, UECs are implemented to protect public and environmental receptors from exposure to those substances that remain in soil and/or groundwater. This is accomplished through permanent controls and restrictions on property usage; compliance is required under Georgia's Uniform Environmental Covenants Act, O.C.G.A. § 44-16-1 et. seq., which became effective on July 1, 2008.

Government Publication Date: Mar 10, 2022

Voluntary Remediation Program:

VCP

List of Voluntary Remediation Program Applications, made available by the Environmental Protection Division (EPD) of the Georgia Department of Natural Resources. Georgia's Voluntary Remediation Program Act, created to encourage voluntary investigation and remediation of contaminated properties, became effective on June 1, 2009.

Government Publication Date: May 13, 2022

Brownfields Public Record List:

BROWNFIELDS

The Georgia Brownfields Public Record lists properties under the Hazardous Site Reuse and Redevelopment Act (Georgia's brownfields statute) which have been proposed for a response action, have response actions underway, or have completed response actions. This list is maintained by the Environmental Protection Division (EPD) of the Georgia Department of Natural Resources.

Government Publication Date: Mar 24, 2022

Tribal

Leaking Underground Storage Tanks (LUSTs) on Indian Lands:

INDIAN LUST

LUSTs on Tribal/Indian Lands in Region 4, which includes Georgia. There are no LUST records in Georgia at this time.

Government Publication Date: Oct 14, 2017

Underground Storage Tanks (USTs) on Indian Lands:

INDIAN UST

USTs on Tribal/Indians in Region 4, which includes Georgia. There are no UST records in Georgia at this time.

Government Publication Date: Oct 14, 2017

Delisted Tribal Leaking Storage Tanks:

DELISTED ILST

Leaking Underground Storage Tank facilities which have been removed from the Regional Tribal LUST lists made available by the EPA.

Government Publication Date: Oct 12, 2021

Delisted Tribal Underground Storage Tanks:

DELISTED IUST

Underground Storage Tank facilities which have been removed from the Regional Tribal UST lists made available by the EPA.

Government Publication Date: Oct 13, 2021

County

No County standard environmental record sources available for this State.

Additional Environmental Record Sources

Federal

Facility Registry Service/Facility Index:

FINDS/FRS

The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the Environmental Protection Agency (US EPA).

Government Publication Date: Nov 2, 2020

Toxics Release Inventory (TRI) Program:

TRIS

The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment.

Government Publication Date: Aug 24, 2021

Perfluorinated Alkyl Substances (PFAS) Releases:

PFAS TRI

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a Per- or polyfluorinated alkyl substance (PFAS) included in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances. The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment.

Government Publication Date: Aug 24, 2021

PFOA/PFOS Contaminated Sites:

PFAS NPL

List of sites where PFOA or PFOS contaminants have been found in drinking water or soil. Made available by the Federal Environmental Protection Agency (EPA).

Government Publication Date: Jan 11, 2022

Perfluorinated Alkyl Substances (PFAS) Water Quality:

PFAS WATER

The Water Quality Portal (WQP) is a cooperative service sponsored by the United States Geological Survey (USGS), the Environmental Protection Agency (EPA), and the National Water Quality Monitoring Council (NWQMC). This listing includes records from the Water Quality Portal where the characteristic (environmental measurement) is in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances.

Government Publication Date: Jul 20, 2020

SSEHRI PFAS Contamination Sites:

PFAS SSEHRI

This PFAS Contamination Site Tracker database is compiled by the Social Science Environmental Health Research Institute (SSEHRI) at Northeastern University. According to the SSEHRI, the database records qualitative and quantitative data from each known site of PFAS contamination, including timeline of discovery, sources, levels, health impacts, community response, and government response. The goal of this database is to compile information and support public understanding of the rapidly unfolding issue of PFAS contamination. All data presented was extracted from government websites, news articles, or publicly available documents, and this is cited in the tracker. Disclaimer: The source conveys this database undergoes regular updates as new information becomes available, some sites may be missing and/or contain information that is incorrect or outdated, as well as their information represents all contamination sites SSEHRI is aware of, not all possible contamination sites. This data is not intended to be used for legal purposes. Limited location details are available with this data. Access the following for the most current informations <https://pfasproject.com/pfas-contamination-site-tracker/>

Government Publication Date: Dec 12, 2019

National Response Center PFAS Spills:

ERNS PFAS

National Response Center (NRC) calls from 1990 to the most recent complete calendar year where there is indication of Aqueous Film Forming Foam (AFFF) usage. NRC calls may reference AFFF usage in the "Material Involved" or "Incident Description" fields. Data made available by the US Environmental Protection Agency (EPA). Disclaimer: dataset may include initial or misidentified incident data not yet validated or investigated by a federal/state response agency.

Government Publication Date: Feb 23, 2022

Hazardous Materials Information Reporting System:

HMIRS

US DOT - Department of Transportation Pipeline and Hazardous Materials Safety Administration (PHMSA) Incidents Reports Database taken from Hazmat Intelligence Portal, U.S. Department of Transportation.

Government Publication Date: Sep 1, 2020

National Clandestine Drug Labs:

NCDL

The U.S. Department of Justice ("the Department") provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Nov 22, 2021

Toxic Substances Control Act:

TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.

The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI).

Government Publication Date: Apr 11, 2019

Hist TSCA:

HIST TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.

The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.

Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing:

FTTS ADMIN

An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing:

[FTTS INSP](#)

An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List:

[PRP](#)

Early in the cleanup process, the Environmental Protection Agency (EPA) conducts a search to find the potentially responsible parties (PRPs). EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site.

Government Publication Date: Mar 30, 2022

State Coalition for Remediation of Drycleaners Listing:

[SCRD DRYCLEANER](#)

The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS):

[ICIS](#)

The Integrated Compliance Information System (ICIS) is a system that provides information for the Federal Enforcement and Compliance (FE&C) and the National Pollutant Discharge Elimination System (NPDES) programs. The FE&C component supports the Environmental Protection Agency's (EPA) Civil Enforcement and Compliance program activities. These activities include Compliance Assistance, Compliance Monitoring and Enforcement. The NPDES program supports tracking of NPDES permits, limits, discharge monitoring data and other program reports.

Government Publication Date: Jan 15, 2022

Drycleaner Facilities:

[FED DRYCLEANERS](#)

A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) online search. The Environmental Protection Agency (EPA) tracks facilities that possess NAIC and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: May 5, 2021

Delisted Drycleaner Facilities:

[DELISTED FED DRY](#)

List of sites removed from the list of Drycleaner Facilities (sites in the EPA's Integrated Compliance Information System (ICIS) with NAIC or SIC codes identifying the business as a drycleaner establishment).

Government Publication Date: May 5, 2021

Formerly Used Defense Sites:

[FUDS](#)

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DoD) is responsible for an environmental restoration. This list is published by the U.S. Army Corps of Engineers.

Government Publication Date: May 26, 2021

Former Military Nike Missile Sites:

[FORMER NIKE](#)

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents:

[PIPELINE INCIDENT](#)

A list of flagged pipeline incidents made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types.

Government Publication Date: Jul 7, 2020

Material Licensing Tracking System (MLTS):

[MLTS](#)

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites:

[HIST MLTS](#)

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File:

[MINES](#)

The Master Index File (MIF) contains mine identification numbers issued by the Department of Labor Mine Safety and Health Administration (MSHA) for mines active or opened since 1971. Note that addresses may or may not correspond with the physical location of the mine itself.

Government Publication Date: Nov 2, 2021

Surface Mining Control and Reclamation Act Sites:

[SMCRA](#)

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by the Office of Surface Mining Reclamation and Enforcement (OSMRE) to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of Abandoned Mine Land (AML) impacts, as well as information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Government Publication Date: Dec 18, 2020

Mineral Resource Data System:

[MRDS](#)

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2016

Uranium Mill Tailings Radiation Control Act Sites:

[URANIUM](#)

The Legacy Management Office of the Department of Energy (DOE) manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The L.M. Office manages this database of sites registered under the Uranium Mill Tailings Control Act (UMTRCA).

Government Publication Date: Mar 4, 2017

Alternative Fueling Stations:

[ALT FUELS](#)

List of alternative fueling stations made available by the US Department of Energy's Office of Energy Efficiency & Renewable Energy. Includes Biodiesel stations, Ethanol (E85) stations, Liquefied Petroleum Gas (Propane) stations, Ethanol (E85) stations, Natural Gas stations, Hydrogen stations, and Electric Vehicle Supply Equipment (EVSE). The National Renewable Energy Laboratory (NREL) obtains information about new stations from trade media, Clean Cities coordinators, a Submit New Station form on the Station Locator website, and through collaborating with infrastructure equipment and fuel providers, original equipment manufacturers (OEMs), and industry groups.

Government Publication Date: Mar 7, 2022

Superfunds Consent Decrees:

[CONSENT DECREES](#)

A list of Superfund consent decrees made available by the Department of Justice, Environment & Natural Resources Division (ENRD).

Government Publication Date: Sep 30, 2018

Registered Pesticide Establishments:

[SSTS](#)

List of active EPA-registered foreign and domestic pesticide-producing and device-producing establishments based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that facilities producing pesticides, active ingredients, or devices be registered. The list of establishments is made available by the EPA.

Government Publication Date: Mar 30, 2022

Polychlorinated Biphenyl (PCB) Notifiers:

[PCB](#)

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: Jan 20, 2022

State

Oil or Hazardous Material Spills or Releases:

[SPILLS](#)

Listing of oil or hazardous materials spills and releases complaints, maintained by the Environmental Protection Division (EPD) of the Georgia Department of Natural Resources.

Government Publication Date: Mar 28, 2022

Dry Cleaning Facilities:

[DRYCLEANERS](#)

List of drycleaning operations that have submitted information to the Air Protection Branch of the Georgia Department of Natural Resources. This list includes drycleaner facilities that use PERC (perchloroethylene) and that responded to the Notification of Compliance Status forms.

Government Publication Date: Dec 6, 2021

Delisted Dry Cleaning Facilities:

[DELISTED DRYCLEANERS](#)

List of sites removed from the drycleaners database made available by the Air Protection Branch of the Georgia Department of Natural Resources.

Government Publication Date: Dec 6, 2021

Tier 2 Report:

[TIER 2](#)

A list of Tier 2 facilities in Georgia. This list is provided by the Georgia Environmental Protection Division (Georgia EPD).

Government Publication Date: Mar 21, 2022

Tribal

No Tribal additional environmental record sources available for this State.

County

No County additional environmental record sources available for this State.

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.


Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.


Appendix C

Topographic Maps



NOT TO SCALE		Project: JCB 6855 6855 Jimmy Carter Blvd Norcross, GA 30071; Gwinnett County	USGS Topographic Map June 13, 2022	
Drawn By: BDM	Date: 6/13/22		 Point to Point Environmental	
Client:				

Topographic Information



Current USGS Topo (2017)

0 0.2 0.4 0.8 Miles



Quadrangle(s): Chamblee,GA; Norcross,GA

Source: USGS 7.5 Minute Topographic Map



Appendix D

Historical Aerial Report



HISTORICAL AERIALS

Project Property: JCB 6855

6855 Jimmy Carter Blvd

Norcross GA 30071

Project No: E220085

Requested By: Point to Point Environmental

Order No: 22051600831

Date Completed: May 18,2022

Aerial Maps included in this report are produced by the sources listed above and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property. ERIS provides no warranty of accuracy or liability. The information contained in this report has been produced using aerial photos listed in above sources by ERIS Information Inc. (in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS'. The maps contained in this report do not purport to be and do not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com




Date	Source	Scale	Comments
2019	United States Department of Agriculture	1" = 500'	
2017	United States Department of Agriculture	1" = 500'	
2015	United States Department of Agriculture	1" = 500'	
2013	United States Department of Agriculture	1" = 500'	
2010	United States Department of Agriculture	1" = 500'	
2009	United States Department of Agriculture	1" = 500'	
2007	United States Department of Agriculture	1" = 500'	
2006	United States Department of Agriculture	1" = 500'	
2005	United States Department of Agriculture	1" = 500'	
1999	United States Geological Survey	1" = 500'	
1993	United States Geological Survey	1" = 500'	
1982	United States Geological Survey	1" = 500'	
1972	Agricultural Stabilization & Conserv. Service	1" = 500'	
1968	United States Geological Survey	1" = 500'	
1960	Agricultural Stabilization & Conserv. Service	1" = 500'	
1952	United States Air Force	1" = 500'	
1940	Agricultural Stabilization & Conserv. Service	1" = 500'	Adjacent Frame Unavailable
1938	Agricultural Stabilization & Conserv. Service	1" = 500'	

Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com





one inch




Year: 2019
Source: USDA
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 2017
Source: USDA
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831






Year: 2015
Source: USDA
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 2013
Source: USDA
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 2010
Source: USDA
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 2009
Source: USDA
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 2007
Source: USDA
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 2006
Source: USDA
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 2005
Source: USDA
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 1999
Source: USGS
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 1993
Source: USGS
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 1982
Source: USGS
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831






Year: 1972
Source: ASCS
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 1968
Source: USGS
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831



one inch



Year: 1960
Source: ASCS
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 1952
Source: USAF
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831





Year: 1940 Address: 6855 Jimmy Carter Blvd, Norcross, GA
Source: ASCS Approx Center: -84.2370447,33.9416822
Scale: 1" = 500'
Comment: Adjacent Frame Unavailable

Order No: 22051600831





Year: 1938
Source: ASCS
Scale: 1" = 500'
Comment:

Address: 6855 Jimmy Carter Blvd, Norcross, GA
Approx Center: -84.2370447,33.9416822

Order No: 22051600831



Appendix E

Historical City Directory Report



CITY DIRECTORY

Project Property: *JCB 6855
6855 Jimmy Carter Blvd
Norcross, GA 30071*

Project No: *E220085*

Requested By: *Point to Point Environmental*

Order No: *22051600831*

Date Completed: *May 23, 2022*

Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com



May 23, 2022
RE: CITY DIRECTORY RESEARCH
6855 Jimmy Carter Blvd
Norcross,GA 30071

Thank you for contacting ERIS for an City Directory Search for the site described above. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. We have provided the nearest addresses(s) when adjacent addresses are not listed. If we have searched a range of addresses, all addresses in that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on more highly developed areas. Newly developed areas may be covered in the more recent years, but the older directories will tend to cover only the "central" parts of the city. To complete the search, we have either utilized the ACPL, Library of Congress, State Archives, and/or a regional library or history center as well as multiple digitized directories. These do not claim to be a complete collection of all reverse listing city directories produced.

ERIS has made every effort to provide accurate and complete information but shall not be held liable for missing, incomplete or inaccurate information. To complete this search we used the general range(s) below to search for relevant findings. If you believe there are additional addresses or streets that require searching please contact us at 866-517-5204.

Search Criteria:

6700-6900 of Jimmy Carter Boulevard

Search Notes:

Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com





Search Results Summary

Date	Source	Comment
2020	DIGITAL BUSINESS DIRECTORY	
2016	DIGITAL BUSINESS DIRECTORY	
2012	DIGITAL BUSINESS DIRECTORY	
2008	DIGITAL BUSINESS DIRECTORY	
2005-06	HAINES	
2001	HAINES	
1998	HAINES	
1994	HAINES	
1992	HAINES	
1987	HAINES	
1982	HAINES	
1977	HAINES	
1972	HAINES	
1967	POLKS	
1964	POLKS	

Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com



133 total records. Part 1 of 3

6665 AMER RUGS INC...CARPET & RUG-DISTRIBUTORS (WHLS)
 6665 AMER RUGS INC...CARPET & RUGMANUFACTURERS
 6665 WOODSTONE CABINETRY...KITCHEN REMODELING & PLANNING SVC
 6695 ATLANTA OFFICE FURNITURE...FURNITURE-DEALERS-RETAIL
 6695 GEORGIAN STONE INC...GRANITE (WHLS)
 6695 H M STORE FIXTURE RESTAURANT...FEDERAL GOVERNMENT CONTRACTORS
 6695 H M STORE FIXTURE RESTAURANT...SHOW CASES-MFRS
 6695 HANMI COMMERCIAL INC...NONCLASSIFIED ESTABLISHMENTS
 6695 MARTIAL ARTS GROUP...MARTIAL ARTS INSTRUCTION
 6695 PANDA KITCHEN BATH...KITCHEN CABINETS & EQUIPMENT-HOUSEHOLD
 6725 ATLAS NATIONAL CORP...RAGS (WHLS)
 6725 ATLAS NATIONAL CORP...SAFETY EQUIPMENT & CLOTHING (WHLS)
 6725 BEAUTY ELEMENTZ...BEAUTY SALONS
 6725 BEAUTY ELEMENTZ...HEALTH SPAS
 6725 GEORGIA OAK FLOOR...FLOOR MATERIALS
 6725 LABEL Z APPAREL CO...APPAREL & GARMENTS-RETAIL
 6725 ONESOURCE OFFICE FURNITURE INC...FURNITURE-DEALERS-RETAIL
 6725 SEVEN SEAS SECURITY LLC...SECURITY CONTROL EQUIP & SYSTEMS-WHLS
 6725 TANDY LEATHER FACTORY...LEATHER GOODS-DEALERS
 6755 BLAND ENTERPRISES...STORE FIXTURES (WHLS)
 6755 GLOBAL SERVICES INC...SERVICES NEC
 6755 PARADISE GRANITE MARBLE...MARBLE CONTRACTORS
 6760 CHOICE CARE OCCUPATIONAL MDCCN...WORKMEN'S COMPENSATION CONSULTANTS
 6760 CHOICE CARE OCCUPATIONAL MDCCN...REHABILITATION SERVICES
 6825 ALLSTATE INSURANCE...INSURANCE
 6825 ANOINTED VISION...NONCLASSIFIED ESTABLISHMENTS
 6825 ATLANTA PAVING-CONCRETE CONSTR...GENERAL CONTRACTORS
 6825 CET MEDICAL...CLINICS
 6825 CITY OF HOPE CHURCH...CHURCHES
 6825 CLINICA MEDICA DOCTOR VIZCARRA...CLINICS
 6825 DATAFORENSICS LLC...CONSTRUCTION COMPANIES
 6825 DATAFORENSICS LLC...COMPUTER SOFTWARE
 6825 DATAFORENSICS LLC...COMPUTER SERVICES
 6825 DATAFORENSICS LLC...FEDERAL GOVERNMENT CONTRACTORS
 6825 DATAFORENSICS LLC...DATA PROCESSING SOFTWARE
 6825 DOT.COM LENDING SVC...REAL ESTATE LOANS
 6825 GEORGE TOMAS HOMES...HOME BUILDERS
 6825 HEALTHWORX OCCUPATIONAL...NONCLASSIFIED ESTABLISHMENTS
 6825 HIRE VELOCITY...EXECUTIVE SEARCH CONSULTANTS
 6825 HIRE VELOCITY...EMPLOYMENT AGENCIES & OPPORTUNITIES
 6825 ISAAC BROTHERS TRNSPRTN INC...TRUCKING
 6825 IVY DENTAL LAB...LABORATORIES-DENTAL
 6825 LEGACY BUSINESS CONSULTING...BUSINESS MANAGEMENT CONSULTANTS
 6825 MARTIN GARAGE DOOR PROS...DOORS-GARAGE
 6825 MAXIM INTEGRATED...SEMICONDUCTOR DEVICES (MFRS)
 6825 MAXITRANSFERS CORP...MONEY TRANSFER SERVICE
 6825 MEDLINK EMS...EMERGENCY MEDICAL & SURGICAL SERVICE
 6825 MEHA ENGINEERING...ENGINEERS
 6825 MILLIONAIRE TEAM SOUTH LLC...RECORDING STUDIOS
 6825 MORRIS E HARRISON ASSOC...NONCLASSIFIED ESTABLISHMENTS
 6825 OCCUPATIONAL HEALTHWORX...OCCUPATIONAL THERAPISTS
 6825 OFFICE CLIP...DATA PROCESSING SOFTWARE
 6825 OPTIMUM TAX FINANCIAL...TAX RETURN PREPARATION & FILING
 6825 PATEL, KRISHNA S PA...PHYSICIANS ASSISTANTS
 6825 RADIO INFORMACION INC...FEDERAL GOVERNMENT CONTRACTORS
 6825 RADIO INFORMACION INC...RADIO STATIONS & BROADCASTING COMPANIES
 6825 SCOTT, STEVE CHRIS PT...PHYSICAL THERAPISTS
 6825 SITE TRUSTEE LLC...WEBSITE DESIGN SERVICE
 6825 SOFT TRENDS LLC...COMPUTER-SOFTWARE DEVELOPERS
 6825 TECH COMM...CELLULAR TELEPHONES (SERVICES)
 6825 TECH SCIENCE PRESS...PERIODICALS-PUBLISHING & PRINTING (MFRS)
 6825 TIMEDOX...NONCLASSIFIED ESTABLISHMENTS
 6825 VIZCARRA-FALLA, LUIS RAFAEL MD...PHYSICIANS & SURGEONS
 6855 BURGESS CONSULTING...CONSULTANTS-BUSINESS NEC

Part 2 of 3

6855 KIMLEY-HORN ASSOC INC...ENGINEERING
 6855 LEN MAR INC...NONCLASSIFIED ESTABLISHMENTS
 6855 MICHAEL R MARTIN PC...NONCLASSIFIED ESTABLISHMENTS
 6855 MICHAEL R MARTIN PC...ATTORNEYS
 6855 MOBILE WORLD...NONCLASSIFIED ESTABLISHMENTS
 6855 MTM UNIVERSE...NONCLASSIFIED ESTABLISHMENTS
 6855 TAYLOR HERNAN...RESIDENTIAL
 6855 TAYLOR LEE ASSOC LLC...IMMIGRATION & NATURALIZATION SERVICES
 6859 CAPTAIN D'S SEAFOOD...RESTAURANTS
 6865 PET SUITES RESRT-SPA-NORCROSS...HOTELS & MOTELS
 6865 PETSUITES NORCROSS...PET BOARDING SITTING & KENNELS
 6865 PETSUITES NORCROSS...HOTELS & MOTELS
 6875 ALL AMERICAN SEMICONDUCTOR...SEMICONDUCTOR DEVICES (MFRS)
 6875 DENARII PAYMENT INC...EMPLOYEE BENEFIT CONSULTANTS
 6875 EDWARDS BAKING CO...BAKERS-RETAIL
 6875 RACETRAC...CONVENIENCE STORES
 6895 ZAXBY'S...RESTAURANTS
 7000 BARBER SHOP SALON...BEAUTY SALONS
 7000 ELDORADO SUPERMARKET...GROCERS-RETAIL
 7000 ELDORADO SUPERMARKET...CONVENIENCE STORES
 7005 MIDAS AUTO SVC EXPERTS...AUTOMOBILE REPAIRING & SERVICE
 7040 BLESSED AFRICAN MARKET...AFRICAN GOODS-RETAIL
 7040 CHEFS ON WHEELS...WHEELS & WHEEL COVERS
 7040 ING WIRELESS...CELLULAR TELEPHONES (SERVICES)
 7040 NIKKI'S ITALIAN ICES...MOBILE CONCESSIONS
 7040 SAIGON CAFE...RESTAURANTS
 7040 TINA'S ALTERATIONS...ALTERATIONS-CLOTHING
 7044 WAFFLE HOUSE...RESTAURANTS
 7046 DEKRA EMISSION CHECK INC...AUTOMOBILE EMISSION TESTING
 7046 DEKRA EMISSION CHECK INC...AUTOMOBILE INSPECTION STATIONSNEW/USED
 7046 EMMISSIONS CHECK...AUTOMOBILE MOTOR REBUILDING
 7046 EMMISSIONS CHECK...ENGINES-REBUILDING & EXCHANGING
 7050 ABBEY INSURANCE SVC INC...INSURANCE
 7050 AHMED, HANNAN DC...CHIROPRACTORS DC
 7050 AHMED, HANNAN DC...SPORTS MEDICINE & INJURIES
 7050 AHMED, HANNAN DC...MASSAGE THERAPISTS
 7050 ALWAYS CUTTING...COMPUTER TRAINING
 7050 ATLANTA INTERNATIONAL TRAVEL...TRAVEL AGENCIES & BUREAUS
 7050 BUDDY BEAUTY MART...BEAUTY SALONS-EQUIPMENT & SUPLS (WHLS)
 7050 CITY WIRELESS...CELLULAR TELEPHONES (SERVICES)
 7050 DEKRA AUTOMOBIL GMBH...NONCLASSIFIED ESTABLISHMENTS
 7050 ENVIOS LA FAMILIA PERUANA...EXPORTERS (WHLS)
 7050 FAMILY DOLLAR STORE...VARIETY STORES
 7050 HR BLOCK...TAX RETURN PREPARATION & FILING
 7050 I AM HAIR STUDIO...BEAUTY SALONS
 7050 KRUTI INC...NONCLASSIFIED ESTABLISHMENTS
 7050 LA FITNESS...HEALTH CLUBS STUDIOS & GYMNASIUMS
 7050 MANE PRIORITY BARBER SHOP...BARBERS
 7050 MEXIVEN MULTISERVICIOS...ALL OTHER PROFESSIONAL, SCIENTIFIC/TECHNICAL SVCS
 7050 NAILS MORE INC...MANICURING
 7050 OLAN COMPREHENSIVE HEALTH CARE...CLINICS
 7050 POPEYES LOUISIANA KITCHEN...RESTAURANTS
 7050 PRO DRIVERS...TRUCK DRIVER-LEASING
 7050 PRO DRIVERS...EMPLOYMENT CONTRACTORSTEMPORARY HELP
 7050 PROGRESSIVE INSURANCE...INSURANCE
 7050 RINCONCITO CENTRO AMERICANO...RESTAURANTS
 7050 TURN KEY RENOVATIONS...REMODELING & REPAIRING BLDG CONTRACTORS
 7050 URBAN CLOTHING...MEN'S CLOTHING & FURNISHINGS-RETAIL
 7055 SIMONIZ CAR WASH...CAR WASHING & POLISHING
 7065 EXTENDED STAY AMERICA...HOTELS & MOTELS
 7070 MC DONALD'S...RESTAURANTS
 7075 CROWNE SPORTS BAR GRILL...BARS
 7085 ALAMO RENT-A-CAR...AUTOMOBILE RENTING
 7085 ANDY AGEE STATE FARM...INSURANCE
 7085 NATIONAL CAR RENTAL...AUTOMOBILE RENTING
 7095 ALL TUNE LUBE NORCROSS...AUTOMOBILE REPAIRING & SERVICE

Part 3 of 3

7095 NORTH ATLANTA AUTOMOTIVE...AUTOMOBILE REPAIRING & SERVICE

165 total records. Part 1 of 3

6600 PEACE INDUSTRY GROUP USA INC...WHOLESALE
6624 NATIONAL SUPPLY...UNIFORM SUPPLY SERVICE
6624 NATIONAL SUPPLY...CLEANERS & DYERS SUPPLIES (WHLS)
6654 MOTOR WHOLESALE INC...ELECTRIC MOTORS-DLRS/REPAIRING (WHLS)
6654 SAFELITE AUTO GLASS...GLASS-AUTO PLATE & WINDOW & ETC
6654 SAFELITE AUTO GLASS...AUTOMOBILE GLASS-SERVICE & INSTALLATION
6665 AMER RUG...CARPET & RUG DEALERS-NEW
6679 KYS INTERNATIONAL...NONCLASSIFIED ESTABLISHMENTS
6683 LEADING LASER TECHNOLOGIES...NONCLASSIFIED ESTABLISHMENTS
6684 JUST CLAMPS...WOODWORKERS
6684 PEACHTREE WOODWORKING SUPPLY...WOODWORKERS
6684 SPECTRA CONTRACT FLOORING...CARPET & RUG-MANUFACTURERS
6684 SPECTRA CONTRACT FLOORING...FLOOR LAYING REFINISHING &
6684 RESURFACING
6684 TRI MARK CENTURY CONCEPTS...APPLIANCES-HOUSEHOLD-MAJOR-DEALERS
6695 ATLANTA OFFICE FURNITURE...FEDERAL GOVERNMENT CONTRACTORS
6695 ATLANTA OFFICE FURNITURE...OFFICE FURNITURE & EQUIP-DEALERS (WHLS)
6695 GEORGIAN STONE INC...GRANITE (WHLS)
6695 GLOBAL FREIGHT LIQUIDATORS...FURNITURE-DEALERS-RETAIL
6695 H M STORE FIXTURE & RESTAURANT...SHOW CASES (WHLS)
6695 H M STORE FIXTURE & RESTAURANT...SHOW CASES-MFRS
6695 MARTIAL ARTS GROUP...MARTIAL ARTS INSTRUCTION
6695 PANDA KITCHEN & BATH...KITCHEN CABINETS & EQUIPMENT-HOUSEHOLD
6702 BRAMBLE NOW...FURNITURE-DEALERS-WHOLESALE
6702 DUTCHMAN'S...NONCLASSIFIED ESTABLISHMENTS
6725 ATLANTIC OFFICE FURNITURE...OFFICE FURNITURE & EQUIP-USED
6725 ATLANTIC OFFICE FURNITURE...OFFICE FURNITURE & EQUIP-DEALERS (WHLS)
6725 ATLAS NATIONAL CORP...RAGS (WHLS)
6725 ATLAS NATIONAL CORP...NONCLASSIFIED ESTABLISHMENTS
6725 BRANDON'S PRINTING COMMERCIAL...PRINTERS (MFRS)
6725 GEORGIA OAK FLOOR DISTRIBUTORS...FLOOR MATERIALS
6725 GEORGIA OAK FLOOR DISTRIBUTORS...FLOOR MATERIALS-WHOLESALE
6725 J S SCOTT CORP...NONCLASSIFIED ESTABLISHMENTS
6725 LABEL Z APPAREL CO...APPAREL & GARMENTS-RETAIL
6725 SEVEN SEAS SECURITY LLC...SECURITY CONTROL EQUIP & SYSTEMS-WHLS
6725 TANDY LEATHER FACTORY...LUGGAGE & LEATHER GOODS STORES
6725 ZHIZHENG INDUSTRIAL TRADE USA...NONCLASSIFIED ESTABLISHMENTS
6734 FRUGAL FABRICS & DESIGN...DRAPERIES & CURTAINS-RETAIL/CUSTOM MADE
6734 FRUGAL FABRICS & DESIGNS INC...FABRIC SHOPS
6734 TUPPERWARE...PLASTIC CONTAINERS (WHLS)
6755 BLAND ENTERPRISES...DISPLAY FIXTURES & MATERIALS (WHLS)
6755 PARADISE GRANITE & MARBLE...GRANITE (WHLS)
6760 ACTIX COMPUTER RENTALS...COMPUTERS-RENTING & LEASING
6760 AID INTERNATIONAL...NONCLASSIFIED ESTABLISHMENTS
6760 AMC GLOBAL COMMUNICATIONS...COMMUNICATIONS
6760 AMERICAN INTERNATIONAL COMMS...TELEPHONE EQUIPMENT & SUPPLIES
6760 ANDY'S BRITE IDEAS...CHRISTMAS LIGHTS & DECORATIONS
6760 AUTO GLASS FITTERS...AUTOMOBILE GLASS-SERVICE & INSTALLATION
6760 CHOICE CARE OCCUPATIONAL MDCCN...WORKMEN'S COMPENSATION
6760 CONSULTANTS
6760 P C WAREHOUSE...COMPUTERS-NETWORKING
6760 REDEMERS MEDICAL CTR...CLINICS
6796 AMB INTERNATIONAL CO LTD...COMPUTERS-WHOLESALE
6796 AMERICAN FREIGHT...TRANSPORTATION CONSULTANTS
6796 AMERICAN FREIGHT...FURNITURE-DEALERS-RETAIL
6796 AVANTI MOTORS INC...AUTOMOBILE DEALERS-USED CARS
6825 ALLSTATE INSURANCE...INSURANCE
6825 ANOINTED VISION...NONCLASSIFIED ESTABLISHMENTS
6825 BRIGHT UNLIMITED LLC...CARPET & RUG CLEANERS
6825 C4 CONNECTIONS...UNCLASSIFIED ESTABLISHMENTS
6825 CET MEDICAL...CLINICS
6825 CLINICA MEDICA DOCTOR VIZCARRA...CLINICS
6825 DATA FORENSICS...FEDERAL GOVERNMENT CONTRACTORS

Part 2 of 3

6825 DATAFORENSICS LLC...COMPUTER SOFTWARE
 6825 DOT.COM LENDING SVC...REAL ESTATE LOANS
 6825 HEALTHWORX OCCUPATIONAL...UNCLASSIFIED ESTABLISHMENTS
 6825 HIRE VELOCITY...EXECUTIVE SEARCH CONSULTANTS
 6825 IVY DENTAL LAB...LABORATORIES-DENTAL
 6825 LEGACY PAINTED SYSTEMS...UNCLASSIFIED ESTABLISHMENTS
 6825 MARTIN GARAGE DOOR PROS...OTHER BUILDING MATERIAL DEALERS
 6825 MATTHEW P HOGAN & ASSOC...NONCLASSIFIED ESTABLISHMENTS
 6825 MAXIM INTEGRATED...SEMICONDUCTOR DEVICES (MFRS)
 6825 MAXITRANSFERS CORP...MONEY TRANSFER SERVICE
 6825 MCCAIN, JOSEPH AGT...INSURANCE
 6825 MOBILE WORLD...CELLULAR TELEPHONES (SERVICES)
 6825 MONEY STORE...ALL OTHER GENERAL MERCHANDISE STORES
 6825 NORCROSS WELLNESS ASSOC LLC...WELLNESS PROGRAMS
 6825 NORCROSS WHOLESALE...WHOLESALE
 6825 OCCUPATIONAL HEALTHWORX...OCCUPATIONAL THERAPISTS
 6825 OFFICE CLIP...COMPUTER SERVICES
 6825 RADIO INFORMACION INC...RADIO STATIONS & BROADCASTING COMPANIES
 6825 TECH COMM...CELLULAR TELEPHONES (SERVICES)
 6825 TECH SCIENCE PRESS...PERIODICAL PUBLISHERS
 6836 PETER MALLEN...RESIDENTIAL
 6854 SAFELITE AUTO GLASS...GLASS-AUTO PLATE & WINDOW & ETC
 6855 AMERICAN FOAM...NONCLASSIFIED ESTABLISHMENTS
 6855 BURGESS CONSULTING...CONSULTANTS-BUSINESS NEC
 6855 FEDERAL BILLING INVESTIGATION...INVESTIGATORS
 6855 KENWOOD AUTHORIZED SALES & SVC...GENERAL MERCHANDISE-RETAIL
 6855 MED SOUTH SURGICAL INC...UNCLASSIFIED ESTABLISHMENTS
 6855 MICHAEL R MARTIN PC...NONCLASSIFIED ESTABLISHMENTS
 6855 MOBILE WORLD...NONCLASSIFIED ESTABLISHMENTS
 6855 TAYLOR HERNAN...RESIDENTIAL
 6855 TAYLOR, CHRIS...ATTORNEYS
 6866 M JAY'S SPECIALTY BAKED FOODS...BAKERS-RETAIL
 6875 ALL AMERICAN SEMICONDUCTOR...SEMICONDUCTOR DEVICES (MFRS)
 6875 DENARII PAYMENT INC...HUMAN RESOURCES CONSULTING SERVICES
 6875 RACETRAC...CONVENIENCE STORES
 6895 ZAXBY'S...FULL-SERVICE RESTAURANTS
 6920 NEW LIFE SEVENTH-DAY ADVENTIST...CHURCHES
 6920 WORLD CHANGERS MINISTRIES...RELIGIOUS ORGANIZATIONS
 6925 PLATINUM FEDERAL CREDIT UNION...CREDIT UNIONS
 7000 ATM...AUTOMATED TELLER MACHINES
 7000 ELDORADO SUPERMARKET...GROCERS-RETAIL
 7000 LA PLAZITA...NONCLASSIFIED ESTABLISHMENTS
 7000 TOMASA...NONCLASSIFIED ESTABLISHMENTS
 7005 MECHANICS NORCROSS HTG & AIR...AUTOMOBILE REPAIRING & SERVICE
 7005 MIDAS AUTO SVC EXPERTS...AUTOMOBILE REPAIRING & SERVICE
 7005 MIDAS AUTO SVC EXPERTS...MUFFLERS & EXHAUST SYSTEMS-ENGINE
 7035 HOLIDAY INN EXPRESS...HOTELS & MOTELS
 7040 BLESSED AFRICAN MARKET...AFRICAN GOODS-RETAIL
 7040 BOILING CRAB...FULL-SERVICE RESTAURANTS
 7040 ING WIRELESS...CELLULAR TELEPHONES (SERVICES)
 7040 SAIGON CAFE...RESTAURANTS
 7040 TINA'S ALTERATIONS...ALTERATIONS-CLOTHING
 7044 WAFFLE HOUSE...FOODS-CARRY OUT
 7044 WAFFLE HOUSE...RESTAURANTS
 7046 DEKRA EMISSION CHECK INC...AUTOMOBILE EMISSION TESTING
 7049 CROSSLAND ECONOMY STUDIOS...HOTELS & MOTELS
 7049 HOMESTEAD STUDIO SUITES...FEDERAL GOVERNMENT CONTRACTORS
 7050 A1 FITNESS LLC...UNCLASSIFIED ESTABLISHMENTS
 7050 ABBEY INSURANCE...INSURANCE AGENCIES & BROKERAGES
 7050 ABBEY INSURANCE SVC INC...INSURANCE
 7050 ACE CASH EXPRESS...CHECK CASHING SERVICE
 7050 ACE CASH EXPRESS...PAYDAY LOANS
 7050 AHMED, HANNAN DC...CHIROPRACTORS DC
 7050 ATLANTA INTERNATIONAL TRAVEL...TRAVEL AGENCIES & BUREAUS
 7050 BUDDY BEAUTY MART...BEAUTY SALONS-EQUIPMENT & SUPLS (WHLs)
 7050 CITY WIRELESS...CELLULAR TELEPHONES (SERVICES)

Part 3 of 3

7050 FAMILY DOLLAR STORE...ALL OTHER GENERAL MERCHANDISE STORES
 7050 FEDERAL ASSET SOLUTIONS...NONCLASSIFIED ESTABLISHMENTS
 7050 FOUR PILLARS OF HEALTH...HEALTH SERVICES
 7050 H&R BLOCK...TAX RETURN PREPARATION & FILING
 7050 HAIR OF GLORY...BEAUTY SALONS
 7050 I AM HAIR STUDIO...BEAUTY SALONS
 7050 LA FITNESS...GYMNASIUMS
 7050 LA FITNESS...HEALTH CLUBS STUDIOS & GYMNASIUMS
 7050 MANE PRIORITY BARBER SHOP...BARBERS
 7050 MEXIVEN MULTISERVICIOS...ALL OTHER PROFESSIONAL, SCIENTIFIC/TECHNICAL SVCS
 7050 NAILS 'N MORE...MANICURING
 7050 NATIONWIDE INSURANCE...INSURANCE
 7050 NORTH ATLANTA CHIROPRACTIC CTR...OFFICES OF CHIROPRACTORS
 7050 OLAN COMPREHENSIVE HEALTH CARE...CLINICS
 7050 POPEYE'S CHICKEN & BISCUITS...FOODS-CARRY OUT
 7050 POPEYE'S CHICKEN & BISCUITS...RESTAURANTS
 7050 PRO DRIVERS...TRUCK DRIVER-LEASING
 7050 SUPERFICIAL LLC...NONCLASSIFIED ESTABLISHMENTS
 7050 TURN KEY RENOVATIONS...REMODELING & REPAIRING BLDG CONTRACTORS
 7050 U-HAUL NEIGHBORHOOD DEALER...TRAILER RENTING & LEASING
 7050 U-HAUL NEIGHBORHOOD DEALER...TRUCK RENTING & LEASING
 7050 URBAN CLOTHING...MEN'S CLOTHING & FURNISHINGS-RETAIL
 7050 VANCE PERSONNEL LLC...HUMAN RESOURCES CONSULTING SERVICES
 7055 SIMONIZ CAR WASH...CAR WASHING & POLISHING
 7065 EXTENDED STAY AMERICA...HOTELS & MOTELS
 7065 STUDIO PLUS-PEACHTREE CORNERS...FEDERAL GOVERNMENT CONTRACTORS
 7070 MC DONALD'S...FOODS-CARRY OUT
 7070 MC DONALD'S...RESTAURANTS
 7075 GRAND BUFFET...RESTAURANTS
 7085 ANDY AGEE STATE FARM...INSURANCE
 7085 BITES THAI CUISINE...RESTAURANTS
 7085 TRIANGLE RENT A CAR...AUTOMOBILE RENTING
 7095 ALL TUNE LUBE NORCROSS...AUTOMOBILE REPAIRING & SERVICE
 7095 GARAGE DOOR EXPERT...DOORS-GARAGE
 7095 ORDAN REPAIR SHOP...AUTOMOBILE REPAIRING & SERVICE
 7095 ORDHN INC...AUTOMOBILE DEALERS-USED CARS

104 total records. Part 1 of 2

6600 PEACE INDUSTRY GROUP USA INC...MANUFACTURERS
 6624 NATIONAL SUPPLY...CLEANERS & DYERS SUPPLIES (WHLS)
 6654 MOTOR WHOLESALE INC...ELECTRIC MOTORS-DLRS/REPAIRING (WHLS)
 6654 SAFELITE AUTO GLASS...GLASS-AUTO PLATE & WINDOW & ETC
 6654 TRIUMPH AUTO GLASS...GLASS-AUTO PLATE & WINDOW & ETC
 6679 KYS INTL...NONCLASSIFIED ESTABLISHMENTS
 6683 LEADING LASER TECHNOLOGIES...NONCLASSIFIED ESTABLISHMENTS
 6684 JUST CLAMPS...WOODWORKERS
 6684 MIGHT-T-TRACK...WOODWORKERS
 6684 PEACHTREE WOODWORKING SUPPLY...WOODWORKERS
 6684 SPECTRA CONTRACT FLOORING...CARPET & RUG-DISTRIBUTORS (WHLS)
 6695 ATLANTA OFFICE FURNITURE...OFFICE FURNITURE & EQUIP-DEALERS (WHLS)
 6695 GEORGIAN STONE INC...GRANITE (WHLS)
 6695 GLOBAL FREIGHT LIQUIDATORS...FURNITURE-DEALERS-RETAIL
 6695 H M STORE FIXTURE & RESTAURANT...SHOW CASES-MFRS
 6695 MARTIAL ARTS GROUP...MARTIAL ARTS INSTRUCTION
 6695 PANDA KITCHEN & BATH...KITCHEN CABINETS & EQUIPMENT-HOUSEHOLD
 6702 BROOK FURNITURE RENTAL...FURNITURE-RENTING & LEASING
 6725 ATLANTA REAL ESTATE THIS WEEK...COMMERCIAL PRINTING NEC (MFRS)
 6725 ATLANTIC OFFICE FURNITURE...OFFICE FURNITURE & EQUIP-DEALERS (WHLS)
 6725 BRANDON'S PRINTING COMMERCIAL...PRINTERS (MFRS)
 6725 GEORGIA OAK FLOOR DISTRIBUTORS...FLOOR MATERIALS
 6734 SDF INTL...BUSINESS MANAGEMENT CONSULTANTS
 6755 BLAND ENTERPRISES...STORE FIXTURES (WHLS)
 6755 J M CABINET & DESIGN GROUP INC...CABINETS
 6755 WN COMMUNICATIONS...TELEPHONE EQUIPMENT & SYSTEMS-WHOLESALE
 6760 AMC GLOBAL COMMUNICATIONS...COMMUNICATIONS
 6760 AMERICAN INTERNATIONAL COMMS...TELEPHONE EQUIPMENT & SUPPLIES
 6760 ANDY'S BRITE IDEAS...CHRISTMAS LIGHTS & DECORATIONS
 6760 BEREKET TURKISH GROCERY MARKET...GROCERS-ETHNIC FOODS
 6760 REDEMERS MEDICAL CTR...CLINICS
 6760 SUTPHEN, SUSAN...MEDICAL RESEARCH
 6796 AMART ELECTRONICS...ELECTRONIC EQUIPMENT & SUPPLIES-RETAIL
 6796 AMB INTL CO LTD...COMPUTERS-WHOLESALE
 6796 AMERICAN FREIGHT...TRANSPORTATION CONSULTANTS
 6796 AVANTI MOTORS INC...AUTOMOBILE DEALERS-USED CARS
 6825 BRIGHT UNLIMITED LLC...CARPET & RUG CLEANERS
 6825 DATA FORENSICS...FORENSIC CONSULTANTS
 6825 DATAFORENSICS LLC...COMPUTER SOFTWARE
 6825 DOT.COM LENDING SVC...REAL ESTATE LOANS
 6825 HIRE VELOCITY...EXECUTIVE SEARCH CONSULTANTS
 6825 IVY DENTAL LAB...LABORATORIES-DENTAL
 6825 MATTHEW P HOGAN & ASSOC...NONCLASSIFIED ESTABLISHMENTS
 6825 MAXIM INTEGRATED PRODUCTS INC...SEMICONDUCTOR DEVICES (MFRS)
 6825 MAXITRANSFERS CORP...MONEY TRANSFER SERVICE
 6825 OFFICE CLIP...COMPUTER SOFTWARE
 6825 REAL SOFT TECHNOLOGIES LLC...NONCLASSIFIED ESTABLISHMENTS
 6825 TECH COMM...CELLULAR TELEPHONES (SERVICES)
 6825 U BRIGHT...RESIDENTIAL
 6836 PETER MALLEN...RESIDENTIAL
 6854 SAFELITE AUTO GLASS...GLASS-AUTO PLATE & WINDOW & ETC
 6855 AMERICAN FOAM...NONCLASSIFIED ESTABLISHMENTS
 6855 AMERICAN MADE ART...ASSOCIATIONS
 6855 BURGESS CONSULTING...CONSULTANTS-BUSINESS NEC
 6855 EDEC INC...ENGINEERS-ELECTRICAL
 6855 IMAGE STAFFING SVC...PERSONNEL CONSULTANTS
 6855 KENWOOD AUTHORIZED SALES & SVC...GENERAL MERCHANDISE-RETAIL
 6855 MED SOUTH SURGICAL INC...NONCLASSIFIED ESTABLISHMENTS
 6866 MIDDLE EAST BAKING CO...BAKERS-WHOLESALE
 6875 ALL AMERICAN SEMICONDUCTOR...SEMICONDUCTOR DEVICES (MFRS)
 6875 UPS OVERGOODS...NONCLASSIFIED ESTABLISHMENTS
 6920 GEORGIA CLINIC AT PEACHTREE...CLINICS
 6920 GEORGIA CLINIC-PEACHTREE CORS...PHYSICIANS & SURGEONS

Part 2 of 2

6920 WORLD CHANGERS MINISTRIES...RELIGIOUS ORGANIZATIONS
 7000 ELDORADO SUPERMARKET...GROCERS-RETAIL
 7000 LA PLAZITA...NONCLASSIFIED ESTABLISHMENTS
 7005 MIDAS AUTO SVC EXPERTS...AUTOMOBILE REPAIRING & SERVICE
 7035 HOLIDAY INN EXPRESS...HOTELS & MOTELS
 7040 ING WIRELESS...CELLULAR TELEPHONES (SERVICES)
 7040 SAIGON CAFE...RESTAURANTS
 7040 TINA'S ALTERATIONS...ALTERATIONS-CLOTHING
 7044 WAFFLE HOUSE...RESTAURANTS
 7045 RYAN'S GRILL BUFFET & BAKERY...RESTAURANTS
 7045 RYANS...NONCLASSIFIED ESTABLISHMENTS
 7049 HOMESTEAD-STUDIO SUITES...HOTELS & MOTELS
 7050 ABBEY INSURANCE SVC INC...INSURANCE
 7050 ACE CASH EXPRESS...PAYDAY LOANS
 7050 ANGEL MINI MART...CONVENIENCE STORES
 7050 ATLANTA INTERNATIONAL TRAVEL...TRAVEL AGENCIES & BUREAUS
 7050 BUDDY BEAUTY MART...BEAUTY SALONS-EQUIPMENT & SUPPL (WHLS)
 7050 CHINESE SHAOLIN CTR...MARTIAL ARTS INSTRUCTION
 7050 CITY WIRELESS...CELLULAR TELEPHONES (SERVICES)
 7050 DEFENSIVE DRIVING & DUI...DRIVING INSTRUCTION
 7050 DRIVERS LICENSE REINSTATEMENT...DRIVING INSTRUCTION
 7050 ENVIOS LA FAMILIA PERUANA...NONCLASSIFIED ESTABLISHMENTS
 7050 ETERNAL LIGHT ENTERPRISES...PERSONNEL CONSULTANTS
 7050 FOUR PILLARS OF HEALTH...HEALTH SERVICES
 7050 H&R BLOCK...TAX RETURN PREPARATION & FILING
 7050 HAIR OF GLORY...BEAUTY SALONS
 7050 LA FITNESS...HEALTH CLUBS STUDIOS & GYMNASIUMS
 7050 NAILS 'N MORE...MANICURING
 7050 PEACHTREE CORNERS...SHOPPING CENTERS & MALLS
 7050 POPEYE'S CHICKEN & BISCUITS...RESTAURANTS
 7050 PRO DRIVERS...TRUCK DRIVER-LEASING
 7050 TAGGARTS DRIVING SCHOOL...DRIVING INSTRUCTION
 7050 TURN KEY RENOVATIONS...REMODELING & REPAIRING BLDG CONTRACTORS
 7050 U-HAUL NEIGHBORHOOD DEALER...TRUCK RENTING & LEASING
 7050 URBAN CLOTHING...MEN'S CLOTHING & FURNISHINGS-RETAIL
 7055 SIMONIZ CAR WASH...CAR WASHING & POLISHING
 7065 STUDIO PLUS-PEACHTREE CORNERS...HOTELS & MOTELS
 7070 MC DONALD'S...RESTAURANTS
 7075 GRAND BUFFET...RESTAURANTS
 7095 ATLANTIC ROOF DESIGN...ROOFING SERVICE CONSULTANTS

256 total records. Part 1 of 4

6600 LABS...GIFT & NOV SHOPS
 6600 PEACE INDUSTRY GROUP USA INC...DURABLE GOODS NEC
 6600 PETZETAKIS USA INC...WHOL PVC HOSE
 6600 SERVICE ATLANTA 618...SERVICE CENTER
 6624 S E WIRELESS...MISC RETAIL STORES
 6624 SE WIRELESS INC...RADIOTELEPHONE COMMUNICATION
 6624 UNIVERSAL WIRELESS...CELLULAR TELEPHONES-EQUIPMENT & SUPPL
 6624 UNIVERSAL WIRELESS INC...MISC RETAIL STORES
 6624 UNIVERSAL WIRELESS INC...CELLULAR WHOLESALER
 6654 DIAMOND AUTO GLASS...GLASS-AUTO PLATE & WINDOW & ETC
 6654 DIAMOND AUTO GLASS...AUTO GLASS REPLACE
 6654 EL JAROCHO DISTRIBUTORS...WHOLESALES SPECIALTY ITEMS
 6654 TRIUMPH AUTO GLASS...AUTO GLASS REPLACE
 6664 HALCO LIGHTING CORP...LIGHT BULBS & TUBES (WHOLESALE)
 6664 HALCO LIGHTING INC...WHOL ELECTRICAL EQUIPMENT
 6673 PROLINE BILLIARD FACTORY SALES...BILLIARD EQUIPMENT & SUPPLIES
 (WHOL)
 6681 CASH & CARRY OFFICE FURNITURE...RET USED MERCHANDISE RET
 FURNITURE
 6681 OFFICE FURNITURE TODAY...OFFICE FURNITURE & EQUIP-DEALERS (WHOL)
 6684 NORCOM INC...PAPER MILLS
 6684 STANDARD DISTRIBUTING & SUPPLY...DISTRIBUTION SERVICES
 6687 MISSION FOODS...WAREHOUSE
 6695 GEORGIAN STONE CORP...STONE
 6695 GEORGIAN STONE INC...STONE-NATURAL
 6695 GEORGIAN STONE INC...BRICK, STONE, REL MTL
 6695 H M RESTAURANT EQUIPMENT CO...RESTAURANT EQ,SUP NEC
 6695 H M STORE FIXTURE CO...STORE FIXTURES (WHOLESALE)
 6695 H M STORE FIXTURE CO...MET PARTITIONS, FIX
 6695 HM STORE FIXTURES COMPANY...MFG PARTITIONS/FIXTURES-NONWOOD
 6695 IAVIONICS CORP...WHOL COMPUTERS
 6695 OFFICE FURNITURE TODAY...OFF,PUBLIC BLDG FURN
 6695 PANDA KITCHEN & BATH...CABINETS EX CUST MADE
 6695 PANDA KITCHEN & BATH...KITCHEN CABINETS & EQUIPMENT-HOUSEHOLD
 6695 PROLINE BILLIARDS ETC...BILLIARD EQP & SUPS
 6702 ALLTEL...CELLULAR PHONE SVCS
 6702 ALLTEL...GENERAL WAREHOUSE/STORAGE
 6702 AMINDO INC...ANTIQUES-REPRODUCTIONS
 6702 AMINDO INC...ANTIQUES
 6702 BROOK FURNITURE RENTAL...FURNITURE RENTAL
 6702 BROOK FURNITURE RENTAL...FURNITURE-RENTING & LEASING
 6725 ATLANTA REAL ESTATE THIS WEEK...COML PRINTING NEC
 6725 ATLANTIC OFFICE FURNITURE...USED MERCHANDISE
 6725 ATLANTIC OFFICE FURNITURE INC...RET USED MERCHANDISE RET FURNITURE
 6725 BRANDONS PRINTING...LITHO,COML PRINTING
 6725 BRANDONS PRINTING...PRINTERS
 6725 FLYER ALTERNATIVE...LITHO,COML PRINTING
 6725 GEORGIA OAK FLOOR DISTRIBUTORS...HARDWD DIM, FLRG ML
 6725 GEORGIA OAK FLOOR DISTRIBUTORS...FLOOR MATERIALS
 6725 PERFECT COLOR...LITHO,COML PRINTING
 6734 E SQUARE M...NCLASSIFIABLE ESTAB
 6734 E SQUARED M...SYSTEM INTEGRATION SERVICES
 6734 SDF INTL...MGMT CONSULTING
 6755 AMERITEL FINANCIAL SERVICES...BUSINESS SERVICES EQUIPMENT
 RENTAL/LEASING
 6755 BLAND ENTERPRISES...DISPLAY FIXTURES & MATERIALS (WHOLESALE)
 6755 BLAND ENTERPRISES...COMMERCIAL EQP NEC
 6755 BLAND ENTERPRISES INC...WHOLESALE STORE FIXTURES AND EQUIPMENT
 6755 CAL STATE STORE FIXTURES INC...RET ALCOHOLIC BEVERAGES
 6755 POOLE FINANCIAL SERVICES INC...HOLDING COMPANY
 6755 WIN COMMUNICATIONS...TELEPHONE,TELEGRAPHIC
 6755 WIN COMMUNICATIONS...TELEPHONE EQUIPMENT & SYSTEMS-WHOLESALE
 6755 WIN COMMUNICATIONS CORPORATION...WHOL ELECTRONIC
 PARTS/EQUIPMENT MFG TELEPHONE/TELEGRAPH
 6760 AIC...TELEPHONE EQUIPMENT & SUPPLIES
 6760 AMC GLOBAL COMMUNICATIONS...COMMUNICATIONS SVS

Part 2 of 4

6760 AMERICAN INTERNATIONAL COMMUNI...TELEPHONE,COMM EQUIP
 6760 AMERICAN MARBACOM COMMUNITIES...NCLASSIFIABLE ESTAB
 6760 BEREKET TURKISH GROCERY MARKET...GROCERY STORES
 6760 BEREKET TURKISH GROCERY MARKET...GROCERS-RETAIL
 6760 GLOBAL SPECTRUM FOUNDATION INC...NCLASSIFIABLE ESTAB
 6760 GLOBAL SPECTRUM FOUNDATION INC...NONCLASSIFIED ESTABLISHMENTS
 6760 MARBACOM COMMS INC...UNCLASSIFIED
 6760 P C WAREHOUSE...COMPUTER SVS NEC
 6760 P C WAREHOUSE...COMPUTERS-NETWORKING
 6760 PC WAREHOUSE OF GEORGIA INC...VALUE ADDED RESELLER OF
 COMPUTERS COMPUTER PERIPHERALS
 6760 PLASTIKOIL BINDING SYSTEMS GA...UNCLASSIFIED
 6760 TOWER TELECOM USA INC...TELEPHONE COMM
 6760 TOWER TELECOM USA INC...TELECOMMUNICATIONS SERVICES
 6760 WIRELESS CONNECTIONS...CELLULAR TELEPHONES (SERVICES)
 6796 AAA AUTOPARTS USA INC...RET AUTO/HOME SUPPLIES
 6796 AMB INTERNATIONAL CO LTD...WHOLESALE COMPUTER PARTS
 6796 S MOTOR...ELC APPARATUS & EQP
 6825 AMERICAN LANGUAGE SCHOOL INC...SCHOOL/EDUCATIONAL SERVICES
 6825 COMM TECH...RESIDENTIAL
 6825 FELICIA CPA HAIR...RESIDENTIAL
 6825 GRANITE NETWORK INTERNATIONAL...IMPORTER OF GRANITE
 6825 JANE T ST CLAIR...RESIDENTIAL
 6825 MAXIM INTEGRATED PRODUCTS...SEMICONDUCTOR DEVICES
 (MANUFACTURERS)
 6825 MEP DESIGN ENGINEERS INC...ENGINEERING SERVICE
 6825 ONSITE REHAB NORCROSS DRVLL...MEDICAL DOCTORS OFF
 6825 ONSITE REHAB NORCROSS DRVLL...REHABILITATION SERVICES
 6825 TECHNICAL COMM A TOUCH...TELECOMMUNICATION MARKETING
 6825 WELLBNGS OCCPATIONAL HLTH CARE...OCCUPATIONAL HEALTHCARE
 6836 MALLEN INDUSTRIES...FABRICATED TEX PDTS
 6836 MALLEN INDUSTRIES INC...TEXTILE-MANUFACTURERS
 6855 ACCUCARE MEDICAL EQUIPMENT...MEDICAL EQUIP,SUPPS
 6855 AMERICAN FOAM...NCLASSIFIABLE ESTAB
 6855 BLUE SKY TRADING INC...RET MISC GENERAL MERCHANDISE
 6855 BLUE SKY TRADING INC...NCLASSIFIABLE ESTAB
 6855 BURGESS CONSULTING...BUS CONSULTING NEC
 6855 CARRICK CONTRACTING CORP...TRADE CONTRACTOR
 6855 CHALLENGER SPORTS CORP...MEMBERSHIP SPT CLUB
 6855 COLONIAL SERVICES CPA...SERVICES NEC
 6855 COLT SOUTHERN COMMUNICATIONS...COMMUNICATION SERVICES
 6855 COLT SOUTHERN SVC...SERVICES NEC
 6855 DANELLA SE INC...UNCLASSIFIED
 6855 DIVERSAPACK...NCLASSIFIABLE ESTAB
 6855 DIVERSAPACK LLC...FLEXIBLE PACKAGING AND CONTRACT MANUFACTURING
 6855 DRUMMOND CONSULTING LTD...BUS CONSULTING NEC
 6855 FIDELITY 1ST FINANCIAL SVCS...INVESTMENT SERVICES
 6855 GLOBAL MANAGEMENT (NOT INC)...WHOL COMPUTERS/PERIPHERALS REAL
 ESTATE AGENT/MANAGER
 6855 GP BUSINESS CENTER...SECRETARIAL/COURT REPORTING
 6855 JOHN E CPA MCCABE...RESIDENTIAL
 6855 JOHN E MC CABE CPA...ACCOUNTANTS
 6855 KENWOOD AUTHORIZED SALES & SVC...MISC GEN MDSE STRS
 6855 KOCHAN ROBERT...RET RADIO/TV/ELECTRONICS
 6855 LAUNCH FUNDING NETWORK INC...SHORT-TERM BUSINESS CREDIT
 INSTITUTION
 6855 LEXIS PRINTING & FULFILLMENT I...LITHOGRAPHIC COMMERCIAL PRINTING
 6855 MARINE CORP RECRUITING...UNCLASSIFIED
 6855 MOTOROLA...DISCRETE SEMICONDUCTORS
 6855 NEXTEL...CELLULAR PHONE SVCS
 6855 PEACHTREE CORNERS CAFE...EATING PLACE
 6855 REP INC...MANUF AGENTS
 6855 REP INC...MANUFACTURERS-AGENTS & REPRESENTATIVES
 6855 ROBERT KOCHAN...RESIDENTIAL
 6855 ROGER BONDS...RESIDENTIAL
 6855 THG HOLDINGS...EATING PLACES
 6855 THG HOLDINGS...HOLDING COMPANIES (NON-BANK)
 6855 XILINX NOVUS GROUP...WHOL ELECTRONIC PARTS/EQUIPMENT

Part 3 of 4

6875 EDWARDS BAKING CO...RETAIL BAKERIES
 6875 HEIDIS GOURMET SATELLITE OFC...GOURMET FOOD STORES
 6875 IBM...COMPUTER SERVICES
 6875 PURSUANT TECHNOLOGIES INC...SOFTWARE DEVELOPMENT
 6875 UPS OVERGOOD...NONCLASSIFIED ESTABLISHMENTS
 6875 UPS OVERGOODS...NCLASSIFIABLE ESTAB
 6920 AMERICAN HEALTHCHOICE INC...MEDICAL DOCTOR'S OFFICE
 6920 ATLANTA VINEYARD CHURCH...RELIGIOUS ORGANIZ
 6920 ATLANTA VINEYARD CHURCH...RELIGIOUS ORGANIZATION
 6920 DEANNA MD ROY...RESIDENTIAL
 6920 DENTAL ONE ASSOCIATES...OFCSCNLS OF DNTSTS
 6920 GEORGIA CLINIC AT PEACHTREE...MEDICAL GRPS & CLNCS
 6920 GEORGIA CLINIC-PEACHTREE CORN...CARDIOVASCULAR DISEASE
 6920 HARRISON C MD STETLER...RESIDENTIAL
 6920 JULIUS MD AJAYI...RESIDENTIAL
 6920 PEACHTREE CORNERS OCCUPATIONAL...NCLASSIFIABLE ESTAB
 6920 TINA V MD WILLIAMS...RESIDENTIAL
 6920 URGENT CARE...SPECIALTY UNKNOWN
 6920 URGENT CARE...CLINICS
 6920 VINEYARD CHRISTIAN FELLOWSHIP...CHURCHES
 6925 H & R BLOCK FINANCIAL ADVISORS...SECURITY BROKER/DEALER
 6925 WORLD FIBER TECHNOLOGY...NCLASSIFIABLE ESTAB
 7000 BARRIO MUSIC...MUSIC DEALERS
 7000 ELDORADO SUPERMARKET...GROCERY STORES
 7000 ELDORADO SUPERMARKET...RET GROCERIES
 7000 LA PLAZITA...NCLASSIFIABLE ESTAB
 7000 VENEMEX...INSURANCE-AUTOMOBILE
 7005 MIDAS AUTO SVC EXPERTS...GENERAL AUTO REPAIR
 7005 MIDAS AUTO SVC EXPERTS...MUFFLERS & EXHAUST SYSTEMS-ENGINE
 7005 MIDAS MUFFLER...AUTO REPAIR & SERVICE
 7020 J BRAGG...RESIDENTIAL
 7035 BEST WESTERN...HOTEL/MOTEL OPERATION NONRESIDENTIAL BUILDING OPERATOR
 7035 BEST WESTERN INN...HOTELS & MOTELS
 7035 BEST WESTERN PEACHTREE CORNER...HOTELS & MOTELS
 7040 BEST PAGER...BEEPERS-EQUIPMENT SERVICE & REPAIR
 7040 BEST PAGER...CELLULAR PHONE SVCS
 7040 ING WIRELESS...CELLULAR PHONE SVCS
 7040 PRESTIGE CLEANERS...DRYCLEANING PLANT
 7040 PRESTIGE CLEANERS...GMT PRESSG,CLRS AGT
 7040 SAIGON CAFE...EATING PLACE
 7040 SAIGON CAFE...EATING PLACES
 7040 TINAS ALTERATIONS...CUSTOM TAILOR
 7040 TINAS ALTERATIONS...ALTERATIONS-CLOTHING
 7040 VERIZON...RET MISC MERCHANDISE
 7044 WAFFLE HOUSE...RESTAURANTS
 7044 WAFFLE HOUSE RESTAURANT...COFFEE SHOP
 7045 FIRE MOUNTAIN...EATING PLACES
 7045 FIRE MOUNTAIN...RESTAURANTS
 7045 RYANS...RESTAURANT
 7046 DEKRA EMISSION CHECK INC...AUTO SV EX REPAIR
 7046 EMISSIONS CHECK...AUTOMOTIVE SERVICES
 7049 HOMESTEAD...HOTELS & MOTELS
 7049 HOMESTEAD STUDIO SUITES HOTEL...HOTEL EFFICIENCIES
 7050 ABBEY INSURANCE...INSURANCE
 7050 ABBEY INSURANCE OF NORCROSS...INSURANCE
 7050 ABBEY INSURANCE SERVICES INC...INSURANCE AGENCY
 7050 ACE CASH EXPRESS...DEPOSITORY BANKING SERVICES
 7050 AMARAL ANGELA DC...OFCSCNLS CHRPRCTRS
 7050 AMERICAN DENTAL GROUP...DENTISTS
 7050 ANGELA AMARAL...RESIDENTIAL
 7050 ARBYS...RESTAURANTS
 7050 ASSOCIATED DENTAL GROUP...DENTISTS OFFICE
 7050 ATLANTA INTERNATIONAL TRAVEL...TRAVEL AGENCIES & BUREAUS
 7050 ATLANTA INTERNATIONAL TRAVEL...TRAVEL AGENCIES
 7050 BAL TIC DELI...DELICATESSENS
 7050 BALTICA EUROPEAN MARKET...WHOL NONDURABLE GOODS
 7050 BARRONS JEWELERS...RET JEWELRY

Part 4 of 4

7050 BODY OF CHANGE INC...NONCLASSIFIED ESTABLISHMENTS
 7050 BUDDY BEAUTY MART...BEAUTY SALONS-EQUIPMENT & SUPLS (WHOL)
 7050 BUDDY BEAUTY MART...BEAUTY SALON,BARBERS
 7050 CHINESE SHAOLIN CTR...MARTIAL ARTS
 7050 CHINESE SHAOLIN CTR...RESTAURANTS
 7050 CITIFINANCIAL...BUSINESS SERVICES
 7050 CREATING CAKES...BAKERS-RETAIL
 7050 DAVID EHRMAN...RESIDENTIAL
 7050 ENVIOS LA FAMILIA PERUANA...NONCLASSIFIED ESTABLISHMENTS
 7050 ENVIOS LA FAMILIA PERUANA...EXPORTERS
 7050 GREAT EXPRESSIONS DENTAL CTR...DENTISTS OFF,CLINIC
 7050 GYE NYAME TROPICAL FOOD...RET GROCERIES
 7050 H & R BLOCK...TAX RETURN PREPARATION SERVICES
 7050 H & R BLOCK TAX SVC...TAX RETURN PREPARATION & FILING
 7050 H & R BLOCK TAX SVC...TAX RETURN PREP SV
 7050 HAIR OF GLORY...HAIRDRESSERS
 7050 HAIR OF GLORY...BEAUTY SHOP
 7050 HR INVISION...NCLASSIFIABLE ESTAB
 7050 KITCHEN CREATIONS...RETAIL AND INSTALL KITCHEN CABINETS BATHROOM
 7050 L A FITNESS SPORTS CLUB...PHYSICAL FITNESS CT
 7050 L A FITNESS SPORTS CLUB...HEALTH CLUBS STUDIOS & GYMNASIUMS
 7050 LOUISIANA KITCHEN...CABINETS EX CUST MADE
 7050 MANE PRIORITY...BEAUTY SALONS
 7050 MANE PRIORITY BARBER SHOP...BARBER SHOP
 7050 N B COLLECTION...CLOTHING-RETAIL
 7050 NAILS & MORE INC...BEAUTY SHOP
 7050 NAILS N MORE...BEAUTY SHOPS
 7050 NAILS N MORE...MANICURING
 7050 NORTH ATLANTA CHIROPRACTIC CTR...CHIROPRACTORS OFF
 7050 NORTH ATLANTA CHIROPRACTIC CTR...CHIROPRACTORS DC
 7050 PAYLESS SIGN...SIGNS & ADVERTISING SPECIALTIES (MFRS)
 7050 PAYLESS SIGNS...MFG ELECTRIC SIGNS
 7050 PEACHTREE CORNERS JUICE BAR...FRUIT & VEG MARKETS
 7050 PERLINOS...RESTAURANTS
 7050 PERLINOS...ITALIAN RESTURANT
 7050 PSG III LLC...NCLASSIFIABLE ESTAB
 7050 ROLY POLY MRB MANAGEMENT...EATING PLACE
 7050 SPORTS FOUNTAIN 5...PHYSICAL FITNESS CT
 7050 TOTAL AWARENESS & ASSOCIATES...ACCOUNTING/AUDITING/BOOKKEEPING
 7050 TURN KEY RENOVATIONS...REMODELING & REPAIRING BLDG CONTRACTORS
 7050 TURN KEY RENOVATIONS...FAMILY HSNQ CONSTR
 7050 UNIVERSAL COMPUTER...COMPUTER,SOFTWR STR
 7055 SIMONIZ...CARWASH & CONVENIENCE STORE
 7055 SIMONIZ AUTOWASH & MARKET...CAR WASHING & POLISHING
 7055 SIMONIZ CAR WASH...CARWASHES
 7065 STUDIO PLUS...HOTELS & MOTELS
 7065 STUDIO PLUS HOTELS INC...HOTELS & MOTELS
 7065 STUDIOPLUS PEACHTREE CORNERS...HOTEL
 7065 V BROOKS...RESIDENTIAL
 7070 MC DONALDS...RESTAURANTS
 7070 MC DONALDS HAMBURGERS...QUICK SERV BURGER
 7070 MCDONALDS...EATING PLACE
 7075 BLACK-EYED PEA RESTAURANT...CHAIN HOMESTYLE FULL-SERVICE
 7075 GRAND BUFFET...EATING PLACES
 7085 BITES THAI CUISINE...ORIENTAL MENU
 7085 BITES THAI CUISINE...EATING PLACE
 7085 JERSEY MIKES SUBMARINES...SANDWICHES
 7085 TWO BUCKS INC...EATING PLACE
 7095 ECONO LUBE N TUNE...OIL & LUBRICATION SERVICE
 7095 ECONO LUBE N TUNE...AUTOMOBILE REPAIRING & SERVICE

.....

=DO NOT CALL @=DO NOT MAIL @=DO NOT CALL OR MAIL

[illegible]

1982

JIMMY CARTER BOULEVARD

SOURCE: HAINES

1977

JIMMY CARTER BOULEVARD

SOURCE: HAINES

STREET NOT LISTED

JIMMY CARTER BLVD			30071 CONT.
6695	WALK SOFTLY INC	449-3773	1
6702	HERMAN MILLER INC	449-7551	9
6725	BUSCH INDSTR PROO	449-8548	+2
	D A T E C SYSTEMS	447-9202	1
	DATEC SYSTEMS INC	447-9202	0
	MINTON JONES CO	449-8787	9
	TEAPO ELECTRONIC	449-0034	+2
	ACE FIREPLACE SALES	447-8040	9
	ACE SALES DISTRIBTN	447-8040	9
	COLORAY PAINT CO	447-9684	0
	FLOOR SUPPLY CO	447-9684	0
6734	PREMIUM INNOVATIONS	448-3102	1
	PROMOTIONS&MCHNDSE	449-8018	0
	CENTRAL TEXT BOOK	447-8773	0
6755	MACMILLAN PUBLISHING	448-7997	5
	MCGRAW HILL INC	449-1836	+2
	LENI VLV&CPLNG HS	449-8330	1
6796	PARKER HANNIFIN CRP	449-8330	9
	PARKER HANNIFIN FLD	449-0889	+2
	PARKER MARINE CORP	447-9384	1
6836	DOWN CORPORATION	449-5841	9
6855	BUILDING	448-1291	1
	BALCOR PROP MNGMNT	447-8272	1
	BAYCOR	449-4500	9
	BEMIS CO INC	447-1451	+2
	BLACK BROS INC	448-8890	8
	BOOTH HINSON NOACK	448-7353	1
	C F S CONTINENTAL	449-5595	9
	CALORIC CORP	449-5603	9
	CHICOPEE MILLS INC	449-4960	9
	CHICOPEE MILLS INC	441-1331	+2
	CONSUMER FNCL INF	448-8162	+2
	CONTL TRANSACTION	447-9760	0
	COVENANT CNSTRCTM	447-8190	0
	CURWOOD INC	447-9500	0
	DANIELS ROBERT D	448-6072	+2
	DATA GENERAL CORP	448-1515	0
	DATAQUIP INC	449-4810	+2
	DUNN BOB&ASC	448-1515	0
	FISCHER&PORTER	448-5407	9
	FULLER CLIFTON S JR	448-1515	0
	G A INDUSTRIES	449-7950	1
	GENL ELC CRYT CNSTR	448-6800	8
	GILMAN PAPER CO	448-1515	8
	HENRY PRATT CO	449-8712	9
	HUBER J M CORP	449-8510	+2
	I N A REHAB SV	441-8800	+2
	I S A RESOURCES MNG	441-8800	+2
	INSURANCE SYSTEMS	449-8510	9
	INTL REHABILITATION	449-4200	0
	KATHSAM CO	448-1515	8
	LEOPOLD F B&CO	448-1980	0
	LOVABLE COMPANY	448-1225	+2
	MANUFRS MKTG ASSOC	449-3725	9
	MCGRAW EDISON POWR	449-3723	9
	MCGRAW EDISON POWR	447-6272	1
	NICOLON CORP	448-5235	8
	OPTIMAL SYSTEMS INC	448-5235	1
	OS I WEAR ANALYSIS	448-1515	8
	PASSOVANT CORP	448-5653	1
	PEACHTRE COR SNOWCH	448-0220	0
	PEACHTRE COR TRAVEL	441-0100	1
	R E MAX PCHTREE COR	448-1515	8
	SMITH&LOVELESS CO	449-1476	1
	SPRINT PRINT	448-5407	9
	STROTHER GLENN H	448-5407	9
	STROTHER HICKS	447-8440	1
	TELAUTOGRAPH CORP	448-1044	+2
	TELEPHONE CONSLTNTS	449-8998	+2
	TEMPO WEATHER	448-1044	+2
	THE PIEDMONT GROUP	447-8800	8
	TRANSIT CASUALTY CO	448-5235	9
	VACHON NIX&ASSOCTS	448-5448	9
	WALLACE JOHN E JR	447-8330	1
	WESTINGHS ELC SALES	449-8050	8
	WHEELING CORRUG	447-8330	8
	WHITE WESTINGHSE	448-1515	8
	WICKLIFFE A & CO	447-9426	0
	WILSON ELMER I JR	447-9426	1
	WILSON HOLMES&ASC		
6855		447-5525	1
6866	NORCOM INC	449-8464	+2
6885	CASE J I CO CE AREA	449-3720	+2
6924	FIRST INTL GWNT PCHT	00	
6925	XXXX	449-6636	0
NO #	DESIGNHOUSE INTL	449-8642	0
NO #	DESIGNHOUSE INTL	449-5300	9
NO #	PEACH ST FORD TRUCK		
	* 365 BUS 28 RES 148 NEW		

JIMMY CARTER DR 30083

1972

JIMMY CARTER BOULEVARD

SOURCE: HAINES

STREET NOT LISTED

1967

JIMMY CARTER BOULEVARD

SOURCE: POLKS

STREET NOT LISTED

STREET NOT LISTED

Appendix F

Certificate of Liability Insurance



CERTIFICATE OF LIABILITY INSURANCE

DATE (MM/DD/YYYY)

06/09/2022

THIS CERTIFICATE IS ISSUED AS A MATTER OF INFORMATION ONLY AND CONFERS NO RIGHTS UPON THE CERTIFICATE HOLDER. THIS CERTIFICATE DOES NOT AFFIRMATIVELY OR NEGATIVELY AMEND, EXTEND OR ALTER THE COVERAGE AFFORDED BY THE POLICIES BELOW. THIS CERTIFICATE OF INSURANCE DOES NOT CONSTITUTE A CONTRACT BETWEEN THE ISSUING INSURER(S), AUTHORIZED REPRESENTATIVE OR PRODUCER, AND THE CERTIFICATE HOLDER.

IMPORTANT: If the certificate holder is an ADDITIONAL INSURED, the policy(ies) must have ADDITIONAL INSURED provisions or be endorsed. If SUBROGATION IS WAIVED, subject to the terms and conditions of the policy, certain policies may require an endorsement. A statement on this certificate does not confer rights to the certificate holder in lieu of such endorsement(s).

PRODUCER RSC Insurance Brokerage, Inc. 1745 N. Brown Road Suite 250 Lawrenceville GA 30043	CONTACT NAME: Megan Willard PHONE (A/C, No, Ext): FAX (A/C, No): E-MAIL ADDRESS: mwillard@risk-strategies.com																					
INSURED Point To Point Enviromental, Inc. 1010 Pennsylvania Ave McDonough GA 30253	<table><tr><th colspan="2">INSURER(S) AFFORDING COVERAGE</th><th>NAIC #</th></tr><tr><td>INSURER A:</td><td>Travelers Property Casualty Company of America</td><td>25674</td></tr><tr><td>INSURER B:</td><td>Phoenix Insurance Co</td><td>25623</td></tr><tr><td>INSURER C:</td><td>Travelers Casualty Ins.Co of America</td><td>19046</td></tr><tr><td>INSURER D:</td><td></td><td></td></tr><tr><td>INSURER E:</td><td></td><td></td></tr><tr><td>INSURER F:</td><td></td><td></td></tr></table>	INSURER(S) AFFORDING COVERAGE		NAIC #	INSURER A:	Travelers Property Casualty Company of America	25674	INSURER B:	Phoenix Insurance Co	25623	INSURER C:	Travelers Casualty Ins.Co of America	19046	INSURER D:			INSURER E:			INSURER F:		
INSURER(S) AFFORDING COVERAGE		NAIC #																				
INSURER A:	Travelers Property Casualty Company of America	25674																				
INSURER B:	Phoenix Insurance Co	25623																				
INSURER C:	Travelers Casualty Ins.Co of America	19046																				
INSURER D:																						
INSURER E:																						
INSURER F:																						

COVERAGES **CERTIFICATE NUMBER:** CL226979138 **REVISION NUMBER:**

THIS IS TO CERTIFY THAT THE POLICIES OF INSURANCE LISTED BELOW HAVE BEEN ISSUED TO THE INSURED NAMED ABOVE FOR THE POLICY PERIOD INDICATED. NOTWITHSTANDING ANY REQUIREMENT, TERM OR CONDITION OF ANY CONTRACT OR OTHER DOCUMENT WITH RESPECT TO WHICH THIS CERTIFICATE MAY BE ISSUED OR MAY PERTAIN, THE INSURANCE AFFORDED BY THE POLICIES DESCRIBED HEREIN IS SUBJECT TO ALL THE TERMS, EXCLUSIONS AND CONDITIONS OF SUCH POLICIES. LIMITS SHOWN MAY HAVE BEEN REDUCED BY PAID CLAIMS.

INSR LTR	TYPE OF INSURANCE	ADDL INSD	SUBR WVD	POLICY NUMBER	POLICY EFF (MM/DD/YYYY)	POLICY EXP (MM/DD/YYYY)	LIMITS
A	☒ COMMERCIAL GENERAL LIABILITY ☐ CLAIMS-MADE ☒ OCCUR GEN'L AGGREGATE LIMIT APPLIES PER: ☐ POLICY ☒ PRO-JECT ☐ LOC OTHER:			6809N12580A	06/15/2022	06/15/2023	EACH OCCURRENCE \$ 1,000,000 DAMAGE TO RENTED PREMISES (Ea occurrence) \$ 1,000,000 MED EXP (Any one person) \$ 5,000 PERSONAL & ADV INJURY \$ 1,000,000 GENERAL AGGREGATE \$ 2,000,000 PRODUCTS - COMP/OP AGG \$ 2,000,000
B	☒ AUTOMOBILE LIABILITY ☒ ANY AUTO ☐ OWNED AUTOS ONLY ☐ SCHEDULED AUTOS ☐ HIRED AUTOS ONLY ☐ NON-OWNED AUTOS ONLY			BA8R518415	06/15/2022	06/15/2023	COMBINED SINGLE LIMIT (Ea accident) \$ 1,000,000 BODILY INJURY (Per person) \$ BODILY INJURY (Per accident) \$ PROPERTY DAMAGE (Per accident) \$
A	☒ UMBRELLA LIAB ☒ OCCUR ☐ EXCESS LIAB ☐ CLAIMS-MADE DED ☒ RETENTION \$ 10,000			CUP9N627903	06/15/2022	06/15/2023	EACH OCCURRENCE \$ 1,000,000 AGGREGATE \$ 1,000,000
C	WORKERS COMPENSATION AND EMPLOYERS' LIABILITY ANY PROPRIETOR/PARTNER/EXECUTIVE OFFICER/MEMBER EXCLUDED? (Mandatory in NH) If yes, describe under DESCRIPTION OF OPERATIONS below		N/A	UB9N129705	06/15/2022	06/15/2023	☒ PER STATUTE ☐ OTH-ER E.L. EACH ACCIDENT \$ 1,000,000 E.L. DISEASE - EA EMPLOYEE \$ 1,000,000 E.L. DISEASE - POLICY LIMIT \$ 1,000,000
C	Professional Liability			107110655	06/15/2022	06/15/2023	Each Claim \$1,000,000 Aggregate \$2,000,000

DESCRIPTION OF OPERATIONS / LOCATIONS / VEHICLES (ACORD 101, Additional Remarks Schedule, may be attached if more space is required)

CERTIFICATE HOLDER**CANCELLATION**

Specimen Certificate of Insurance

SHOULD ANY OF THE ABOVE DESCRIBED POLICIES BE CANCELLED BEFORE THE EXPIRATION DATE THEREOF, NOTICE WILL BE DELIVERED IN ACCORDANCE WITH THE POLICY PROVISIONS.

AUTHORIZED REPRESENTATIVE

© 1988-2015 ACORD CORPORATION. All rights reserved.